Index 641-020 Concrete CCTV Pole

ORIGINATION

Date: June 28, 2022 Name: Matthew DeWitt Phone: (850) 921-7353 Email: Matthew.Dewitt@dot.state.fl.us

COMMENTARY

These proposed changes were developed based on implementing a maintenance service slab for ITS cabinets recommended during the TDH integration into statewide criteria. Language has also been added to Specification 676 for the maintenance service slab.

COMMENTS AND RESPONSES

BLACK = Industry Review Comments **BLUE** = Standard Plans Response **GREEN** = Change Made to Index


Name: Miguel Villegas Date: 8/17/2022

COMMENT: On sheet 6 of 6, maybe the location of the proposed maintenance slab can be shown to be cast against the shaft as opposed to being cast against the conduits. Also, will the Department consider making the maintenance slab of a standard thickness or will it need to be designed by a structural engineer.

RESPONSE: Agree the slab should be shown to be cast against the shaft and the conduits should be adjusted. The maintenance slab is intended to be 6" thick. This is shown in Index 676-010 but will be clarified. We will revise 641-020, 649-020 and 676-010 to show the slab thicknesses accurately.

CHANGE TO THE INDEX: Edit slab adjacent to shaft and adjust conduit. Edit pull boxes throughout the index to show 6" aprons to match maintenance service slabs.


Response Date: 8/23/2022



	~	DECON
T	≲	DESCRI
	$ \Sigma $	
ION	$\overline{\mathcal{O}}$	







CCUC/ 1/