ORIGINATION FORM

Proposed Revisions to a Standard Plans Index

(Please provide all information — Incomplete forms will be returned)

Contact Information:

Date: July 5, 2023 Originator: Rick Jenkins Phone: (850) 414-4355 Email: Rick.Jenkins@dot.state.fl.us

Standard Plans:

Index Number: 676-010 Sheet Number (s): 4 of 4 Index Title: Cabinet Installation Detalis

Summary of the changes:

Sheets 1-3: Renumbered.

Sheet 1: Deleted Existing Controller Cabinet elevation

Sheet 2: Updated Metal Pole cabinet to ITS cabinet

Sheet 4: New Sheet for Ground Mounted Controller Cabinet Riser

Commentary / Background:


This request came from the Districts and was coordinated with the TERL and Structures Design. Some Districts are installing these and the addition to the Standard Plans Index will allow use without a special detail in every plan set. This detail is for a concrete riser only. An associated change is being made to Specification 676 regarding this revision.

The deletion of the Existing Controller Cabinet elevation and notes was requested by the TERL due to the requirements referenced in the notes being removed and the requirements for retrofitting cabinets varying based on agency needs. They also suggested we update the ITS cabinet on Sheet 2.

Other Affected Offices / Documents: (Provide name of person contacted)


Yes	No					
	\checkmark	Other Standard Plans –				
	\checkmark	FDOT Design Manual –				
\checkmark		Basis of Estimates Manual – Ryan Gray				
\checkmark		Standard Specifications – Daniel Strickland				
	\checkmark	Approved Product List –				
	\checkmark	Construction –				
	\checkmark	Maintenance –				
<u>Origin</u>	atio	n Package Includes: (Submit package to Rick Jenkins)	Implementation:			
Yes	N/A	A	🔲 Design Bulletin (Interim)			
\checkmark	\Box	Redline Mark-ups	🔲 DCE Memo			
		Revised or Proposed Standard Plan Instruction (SPI)	🔲 Program Mgmt. Bulletin			
		Other Support Documents	FY-Standard Plans (Next Release)			
Contract the Development Office for excitations in convertation this form						

— Contact the Roadway Design Office for assistance in completing this form — Email to: Rick Jenkins <u>rick.jenkins@dot.state.fl.us</u> and Darren Martin <u>darren.martin@dot.state.fl.us</u>




NOTES:

- 1. Maintenance Service Slab: Use Class NS concrete and slope 1/4" to 1" for drainage. Not required in sidewalk, pavement areas, or where R/W is restricted.
- 2. If cabinet mounting requires relocation of hole in concrete pole, fill existing hole with concrete or cover with a noncorrosive cover plate.
- 3. Liquidtight flexible conduit is approved for use from the electrical disconnect to the cabinet when both are installed on the same pole.
- 4. Where a pull box is to be placed within the maintenance service slab, the slab width must be extended to provide for the required pull box concrete apron as detailed in Index 635-001.
- 5. Coordinate placement of maintenance service slab with proposed final grade. Grade and compact side slopes around the maintenance service slab to provide a stable and level working area and tie into the proposed embankment.



NOTES:

- 1. Maintenance Service Slab: Use Class NS concrete and slope $\frac{1}{4}$ " to 1" for drainage. Not required in sidewalk, pavement areas, or where R/W is restricted.
- 2. The number, size and orientation of conduit sweep will vary according to site condition or locations. Provided two spare 2" PVC conduits in all bases. Place the exits of the spare conduits in the direction of the center rear of the cabinet base and into a pull box. If obstructions prevent the spare conduit from exiting to the rear, or the rear of the cabinet is located on the R/W line, locate as directed by the Engineer. Cap all spare conduit sweeps with a weatherproof fitting.
- 3. When a pull box is to be placed within the maintenance service slab, the slab width must be extended to provide for the required pull box apron as detailed in Index 635-001.
- 4. Coordinate placement of maintenance service slab with proposed final grade. Grade and compact side slopes around the maintenance service slab to provide a stable and level working area and tie into the proposed embankment.



GROUND MOUNTED INTELLIGENT TRANSPORTATION SYSTEMS (ITS) CABINET

LAST


REVISION - 11/01/23 11/01/22


DESCRIPTION:



FY 2023-24 STANDARD PLANS

CABINET INSTALLATION DETAILS






3 of 4				
	INDEX	SHEET		
DETAILS	676-010	3 of 3		

NEW SHEET 4

GROUND MOUNTED CONTROLLER CABINET RISER


676-010 4 of 4



	INDEX	SHEET
DETAILS	676-010	1 of 4


NOTES:

- 1. Maintenance Service Slab: Use Class NS concrete and slope $\frac{1}{4}$ " to 1" for drainage. Not required in sidewalk, pavement areas, or where R/W is restricted.
- 2. If cabinet mounting requires relocation of hole in concrete pole, fill existing hole with concrete or cover with a noncorrosive cover plate.
- 3. Liquidtight flexible conduit is approved for use from the electrical disconnect to the cabinet when both are installed on the same pole.
- 4. Where a pull box is to be placed within the maintenance service slab, the slab width must be extended to provide for the required pull box concrete apron as detailed in Index 635-001.
- 5. Coordinate placement of maintenance service slab with proposed final grade. Grade and compact side slopes around the maintenance service slab to provide a stable and level working area and tie into the proposed embankment.



NOTES:

- 1. Maintenance Service Slab: Use Class NS concrete and slope $\frac{1}{4}$ " to 1" for drainage. Not required in sidewalk, pavement areas, or where R/W is restricted.
- 2. The number, size and orientation of conduit sweep will vary according to site condition or locations. Provide two spare 2" PVC conduits in all bases. Place the exits of the spare conduits in the direction of the center rear of the cabinet base and into a pull box. If obstructions prevent the spare conduit from exiting to the rear, or the rear of the cabinet is located on the R/W line, locate as directed by the Engineer. Cap all spare conduit sweeps with a weatherproof fitting.
- 3. When a pull box is to be placed within the maintenance service slab, the slab width must be extended to provide for the required pull box apron as detailed in Index 635-001.
- 4. Coordinate placement of maintenance service slab with proposed final grade. Grade and compact side slopes around the maintenance service slab to provide a stable and level working area and tie into the proposed embankment.



GROUND MOUNTED INTELLIGENT TRANSPORTATION SYSTEMS (ITS) CABINET

LAST

11/01/23


DESCRIPTION: REVISION



FY 2024-25 STANDARD PLANS

CABINET INSTALLATION DETAILS

INDEX SHEET 676-010 2 of 4



	INDEX	SHEET
DETAILS	676-010	3 of 4

