


October 28-29, 2025

Orlando, FL




**TRANSPORTATION
SYMPOSIUM**

SR 115, Arlington Expressway, Jacksonville, Florida Over Red Bay Branch Bridge Repair, Bridge No. 720136 – Lessons Learned

Andrew Pinkham
Zachary Behring, PE
Sam Middleton, PE, PTOE


Transportation Symposium
Website



SCAN ME

1

Project Background



**TRANSPORTATION
SYMPOSIUM**

2

2

Project Background




TRANSPORTATION
SYMPOSIUM

3

3

Project Background



Construction 1960
 FDOT began maintenance 1970-1972
 Slabs tied together by post tension bar
 Distress indicated separation of the slabs

TRANSPORTATION
SYMPOSIUM

4

4



Key Lessons

- Select appropriate repair
- Early coordination
- Education

TRANSPORTATION
SYMPOSIUM

5

5



TRANSPORTATION
SYMPOSIUM

6

6

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/29/2015 UNDERWATER: N/A	
SMART FLAGS: OVERALL NBI RATINGS:	
None	DECK: 7 Good SUPERSTRUCTURE: 7 Good SUBSTRUCTURE: 6 Satisfactory PERF. RATING: Good
2015	CHANNEL: 7 Minor Damage CULVERT: N N/A (NBI) SUFF. RATING: 91.9 HEALTH INDEX: 80.16

Bridge# 720136
(North Bridge)

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/12/2017 UNDERWATER: N/A	
OVERALL NBI RATINGS:	
DECK: 7 Good SUPERSTRUCTURE: 5 Fair SUBSTRUCTURE: 6 Satisfactory PERF. RATING: 3 - Fair	CHANNEL: 7 Minor Damage CULVERT: N N/A (NBI) SUFF. RATING: 91.9 HEALTH INDEX: 99.58
	2017

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input checked="" type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/5/2019 UNDERWATER: N/A	
OVERALL NBI RATINGS:	
DECK: 4 Poor SUPERSTRUCTURE: 4 Poor SUBSTRUCTURE: 6 Satisfactory PERF. RATING: Poor	CHANNEL: 7 Minor Damage CULVERT: N N/A (NBI) SUFF. RATING: 47.8 HEALTH INDEX: 94.66
	2019
The NBI rating for Superstructure was lowered from a "5" to a "4" due to new guidance for rating sonovoid slabs. The NBI rating for Deck was lowered from a "7" to a "4" due to new guidance for rating sonovoid slabs. The District Structures Maintenance Engineer was notified as well as the District Bridge Engineering Section.	

TRANSPORTATION
SYMPOSIUM

7

7



TRANSPORTATION
SYMPOSIUM

8

8



PHOTO 10 – ELEMENT 8099/510
VIEW OF UP TO MODERATE SIZE LONGITUDINAL CRACKS
IN ASPHALT WEARING SURFACE

Bridge# 720136

TRANSPORTATION
SYMPOSIUM

9

9

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/30/2015 UNDERWATER: N/A	
SMART FLAGS: None	
OVERALL NBI RATINGS:	
DECK: 7 Good	CHANNEL: 7 Minor Damage
SUPERSTRUCTURE: 7 Good	CULVERT: N N/A (NBI)
SUBSTRUCTURE: 6 Satisfactory	SUFF. RATING: 92.9
PERF. RATING: Good	HEALTH INDEX: 81.35

2015

Bridge# 720148
(South Bridge)

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/13/2017 UNDERWATER: N/A	
OVERALL NBI RATINGS:	
DECK: 5 Fair	CHANNEL: 7 Minor Damage
SUPERSTRUCTURE: 7 Good	CULVERT: N N/A (NBI)
SUBSTRUCTURE: 6 Satisfactory	SUFF. RATING: 92.9
PERF. RATING: 3 - Fair	HEALTH INDEX: 98.72

2017

<input type="checkbox"/> FUNCTIONALLY OBSOLETE	<input checked="" type="checkbox"/> STRUCTURALLY DEFICIENT
TYPE OF INSPECTION: Regular NBI	
DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 12/5/2019 UNDERWATER: N/A	
OVERALL NBI RATINGS:	
DECK: 4 Poor	CHANNEL: 7 Minor Damage
SUPERSTRUCTURE: 4 Poor	CULVERT: N N/A (NBI)
SUBSTRUCTURE: 6 Satisfactory	SUFF. RATING: 62.9
PERF. RATING: Poor	HEALTH INDEX: 87.91

2019

The NBI rating for Deck was dropped from a "5" to a "4" during this inspection per recommendations from the Central Office regarding sonovoid slab units.
The NBI rating for Superstructure was dropped from a "7" to a "4" during this inspection per recommendations from the Central Office regarding sonovoid slab units. The District Structures Maintenance Engineer was notified as well as the District Bridge Engineering Section.

TRANSPORTATION
SYMPOSIUM

10

10



PHOTO 10 – ELEMENT 8099/510
TYPICAL VIEW OF UP TO WIDE SIZE LONGITUDINAL CRACKS IN ASPHALT
SURFACE OVER SLAB UNIT JOINTS AT RANDOM LOCATIONS

Bridge# 720148

TRANSPORTATION
SYMPOSIUM

11

11



PHOTO 3 – ELEMENT 8099 (W/O)
TYPICAL VIEW OF TRANSVERSE POST TENSIONING BARS
WITH SURFACE CORROSION



PHOTO 6 – ELEMENT 8099
TYPICAL VIEW OF EFFLORESCENCE AND CORROSION BLEEDOUT EMITTING
FROM LONGITUDINAL JOINT BETWEEN SLAB UNITS

TRANSPORTATION
SYMPOSIUM

12

12



BRIDGE MAINTENANCE AND REPAIR HANDBOOK

Florida Department of Transportation
Office of Maintenance
1-866-374-3368 Phone
1-850-410-5511 Fax

BRIDGE MAINTENANCE & REPAIR HANDBOOK

2. Transverse cracks may also be caused by flexure of the deck or lack of cover on the reinforcement.
3. Longitudinal cracks are common over the joints between prestresses, precast adjacent concrete box beams or sonovoid slab units. The cracks are caused by non-uniform bending action of the beams under traffic. Longitudinal cracks also occur over the longitudinal beams of other bridge types when the beam spacing is large and the deck bends over the beams.
4. Random, map or alligator cracking results at locations where excessive shrinkage occurs in fresh concrete due to rapid evaporation, or they result due to factors such as aggregate-cement reaction.
5. Foundation settlement can cause a twisting force on a concrete deck that generally results in a diagonal cracking pattern.
6. Thermal expansion caused by a high temperature combined with debris filled expansion joints can cause deck cracking, or spalling, near expansion joints.

**TRANSPORTATION
SYMPOSIUM**

13

13

BRIDGE MAINTENANCE & REPAIR HANDBOOK

4.5 CONCRETE BEAM & GIRDER REPAIR

4.5.1 Crack Repair

A. Epoxy Injection

1. Clean the cracks by air or brush.
2. Install the ports along the crack and seal all the other cracks with epoxy.
3. After the sealing is cured, begin pumping epoxy into the first port that is normally the lowest port.
4. Continue pumping until epoxy flows from a second port.
5. Seal the first port and begin pumping at the second port.
6. Repeat steps 3, 4 and 5 until all ports are full.
7. Remove ports and surface seal after epoxy has cured.

B. Penetrant Sealer

1. The concrete surfaces shall be prepared for sealing by using high pressure (6,000 psi nozzle pressure) water blasting to remove all traces of dirt, grime, mineral deposits and all other deleterious material.
2. Apply the penetrant sealer in accordance with the specification and the manufacturer's recommendation.

C. Drypacking

Drypack can be used for filling narrow slots cut for the repair of dormant cracks. Repair the crack by hand placement of a low water content mortar followed by tamping or ramming of the mortar into place. The use of drypack is not recommended for "active" cracks.


1. Before a crack can be repaired by drypacking, the portion adjacent to the surface should be widened to a slot about 1 inch wide and 1 inch deep using a power-driven sawtooth bit. The slot should be undercut so that the base width is slightly greater than the surface width.
2. Clean the slot thoroughly.
3. Apply a bond coat, consisting of cement slurry or equal quantities of cement and fine sand, mixed with water to a fluid paste consistency.

None of the repair procedures given in the Bridge Maintenance and Repair Handbook address the underlying issue of differential beam deflections

**TRANSPORTATION
SYMPOSIUM**

14

14



15

Table 4.2 Rating of Double-Tee Bridge Longitudinal Joint Rehabilitation Alternatives

Alt. No.	Alt. Name	Filler Material	Reinforcement Type	Const. Risk Rating	Durability Rating	Perform. Rating	Inspect. Rating	Cost Rating	Overall Rating
1	CUH	UHPC	Headed-Bar	0, -1, 0	2, 1, 1	2, 1, 1	0, 0, 0	-2	5
2	CUW	UHPC	Wire-Mesh	0, 0, 0	2, 0, 1	2, -1, 1	0, 0, 0	-2	3
3	CNH	NSG	Headed-Bar	0, -1, 0	-1, 1, 1	0, 1, 1	0, 0, 0	0	2
4	CNW	NSG	Wire-Mesh	0, 0, 0	-1, 0, 1	0, -1, 1	0, 0, 0	0	0
5	CMH	MAP	Headed-Bar	0, -1, 0	-1, 1, 1	1, 1, 1	0, 0, 0	-2	1
6	CMW	MAP	Wire-Mesh	0, 0, 0	-1, 0, 1	1, -1, 1	0, 0, 0	-2	-1
7	CLH	LMC	Headed-Bar	0, -1, 0	2, 1, 1	2, 1, 1	0, 0, 0	-2	5
8	CLW	LMC	Wire-Mesh	0, 0, 0	2, 0, 1	2, -1, 1	0, 0, 0	-2	3
9	CFH	FRG	Headed-Bar	-1, -1, 0	1, 1, 1	1, 1, 1	0, 0, 0	-1	3
10	CFW	FRG	Wire-mesh	-1, 0, 0	1, 0, 1	1, -1, 1	0, 0, 0	-1	1
11	DUH	UHPC	Headed-Bar	0, -1, -1	2, 1, -1	2, 1, -2	0, 0, 0	-2	-1
12	DUR	UHPC	Rebar	0, 0, -1	2, 0, -1	2, -1, -2	0, 0, 0	-2	-3
13	DNH	NSG	Headed-Bar	0, -1, -1	-1, 1, -1	0, 1, -2	0, 0, 0	0	-4
14	DNR	NSG	Rebar	0, 0, -1	-1, 0, -1	0, -1, -2	0, 0, 0	0	-6
15	DMH	MAP	Headed-Bar	0, -1, -1	-1, 1, -1	1, 1, -2	0, 0, 0	-2	-5
16	DMR	MAP	Rebar	0, 0, -1	-1, 0, -1	1, -1, -2	0, 0, 0	-2	-7
17	DLH	LMC	Headed-Bar	0, -1, -1	2, 1, -1	2, 1, -2	0, 0, 0	-2	-1
18	DLR	LMC	Rebar	0, 0, -1	2, 0, -1	2, -1, -2	0, 0, 0	-2	-3
19	DFH	FRG	Headed-Bar	-1, -1, -1	1, 1, -1	1, 1, -2	0, 0, 0	-1	-3
20	DFW	FRG	Rebar	1, 0, -1	1, 0, -1	1, -1, -2	0, 0, 0	-1	-5

Notes: The rehabilitation alternative names consist of letters referring to:
 C – Continuous Joint Rehabilitation, D – Dowel Bar Retrofit, U – Ultra-High Performance Concrete, L – Latex Modified Concrete, F – Fiber Reinforced Grout, N – Non-Shrink Grout, M – Magnesium Ammonium Phosphate Grout, H – Headed Bar, W – Wire Mesh, R-Rebar.

(Bohn)2019

TRANSPORTATION SYMPOSIUM

16

16

Table 25.3.1-1 Joint Type

Joint Type [material used]	Applications	Width of Joint
Match-Cast Joints [two-face epoxy]	Adjoining members are post-tensioned together. Adjoining substructure members are connected with grouted reinforcing sleeve couplers at a horizontal joint ¹	zero
Pseudo Match-Cast Joints ² [two-face epoxy]	Adjoining members are post-tensioned together. One of the elements is precast and the other is cast-in-place. Adjoining substructure members are connected with grouted reinforcing sleeve couplers at a horizontal joint ¹	zero
Non-Match-Cast Grouted Joints (excluding beam buildups between beam and precast deck panels) [non-shrink grout]	Adjoining members are not post-tensioned together. Members are joined with grouted reinforcing sleeve couplers. Element to element tolerances within ±1/4-inch	Varies depending on element tolerances 1/4-inch minimum
Closure Pours Adjoining members are post-tensioned together [concrete]	Where dimensional variability of adjoining ducts is high or where jack access is required	2'-0" minimum
Closure Pours Adjoining members are not post-tensioned together [concrete]	Where duct coupling is required and dimensional variability of adjoining ducts is relatively low and jack access is not required	1'-6" minimum
Closure Pours Adjoining members are not post-tensioned together [concrete]	Members are joined with reinforcing bar extensions (Lap Splices)	As required to develop reinforcing 2'-0" minimum
Closure Pours Adjoining members are not post-tensioned together [Ultra High Performance Concrete (UHPC)]	Members are joined with reinforcing bar extensions	As required to develop reinforcing 6-inches minimum

1. LRFD 5.12.5.4.2 requirements for minimum stress across epoxy joints are intended to control geometry for segmental applications and may be waived for this application.
2. See Section 25.4.3.5 for Pseudo Match-Cast Epoxy example.
3. Concrete mixes with shrinkage reducing admixtures.
4. Prepare specification requirements to prevent sole-sourcing a proprietary product.
5. LRFD 5.12.2.3.3e requirement for a minimum pour width is waived for UHPC.

Figure 25.3.3-4 Headed Bars and Hooks Closure Pour







Figure 25.3.3-3 Splice Overlap Closure Pour




5.12.2.3.3e—Cast-in-Place Closure Joints


Concrete in the closure joint should have strength comparable to that of the precast components. The width of the longitudinal joint shall be large enough to accommodate development of reinforcement in the joint, but in no case shall the width of the joint be less than 12.0 in.

TRANSPORTATION
SYMPOSIUM



(Garber, 2021)





- [I-10 over CR268A Approach Slab Replacement](#)
- [I-10 over Flat Creek Approach Slab Replacement](#)
- [I-95 over CR5A - Precast Deck Panel Replacement](#)
- [I-95/JT Butler Interchange Bridge U-Beam Repair](#)
- [SR 115/Arlington Expy over Red Bar Branch](#)
- [SR25\(US27\) NB over Fisheating Creek](#)
- [SR 714/Danforth Creek - Sonovoid Rehab](#)
- [SR 924/NW 119th St over Rio Vista Canal](#)
- [SR 994/Quail Roost Dr over Canal C-102](#)
- [US1 over Little Duck Key Channel](#)
- [US441 over Taylor Creek - Span 12 Replacement](#)
- [US41 over Sunset Waterway Link Slab](#)
- [CR339/Waccasassa River Pile Demonstration](#)

Closure pours or
Longitudinal Joint Repair

TRANSPORTATION
SYMPOSIUM

SR 25 (US27) NB over Fisheating Creek Overflow

19

19

References:

- FDOT Bridge Maintenance & Repair Handbook (2019)
- FDOT Structures Manual (2025)
- Review and Structural Investigation of Cracked Bridge Decks (Shahawy, 2001)
- Rehabilitation of Longitudinal Joints in Double-Tee Girder Bridges (Bohn, 2019)
- Bridge Maintenance Reference Manual (FHWA, 2015)
- Florida Slab Beam Bridge with UHPC Joint connections (Garber, 2021)
- <https://www.fdot.gov/structures/innovation/uhpc.shtm>

TRANSPORTATION
SYMPOSIUM

20

20

History of UHPC


- 1980s designed by the US Army Corps of Engineers to harden military structures
- 1997 First use of UHPC in North America was the Sherbrooke Pedestrian Bridge in Quebec
- 2000 (+/-) UHPC becomes commercially available
- 2006 First use in United States was on the Mars Hill Bridge
- 2016 FDOT utilizes UHPC for sonovoid repair (SR714/Martin Downs Blvd over Danforth Ck)
- 2020 FDOT installs first UHPC H-pile (County Road 339 Waccasassa River)
- **2024 Largest use of UHPC in FDOT to date (Arlington Expressway)**



Sherbrooke Pedestrian Bridge, Quebec (Perry)



Mars Hill Bridge (FHWA)



Current UHPC projects in United States and Florida (as of October 2025)

**TRANSPORTATION
SYMPOSIUM**

21

21

What is UHPC?

****No industry-wide standard definition exists****

- Generally, UHPC can be defined as a material that far exceeds the capabilities of conventional concretes.

- Very low w/b ratio (< 0.2)
- Low to extremely low permeability
- High compressive and tensile strengths
- Sustained post cracking tensile resistance



Credit: Kyle Riding

**TRANSPORTATION
SYMPOSIUM**

22

UHPC Materials

- UHPC is commonly prepackaged, proprietary material, however, careful selection and testing of materials does permit “locally sourced” UHPCs.
- Cement – most commonly Type I/II
- Supplementary Cementitious Materials (commonly silica based)
- Fine sand
- Fiber reinforcement – traditionally metallic, however, non-metallic also utilized
- Admixtures
- Water – ice may also be specified
- Particle packing to achieve discontinuous pore structure
- Properties of UHPC products vary greatly from producer-to-producer and by specified use

TOP SECRET

TRANSPORTATION
SYMPOSIUM

23

FDOT UHPC Plastic Properties Testing

- Temperature – ASTM C1064
- Flow Spread – ASTM C1437 (as modified by ASTM C1856)
Working Time – elapsed time when flow drops below 7”
Fiber segregation can also be visually verified
- Density – ASTM C138
- Time of Set – ASTM C191 (as modified by ASTM C1856)



TRANSPORTATION
SYMPOSIUM

24

FDOT UHPC Hardened Properties Testing

FDOT required values at 28 days

- Compressive strength – ASTM C39 (as modified by ASTM C1856) ≥17,500 psi
 Note: C1856 specifies grinding cylinder ends
- Flexural Strength (first peak)– ASTM C1609 (as modified by ASTM C1856) ≥1,200 PSI
 Effective cracking strength – AASHTO T397 ≥1,000 PSI
 Crack localization strength – AASHTO T397 ≥1,000 PSI
 Crack Localization Strain – AASHTO T397 ≥ 0.0035
- Length Change of Hardened Concrete – ASTM C157 (as modified by ASTM C1856) ≤800 micro-strain
- Tensile strength and relative toughness of cylinders by Double-Punch (Barcelona Test) – FM 5-516 –
 Informational only at this time



25

FDOT UHPC Durability requirements


FDOT required values at 28 days

- Chloride Content – FM 5-516 ≤ 0.40 lb/yd³
 Note: FDOT has specified that chloride samples shall be taken prior to addition of fibers.
 Composite density utilized.
- Chloride ion permeability – AASHTO T259 (0.5-inch depth) <0.1 lb/yd³
- Scaling Resistance – ASTM C672 Y < 3
- Freeze-Thaw resistance - AASHTO T 161/ASTM C666A (600 cycles) Relative Dynamic Modulus of Elasticity ≥ 95%
- Alkali-Silica Reaction - ASTM C1567 Innocuous

Note: Test methods/requirements subject to change as new research and specifications develop

TRANSPORTATION
SYMPOSIUM


26



27

FDOT UHPC Approval

FDOT is utilizing the Approved Products List (APL)/PATH program to preapprove UHPC as individual PRODUCTS by the producer.



28

28

Early Coordination

- State Materials Office
 - Developmental Specifications
 - <https://www.fdot.gov/programmanagement/otherfdotlinks/developmental/default.shtm>

Dev349UHPC - Ultra-High-Performance Concrete	Must Be Used Together Allows the use of Ultra-High-Performance Concrete.	Oliver Chung	N/A
Dev927UHPC - Prepackaged Ultra-High-Performance Concrete			

Early Coordination

- 349-3.3 – Manufacturer Technical Rep
- 349-4 – Construction work plan
- 349-6 Mockup

Early Coordination

• 349-3.3 – Manufacturer Technical Rep



TRANSPORTATION
SYMPOSIUM

35

35

Early Coordination

ceEntek
Next Generation UHPC 2.0™

**UHPC FIELD CAST CLOSURE POURS
CONSTRUCTION PLACEMENT & QA/QC PLAN**

Project: FL T2934 SR 115 (Jalington Expressway) over Red Bay Branch Bridge Repair
Contractor: Superior Construction
Date: June 29, 2023

Photo: UHPC Connection for Precast Elements with Thermal Control

Introduction
The following outlines the procedures and equipment to be used for the production of field cast UHPC closure pours, casting, and construction for the project FL T2934 SR 115 (Jalington Expressway) over Red Bay Branch Bridge Repair by Superior Construction, using ceEntek's Next Generation ce2005F-G™ UHPC 2.0™ mix, under the guidance of ceEntek's technicians.

This Construction Placement & QA/QC Plan covers the means and methods associated with the UHPC connection on this project. This submission is for review and acceptance by the owner &/or owner's representative prior to placing UHPC.

Raw Materials
ceEntek will supply UHPC preblended (ce2005F-G™) in bulk bags, the CMI paste and admixtures in pails, and the steel fibers in paper bags. One bulk bag will batch 0.65 cubic yards of UHPC.

Equipment
Mixers
ceEntek will provide 2- Model 30 mixers, each with a mixing capacity of 0.65 cubic yard batch size for the batching.

Confidential

Page | 3 of 8

• 349-4 – Construction work plan

TRANSPORTATION
SYMPOSIUM

36

36

Early Coordination

- 349-6 Mockup



TRANSPORTATION
SYMPOSIUM

37

37

Early Coordination

- Technical Special Provision Library
 - <https://www.fdot.gov/programmanagement/otherfdotlinks/technical-special-provision-library/tsp-library>
- Section T401
 - It is a DRAFT
 - EOR needs to **MODIFY TO FIT THE PROJECT**
 - EOR holds **FULL RESPONSIBILITY**

TRANSPORTATION
SYMPOSIUM

38

38

Early Coordination

- Use requires Structures Design review.
- Technically meets Category 2 criteria.
- APL product: <https://path.fdot.gov/ProductTypes/Index/750>



TRANSPORTATION
SYMPOSIUM

39

39

Education

- UHPC limited use
- Test procedures
- Labs have limited experience



TRANSPORTATION
SYMPOSIUM

40

40

Summary

- Chose the right repair material
 - UHPC is one of many tools available
 - Not a one size fits all
- Early Coordination
 - Developmental Specification
 - APL product
- Education
 - UHPC limited use in Florida
 - Technical Specifications
 - Many testing labs lack experience

TRANSPORTATION
SYMPOSIUM

41


41

Safety Message



When the gates are down, don't go around
Think train

Freight and passenger trains travel at different speeds
Double tracks – possibly two trains different directions
Stopping distance loaded freight almost one mile



TRANSPORTATION
SYMPOSIUM

42

42


Contact Us


- Andrew Pinkham – State Materials Office
 - Andrew.Pinkham@dot.state.fl.us
 - 352-955-6684
- Sam Middleton – District 2 Materials
 - Sam.Middleton@dot.state.fl.us
 - 386-961-7853
- Zach Behring – State Structures Design Office
 - Zachary.Behring@dot.state.fl.us
 - 850-414-4780


TRANSPORTATION
SYMPOSIUM

43


43

 October 28-29, 2025

 Orlando, FL




DEADLINE



Please be sure to **certify your attendance** before leaving this event or no later than **November 30th**, in order to receive PDH/CEC. Detailed instructions are available on the Transportation Symposium website.

Transportation Symposium Website



SCAN ME

44