



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:06:31AM

Valid from April 1, 2015 to June 30, 2015

## DISTRICT: 01

| Mine  | Company Name                          | Product                | Process | Description | Est. Optimum Moisture* | Pit Proctor (pcf) |                          |
|-------|---------------------------------------|------------------------|---------|-------------|------------------------|-------------------|--------------------------|
| 01305 | EARTHSOURCE INC.                      | <a href="#">Map it</a> | B11     | 1           | Shell Rock             | 9.0               | 127                      |
| 01495 | SOUTHWEST AGGREGATES                  | <a href="#">Map it</a> | B11     | 1           | Shell Rock             |                   | Roadway Testing Required |
| 01730 | ALLIGATOR ALLEY AGGREGATE AND ASPHALT | <a href="#">Map it</a> | B11     | 1           | Shell Rock             | 8.7               | 131                      |
| 01791 | WATERMELON PIT, LLC                   | <a href="#">Map it</a> | B02     | 1           | Bank Run Shell         |                   | Roadway Testing Required |
| 03037 | VULCAN MATERIALS COMPANY              | <a href="#">Map it</a> | B01     | 1           | Limerock               | 9.2               | 123                      |
| 03340 | ALLIGATOR ALLEY AGGREGATE AND ASPHALT | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 03616 | CONRAD YELVINGTON DISTRIBUTORS        | <a href="#">Map it</a> | B01     | 1           | Limerock               | 9.8               | 127                      |
| 05354 | RIDGDILL & SONS INC.                  | <a href="#">Map it</a> | B01     | 1           | Limerock               | 9.0               | 129                      |
| 05354 | RIDGDILL & SONS INC.                  | <a href="#">Map it</a> | B01     | 2           | Limerock               |                   | Roadway Testing Required |
| 05771 | SEMINOLE TRIBE OF FLORIDA, INC.       | <a href="#">Map it</a> | B11     | 1           | Shell Rock             |                   | Roadway Testing Required |
| 12008 | CEMEX                                 | <a href="#">Map it</a> | B01     | 2           | Limerock               | 7.2               | 135                      |
| 12260 | VULCAN MATERIALS COMPANY              | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 12260 | VULCAN MATERIALS COMPANY              | <a href="#">Map it</a> | B01     | 2           | Limerock               | 9.7               | 127                      |
| 12521 | BONITA GRANDE AGGREGATES              | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 12521 | BONITA GRANDE AGGREGATES              | <a href="#">Map it</a> | B01     | 2           | Limerock               | 9.4               | 127                      |
| 12599 | YOUNGQUIST BROTHERS ROCK INC.         | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 12726 | WHITEHEAD AND JOHNS, LLC              | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 12743 | DS & S CONSTRUCTION MATERIALS, INC.   | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 17724 | MASTERROCK LLC.                       | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 91649 | DICKERSON AGGREGATES INC.             | <a href="#">Map it</a> | B03     | 1           | Cemented Coquina       |                   | Roadway Testing Required |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30,2015

## DISTRICT: 02

| Mine  | Company Name                 |                        | Product | Process | Description      | Est. Optimum Moisture* | Pit Proctor (pcf)        |
|-------|------------------------------|------------------------|---------|---------|------------------|------------------------|--------------------------|
| 26001 | LIMESTONE PRODUCTS INC.      | <a href="#">Map it</a> | B01     | 1       | Limerock         | 13.0                   | 116                      |
| 26002 | LIMESTONE PRODUCTS INC.      | <a href="#">Map it</a> | B01     | 1       | Limerock         |                        | Roadway Testing Required |
| 26098 | WHITE HOLDING COMPANY LLC.   | <a href="#">Map it</a> | B01     | 1       | Limerock         | 13.3                   | 117                      |
| 26099 | LIMESTONE PRODUCTS INC.      | <a href="#">Map it</a> | B01     | 1       | Limerock         | 12.5                   | 118                      |
| 26100 | LIMESTONE PRODUCTS INC.      | <a href="#">Map it</a> | B01     | 1       | Limerock         |                        | Roadway Testing Required |
| 26782 | LIMESTONE MATERIALS          | <a href="#">Map it</a> | B01     | 1       | Limerock         | 12.0                   | 116                      |
| 33496 | BLUE ROK INC.                | <a href="#">Map it</a> | B01     | 1       | Limerock         | 11.4                   | 122                      |
| 34104 | V.E. WHITEHURST & SONS, INC. | <a href="#">Map it</a> | B01     | 1       | Limerock         |                        | Roadway Testing Required |
| 37112 | SUWANNEE AMERICAN CEMENT     | <a href="#">Map it</a> | B01     | 1       | Limerock         | 12.3                   | 118                      |
| 37112 | SUWANNEE AMERICAN CEMENT     | <a href="#">Map it</a> | B01     | 2       | Limerock         |                        | Roadway Testing Required |
| 37622 | DENALI INVESTMENTS INC.      | <a href="#">Map it</a> | B01     | 1       | Limerock         | 13.6                   | 115                      |
| 38228 | MARTIN MARIETTA MATERIALS    | <a href="#">Map it</a> | B01     | 1       | Limerock         | 9.4                    | 129                      |
| 38627 | A MINING GROUP, LLC          | <a href="#">Map it</a> | B01     | 1       | Limerock         | 10.6                   | 121                      |
| 72768 | ANDERSON COLUMBIA            | <a href="#">Map it</a> | B01     | 1       | Limerock         | 11.6                   | 119                      |
| 78697 | EAST COAST AGGREGATES LLC    | <a href="#">Map it</a> | B11     | 1       | Shell Rock       | 8.0                    | 134                      |
| GA206 | VULCAN MATERIALS COMPANY     | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate |                        | Roadway Testing Required |
| GA553 | JUNCTION CITY MINING         | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate |                        | Roadway Testing Required |
| GA553 | JUNCTION CITY MINING         | <a href="#">Map it</a> | B10     | 2       | Graded Aggregate |                        | Roadway Testing Required |
| GA753 | MIDSOUTH AGGREGATES          | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate |                        | Roadway Testing Required |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30,2015

## DISTRICT: 03

| Mine  | Company Name                |                        | Product | Process | Description           | Est. Optimum Moisture* | Pit Proctor (pcf)        |
|-------|-----------------------------|------------------------|---------|---------|-----------------------|------------------------|--------------------------|
| 53271 | DOLOMITE INC.               | <a href="#">Map it</a> | B01     | 1       | Limerock              | 15.0                   | 114                      |
| 53357 | NORTH FLORIDA ROCK LTD.     | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 53357 | NORTH FLORIDA ROCK LTD.     | <a href="#">Map it</a> | B01     | 2       | Limerock              | 13.0                   | 113                      |
| 53575 | MARIANNA LIMESTONE, LLC     | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 53575 | MARIANNA LIMESTONE, LLC     | <a href="#">Map it</a> | B01     | 2       | Limerock              |                        | Roadway Testing Required |
| 53575 | MARIANNA LIMESTONE, LLC     | <a href="#">Map it</a> | B01     | 3       | Limerock              |                        | Roadway Testing Required |
| 53670 | MARIANNA LIME PRODUCTS INC. | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 53706 | ANDERSON COLUMBIA           | <a href="#">Map it</a> | B01     | 1       | Limerock              | 12.8                   | 117                      |
| 56626 | GULF COAST AGGREGATES       | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 61377 | SIKES SAND & GRAVEL         | <a href="#">Map it</a> | B12     | 1       | Recycled Concrete Agg |                        | Roadway Testing Required |
| 61391 | WHITE HOLDING COMPANY LLC.  | <a href="#">Map it</a> | B01     | 1       | Limerock              | 12.5                   | 121                      |
| AL149 | VULCAN MATERIALS COMPANY    | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate      |                        | Roadway Testing Required |
| AL526 | MARTIN MARIETTA MATERIALS   | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate      |                        | Roadway Testing Required |
| AL585 | SOUTHERN ROCK AND LIME      | <a href="#">Map it</a> | B01     | 1       | Limerock              | 13.8                   | 119                      |
| AL585 | SOUTHERN ROCK AND LIME      | <a href="#">Map it</a> | B01     | 2       | Limerock              |                        | Roadway Testing Required |
| AL612 | VULCAN MATERIALS COMPANY    | <a href="#">Map it</a> | B10     | 1       | Graded Aggregate      |                        | Roadway Testing Required |
| AL775 | BROOKLYN LIMESTONE QUARRY   | <a href="#">Map it</a> | B01     | 1       | Limerock              | 11.6                   | 123                      |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
 Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30, 2015

## DISTRICT: 04

| Mine  | Company Name                   | Product                | Process | Description | Est. Optimum Moisture* | Pit Proctor (pcf) |                          |
|-------|--------------------------------|------------------------|---------|-------------|------------------------|-------------------|--------------------------|
| 88749 | WILD TURKEY ESTATES            | <a href="#">Map it</a> | B03     | 1           | Cemented Coquina       |                   | Roadway Testing Required |
| 88783 | BLUE GOOSE MINE                | <a href="#">Map it</a> | B03     | 1           | Cemented Coquina       | 8.0               | 132                      |
| 89673 | LAKE POINT RESTORATION, LLC    | <a href="#">Map it</a> | B11     | 1           | Shell Rock             | 9.5               | 128                      |
| 93366 | STAR QUARRIES LLC              | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 93366 | STAR QUARRIES LLC              | <a href="#">Map it</a> | B11     | 1           | Shell Rock             | 10.7              | 122                      |
| 93406 | PALM BEACH AGGREGATES INC.     | <a href="#">Map it</a> | B11     | 2           | Shell Rock             | 8.7               | 128                      |
| 93721 | 5 STONES MINE, LLC             | <a href="#">Map it</a> | B11     | 1           | Shell Rock             |                   | Roadway Testing Required |
| 93793 | D.S. EAKINS CONSTRUCTION CO.   | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 94209 | VULCAN MATERIALS COMPANY       | <a href="#">Map it</a> | B03     | 2           | Cemented Coquina       | 7.7               | 128                      |
| 94488 | STEWART MINING INDUSTRIES INC. | <a href="#">Map it</a> | B03     | 1           | Cemented Coquina       |                   | Roadway Testing Required |
| 94745 | PATRICK JAMES ECYCLE           | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 94789 | STEWART MINING INDUSTRIES INC. | <a href="#">Map it</a> | B03     | 1           | Cemented Coquina       | 9.0               | 128                      |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30, 2015

## DISTRICT: 05

| Mine  | Company Name                  | Product                | Process | Description | Est. Optimum Moisture* | Pit Proctor (pcf) |                          |
|-------|-------------------------------|------------------------|---------|-------------|------------------------|-------------------|--------------------------|
| 18020 | CEMEX                         | <a href="#">Map it</a> | B01     | 1           | Limerock               | 12.4              | 117                      |
| 18020 | CEMEX                         | <a href="#">Map it</a> | B01     | 2           | Limerock               |                   | Roadway Testing Required |
| 18056 | DIXIE LIME & STONE CO.        | <a href="#">Map it</a> | B01     | 1           | Limerock               | 13.0              | 115                      |
| 18058 | CEMEX                         | <a href="#">Map it</a> | B01     | 1           | Limerock               | 12.2              | 117                      |
| 18058 | CEMEX                         | <a href="#">Map it</a> | B01     | 2           | Limerock               |                   | Roadway Testing Required |
| 18393 | BEDROCK RESOURCES             | <a href="#">Map it</a> | B01     | 1           | Limerock               | 12.8              | 116                      |
| 18634 | MID-COAST AGGREGATES, LLC     | <a href="#">Map it</a> | B01     | 1           | Limerock               | 12.5              | 118                      |
| 36246 | M. J. STAVOLA INDUSTRIES      | <a href="#">Map it</a> | B01     | 2           | Limerock               | 11.7              | 121                      |
| 36350 | MAGNUM CONSTRUCTION SOLUTIONS | <a href="#">Map it</a> | B01     | 1           | Limerock               | 11.9              | 120                      |
| 36566 | COUNTS CONSTRUCTION CO. INC.  | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 36654 | COMMERCIAL INDUSTRIAL CORP.   | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 70729 | CONNOR AGGREGATE MATERIALS    | <a href="#">Map it</a> | B12     | 1           | Recycled Concrete Agg  |                   | Roadway Testing Required |
| 79767 | FLORIDA SAND AND SHELL        | <a href="#">Map it</a> | B11     | 1           | Shell Rock             |                   | Roadway Testing Required |
| 92757 | BUCK HAMMOCK MINE             | <a href="#">Map it</a> | B02     | 1           | Bank Run Shell         |                   | Roadway Testing Required |
| BA348 | BAHAMAS ROCK LIMITED          | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30, 2015

## DISTRICT: 06

| Mine  | Company Name                | Product                | Process | Description | Est. Optimum Moisture* | Pit Proctor (pcf) |                          |
|-------|-----------------------------|------------------------|---------|-------------|------------------------|-------------------|--------------------------|
| 87049 | VULCAN MATERIALS COMPANY    | <a href="#">Map it</a> | B01     | 1           | Limerock               | 8.7               | 128                      |
| 87089 | CEMEX                       | <a href="#">Map it</a> | B01     | 1           | Limerock               | 8.3               | 130                      |
| 87090 | CEMEX                       | <a href="#">Map it</a> | B01     | 1           | Limerock               | 8.5               | 129                      |
| 87090 | CEMEX                       | <a href="#">Map it</a> | B01     | 2           | Limerock               |                   | Roadway Testing Required |
| 87090 | CEMEX                       | <a href="#">Map it</a> | B01     | 3           | Limerock               |                   | Roadway Testing Required |
| 87145 | TITAN AMERICA, LLC.         | <a href="#">Map it</a> | B01     | 1           | Limerock               | 8.5               | 130                      |
| 87145 | TITAN AMERICA, LLC.         | <a href="#">Map it</a> | B01     | 2           | Limerock               | 8.9               | 126                      |
| 87145 | TITAN AMERICA, LLC.         | <a href="#">Map it</a> | B01     | 4           | Limerock               |                   | Roadway Testing Required |
| 87339 | WHITE ROCK QUARRIES         | <a href="#">Map it</a> | B01     | 1           | Limerock               | 7.8               | 133                      |
| 87343 | SUNSHINE ROCK INC.          | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 87541 | COMMUNITY ASPHALT CORP.     | <a href="#">Map it</a> | B01     | 1           | Limerock               | 7.7               | 133                      |
| 87633 | WHITE ROCK QUARRIES         | <a href="#">Map it</a> | B01     | 1           | Limerock               | 10.2              | 130                      |
| 87648 | SDI QUARRY, INC.            | <a href="#">Map it</a> | B01     | 1           | Limerock               | 8.0               | 130                      |
| 90638 | CHARLIE TOPPINO & SONS INC. | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |
| 90765 | GRADER MIKE, LLC            | <a href="#">Map it</a> | B01     | 1           | Limerock               |                   | Roadway Testing Required |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
Reference: Section 200



# Pit Proctor Quarterly Report

Print Date: 4/1/2015  
9:10:54AM

Valid from April 1, 2015 to June 30, 2015

## DISTRICT: 07

| Mine  | Company Name                  |                        | Product | Process | Description           | Est. Optimum Moisture* | Pit Proctor (pcf)        |
|-------|-------------------------------|------------------------|---------|---------|-----------------------|------------------------|--------------------------|
| 02018 | CRYSTAL RIVER QUARRIES INC.   | <a href="#">Map it</a> | B01     | 2       | Limerock              |                        | Roadway Testing Required |
| 02675 | CEMEX                         | <a href="#">Map it</a> | B01     | 1       | Limerock              | 8.3                    | 130                      |
| 08050 | E.R. JAHNA INDUSTRIES INC.    | <a href="#">Map it</a> | B01     | 1       | Limerock              | 12.3                   | 117                      |
| 10645 | VULCAN MATERIALS COMPANY      | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 10679 | TRANSCOR RECYCLING LLC        | <a href="#">Map it</a> | B12     | 1       | Recycled Concrete Agg |                        | Roadway Testing Required |
| 13662 | VULCAN MATERIALS COMPANY      | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 13700 | WOODRUFF AND SONS, INC.       | <a href="#">Map it</a> | B12     | 1       | Recycled Concrete Agg |                        | Roadway Testing Required |
| 14262 | CENTRAL STATE AGGREGATES, LLC | <a href="#">Map it</a> | B01     | 1       | Limerock              |                        | Roadway Testing Required |
| 14262 | CENTRAL STATE AGGREGATES, LLC | <a href="#">Map it</a> | B01     | 2       | Limerock              | 11.8                   | 119                      |
| 14262 | CENTRAL STATE AGGREGATES, LLC | <a href="#">Map it</a> | B01     | 3       | Limerock              |                        | Roadway Testing Required |
| 14699 | SUN WEST AQUISITION CORP.     | <a href="#">Map it</a> | B01     | 1       | Limerock              | 11.5                   | 117                      |
| 15755 | SONNY GLASBRENNER             | <a href="#">Map it</a> | B12     | 1       | Recycled Concrete Agg |                        | Roadway Testing Required |

Est. Optimum Moisture\* = Department's estimate of optimum moisture based on data from the mine.  
 Data from Mines for Date Range: 12/22/2014 to 3/22/2015  
 Reference: Section 200