

SYMBOLS:

Work Zone Sign

Corrected: Signs -



Lane Identification and Direction of Traffic



(1) PCMS= Portable Changeable (Variable) Message Sign



(2) PRS= Portable Regulatory Sign-Speed Limit When Flashing



DESCRIPTION:

(2) RSDU= Radar Speed Display Unit

NOTES:

- 1. When called for in the Plans, use the Motorist Awareness System (MAS) in accordance with the Plans and this Index. When using this detail, locate the MAS devices (i.e., PCMS, PRS, and RDSU) within the advance warning signs as shown. Continue with the remainder of the work zone sings and devices in accordance with the Plans or Standard Plans after the appropriate "Lane Closed Ahead" (W20-XX) sign.
- 2. For a posted speed of 65 mph or greater, display speed with a ten mph reduction. For a posted speed of 60 mph, display a reduced speed of 55 mph. For areas outside of the lane closure, use the posted speed as the work zone speed.
- 3. Omit the PCMS in the median for roadways with three lanes or less in the same direction of traffic.

TYPICAL PCMS DISPLAY:

With speed reduction:

Message 1: WORKERS PRESENT AHEAD Message 2: SPEED REDUCED NEXT XXMI

Without speed reduction:

Message 1: WORKERS PRESENT AHEAD

Message 2: NEXT XX MILES

REVISION 11/01/20