
Index 654-001 Rectangular Rapid Flashing Beacon Assembly

ORIGINATION

Date: 6-6-21

Name: Derwood Sheppard

Phone: 850 414-4334

Email: Derwood.Sheppard@dot.state.fl.us

COMMENTARY

The foundations within Indexes 646-001, 654-001, 695-001, and 700-120 are being updated to be more consistent between applications. A structural analysis was completed to determine if the foundations could be revised to provide a more consistent design between the various applications.

COMMENTS AND RESPONSES

BLACK = Internal Review Comments **RED** = Standard Plans Response **GREEN** = Change Made to Index

Name: Shirish Bhat

Date: 8-19-21

COMMENT: Sheet 1 of 2: Side Elevation – if we are showing bars in front elevation, why is it not depicted in side elevation?

Sheet 2 of 2: Side Elevation – if we are showing bars in side front elevation, why is it not depicted in front elevation?

RESPONSE: To prevent duplicate information the reinforcement was not shown in the referenced details. Instead, a note was added under each detail to state “Reinforcement Not Shown.”

No change made to Index.

Date: 8-24-21