FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM Inspection/CIDR Report with PDF attachment(s)

Inspection/CIDR Report with PDF attachment(s)
Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

STRUCTURE NAME: US41NB/FAKA UNION CANAL

INSPECTION DATE: 3/27/2019 MYDL

OWNER: 1 State Highway Agency YEAR BUILT: 1969

MAINTAINED BY: 1 State Highway Agency SECTION NO.: 03 010 000

STRUCTURE TYPE: 5 Prestressed Concrete - 02 Stringer/Girder MP: 34.229

LOCATION: 13.7 MILES SE OF SR-951 ROUTE: 00041
SERV. TYPE ON: 1 Highway FACILITY CARRIED: US-41 NB

SERV. TYPE UNDER: 5 Waterway FEATURE INTERSECTED: FAKA UNION CANAL

FUNCTIONALLY OBSOLETE STRUCTURALLY DEFICIENT

TYPE OF INSPECTION: Regular NBI

BY: Volkert

DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 3/27/2019 UNDERWATER: 2/12/2019

Attach Sufficiency Rating: 99.9

BRIDGE MANAGEMENT SYSTEM

Structure ID: 030145

Inspection/CIDR Report with PDF attachment(s)
Inspection

DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL BY: Volkert STRUCTURE NAME: US41NB/FAKA UNION CANAL OWNER: 1 State Highway Agency YEAR BUILT: 1969 MAINTAINED BY: 1 State Highway Agency SECTION NO.: 03 010 000 34.229 STRUCTURE TYPE: 5 Prestressed Concrete - 02 Stringer/Girder MP: ROUTE: 00041 LOCATION: 13.7 MILES SE OF SR-951 SERV. TYPE ON: 1 Highway FACILITY CARRIED: US-41 NB SERV. TYPE UNDER: 5 Waterway FEATURE INTERSECTED: FAKA UNION CANAL THIS BRIDGE CONTAINS FRACTURE CRITICAL COMPONENTS THIS BRIDGE IS SCOUR CRITICAL THIS REPORT IDENTIFIES DEFICIENCIES WHICH REQUIRE PROMPT CORRECTIVE ACTION **FUNCTIONALLY OBSOLETE** STRUCTURALLY DEFICIENT TYPE OF INSPECTION: Regular NBI DATE FIELD INSPECTION WAS PERFORMED: ABOVE WATER: 3/27/2019 UNDERWATER: 2/12/2019 **OVERALL NBI RATINGS:** DECK: 7 Good CHANNEL: 6 Bank Slumping SUPERSTRUCTURE: 7 Good CULVERT: N N/A (NBI) SUBSTRUCTURE: 7 Good SUFF. RATING: 99.9 HEALTH INDEX: 95.81 PERF. RATING: Good FIELD PERSONNEL / TITLE / NUMBER: **INITIALS** Coon, Elliott - Bridge Inspector (CBI #00530) (lead) Bibelhauser, Anthony - Bridge Inspector (CBI #00359) Coon, Elliott J. - CBI Diver-Inspector (CBI #00530) Lead Hoogland, Keith S. - CBI Diver-Inspector (CBI #00341) D'Amico, Joseph M - Assistant UW Bridge Inspector/Diver **REVIEWING BRIDGE INSPECTION SUPERVISOR:** Rucks, Edward - CBI (#00273) **CONFIRMING REGISTERED PROFESSIONAL ENGINEER:** Appler, James - Professional Engineer (PE#76076) Volkert, Inc. 1408 N. Westshore Blvd., Suite 600 **CERTIFICATE OF AUTHORIZATION NUMBER 4641** Tampa FL 33607 SIGNATURE: DATE:

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

INSPECTION DATE: 3/27/2019 MYDL

All Elements


DECKS: Decks/Slabs

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	12 / 4	Re Concrete Deck	9206	99.99	1	0.01	0		0		9207 sq.ft
0	1080 / 4	Delamination/Spall/Patched Area	0		1	100	0		0		1 sq.ft



DECKS: Joints

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	304 / 4	Open Expansion Joint	181	86.19	26	12.38	3	1.43	0		210 ft
0	2360 / 4	Adjacent Deck or Header	0		26	89.66	- 3	10.34	0		29 ft



MISCELLANEOUS: Channel

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	8290 / 4	Channel	0		0		1	100	0		1 (EA)
0	9120 / 4	Degradation	0		0		1	100	0		1 (EA)

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

INSPECTION DATE: 3/27/2019 MYDL



MISCELLANEOUS: Other Elements

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	321 / 4	Re Conc Approach Slab	1680	100	0		0		0		1680 sq.ft
0	510 / 4	Wearing Surfaces	1582	98.14	30	1.86	0		0		1612 sq.ft
0	3220 /	4 Crack (Wearing Surface)	0		30	100	0		0		30 sq.ft



MISCELLANEOUS: Other Elements


Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	8475 / 4	R/Conc Walls	30	100	0		0		0		30 ft

SUBSTRUCTURE: Substructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	215 / 4	Re Conc Abutment	85	100	0		0		0		85 ft

SUBSTRUCTURE: Substructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	226 / 4	Pre Conc Pile	17	94.44	0		1	5.56	0		18 (EA)
0	1080 / 4	Delamination/Spall/Patched	0		0		1	100	0		1 (EA)



This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

INSPECTION DATE: 3/27/2019 MYDL

SUBSTRUCTURE: Substructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	234 / 4	Re Conc Pier Cap	108	86.4	7	5.6	10	8	0		125 ft
0	1080 / 4	Delamination/Spall/Patched Area	0		0		6	100	0		6 ft
0	1120 / 4	Efflorescence/Rust Staining	0		5	55.56	4	44.44	0		9 ft
0	1130 / 4	Cracking (RC and Other)	0		2	100	0		0		2 ft



This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

INSPECTION DATE: 3/27/2019 MYDL

SUBSTRUCTURE: Substructure

Str Uni	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	8396 / 4	Other Abutment Slope Protection	4024	98.89	0		45	1.11	0		4069 (SF)
0	1080 / 4	Delamination/Spall/Patched Area	0		0		15	100	0		15 (SF)
0	6000 / 4	Scour	0		0		30	100	0		30 (SF)



SUPERSTRUCTURE: Bearings

St	r Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0		311 / 4	Moveable Bearing	27	67.5	11	27.5	2	5	0		40 each
П	0	1000 / 4	Corrosion	0		1	100	0		0		1 each
[0	1020 / 4	Connection	0		10	83.33	2	16.67	0		12 each
	0	8518 / 4	Galvanized Steel	39	97.5	0		1	2.5	0		40 sq.ft
	0	3440 / 4	Eff (Stl Protect Coat)	0		0		1	100	0		1 sq.ft

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 **DISTRICT: D1 - Bartow**

INSPECTION DATE: 3/27/2019 MYDL



00: L:	.01110011	JILE I Superediadad						_			
Str Unit	Elem/Env	Description	Qty1	%1	Qty2	% 2	Qty3	%3	Qty4	%4	T Qty
0	109 / 4	Pre Opn Conc Girder/Beam	1094	99.82	0		2	0.18	0		1096 ft
0	1080 / 4	Delamination/Spall/Patched Area	0		0		2	100	0	·	2 ft

SUPERSTRUCTURE: Superstructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	330 / 3	Metal Bridge Railing	440	100	0		0		0		440 ft
0	8518 / 3	Galvanized Steel	2200	100	0		0		0		2200 sq.ft

Total Number of Elements*: 12 *excluding defects/protective systems

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

INSPECTION DATE: 3/27/2019 MYDL

This report contains information relating to the physical security of a structure and depictions of the structure. This information is confidential and exempt from public inspection pursuant to sections 119.071(3)(a) and 119.071(3)(b), Florida Statutes. Only the cover page of this report may be inspected and copied.

INSPECTION DATE: 3/27/2019 MYDL

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145 DISTRICT: D1 - Bartow

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM Inspection/CIDR Report with PDF attachment(s)

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145
DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145

DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM Inspection/CIDB Beneft with BDE ettechment(s)

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145

DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145
DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL

INSPECTION DATE: 3/27/2019 MYDL

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145
DISTRICT: D1 - Bartow

Inspection/CIDR Report with PDF attachment(s) Inspection

Structure ID: 030145
DISTRICT: D1 - Bartow INSPECTION DATE: 3/27/2019 MYDL





BRIDGE INSPECTION REPORT

PREPARED FOR: FLORIDA DEPARTMENT OF TRANSPORTATION

BRIDGE OWNER: FLORIDA DEPARTMENT OF TRANSPORTATION

ICA

INSPECTED BY:

VOLKERT

BRIDGE NO. 030145 CONTENTS OF REPORT INSPECTION DATE: 03/27/2019

BrM Report

CIDR

Scour Elevation (Profile)

U/W Inspection Report


- Fracture Critical Data
- * Load Rating Analysis Summary
- * Addendum (Element Notes & Photos/Sketches)

*This section is not included in this report.



US-41 NB OVER FAKA UNION CANAL

13.7MI SOUTHEAST OF SR-951



Routine Underwater Bridge Inspection Report **BOLT UNDERWATER SERVICES, INC.** for **VOLKERT, INC.**

NBI Structure ID. (8): 030145

Underwater Date (93): 02/12/19

Structure/Roadway Identification:

Underwater Inspection Details: Special Crew Hours: 3.0

District (2): 01 Collier

AUBIT

County (3):

Max. Depth: Type of Dive Insp.:

8ft. at Bent 2

Feature Intersected (6):

Fahka Union Canal

Level II (SCUBA) N/A

Facility Carried (7):

US-41 NB

Type of Boat Used: Water Type/Marine Growth:

Brackish/Tidal - Algae/Barnacles/Mussels

Previous Inspection:

Lead Diver: Hoogland, Keith S. C.B.I. No.: 00341

Inspection Date:

02/07/17

Inspection Personnel:

D'Amico, Joseph M.

Field Personnel: Title Coon, Elliott J. SUCBI Hoogland, Keith S. SUCBI

P.E./C.B.I. No.: 00530/Lead 00341

Duty: Dive Dive Tend

Signature:

BOLT UNDERWATER SERVICES, INC.

Structure ID: 030145

District: 01 Inspection Date: 02/12/19

BOLT UNDERWATER SERVICES, INC.

Structure ID: 030145

District: 01

Inspection Date: 02/12/19

FLORIDA DEPARTMENT OF TRANSPORTATION

BRIDGE MANAGEMENT SYSTEM BRIDGE INSPECTION REPORT ADDENDUM

BRIDGE ID: 030145 PAGE: A1 OF A1
DISTRICT: 01 BARTOW INSPECTION DATE: 03/27/2019



DATE PRINTED: 11/17/2020

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM

Inspection/CIDR Report with PDF attachment(s)
CIDR

Description

REPORT ID: INSP005

Structure ID: 030145

Structure Unit Identification

Bridge/Unit Key: 030145 0

Structure Name: US41NB/FAKA UNION CANAL

Description: MAIN SPAN 1

Type: M - Main

Roadway Identification

NBI Structure No (8): 030145

Position/Prefix (5): 1 - Route On Structure Kind Hwy (Rte Prefix): 2 U.S. Numbered Hwy

Design Level of Service: 1 Mainline

Route Number/Suffix: 00041 / 0 N/A (NBI)
Feature Intersect (6): FAKA UNION CANAL
Critical Facility: Not Defense-crit
Facility Carried (7): US-41 NB

Mile Point (11): 34.229

Latitude (16): 025d57'34.8" Long (17): 081d30'35.0"

Roadway Traffic and Accidents

Lanes (28): 2 Medians: 0 Speed: 60 mph

ADT Class: 3 ADT Class 3

Recent ADT (29): 1550 Year (30): 2019 Future ADT (114): 2689 Year (115): 2041

Truck % ADT (109): 8
Detour Length (19): 1 mi

Detour Speed:

Accident Count:

Rate:

Roadway Classification

Nat. Hwy Sys (104): 1 On the NHS National base Net (12): 1 - On Base Network

LRS Inventory Rte (13a): 03 010 000 Sub Rte (13b): 00

Functional Class (26): 02 Rural Other Princ

Federal Aid System: ON

Defense Hwy (100): 0 Not a STRAHNET hwy

Direction of Traffic (102): 1 1-way traffic

Emergency: X

Roadway Clearances

Vertical (10): 99.99 ft Appr. Road (32): 40.3 ft

Horiz. (47): 40.3 ft Roadway (51): 40.3 ft

Truck Network (110): 0 Not part of natl netwo

Toll Facility (20): 3 On free road

Fed. Lands Hwy (105): 0 N/A (NBI)

School Bus Route: X

Transit Route:

NBI Project Data

Proposed Work (075A): Not Applicable (P) Work To Be Done By (075B): Not Applicable (P)

Improvement Length (076): 0 ft

Improvement Cost (094): \$ 0.00

Roadway Improvement Cost (095): \$ 0.00 Total Cost (096): \$ 0.00

Year of Estimate (097):

NBI Rating

Channel (61): 6 Bank Slumping

Deck (58): 7 Good Superstructure (59): 7 Good Substructure (60): 7 Good Culvert (62): N N/A (NBI)

Waterway (71): 8 Equal Desirable

Unrepaired Spalls:

Review Required:

DATE PRINTED: 11/17/2020

FLORIDA DEPARTMENT OF TRANSPORTATION BRIDGE MANAGEMENT SYSTEM

REPORT ID: INSP005 Structure ID: 030145

Inspection/CIDR Report with PDF attachment(s) CIDR

Structure Identification

Admin Area: Collier County
District (2): D1 - Bartow
County (3): (03)Collier
Place Code (4): No city involved

Location (9): 13.7 MILES SE OF SR-951 Border Br St/Reg (98): Not Applicable (P) Share: 0 %

Border Struct No (99):

FIPS State/Region (1): 12 Florida Region 4-Atlanta

NBIS Bridge Len (112): Y - Meets NBI Length

Parallel Structure (101): Right of || bridge
Temp. Structure (103): Not Applicable (P)
Maint. Resp. (21): 1 State Highway Agency
Owner (22): 1 State Highway Agency

Historic Signif. (37): 5 Not eligible for NRHP

Structure Type and Material

Curb/Sidewalk (50): Left: 0 ft Right: 0 ft

Bridge Median (33): 0 No median

Main Span Material (43A): 5 Prestressed Concrete Appr Span Material (44A): Not Applicable (P) Main Span Design (43B): 02 Stringer/Girder

Appr Span Design (44B): 00 Other (NBI)

Appraisal

Structure Appraisal

Open/Posted/Closed (41): A Open, no restriction

Deck Geometry (68): 7 Above Min Criteria

Underclearances (69): N Not applicable (NBI)

Approach Alignment (72): 8-No Speed Red thru Curv Bridge Railings (36a): 1 Meets Standards

Transitions (36b): 1 Meets Standards

Approach Guardrail (36c): 1 Meets Standards Approach Guardrail Ends (36d): 1 Meets Standards Scour Critical (113): 3 SC - Unstable

Minimum Vertical Clearance

Over Structure (53): 99.99 ft

Under (reference) (54a): N Feature not hwy or RR

Under (54b): 0 ft

Schedule

Current Inspection

Inspection Date: 03/27/2019

Inspector: KNVOLEC - Elliott Coon

Bridge Group: E1N92

Alt. Bridge Group:

Primary Type: Regular NBI

Review Required: X

Geometrics

Spans in Main Unit (45): 4
Approach Spans (46): 0
Length of Max Span (48): 54.79 ft
Structure Length (49): 219.2 ft
Total Length: 259 ft
Deck Area: 9207 sqft

Structure Flared (35): 0 No flare

Age and Service

Year Built (27): 1969 Year Reconstructed (106): 0

Type of Service On (42a): 1 Highway

Under (42b): 5 Waterway
Fracture Critical Details: Not Applicable

Deck Type and Material

Deck Width (52): 42 ft

Skew (34): 0 deg

Deck Type (107): 1 Concrete-Cast-in-Place

Surface (108): 0 None Membrane: 0 None Deck Protection: None

<u>vigation Data</u>

Navigation Control (38): Permit Not Required

Nav Vertical Clr (39): 0 ft Nav Horizontal Clr (40): 0 ft Min Vert Lift Clr (116): 0 ft

Pier Protection (111): Not Applicable (P)

NBI Condition Rating

Sufficiency Rating: 99.9 Health Index: 95.81

Structural Eval (67): 7 Above Min Criteria

Deficiency: Not Deficient

Minimum Lateral Underclearance

Reference (55a): N Feature not hwy or RR

Right Side (55b): 0 ft Left Side (56): 0 ft

Next Inspection Date Scheduled

NBI: 03/27/2021 Element: 03/27/2021

Fracture Critical:

Underwater: 02/12/2021

Other/Special:

Inventory Photo Update Due:

Inspection/CIDR Report with PDF attachment(s) **REPORT ID: INSP005** Structure ID: 030145

CIDR DATE PRINTED: 11/17/2020

Schedule Cont.					
Inspection Types Performed	NBI X Ele	ment X F	racture Critical	Underwater X	Other Special
Inspection Intervals	Required (92)	Frequency (92) Last Date (93)	Inspection Resou	<u>urces</u>
Fracture Critical		mos		Crew Hou	ırs: 4
Underwater	X	24 mos	02/12/2019	Flagger Hou	ırs: 0
Other Special	Ħ	mos		Helper Hou	ırs: 0
NBI		24 mos (91)	03/27/2019 (90) Snooper Hou	ırs: 0
				Special Crew Hou	ırs: 3
Bridge Related				Special Equip Hou	urs: 0
General Bridge Informa	ation				
Parallel Bridge Seq:	0146		Bridg	e Rail 1: Steel guard/stee	el post
Channel Depth:				e Rail 2: Not applicable-N	
Radio Frequency:				Devices: No electric servi	ce
Phone Number:				ert Type: Not applicable	lna.
Exception Date: Exception Type:				ce Yard: 192-Ft. Myers O N / OFF: No Routes on Fl	
Accepted By Maint:			Previous S		
Warranty Expiration:			2nd Previous S		
Performance Rating:			Replacement S	Structure:	
Permitted Utilities: Power	Water	Gas Fib	er Optic Sewa	age Other	
Bridge Load Rating Inf	formation				
Inventory Type (065):			Inventory Rati	ng (066): 39.7 tons	
Operating Type (063):	1 LF Load Factor	_	•	ng (064): 66.3 tons	
Original Design Load (031):		ook	FL120 Perm		
	08/09/2010		HS20/FL120 Max Spa		
Initials:			Dynamic Impact in		
Load Rating Rev. Recom.:		un.	Governing Spar		
Load Rating Plans Status:	Design of Construction)	Minimum Spar Distribution	-	
Load Rating Notes:			Diotribution	Woulde.	
LEGAL LOADS		<u> </u>	POSTING		
SU2:			Recom. SU	Posting:	
SU3:			Recom. C	Posting:	
SU4:			Recom. ST5	9	
C3:			Actual SU	-	
C4: C5:			Actual C Actual ST5		
ST5:			Actual Blanket	-	
	5 At/Above Legal Loa	ds	Emergency	•	
Open/Posted/Closed (041):	_				_
FLOOR BEAM (FB)	FB Present: No	<u>;</u>	SEGMENTAL (SEG)		
FB Span Length, Gov:	0.0 ft		SEG Wii	ng-Span: -1.0 ft	
FB Spacing, Gov:				eb Span: -1.0 ft	
FB OPR Rating:		;	SEG Transverse HL93 O	perating:	
FB SU4 OPR Rating:					
FB FL120 Rating: Bridge Scour and Stor					
Pile Driving Record:			Scour Recomm	nended I:	
Foundation Type:			Scour Recomm		
Mode of Flow:			Scour Recomme		
Rating Scour Eval:			Scour E	levation:	
Highest Scour Eval:				levation:	
Scour Evaluation Method:			Storm Fre	equency:	

Inspection/CIDR Report with PDF attachment(s)

REPORT ID: INSP005 CIDR Structure ID: 030145 **DATE PRINTED: 11/17/2020**

Elements

MYDL Inspection Date: 03/27/2019

DECKS: Decks/Slabs

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	12 / 4	Re Concrete Deck	9206	99.99	1	0.01	0		0		9207 sq.ft
0	1080 / 4	Delamination/Spall/Patched Area	0		1	100	0		0		1 sq.ft

DECKS: Joints

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	304 / 4	Open Expansion Joint	181	86.19	26	12.38	3	1.43	0		210 ft
0	2360 / 4	Adjacent Deck or Header	0		26	89.66	3	10.34	0		29 ft

MISCELLANEOUS: Channel

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty	
0	8290 / 4	Channel	0		0		1	100	0		1 (EA)	
0	9120 / 4	Degradation	0		0		1	100	0		1 (EA)	

MISCELLANEOUS: Other Elements

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	321 / 4	Re Conc Approach Slab	1680	100	0		0		0		1680 sq.ft
0	510 / 4	Wearing Surfaces	1582	98.14	30	1.86	0		0		1612 sq.ft
0	3220 / 4	Crack (Wearing Surface)	0		30	100	0		0		30 sq.ft

MISCELLANEOUS: Other Elements

Str Unit	Elem/Env	Description		Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	8475 / 4	R/Conc Walls	44	30	100	0		0		0		30 ft

SUBSTRUCTURE: Substructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	215 / 4	Re Conc Abutment	85	100	0		0		0		85 ft

SUBSTRUCTURE: Substructure

Str l	Jnit l	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	2	226 / 4	Pre Conc Pile	17	94.44	0		1	5.56	0		18 (EA)
0		1080 / 4	Delamination/Spall/Patched Area	0		0		1	100	0		1 (EA)

SUBSTRUCTURE: Substructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	234 / 4	Re Conc Pier Cap	108	86.4	7	5.6	10	8	0		125 ft
0	1080 / 4	Delamination/Spall/Patched Area	0		0		6	100	0		6 ft
0	1120 / 4	Efflorescence/Rust Staining	0		5	55.56	4	44.44	0		9 ft
0	1130 / 4	Cracking (RC and Other)	0		2	100	0		0		2 ft

SUBSTRUCTURE: Substructure

S	tr Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0			Other Abutment Slope Protection	4024	98.89	0		45	1.11	0		4069 (SF)
	0	1080 / 4	Delamination/Spall/Patched Area	0	·	0		15	100	0		15 (SF)
	0	6000 / 4	Scour	0		0		30	100	0		30 (SF)

DATE PRINTED: 11/17/2020

FLORIDA DEPARTMENT OF TRANSPORTATION **BRIDGE MANAGEMENT SYSTEM**

REPORT ID: INSP005 Structure ID: 030145

Inspection/CIDR Report with PDF attachment(s)

SUPERSTRUCTURE: Bearings

CIDR

St	r Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0		311 / 4	Moveable Bearing	27	67.5	11	27.5	2	5	0		40 each
П	0	1000 / 4	Corrosion	0		1	100	0		0		1 each
	0	1020 / 4	Connection	0		10	83.33	2	16.67	0		12 each
	0	8518 / 4	Galvanized Steel	39	97.5	0		1	2.5	0		40 sq.ft
	0	3440 / 4	Eff (Stl Protect Coat)	0		0		1	100	0		1 sq.ft

SUPERSTRUCTURE: Superstructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	109 / 4	Pre Opn Conc Girder/Beam	1094	99.82	0		2	0.18	0		1096 ft
0	1080 / 4	Delamination/Spall/Patched Area	0		0		2	100	0	·	2 ft

SUPERSTRUCTURE: Superstructure

Str Unit	Elem/Env	Description	Qty1	%1	Qty2	%2	Qty3	%3	Qty4	%4	T Qty
0	330 / 3	Metal Bridge Railing	440	100	0		0		0		440 ft
0	8518 / 3	Galvanized Steel	2200	100	0		0		0		2200 sq.ft

Total Number of Elements*: 12 *excluding defects/protective systems

Inspection Information

Inspection Date: 03/27/2019 Type: Regular NBI

Inspector: KNVOLEC - Elliott Coon

