

**State of Florida Department of Transportation
PAVEMENT EVALUATION AND CONDITION DATA SHEET**

Project No.: 445690-1	Cored By: FDOT (GS/RS)	Date: 12/2/2020	Page No.: 1 of 1
County: Flagler	Highway Sect. No: 73030	From: Shelter Cove Drive	To: just South of Lula Lane
Road No.: SR A1A	Begin MP: 6.882	End MP: 7.271	Length: 0.385 mile

Core No.	MP	Distance from left edge of lane (ft)	Lane	Wheel Path	Pavement Layer (in.)							Base			Crack			Pavt Cond.	Rut Depth (in)	Cross Slope (%)	Comments			
					FC-6	Type SP	Type S	Type I	Type II w/ Shell	Surface Treatment	Core Length (in)	Type	Thickness (in)	Depth (in)	Type	Class	Extent							
1	7.260	1.0	OL		1.0	--	2.2	--	1.5	--	4.7	NB	--	B	ST	II	S	F			light rippling occurs			
2	7.260	4.0	L1		1.5	1.2	--	0.6	--	0.6	3.9	SBRM	10.1	B	SL	II	S	P			Rippling occurs in outside wheelpath			
3	7.056	5.0	L1		1.2	1.4	--	--	--	0.6	3.2	SBRM	10.2	B	SL	II	S	P			just south of crosswalk			
4	6.900	5.0	L1		1.0	1.5	--	0.5	--	0.5	3.5	SBRM	10.0	B	ST	II	S	P						
5	6.920	4.0	R1		1.3	1.0	--	--	--	0.8	3.1	SBRM	8.3	B	Br	lb	S	F						
6	6.920	1.5	OR		0.8	--	1.6	--	--	--	6.8	ABC	4.4	--	--	--	--	F						
7	7.141	5.0	R1		1.7	1.0	--	--	--	0.4	3.1	SBRM	8.5	B	SL	lb	M	F						
8	7.141	6.0	OR		--	--	3.9	--	--	--	7.2	ABC	3.3	--	--	--	--	F			Older existing pavement (extended shoulder approx. 10')			
9	7.240	5.0	R1		1.2	1.1	--	0.9	--	0.6	3.8	SBRM	10.2	B	ST	lb	M	P						

Remarks: Crack Depth of "B" indicates full depth crack to the base. EOP = Edge of Pavement
Crack Extent: L= Light; M= Moderate; S= Severe **Pavement Condition:** G= Good; F= Fair; P= Poor
Crack Types: A= Alligator; Bl= Block; Br= Branch; SL= Single Longitudinal; ST= Single Transverse; R= Reflective; J= Joint; OGFC= Open-Graded FC Stress Crack
Base Types: LR= Limerock; COQ= Coquina; SC= Soil Cement; ABC= Asphalt Base; SAHM= Sand Asphalt Hot Mix; SBRM= Sand Bituminous Road Mix; NB= No Base