

9430500 – CORRUGATED STEEL PIPE AND PIPE ARCH (INCLUDING UNDERDRAIN) – BITUMINOUS COATING AND PAVED INVERT.

Anjani Girwarr
863-519-2825
anjani.girwarr@dot.state.fl.us

Comments:

Why should the last sentence be deleted? How do you establish or determine whether there is excess? What problem is caused by excess? Please provide an explanation as to why this action is necessary and how it benefits the Department in any litigation?
