STATE OF FLORIDA DEPARTMENT OF TRANSPORTATION

PAVEMENT EVALUATION CORING AND CONDITION DATA

Cored by: Tierra South Florida, Inc. Date: 9/22 to 9/23/2020 Typical Section No.: 1

W.P.I. No.:		Name:	SNAPPER CREEK SERVICE PLAZA PARKING IMPROVEMENTS MP 19		Lanes:
Fin. Proj. ID:	442620-1	From:			Shoulder Type and Condition:
F.A. Proj. No.:		To:			Inside:
County:	MIAMI-DADE	SR No.: SR 821	Beg MP:	End MP: Length	Outside:
Median Curbed (Y / N):	N	Paved, Lawn, Other:		0	Curb & Gutter (Y / N):

Core No.	Mile Post or Sta. No.	Lane	Wheel Path	Core Offset	Pavement Layer Type (in.) Top FC12.5	S											Pavement Thickness (in.)	Base LR				Total	Stabilized Subgrade Yes / No	Thickness	Crack Depth (in.)	Full Depth	Type	Class	Extent	Pvmt Cond	Rut Depth (in.)	Cross Slope (%)	Cross Slope Direction	Comments	Latitude	Longitude
1	0.167	L1	Y	4' RT 87471257	0.5	1.7											2.2	9.5				9.5			0.7	NO	C	III	Light	Poor				SB Plaza Lane	25.665435	-80.388535
2	0.325	L1	Y	11' RT 87471257	1.0												1.0	9.0				9.0			1.0	YES	B	III	Severe	Poor				SB Plaza Lane	25.663162	-80.388184
3	0.383	L1	Y	82' RT 87471257	1.3												1.3	8.0				8.0								Poor				Truck Parking SB	25.662432	-80.387937
4	0.446	L1	N	88' RT 87471257	1.2												1.2	10.0				10.0			1.2	YES	B	III	Severe	Poor				Truck Parking SB	25.661554	-80.387828
5	0.208	L1	N	107' LT 87471257	0.8												0.8	8.0				8.0								Poor				FHP Building SB	25.664878	-80.388168
6	0.269	L1	N	118' LT 87471257	1.3												1.3	7.5				7.5			0.3	NO	A	III	Light	Poor				FHP Building SB	25.664027	-80.388036
7	0.328	L1	Y	61' LT 87471257	0.8												0.8	8.0				8.0								Poor				FHP Building SB	25.663275	-80.387998
8	0.419	L1	N	4' RT 87471257	1.7												1.7	9.5				9.5			1.7	YES	A	III	Moderate	Poor				SB Plaza Lane	25.661996	-80.387593
9	0.516	L1	Y	126' LT 87471257	2.0												2.0	10.0				10.0			2.0	Yes	A	III	Moderate	Poor				South Parking Lot	25.660503	-80.387315
10	0.203	L1	Y	136' LT 87471257	1.8												1.8	8.5				8.5			1.2	NO	C	III	Moderate	Poor				South Parking Lot	25.660302	-80.386865
11	0.223	R1	N	68' LT 87471254	1.3												1.3	9.0				9.0			1.3	YES	C	III	Moderate	Poor				South Parking Lot	25.660573	-80.386653
12	0.605	L1	N	150' LT 87471257	1.4												1.4	8.5				8.5								Poor				Fire Rescue	25.659395	-80.387424
13	0.662	L1	N	79' LT 87471257	1.4	1.4											2.8	7.5				7.5			2.8	YES	C	III	Moderate	Poor				Fire Rescue	25.658564	-80.387491
14	0.335	R1	Y	5' LT 87471254	1.6												1.6	8.0				8.0			1.6	YES	C	III	Moderate	Poor				NB Plaza Lane	25.662192	-80.386518
15	0.414	R1	Y	5' LT 87471254	1.3												1.3	8.5				8.5			1.3	YES	B	III	Moderate	Poor				NB Plaza Lane	25.663340	-80.386404
16	0.286	R1	Y	102' RT 87471254	1.7												1.7	10.0				10.0			0.9	NO	B	III	Light	Poor				Truck Parking NB	25.661502	-80.386168
17	0.340	R1	N	96' RT 87471254	1.9												1.9	8.0				8.0			1.9	YES	B	III	Light	Poor				Truck Parking NB	25.662229	-80.386232
18	0.416	R1	N	69' LT 87471254	1.3												1.3	10.0				10.0								Poor				Field Office NB	25.663370	-80.386602
19	0.452	R1	Y	128' LT 87471254	1.8												1.8	9.0				9.0			1.8	YES	B	III	Moderate	Poor				FHP Building NB	25.663780	-80.386854
20	0.497	R1	Y	91' LT 87471254	1.2												1.2	9.0				9.0			1.2	YES	B	III	Moderate	Poor				FHP Building NB	25.664422	-80.386911
21	0.673	R1	Y	4' LT 87471254	1.5												1.5	8.0				8.0								Poor				NB Plaza Lane	25.666953	-80.387429

Crack Information	Type	Class	Extent
	A - Alligator	IB	Light
	B - Block	II	Moderate
	C - Combination	III	Severe