FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = BRADFORD ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW LN / RW FY-P / RW FY-F	SYS / %T / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	TYP SPD / AADT	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
28010000	0.000	5.291	R 1	7	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0																	
200 301			2	20.8	27960	RIDE	8.8	8.9	8.9	8.5	8.4	8.4	8.6	8.6	8.5	8.4	8.4	8.4	8.3																	
CR 221 WYE(0.8R)					FC5HP																															
4472041	0.004	5.271	R 2024		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	6.5	6.5	5.5*	5.5*	5.5*	5.5*	5.7*	10.0	9.0																	
ANDERSON COLUMBIA CO., INC(2026)					SPRIDE		8.4	8.3	8.5	8.4	8.6	8.6	8.7	8.5	8.5	8.5	8.6	8.6	9.0	8.8															
28010000	6.038	6.923	R 1	7	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0																	
200 301			2	4.8	10100	RIDE	8.8	8.9	8.9	8.5	8.4	8.4	8.6	8.6	8.5	8.4	8.4	8.4	8.3																	
COMMERCIAL DR L(6.1R)					FC125M																															
4472041	6.038	6.921	R 2024		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	6.5	6.5	5.5*	5.5*	5.5*	5.5*	5.5*	10.0	9.0																	
ANDERSON COLUMBIA CO., INC(2026)					SPRIDE		8.4	8.3	8.5	8.4	8.6	8.5	8.6	8.4	8.4	8.5	8.4	8.4	8.7	8.3															
28010000	6.923	8.044	R 1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5	8.0	8.0																	
200 301			2	4.8	10100	RIDE	8.8	8.9	8.9	8.0	7.9	7.8	8.1	8.0	7.7	7.7	7.8	7.5	7.7																	
ALEXANDER ST(7.0R)					FC125M																															
4342981	6.923	8.044	C 2017		0012	CRACKING	7.0	7.0	7.0	6.5	6.5		10.0	10.0	10.0	10.0	10.0	9.5	9.1	7.5																	
ANDERSON COLUMBIA CO., INC(2020)					SPRIDE		7.3	7.2	7.2	7.0	7.3		8.1	8.0	7.8	7.6	7.8	7.8	7.7	7.3															
28010000	8.044	8.954	R 1	1	30	CRACKING	10.0	9.5	9.5	9.5	9.5	8.0	10.0	10.0	10.0	10.0	9.5	8.0	8.0																	
200 301			2	4.8	19000	RIDE	7.4	7.2	7.2	7.1	6.7	6.5	8.2	8.1	7.9	7.8	7.6	7.3	7.3																	
MADISON ST(8.1C)					FC125M																															
4361561	8.044	8.954	C 2017		0012	CRACKING	7.0	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	8.8	8.4	6.5																	
ANDERSON COLUMBIA CO., INC(2020)					SPRIDE		7.2	6.4	6.8	6.4	6.6		7.7	7.7	7.7	7.7	7.7	7.7	7.6	7.2															
28010000	8.954	9.875	R 1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	7.0	6.0*	6.0*																	
200 301			2	4.8	5500	RIDE	7.9	8.2	8.1	7.9	7.9	7.8	8.1	8.0	7.8	7.8	7.6	7.5	7.4																	
ANDREWS ST(9.0C)					FC125M																															
4323091	8.954	14.320	C 2017		0012	CRACKING	6.0*	6.0*	6.0*	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	8.9	9.5	8.0																	
ANDERSON COLUMBIA CO., INC(2020)					SPRIDE		7.2	6.8	7.2	6.9	7.1		8.5	8.5	8.5	8.5	8.4	8.5	8.4	8.0															
28010000	9.875	11.362	R 1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0																	
200 301			2	4.8	5500	RIDE	8.7	8.9	8.8	8.3	8.3	8.3	8.5	8.5	8.4	8.3	8.3	8.3	8.2																	
UNSIGNED(10.1R)					FC5M																															
4323091	8.954	14.320	C 2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0			10.0	10.0	10.0	10.0	9.1	9.7	7.5																	
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE		8.1	8.1	8.4	8.3	8.5			8.9	8.9	8.9	8.9	8.9	8.9	8.7																	
28010000	11.916	14.330	R 1	1	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0																	
200 301			2	4.8	30500	RIDE	8.7	8.9	8.8	8.3	8.3	8.3	8.5	8.5	8.4	8.3	8.3	8.3	8.2																	
NE 196 TER(12.3R)					FC5M																															
4323091	8.954	14.320	C 2017		0012	CRACKING	7.0	7.0	7.0	7.0	7.0			10.0	10.0	10.0	10.0	8.4	8.9	6.5																	
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE		8.1	8.1	8.4	8.3	8.5			9.1	9.0	9.1	9.0	9.1	9.0	8.8																	
28010000	14.330	15.052	R 1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0	6.5	6.5																	
200 301			2	4.8	30500	RIDE	8.7	8.2	8.3	7.8	7.8	7.6	7.8	7.6	7.0	6.9	6.3*	6.2*	5.9*																	
					FC5M																															
4286921	14.320	15.857	C 2014		0012	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	9.5	7.5	7.5	6.5	6.5	6.5	4.0*	0.0*																	
ANDERSON COLUMBIA CO., INC(2015)					SPRIDE		7.7	8.3	8.4	8.4	8.4	8.2	8.3	8.2	8.1	8.5	8.4	8.3	8.2	8.0															
4286922	14.330	15.875	C 2026		0012																															
28010000	15.052	15.857	R 1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.0	7.0	6.5	6.5																	
200 301			2	4.8	30500	RIDE	8.1	8.2	8.3	7.8	7.8	7.6	7.8	7.6	7.0	6.9	6.3	6.2	5.9																	
CR-225/LAKE ST(15.4R)					FC125M																															
4286921	14.320	15.857	C 2014		0012	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	9.5	7.5	4.5*	4.5*	4.5*	4.3*	3.7*	1.5*																	
ANDERSON COLUMBIA CO., INC(2015)					SPRIDE		7.7	8.3	8.4	8.4	8.4	8.2	8.3	8.2	7.6	7.8	7.9	7.6	7.7	7.3															
4286922	14.330	15.875	C 2026		0012																															
28010000	15.857	20.227	R 1	1	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	7.0	7.0	7.0																	
200 301			2	29.1	24000	RIDE	8.9	8.9	8.9	8.4	8.4	8.3	8.5	8.5	8.4	8.3	8.3	8.3	8.3																	
CR 125(16.3C)					FC5M																															
4323151	15.857	20.078	C 2017		0012	CRACKING	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	6.0*																	
ANDERSON COLUMBIA CO., INC(2019)					SPRIDE		8.2	8.2	8.5	8.4		8.9	8.9	8.9	8.8	8.8	8.9	8.8	8.9	8.7																	
28010000	15.857	20.227	L 1	1	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	7.0	7.0	7.0																	
200 301			2	29.1	24000	RIDE	8.9	8.9	8.8	8.4	8.3	8.4	8.5	8.5	8.4	8.3	8.3	8.3	8.3																	
CR 125(16.3C)					FC5M																															
4323151	15.857	20.078	C 2017		0012	CRACKING	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	8.9	8.9	6.0*																	
ANDERSON COLUMBIA CO., INC(2019)					SPRIDE		8.2	8.1	8.4	8.4		8.9	8.9	8.9	8.8	8.8	8.8	8.8	8.8	8.6																	

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = BRADFORD ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
28010000	15.052	15.857	L	1	1	45					CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5													
200 301			2	4.8	30500					RIDE		8.0	8.3	8.2	7.9	7.9	7.6	7.6	7.6	7.4	7.3	6.9	7.0	7.0													
CR 225(15.3L)										FC125M																											
4286921	14.320	15.857	C	2014		0012					CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	8.5	4.5*	4.5*	4.5*	4.5*	4.5*	2.0*											
ANDERSON COLUMBIA CO., INC(2015)										SPRIDE		7.0	8.3	8.4	8.3	8.4	8.1	8.2	8.1	7.2	7.5	7.7	7.7	7.6	7.2											
4286922	14.330	15.875	C	2026		0012																															
28010000	14.330	15.052	L	1	1	55					CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5													
200 301			2	4.8	30500					RIDE		8.8	8.3	8.2	7.9	7.9	7.6	7.6	7.6	7.4	7.3	6.9	7.0	7.0													
NW 219 ST(14.8L)										FC5M																											
4286921	14.320	15.857	C	2014		0012					CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	6.5	4.5*	5.1*	3.9*	0.0*											
ANDERSON COLUMBIA CO., INC(2015)										SPRIDE		7.0	8.3	8.4	8.3	8.4	8.1	8.2	8.1	8.1	8.4	8.4	8.2	8.0	7.8											
4286922	14.330	15.875	C	2026		0012																															
28010000	11.916	14.330	L	1	1	65					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	7.0													
200 301			2	4.8	30500					RIDE		8.8	8.9	8.9	8.3	8.3	8.3	8.5	8.5	8.4	8.4	8.3	8.3	8.1													
NW 196 ST(12.3L)										FC5M																											
4323091	8.954	14.320	C	2017		0012					CRACKING	7.0	7.0	7.0	7.0	7.0			10.0	10.0	10.0	9.0	8.7	8.8	6.5											
ANDERSON COLUMBIA CO., INC(2021)										SPRIDE		8.1	8.0	8.3	8.2	8.6			9.0	8.9	9.0	8.9	8.9	9.0	8.8											
28010000	9.875	11.362	L	1	1	55					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	7.0													
200 301			2	4.8	5500					RIDE		8.8	8.9	8.9	8.3	8.3	8.3	8.5	8.5	8.4	8.4	8.3	8.3	8.1													
NW 36TH AVE(10.1L)										FC5M																											
4323091	8.954	14.320	C	2017		0012					CRACKING	7.0	7.0	7.0	7.0	7.0			10.0	10.0	10.0	10.0	9.5	9.4	7.0											
ANDERSON COLUMBIA CO., INC(2021)										SPRIDE		8.1	8.0	8.3	8.2	8.6			8.8	8.6	8.7	8.7	8.7	8.7	8.5											
28010000	8.954	9.875	L	1	1	45					CRACKING	10.0	10.0	10.0	9.5	9.5	8.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5													
200 301			2	4.8	5500					RIDE		8.0	8.3	8.1	7.9	7.8	7.5	7.6	7.4	6.9	7.0	6.8	7.3	7.4													
ANDREWS ST(9.0C)										FC125M																											
4323091	8.954	14.320	C	2017		0012					CRACKING	6.5	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	8.9	9.5	8.0											
ANDERSON COLUMBIA CO., INC(2020)										SPRIDE		7.2	6.9	7.1	6.8	7.0		8.5	8.3	8.4	8.4	8.4	8.4	8.4	8.0											
28010000	8.044	8.954	L	1	1	30					CRACKING	10.0	9.5	9.5	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	8.0	7.0	7.0													
200 301			2	4.8	19000					RIDE		7.0	5.9	6.1	6.5	5.9	5.6	8.0	7.9	7.5	6.7	7.4	7.3	6.6													
MADISON ST(8.1C)										FC125M																											
4361561	8.044	8.954	C	2017		0012					CRACKING	6.0*	5.5*	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	10.0	8.9	9.3	7.5											
ANDERSON COLUMBIA CO., INC(2020)										SPRIDE		6.8	5.4*	6.6	6.3	6.5		7.9	7.8	7.8	7.9	7.9	7.9	7.8	7.4											
28010000	6.923	8.044	L	1	1	35					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	8.5	8.5	8.5													
200 301			2	4.8	10100					RIDE		8.8	8.9	8.9	7.4	7.2	7.1	7.7	7.5	7.0	7.2	7.2	6.9	6.8													
BRADFORD SQ(7.6L)										FC125M																											
4342981	6.923	8.044	C	2017		0012					CRACKING	8.5	8.5	8.5	7.0	7.0		10.0	10.0	10.0	10.0	10.0	8.9	8.8	7.0											
ANDERSON COLUMBIA CO., INC(2020)										SPRIDE		6.8	6.6	7.1	7.2	7.2		8.2	8.1	7.8	7.6	7.8	7.8	7.8	7.4											
28010000	6.038	6.923	L	1	7	55					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	7.0													
200 301			2	4.8	10100					RIDE		8.8	8.9	8.9	8.4	8.4	8.4	8.6	8.6	8.4	8.4	8.4	8.3	8.3													
SHOPPING ENT(6.1L)										FC125M																											
4472041	6.038	6.921	L	2024		0012					CRACKING	7.0	7.0	7.0	7.0	7.0	5.5*	3.5*	1.0*	1.0*	1.0*	1.0*	1.0*	10.0	9.0											
ANDERSON COLUMBIA CO., INC(2026)										SPRIDE		8.3	8.0	8.3	8.3	8.5	8.3	8.4	8.3	8.2	8.2	8.2	8.3	8.6	8.2											
28010000	0.000	5.291	L	1	7	65					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	7.0													
200 301			2	20.8	27960					RIDE		8.8	8.9	8.9	8.4	8.4	8.4	8.6	8.6	8.4	8.4	8.4	8.3	8.3													
SW 85TH ST(0.2L)										FC5HP																											
4472041	0.004	5.271	L	2024		0012					CRACKING	7.0	7.0	7.0	7.0	7.0	6.5	6.5	5.5*	5.5*	5.5*	5.5*	5.2*	10.0	9.0											
ANDERSON COLUMBIA CO., INC(2026)										SPRIDE		8.3	8.0	8.3	8.3	8.5	8.4	8.4	8.3	8.3	8.3	8.3	8.3	9.1	8.9											
28010001	0.000	0.447	R	1	1	45					CRACKING																										
200 301			2	4.8	10100					RIDE																											
US-301 S(0.0R)										DGFC																											
											CRACKING																											
		(2021)									RIDE																											
28010001	0.000	0.447	L	1	1	45					CRACKING																										
200 301			2	4.8	10100					RIDE																											
US-301 N ALT(0.0L)										FC125M																											
											CRACKING																											
		(2021)									RIDE																											

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = BRADFORD

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / SURFTYPE / FY-P / FY-F	TYP / AADT / ASTYPE / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
28010002 200 301 NE 187 ST(0.0C)	0.000	0.281	R 2	1 4.8	1 5500 FC125M	45	CRACKING RIDE																											
							CRACKING																										10.0	10.0	10.0	10.0	10.0	9.6	8.0
				(2021)			RIDE																											7.2	6.8
28010002 200 301 NE 187 ST(0.0C)	0.000	0.281	L 2	1 4.8	1 5500 FC125M	45	CRACKING RIDE																											
							CRACKING																										10.0	10.0	10.0	10.0	9.6	9.5	8.0
				(2021)			RIDE																											7.3	6.9
28020000 100 SE 3 AVE(0.2L)	0.000	10.095	C 2	1 9.6	1 7100 FC125M	60	CRACKING RIDE	10.0 8.7	10.0 8.7	9.5 8.5	9.5 7.9	7.0 7.9	7.0 7.9	6.5 7.9	6.5 7.7	4.5* 7.6	4.5* 7.3	10.0 8.2	10.0 8.2	10.0 8.1															
2079566 V. E. WHITEHURST & SONS, I 4472042	4.035 (2011) 0.000	10.168 10.100	C 2010 C 2029	0012 0012			CRACKING RIDE	10.0 8.0	9.5 7.8	9.5 7.7	9.5 7.6	9.5 7.6	9.5 7.5	9.5 7.5	8.0 7.6	7.0 7.4	7.0 7.4	6.0* 7.3	4.9* 7.4	4.1* 7.2	1.0* 6.8													
28020000 100 CR 100A(10.2R)	10.095	11.570	C 2	1 7.8	1 8100 FC125M	45	CRACKING RIDE	10.0 8.7	10.0 8.7	9.5 8.5	9.5 7.9	10.0 7.9		10.0 8.2	10.0 8.0	9.5 8.1	9.5 7.8	9.5 7.9	8.0 7.8	8.0 7.7													
4323141 V. E. WHITEHURST & SONS, I	10.240 (2019)	11.133	C 2017 	0012 SPRIDE			CRACKING RIDE	8.0 7.7	8.0 7.6	8.0 7.7	7.0 7.6	7.0 7.7	10.0 8.1	10.0 7.9	10.0 8.0	10.0 7.3	10.0 6.9	10.0 7.9	9.0 7.9	9.3 7.7	7.5 7.3													
28020000 100 SR 200(11.6C)	11.570	12.829	C 2	1 16.7	1 8900 FC125M	45	CRACKING RIDE	9.5 8.2	9.5 8.3	9.5 8.2	9.5 7.7	9.5 7.7		10.0 7.5	10.0 7.8	9.5 7.3	7.0 7.0	7.0 7.0	7.0 6.8	7.0 6.7													
4361791 PREFERRED MATERIALS, INC.	11.622 (2022)	12.496	C 2019 	0012 SPRIDE			CRACKING RIDE	7.0 6.6	7.0 6.5	7.0 6.6	7.0 6.4	7.0 6.3	5.5* 6.9	5.5* 6.5		10.0 8.0	10.0 8.1	10.0 8.2	9.6 8.1	10.0 8.1	8.5 7.7													
28020000 100 CR 100 A(13.5L)	12.829	13.680	C 2	1 19.2	1 6257 FC125M	45	CRACKING RIDE	6.0* 8.2	6.0* 8.3	6.0* 8.0	4.5* 7.5	4.5* 7.5		10.0 8.3	10.0 8.3	10.0 8.3	9.5 8.2	9.5 8.1	8.0 8.0	7.0 8.0													
4361791 PREFERRED MATERIALS, INC.	12.858 (2021)	13.404	C 2019 	0012 SPRIDE			CRACKING RIDE	6.5 7.9	6.5 7.8	6.5 7.7	6.5 7.6				10.0 8.1	10.0 7.9	10.0 7.9	10.0 7.7	10.0 7.8	9.5 7.7	8.0 7.3													
28020000 100 CROSBY LAKE CEMETERY(13.9L)	13.680	22.169	C 2	1 19.2	1 6257 FC125M	60	CRACKING RIDE	6.0* 8.2	6.0* 8.3	6.0* 8.0	4.5* 7.5	4.5* 7.5		10.0 8.3	10.0 8.3	10.0 8.3	9.5 8.2	9.5 8.1	8.0 8.0	7.0 8.0													
4361791 PREFERRED MATERIALS, INC.	16.174 (2021)	20.162	C 2019 	0012 SPRIDE			CRACKING RIDE	6.5 7.9	6.5 7.8	6.5 7.7	6.5 7.6	6.5 7.7	6.5 7.5	4.5* 6.9	10.0 8.7	10.0 8.7	10.0 8.7	10.0 8.7	9.5 8.7	9.6 8.7	8.0 8.3													
28030000 16 SR 200(0.0C)	0.000	0.691	C 2	1 3.6	1 9900 FC125M	30	CRACKING RIDE	8.0 6.7	8.0 7.1	8.0 6.9	8.0 6.5	7.0 6.2	7.0 5.8	7.0 5.9	10.0 8.1	10.0 7.6	10.0 7.9	10.0 7.7	10.0 7.5	10.0 7.7													
2080022 PREFERRED MATERIALS, INC. (2008) 2080206	0.000 0.000	3.701 3.701	C 2007 C 2029	0012 0012			CRACKING RIDE	10.0 7.5	10.0 7.5	10.0 7.4	10.0 7.6	9.5 7.6	8.5 8.0	8.5 7.8	8.0 7.2	7.0 7.7	7.0 7.5	6.0* 7.6	4.4* 7.6	3.5* 7.7	0.0* 7.3													
28030000 16 FAXON LN(1.1L)	0.691	3.701	C 2	1 10.4	1 6900 FC125M	60	CRACKING RIDE	7.0 8.2	7.0 8.5	7.0 8.4	7.0 7.8	6.0* 7.7	6.0* 7.6	6.0* 6.9	10.0 8.7	10.0 8.5	10.0 8.3	10.0 8.5	10.0 8.4	10.0 8.2													
2080022 PREFERRED MATERIALS, INC. (2008) 2080206	0.000 0.000	3.701 3.701	C 2007 C 2029	0012 0012			CRACKING RIDE	10.0 8.2	9.5 8.1	9.5 8.1	9.5 8.1	9.5 8.1	8.5 8.1	8.5 8.1	8.0 8.1	7.0 8.0	7.0 8.0	7.0 7.9	6.4* 7.9	6.3* 7.8	3.0* 7.4													
28030001 16 ENT TO FSP(0.3R)	0.000	3.860	C 2	1 3.6	1 3900 FC125	55	CRACKING RIDE	1.5* 8.2	1.5* 8.0	1.5* 7.7	10.0 8.3	10.0 8.2	10.0 8.3	10.0 7.4	10.0 8.3	10.0 8.2	8.5 8.0	8.5 8.1	7.5 8.1	7.0 7.9													
2080202 ANDERSON COLUMBIA CO., INC(2004) 2080205	0.000 0.000	9.184 9.163	C 2002 C 2025	0012 SPRIDE 0012			CRACKING RIDE	7.0 7.8	7.0 7.8	7.0 7.8	7.0 7.7	7.0 7.7	6.5 7.6	6.5 7.7	5.5* 7.3	3.5* 7.2	3.5* 7.1	3.5* 6.9	3.3* 7.1	3.1* 7.1	0.0* 6.7													
28030001 16 NW 216TH ST(4.2L)	3.860	7.250	C 2	1 3.6	1 5100 FC125	60	CRACKING RIDE	1.5* 8.2	1.5* 8.0	1.5* 7.7	10.0 8.3	10.0 8.2	10.0 8.3	10.0 7.4	10.0 8.3	10.0 8.2	8.5 8.0	8.5 8.1	7.5 8.1	7.0 7.9													
2080202 ANDERSON COLUMBIA CO., INC(2004) 2080205	0.000 0.000	9.184 9.163	C 2002 C 2025	0012 SPRIDE 0012			CRACKING RIDE	7.0 7.8	7.0 7.8	7.0 7.8	7.0 7.7	7.0 7.7	6.5 7.6	6.5 7.7	6.5 7.9	6.5 7.9	6.5 7.8	6.0* 7.7	6.0* 7.8	4.3* 7.7	0.5* 7.3													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = BRADFORD ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP / W_EMP	EMP / G_EMP / W_EMP	RW / LN / RW / FY-P / FY-F	SYS / %T / RW / FY-P / WKMX-P / WKMX-F	TYP / AADT / SURFTYPE / ASTYPE	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
28030001 16 NW 177TH ST(7.3R) (2020) 2080205	7.250 2 0.000	7.790 3.6 9.163	C 2 C 2025	1 5100 0012	1 FC125M	40	CRACKING RIDE CRACKING RIDE	1.5* 8.2 7.0 7.8	1.5* 8.0 7.0 7.8	1.5* 7.7 7.0 7.8	10.0 8.3 7.0 7.7	10.0 8.2 7.0 7.7	10.0 8.3 6.5 7.6	10.0 7.4 10.0 7.6	10.0 8.3 10.0 7.5	10.0 8.2 9.0 7.5	8.5 8.0 9.0 7.5	8.5 8.1 9.0 7.4	7.5 8.1 8.6 7.4	7.0 7.9 8.8 7.4	7.0 7.0												
28030001 16 HARLEY CIR(7.9R) 2080202 ANDERSON COLUMBIA CO., INC(2004) 2080205	7.790 2 0.000 SPRIDE 0.000	9.184 3.6 9.184 9.163	C 2 C 2002 C 2025	1 5900 0012 0012	1 FC125	40	CRACKING RIDE CRACKING SPRIDE	7.0 7.7 9.5 7.7	6.0* 7.6 7.0 7.7	6.0* 7.4 7.0 7.4	10.0 8.1 7.0 7.4	10.0 8.0 7.0 7.5	10.0 7.8 6.0* 7.3	10.0 7.2 6.0* 7.3	10.0 8.0 6.0* 7.2	10.0 7.8 5.5* 7.2	9.5 7.7 5.5* 7.1	9.5 7.9 3.5* 7.1	9.5 7.8 2.8* 7.1	9.5 7.7 2.4* 7.1	0.0* 6.7												
28040000 18 SW 206 AVE(1.8L) 2079732 ANDERSON COLUMBIA CO., INC(2009) 2079703	0.000 2 0.000 SPRIDE 0.000	5.708 8.0 5.509 7.1 5.708	C 2 C 2007 C 2028	1 900 0221 0012	1 FC125	60	CRACKING RIDE CRACKING SPRIDE	7.0 8.2 8.5 7.1	6.5 8.2 8.5 7.2	6.5 7.8 8.5 7.5	6.5 7.6 8.5 7.4	6.5 7.8 8.5 7.0	6.5 7.6 8.5 7.0	6.5 7.7 7.5 7.1	3.5* 7.8 7.0 7.0	10.0 8.6 7.0 6.6	10.0 8.2 7.0 6.8	10.0 8.3 7.0 6.6	10.0 8.0 6.9 6.6	8.5 7.7 6.2* 6.4*	3.0* 6.0*												
28050000 230 SR 200(0.0C) (2024) 28050000 230 REDGRAVE ST(0.4R) 4244821 V. E. WHITEHURST & SONS, I(2014) 4244823	0.000 2 0.379 2 0.694 SPRIDE 0.379	0.379 2.2 3.843 6.7 3.843 8.5 3.843	C 2 C 2024 C 2013 C 2027	1 3600 0012 1750 0012	1 FC125 1 FC125R	25 55	CRACKING RIDE CRACKING RIDE CRACKING SPRIDE	9.5 5.9* 6.5 5.0* 9.5 8.2 10.0 8.5	9.5 5.4* 6.5 4.7* 9.5 8.7 10.0 8.3	9.5 7.2 5.5* 4.4* 9.5 8.7 10.0 8.2	9.0 6.4 5.5* 4.4* 8.0 8.2 10.0 7.9	9.0 6.5 5.5* 4.5* 8.0 8.1 10.0 7.6	9.0 6.5 5.5* 4.3* 8.0 8.0 10.0 7.0	9.0 7.0 5.5* 4.4* 7.0 8.1 8.5 6.9	6.5 6.6 3.5* 7.0 6.5 7.9 7.0 6.5	6.5 6.4 3.5* 7.0 6.5 7.8 7.0 6.0*	6.5 6.4 3.5* 7.0 6.5 7.3 6.0* 5.8*	6.5 6.3 10.0 7.0 6.5 7.4 6.0* 5.5*	6.5 6.3 10.0 6.9 6.5 7.1 6.0* 5.1*	6.5 6.2 10.0 6.2* 6.5 6.8 6.0* 5.2*	6.5 6.2 9.0 3.8* 6.5 7.4 3.5* 4.8*												
28060000 231 SW 114 ST(0.3L) 2079783 ANDERSON COLUMBIA CO., INC(2009) 2079702	0.000 2 0.000 SPRIDE 0.000	0.657 5.9 0.671 7.3 0.657	C 2 C 2007 C 2028	1 4200 0012 0012	1 FC125	55	CRACKING RIDE CRACKING SPRIDE	9.5 8.0 10.0 7.3	8.0 8.3 9.0 7.2	8.0 8.2 9.0 7.3	7.0 7.7 9.0 7.3	8.0 7.6 9.0 7.3	8.0 7.3 8.5 7.1	6.5 7.7 7.5 7.3	4.5* 7.5 7.0 7.3	10.0 8.2 6.0* 7.3	10.0 7.8 6.0* 7.3	10.0 8.1 5.5* 7.3	10.0 7.8 4.2* 7.3	10.0 7.4 3.7* 7.2	0.5* 6.8												
28090000 21 SE 16TH ST(0.8L) (2022) 28125000 200 301 N END BR #280061(0.0C) 2080014 SUPERIOR CONSTRUCTION COMP(2021)	0.000 2 0.240 0.000 SPRIDE	3.560 7.9 0.240 2.661	C 2 R C 2016	1 9900 1 0002	1 FC125M 1 FC5M	55 55	CRACKING RIDE CRACKING RIDE CRACKING SPRIDE	4.5* 7.5 8.5 8.1 10.0 8.8	3.5* 7.3 7.0 8.0 10.0 8.7	2.5* 5.8* 7.0 7.9 10.0 8.6	2.5* 6.2* 7.0 7.8 10.0 8.6	2.5* 6.1* 7.0 7.8 10.0 8.2	6.0* 7.7 10.0 8.1	10.0 8.4 6.0* 7.7 10.0 8.7	10.0 8.3 5.5* 7.7 10.0 8.6	10.0 8.4 10.0 8.3 7.9	10.0 8.3 10.0 8.3 8.1	10.0 8.2 10.0 8.3 8.2	8.5 8.1 10.0 8.2 7.8	8.5 8.1 8.5 7.8 7.9												
28125000 223 A301 SR 200(0.4R) 2080014 SUPERIOR CONSTRUCTION COMP(2021)	0.240 2 0.000 SPRIDE	0.550 29.2 2.661	R C 2016	1 21900 0002	1 FC125M	55	CRACKING RIDE CRACKING SPRIDE	10.0 8.8	10.0 8.7	10.0 8.6	10.0 8.6	9.5 7.9	10.0 7.8	8.5 7.4																								
28125000 223 A301 (2021) 28125000 200 301 SR 200(6.8R) (2021)	0.550 2 6.640 2	6.640 29.2 6.996	R R	1 19500 1 19500	1 FC5M 1 FC125M	70 55	CRACKING RIDE CRACKING RIDE CRACKING RIDE	10.0 8.8 10.0 8.8	10.0 8.7 10.0 8.7	10.0 8.6 10.0 8.6	10.0 8.6 10.0 8.6	9.0 8.7 9.1 8.2	9.0 8.7 10.0 8.2	7.0 8.5 8.5 7.8																								

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = BRADFORD ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
28125000 200 301 CR 233(7.2C)	6.996	7.166	R	1	1	55	2 29.2	19500 FC5M	CRACKING												10.0	10.0	10.0	10.0	9.0	8.8	6.5									
							(2021)		RIDE												8.8	8.7	8.6	8.6	8.6	8.6	8.4									
28125000 200 301 CR-233(7.2L)	6.996	7.166	L	1	1	55	2 29.2	19500 FC5M	CRACKING												10.0	10.0	10.0	10.0	9.0	9.0	7.0									
							(2021)		RIDE												8.9	8.7	8.6	8.6	8.8	8.9	8.7									
28125000 200 301	6.651	6.996	L	1	1	55	2 29.2	19500 FC125M	CRACKING												10.0	10.0	10.0	10.0	9.1	9.5	8.0									
							(2021)		RIDE												8.9	8.7	8.6	8.6	8.3	8.2	7.8									
28125000 223 A301	0.531	6.651	L	1	1	70	2 29.2	19500 FC5M	CRACKING												10.0	10.0	10.0	10.0	9.0	8.8	6.5									
							(2021)		RIDE												8.9	8.7	8.6	8.6	8.7	8.6	8.4									
28125000 200 301	0.230	0.531	L	1	1	55	2 29.2	21900 FC125M	CRACKING												10.0	10.0	10.0	10.0	10.0	8.5	7.0									
2080014 SUPERIOR CONSTRUCTION COMP	0.000	2.661	C	2016			0002	SPRIDE	RIDE												8.9	8.7	8.6	8.6	8.1	8.1	7.7									
28125000 200 301 N END BR #280061(0.0C)	0.000	0.230	L	1	1	55	2 29.2	21900 FC5M	CRACKING												10.0	10.0	10.0	10.0	9.0	8.3	6.0*									
2080014 SUPERIOR CONSTRUCTION COMP	0.000	2.661	C	2016			0002	SPRIDE	RIDE												8.9	8.7	8.6	8.6	8.1	7.9	7.7									

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).