FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS / LN / FY-P / FY-F	TYP / %T / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	SPD / AADT	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
29001000	0.000	0.363	C	1	1	45	CRACKING																												
100A 441			2	17.8		6800	RIDE																												
SR 25(0.0C)					FC125M																														
4432821	0.026	0.354	C	2022		0012	CRACKING					3.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	9.1	10.0	8.5														
ANDERSON COLUMBIA CO., INC				(2023)			SPRIDE					6.3	6.2	6.8	7.3	6.4	8.0	7.1	7.0	6.6	6.2														
29002000	0.000	3.471	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0	7.0	7.0	7.0															
10A			2	7.6		17200	RIDE	8.3	8.5	8.5	8.0	7.9	7.7	7.3	7.6	7.7	7.1	7.0	7.0	6.9															
DUVAL ST(0.0C)					FC125M																														
4305561	0.959	3.471	R	2016		0012	CRACKING	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.4	6.5	4.5*														
ANDERSON COLUMBIA CO., INC				(2017)			SPRIDE	7.4	6.6	7.0	8.0	7.8	7.5	7.6	7.6	7.4	7.4	7.1	7.1	7.1	6.7														
29002000	0.000	3.471	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0															
10A			2	7.6		17200	RIDE	8.5	8.4	8.4	7.8	7.5	7.1	6.8	7.2	7.2	7.1	7.0	7.0	6.9															
DUVAL ST(0.0C)					FC125M																														
4305561	0.959	3.471	L	2016		0012	CRACKING	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	6.5	4.5*														
ANDERSON COLUMBIA CO., INC				(2017)			SPRIDE	7.4	6.6	7.0	8.0	7.8	7.5	7.6	7.6	6.9	6.8	6.6	6.6	6.5	6.1														
29010000	0.000	4.490	C	1	1	60	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	6.0*	6.0*	6.0*															
10 90			2	5.8		7754	RIDE	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.6	8.4	8.4	8.3	8.2	8.1															
BELL LAKE CT(0.5L)					FC125W																														
4244931	0.687	4.493	C	2013		0012	CRACKING	4.0*	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.0	7.0	6.5	6.5	4.0*														
ANDERSON COLUMBIA CO., INC				(2015)			SPRIDE	8.1	8.5	8.4	8.5	8.4	8.3	8.4	8.4	8.4	8.2	8.4	8.3	8.2	7.8														
29010000	4.490	5.957	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	6.0*	6.0*	6.0*															
10 90			2	5.8		24000	RIDE	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.1	8.1	7.9	7.8	7.9	7.6															
SW EXECUTIVE DR(4.8R)					FC125W																														
							CRACKING	6.0*	6.0*			10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.5	6.5														
				(2018)			RIDE	7.7	7.7			7.9	7.6	7.7	7.6	7.7	7.5	7.6	7.5	7.6	7.2														
29010000	5.957	6.900	R	1	1	45	CRACKING	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.0	8.0															
10 90			2	5.8		30000	RIDE	7.4	6.4*	8.6	8.1	8.3	8.0	8.1	8.1	8.1	7.9	7.9	7.9	7.8															
CR 252B(6.2R)					FC125M																														
4433131	5.908	6.775	R	2022		0012	CRACKING	7.0	7.0	5.5*		6.0*	3.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC				(2024)			SPRIDE	7.8	7.8	7.7		7.5	7.8	8.5	8.5	8.4		8.1	8.1	8.1	7.7														
29010000	6.900	9.137	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5															
10 90			3	5.8		29000	RIDE	8.6	8.4	8.4	8.0	8.1	8.0	7.8	8.2	8.2	7.7	7.6	7.7	7.8															
REAL RD(7.3C)					FC125M																														
4433131	6.775	9.065	R	2022		0012	CRACKING	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.0	7.0		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC				(2024)			SPRIDE	7.7	7.8	7.6	7.7	7.5	7.6	7.6	7.6	7.5		8.7	8.6	8.6	8.2														
29010000	9.137	9.208	R	1	1	45	CRACKING	3.5*	3.5*	1.0*	1.0*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	8.5	8.5															
10 90			2	5.8		19900	RIDE	7.6	7.4	7.2	6.4*	6.3*	5.8	8.1	7.7	7.3	7.3	7.1	7.3	7.2															
BAYA AVE(9.2R)					FC125M																														
4433131	9.065	9.208	R	2022		0012	CRACKING	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	10.0		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC				(2024)			SPRIDE	7.8	7.7	7.7	7.6	7.6	7.7	7.5	7.5	8.2				7.6	7.2														
29010000	9.208	11.191	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5															
10 90			2	5.8		14600	RIDE	8.5	8.4	8.4	7.7	7.9	7.5	7.7	7.4	7.8	7.6	7.7	7.5	7.2															
MCFARLANE AVE R(9.4R)					FC125M																														
4412581	9.208	11.997	C	2020		0012	CRACKING	8.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	4.0*	10.0	10.0	10.0	9.6	10.0	8.5														
ANDERSON COLUMBIA CO., INC				(2022)			SPRIDE	7.3	6.9	7.1	6.9	7.1	7.3	7.3	7.3	8.2	8.1	8.1	8.1	8.0	7.6														
29010000	11.191	12.000	C	1	1	45	CRACKING	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
10 90			4	5.8		10000	RIDE	7.7	7.4	7.5	6.8	6.9	6.5	8.2	8.1	8.3	8.2	8.2	7.7	7.7															
MONTROSE AVE NE(11.2C)					FC125M																														
4412581	9.208	11.997	C	2020		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	10.0	10.0	10.0	9.4	10.0	8.5														
ANDERSON COLUMBIA CO., INC				(2022)			SPRIDE	7.8	7.6	7.7	7.6	7.3	7.4	7.2	7.4	8.2	8.1	8.1	8.0	8.0	7.6														
29010000	12.000	12.589	R	1	1	45	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	4.5*	10.0	10.0															
10 90			2	11.9		7200	RIDE	8.5	8.2	8.7	8.0	8.0	8.1	7.7	8.1	8.0	7.9	7.9	7.8	7.9															
LLEWELLYN AVE SE(12.0R)					FC125M																														
2083663	12.069	14.321	R	2011		0226	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.1*	4.5*	1.5*														
ANDERSON COLUMBIA CO., INC				(2012)			SPRIDE	8.1	7.9	8.2	8.1	8.1	8.2	8.1	8.3	8.2	8.1	8.1	8.0	6.8	6.4														
2083665	12.008	14.663	C	2027		0012																													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	DISTRESS / RATINGS / SURFTYPE / RW FY-P / ASTYPE / RW FY-F	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
29010000	12.589	14.664	R				1		55	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	4.5*	10.0	10.0													
10	90						2	11.9	10700	RIDE	8.5	8.2	8.7	8.0	8.0	8.1	7.7	8.1	8.0	7.9	7.9	7.8	7.9													
DIVISION OF FORESTRY(12.6R)										WKMX-P FC5																											
2083663	12.069	14.321	R	2011					0226	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.1*	4.5*	0.0*													
ANDERSON COLUMBIA CO., INC(2012)										SPRIDE	8.1	7.9	8.2	8.1	8.1	8.2	8.1	8.3	8.2	8.1	8.1	8.0	8.2	8.0													
2083665	12.008	14.663	C	2027					0012																												
29010000	14.664	20.891	C				1		60	CRACKING	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0													
10	90						2	11.9	7500	RIDE	8.7	8.5	8.6	7.7	7.7	7.3	7.3	8.6	8.5	8.4	8.4	8.1	8.0													
BILLY CRAIG CT NE(14.7L)										FC125M																											
2083662	14.920	17.791	C	2007					0012	CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	0.0*													
ANDERSON COLUMBIA CO., INC(2008)										RIDE	8.1	7.8	7.8	7.9	7.7	7.6	7.9	7.8	7.8	7.8	7.6	7.5	7.6	7.2													
2083664	14.663	20.891	C	2027					0012																												
29010000	12.589	14.664	L				1		55	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.0*	10.0	10.0													
10	90						2	11.9	10700	RIDE	8.8	8.5	8.5	8.2	8.2	8.0	8.2	8.2	8.1	8.0	7.9	8.2	8.1													
NE CR-245(12.7L)										FC5																											
2083663	12.069	14.321	L	2011					0226	CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.6*	3.0*	0.0*													
ANDERSON COLUMBIA CO., INC(2012)										SPRIDE	8.3	8.1	8.3	8.3	8.2	8.3	8.3	8.3	8.3	8.1	8.1	8.1	8.2	8.0													
2083665	12.008	14.663	C	2027					0012																												
29010000	12.000	12.589	L				1		45	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.0*	10.0	10.0													
10	90						2	11.9	7200	RIDE	8.8	8.5	8.5	8.2	8.2	8.0	8.2	8.2	8.1	8.0	7.9	8.2	8.1													
CR 100(12.1L)										FC125M																											
2083663	12.069	14.321	L	2011					0226	CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.6*	2.8*	0.0*													
ANDERSON COLUMBIA CO., INC(2012)										SPRIDE	8.3	8.1	8.3	8.3	8.2	8.3	8.3	8.3	8.3	8.1	8.1	8.1	7.2	6.8													
2083665	12.008	14.663	C	2027					0012																												
29010000	9.208	11.191	L				1		45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5													
10	90						2	5.8	14600	RIDE	8.6	8.0	8.4	7.8	8.0	7.7	7.7	7.8	7.9	7.9	7.7	7.5	7.4													
DUVAL ST W(9.3L)										FC125M																											
4412581	9.208	11.997	C	2020					0012	CRACKING	8.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	4.0*	10.0	10.0	10.0	9.7	10.0	8.5													
ANDERSON COLUMBIA CO., INC(2022)										SPRIDE	7.3	6.9	7.1	6.9	7.1	7.3	7.3	7.5	8.2	8.1	7.9	8.0	7.8	7.4													
29010000	9.137	9.208	L				1		45	CRACKING	6.5	6.5	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	8.5	8.5	8.5													
10	90						2	5.8	19900	RIDE	7.3	7.1	7.0	6.0*	6.0*	5.3*	8.1	7.8	7.8	7.7	7.9	7.9	7.7													
EDISON WAY(9.2L)										FC125M																											
4433131	9.065	9.208	L	2022					0012	CRACKING	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	10.0		10.0	10.0	10.0	9.0													
ANDERSON COLUMBIA CO., INC(2024)										SPRIDE	7.8	7.7	7.7	7.6	7.6	7.7	7.5	7.3	8.2				7.7	7.3													
29010000	6.884	9.137	L				1		45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.5	8.5													
10	90						3	5.8	29000	RIDE	8.7	8.5	8.5	7.9	7.9	7.8	7.7	8.0	8.0	7.8	7.5	7.6	7.5													
BROOKSIDE AVE L(7.0L)										FC125M																											
4433131	6.775	9.065	L	2022					0012	CRACKING	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.0	7.0		10.0	10.0	10.0	9.0													
ANDERSON COLUMBIA CO., INC(2024)										SPRIDE	7.7	7.8	7.6	7.7	7.5	7.6	7.6	7.8	7.9		8.6	8.4	8.4	8.0													
29010000	5.957	6.884	L				1		45	CRACKING	7.0	7.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5													
10	90						2	5.8	30000	RIDE	8.0	7.7	8.7	8.2	8.4	7.9	8.0	8.3	8.2	7.7	7.7	7.8	7.6													
NW HARVEY WAY(6.2L)										FC125M																											
4433131	5.908	6.775	L	2022					0012	CRACKING	7.0	7.0	5.5*		6.0*	3.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	9.0													
ANDERSON COLUMBIA CO., INC(2024)										SPRIDE	7.8	7.8	7.7		7.5	7.8	8.5	8.4	8.4		8.5	8.2	8.2	7.8													
29010000	4.490	5.957	L				1		45	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.5	7.0	6.0*	6.0*	6.0*													
10	90						2	5.8	24000	RIDE	9.0	8.9	8.8	8.5	8.6	8.3	8.4	8.2	8.1	7.9	7.8	7.9	7.6													
BROWN RD(4.8L)										FC125M																											
										CRACKING	6.0*	6.0*			10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.0	6.0*													
				(2018)						RIDE	7.7	7.7			7.9	7.9	7.8	7.7	7.4	7.3	7.3	7.2	7.1	6.7													
29020000	0.000	4.326	C				1		60	CRACKING	10.0	10.0	8.5	7.0	7.0	6.0*	5.5*	4.0*	4.0*	10.0	10.0	10.0	10.0													
47							2	7.3	2828	RIDE	8.7	8.8	8.7	7.9	8.0	7.8	7.4	7.1	7.0	8.6	8.6	8.5	8.5													
C-138(0.3R)										FC125																											
2084171	0.000	4.312	C	2009					0012	CRACKING	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.5	7.5	7.5	7.5	6.7	6.5	3.5*													
ANDERSON COLUMBIA CO., INC(2010)										SPRIDE	8.2	8.3	8.1	8.1	8.0	8.1	7.9	8.0	7.9	7.9	7.8	7.8	7.9	7.5													
29020000	4.326	4.963	C				1		35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5	8.5													
47							2	6.1	5100	RIDE	8.3	8.5	8.6	7.9	8.3	8.1	8.1	8.3	7.9	8.0	7.9	7.8	7.7													
SW WELL ST(4.4C)										FC125M																											
										CRACKING	7.0	7.0	7.0	6.5	6.0*	5.5*	10.0	10.0	10.0	10.0	9.0	9.1	8.4	6.5													
				(2020)						RIDE	7.7	7.6	7.6	7.6	7.5	7.6	8.3	8.2	8.1	7.9	7.7	7.7	7.4	7.0													
4454021	4.325	18.676	C	2023					0012																												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / FY-P / FY-F	AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
29020000	4.963	18.000	C	1	1	60			CRACKING	7.5	5.5*	5.0*	5.0*	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5	8.5													
47			2	6.1		6300			RIDE	7.8	7.6	7.5	6.0*	8.3	8.1	8.1	8.1	7.9	8.0	7.9	7.8	7.7													
DEESE LN(5.1L)								FC125M																												
									CRACKING	7.0	7.0	7.0	6.5	6.0*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	9.0												
							(2025)		RIDE	7.7	7.6	7.6	7.6	7.5	7.6	7.4	7.5	7.4	7.3	7.3	8.4	8.3	7.9												
29020000	18.000	18.989	R	1	1	45			CRACKING	10.0	8.5	7.5	7.5	10.0	10.0	9.5	10.0	10.0	10.0	10.0	9.0	9.0													
47			2	6.1		14000			RIDE	8.4	8.3	8.1	7.4	8.3	8.1	8.1	8.0	7.8	7.8	7.9	7.7	7.5													
ARUID DR SW(18.2R)								FC125M																												
									CRACKING	9.0	9.0	8.0	8.0	8.0	6.5	6.5	6.5	6.5	6.5	5.5*	10.0	10.0	9.0												
							(2025)		RIDE	7.7	7.5	7.1	7.0	7.3	7.3	7.3	7.4	7.2	7.4	7.3	8.0	8.0	7.6												
29020000	18.989	22.554	R	1	1	50			CRACKING	7.5	7.0	6.0*	6.0*	6.0*			10.0	10.0	10.0	10.0	10.0	10.0													
47			2	6.1		13000			RIDE	8.5	8.4	8.3	7.7	7.4			8.1	8.2	8.0	8.0	7.9	7.9													
CANNON CREEK PARK(19.1R)								FC125																												
2083631	18.821	22.554	C	2004		0213			CRACKING	10.0	10.0	9.0	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	5.6*	5.0*	1.5*												
ANDERSON COLUMBIA CO., INC					(2008)			SPRIDE	RIDE	7.8	7.8	7.7	7.5	7.6	7.6	7.5	7.5	7.5	7.5	7.3	7.4	7.3	6.9												
4454022	18.676	22.550	C	2029		0012																														
29020000	18.944	22.554	L	1	1	50			CRACKING	7.5	7.0	6.0*	6.0*	6.0*			10.0	10.0	10.0	10.0	10.0	10.0													
47			2	6.1		13000			RIDE	8.5	8.4	8.3	7.7	7.4			8.3	8.2	8.1	8.1	8.0	7.9													
SW RING CT(19.1L)								FC125																												
2083631	18.821	22.554	C	2004		0213			CRACKING	10.0	9.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	6.0*	5.1*	4.2*	1.0*												
ANDERSON COLUMBIA CO., INC					(2008)			SPRIDE	RIDE	7.9	7.8	7.5	7.6	7.4	7.4	7.3	7.4	7.3	7.4	7.3	7.3	7.3	6.9												
4454022	18.676	22.550	C	2029		0012																														
29020000	18.000	18.944	L	1	1	55			CRACKING	10.0	8.5	7.5	7.5	10.0	10.0	9.5	10.0	10.0	10.0	10.0	10.0	10.0													
47			2	6.1		14000			RIDE	8.4	8.3	8.1	7.4	8.3	8.1	8.1	7.6	7.5	7.3	7.4	7.2	7.1													
RIDGE RD(18.3L)								FC125M																												
									CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0	10.0	10.0	9.0												
							(2025)		RIDE	7.1	7.2	6.7	6.6	7.7	7.6	7.6	7.4	7.5	7.6	7.3	8.1	8.2	7.8												
29030000	0.000	9.664	C	1	1	60			CRACKING	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0													
25	41		2	9.6		5400			RIDE	8.4	8.2	8.1		8.1	7.9	8.0	7.9	7.9	7.9	7.9	7.8	7.7													
RIVERVIEW CIR SE(0.2R)								FC125M																												
									CRACKING	6.5	6.5	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.0												
							(2020)		RIDE	7.6	7.2	7.7	7.6	7.4		8.7	8.7	8.7	8.6	8.6	8.6	8.5	8.1												
29030000	9.664	10.377	R	1	1	45			CRACKING	10.0	10.0	8.5		8.5	9.0	9.0	10.0	7.0	6.5	6.5	6.5	10.0													
25	41		2	9.6		5400			RIDE	8.5	8.4	8.4		7.6	7.4	7.4	7.2	7.3	7.0	6.9	7.0	8.1													
								FC125M																												
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	6.5	5.8*	3.0*												
							(2013)		RIDE	8.1	8.0	7.9	7.9	7.8	7.6	7.8	7.8	7.7	7.6	7.5	7.5	7.3	6.9												
29030000	10.377	10.630	R	1	7	45			CRACKING	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0													
25	41		1	7.5		6900			RIDE	9.0	8.9	8.8		7.9	7.6	7.9	8.5	8.5	8.4	8.4	8.1	8.1													
SE SR 238(10.4R)								FC125M																												
2083523	10.344	10.607	R	2022		0012			CRACKING	7.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	9.0												
							(2026)		RIDE	8.0	7.7	7.9	7.9	7.9	7.7	7.7	7.8	7.7	7.7	7.7		8.1	7.7												
29030000	10.630	20.509	C	1	7	60			CRACKING	7.0	6.0*	6.0*	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	9.0													
25	41		2	7.5		6400			RIDE	9.0	8.9	8.8	8.1	7.7	7.8	7.8	8.5	8.5	8.4	8.4	8.1	8.1													
SW TABERNACLE GLN(10.9L)								FC125M																												
2083523	10.607	17.100	C	2022		0012			CRACKING	7.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	9.0												
							(2026)		RIDE	8.0	7.7	7.9	7.9	7.9	7.7	7.7	7.8	7.7	7.7	7.7		9.0	8.6												
29030000	20.509	20.837	R	1	7	45			CRACKING	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0													
25	41		1	7.5		10000			RIDE	7.8	8.3	8.3	7.9	7.8	7.9	7.3	8.5	8.5	8.3	8.2	8.0	7.9													
FINDERS PL SE(20.7R)								FC125M																												
2083523	20.447	20.696	R	2022		0012			CRACKING	8.5	8.5	8.5	7.5	7.5	6.0*	6.0*	5.5*	5.5*	5.5*	5.5*		10.0	9.0												
							(2026)		RIDE	8.0	7.7	7.6	7.6	7.7	7.7	7.6	7.6	7.7	7.4	7.6		8.4	8.0												
29030000	20.837	22.458	R	1	1	55			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0	7.0	6.0*	6.0*	6.0*													
25	41		2	5.5		10100			RIDE	8.8	8.7	8.8	8.2	8.3	8.0	8.1	8.0	8.0	7.9	7.9	7.8	7.7													
ALFRED MAR SE(20.9R)								FC125M																												
4286931	20.837	22.478	C	2014		0012			CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	4.3*	2.0*												
ANDERSON COLUMBIA CO., INC					(2015)			SPRIDE	RIDE	7.7	8.7	8.3	8.2	8.1	8.1	8.0	8.0	8.1	8.0	8.0	8.0	7.9	7.5												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
29030000	22.458	23.949	R	1	1	45	1	7.5	19600	FC125	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	7.5													
25 41			2	7.5							RIDE	8.2	8.2	8.1	7.7	7.7	7.7	7.3	7.5	7.3	7.4	7.7	7.3	7.3													
SHOPPING ENT(22.7R)																																					
4305611	22.458	23.949	C	2015					0012		CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.8	6.5												
ANDERSON COLUMBIA CO., INC				(2017)						SPRIDE	RIDE	7.4	7.2	7.4	7.9	7.8	7.7	7.7	7.6	7.6	7.4	7.5	7.5	7.4	7.0												
29030000	22.458	23.949	L	1	1	45	1	7.5	19600	FC125	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.5	7.5	7.5													
25 41			2	7.5							RIDE	7.9	8.0	8.0	7.7	7.7	7.5	7.6	7.6	7.7	7.6	7.5	7.6	7.3													
SR 47 NB(22.5L)																																					
4305611	22.458	23.949	C	2015					0012		CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.6	6.7	4.5*												
ANDERSON COLUMBIA CO., INC				(2017)						SPRIDE	RIDE	7.4	7.3	7.4	8.0	8.0	7.8	7.9	7.8	7.7	7.6	7.6	7.5	7.5	7.1												
29030000	20.835	22.458	L	1	1	55	2	5.5	10100	FC125M	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0	6.5	4.5*	4.5*	4.5*													
25 41											RIDE	8.8	8.8	8.7	8.0	8.3	8.0	7.9	8.0	7.8	7.5	7.7	7.3	7.1													
UNSIGNED(20.9L)																																					
4286931	20.837	22.478	C	2014					0012		CRACKING	3.5*	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	7.0	6.0*	5.4*	4.5*	2.0*												
ANDERSON COLUMBIA CO., INC				(2015)						SPRIDE	RIDE	7.2	8.6	8.3	7.9	8.1	8.2	8.2	8.1	8.1	8.2	8.0	8.1	7.9	7.5												
29030000	20.509	20.835	L	1	7	45	1	7.5	10000	FC125M	CRACKING	8.5	8.5	8.5	10.0	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0													
25 41			1	7.5							RIDE	7.4	7.1	7.3	8.0	7.0	6.6	6.7	8.5	8.3	8.1	7.9	7.7	7.7													
2083523	20.447	20.696	L	2022					0012		CRACKING	8.5	8.5	7.5	7.5	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	4.0*		10.0	9.0												
				(2026)							RIDE	7.7	7.6	7.5	7.6	7.7	7.4	7.6	7.4	7.3	7.4	7.2		8.3	7.9												
29030000	10.377	10.630	L	1	7	45	1	7.5	6900	FC125M	CRACKING	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0													
25 41			1	7.5							RIDE	9.0	8.9	8.8		7.9	7.6	7.9	8.5	8.5	8.4	8.4	8.1	8.1													
2083523	10.344	10.607	L	2022					0012		CRACKING	7.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	9.0												
				(2026)							RIDE	8.0	7.7	7.9	7.9	7.9	7.7	7.7	7.8	7.7	7.7	7.7		8.1	7.7												
29030000	9.664	10.377	L	1	1	45	2	9.6	5400	FC125M	CRACKING	10.0	10.0	10.0		8.5	8.5	8.5	9.5	8.5	8.5	7.5	7.5	10.0													
25 41											RIDE	8.1	7.6	8.3		7.5	7.2	7.4	7.6	7.2	7.1	7.1	7.0	8.0													
HOWELL ST SW(9.9L)																																					
											CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.5	6.0*	5.5*	3.5*	1.0*												
				(2013)							RIDE	8.1	8.0	7.8	7.8	7.7	7.6	7.7	7.6	7.5	7.4	7.2	7.1	7.0	6.6												
29030002	0.000	0.924	C	1	1		2	2.0	500		CRACKING																											
25F											RIDE																											
											CRACKING													4.9*														
											RIDE													7.5														
29040000	0.000	0.720	R	1	1	45	2	13.8	11200	FC125M	CRACKING	7.0	5.5*	3.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0													
25 41											RIDE	7.3	7.1	7.0		7.8	7.9	7.5	7.7	7.9	7.8	7.8	7.8	7.7													
DUVAL ST(0.0C)																																					
4361781	0.031	1.261	R	2021					0012		CRACKING	8.5	8.5	7.5	5.5*	5.5*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	10.0	8.5													
ANDERSON COLUMBIA CO., INC				(2023)						SPRIDE	RIDE	7.6	7.7	7.5	7.5	7.5	7.4	7.6	7.6	7.3	8.1	7.2	7.3	7.2	6.8												
29040000	0.720	1.934	R	1	1	45	1	13.8	10300	FC125M	CRACKING	8.5	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5													
25 41											RIDE	7.8	7.8	7.7		8.5	8.2	8.1	8.3	8.3	8.2	8.2	8.0	7.9													
LONG ST NW(0.7C)																																					
											CRACKING	7.5	7.5	7.0	5.5*	5.5*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	10.0	8.5													
				(2023)							RIDE	7.8	7.3	7.8	7.7	7.6	7.6	7.9	7.8	7.8	8.1	8.1	8.0	8.1	7.7												
29040000	1.934	4.149	C	1	1	60	2	13.8	8700	FC125M	CRACKING	7.5	7.0	5.5*		10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5													
25 41											RIDE	8.5	8.3	8.2		8.4	8.3	8.4	8.5	8.4	8.4	8.3	8.3	8.1													
MOORE RD NW(3.0C)																																					
											CRACKING	7.0	7.0	7.0	5.5*	6.5	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.5													
				(2023)							RIDE	8.0	8.0	7.9	7.8	7.9	7.8	7.9	7.9	7.8	8.6	8.4	8.4	8.3	7.9												
29040000	4.149	4.788	R	1	1	45	2	13.8	8700	FC125M	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0													
25 41			2	13.8							RIDE	8.9	8.8	8.9	8.4	8.5	8.2	8.1	8.1	8.0	7.9	7.9	7.9	8.2													
CR 25A NW(4.3R)																																					
											CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.5	6.5	5.5*	3.7*	1.0*													
				(2013)							RIDE	8.3	8.2	8.0	7.9	7.9	7.7	7.7	7.6	7.7	7.5	7.4	7.4	7.3	6.9												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
29040000	4.788	11.480	C	1	1	60			CRACKING	7.5	7.5	7.0	5.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0													
25 41			2	13.8		5800			RIDE	8.4	8.1	8.0	7.2	7.0	6.6	6.4*	8.6	8.5	8.4	8.5	8.4	8.3													
FLAMINGO GLEN NW(5.0L)									FC95M																											
2083893	4.788	11.480	C	2007		0012			CRACKING	8.5	8.5	8.5	8.5	7.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.1*	4.3*													1.0*
ANDERSON COLUMBIA CO., INC				(2008)					RIDE	8.3	8.2	8.1	8.1	8.1	8.0	8.0	8.0	8.0	7.9	7.8	7.8	7.7													7.3
2083895	4.837	11.480	C	2027		0012																														
29040000	4.149	4.788	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
25 41			2	13.8		8700			RIDE	8.5	8.3	8.3	7.6	7.8	7.7	7.7	7.8	7.8	7.8	7.7	7.8	8.1													
									FC125M																												
									CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	6.5	5.5*	3.5*													1.0*
				(2013)					RIDE	8.2	8.1	7.9	7.8	7.8	7.6	7.8	7.6	7.6	7.4	7.3	7.3	7.2													6.8
29040000	0.000	1.934	L	1	1	45			CRACKING	7.0	7.0	3.0*		10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5													
25 41			2	13.8		11200			RIDE	6.2*	7.0	7.0		8.3	7.8	8.1	8.0	8.4	7.7	8.1	7.6	7.9													
DUVAL ST(0.0C)									FC125M																											
4361781	0.031	1.261	L	2021		0012			CRACKING	8.5	8.5	8.5	7.5	6.0*	6.0*	6.0*	5.5*	5.5*	10.0	10.0	10.0	10.0													8.5
ANDERSON COLUMBIA CO., INC				(2023)					SPRIDE	7.6	7.8	7.6	7.9	7.7	7.7	7.8	7.8	7.7	8.0	7.7	7.6	7.7													7.3
29050000	0.000	7.219	C	1	7	60			CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0													
20 27			2	7.3		6800			RIDE	8.5	8.8	8.8	8.4	8.6	8.4	8.4	8.5	8.5	8.5	8.4	8.4	8.4													
RIVER RISE STATE PK(0.3R)									FC125M																											
2084183	3.954	11.839	C	2022		0012			CRACKING	8.5	8.5	8.5	8.0	7.0	7.0	7.0	6.0*	5.5*	5.5*	3.5*		10.0													9.0
				(2026)					RIDE	8.4	8.3	8.0	8.0	8.1	8.1	8.0	8.1	8.0	8.0	8.0		8.3													7.9
29050000	7.219	7.968	C	1	7	30			CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5													
20 27			2	7.3		6200			RIDE	7.6	8.5	8.4	7.9	8.1	8.0	8.0	8.1	7.7	7.8	7.8	7.7	7.8													
CR-18(7.3R)									FC125M																											
2084183	3.954	11.839	C	2022		0012			CRACKING	8.5	8.0	8.0	8.0	8.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*		10.0													9.0
				(2026)					RIDE	7.8	7.7	7.4	7.6	7.6	7.5	7.4	7.5	7.4	7.3	7.4		8.2													7.8
29050000	7.968	12.590	C	1	7	60			CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5													
20 27			2	7.3		6200			RIDE	8.6	8.8	8.8	8.5	8.6	8.4	8.5	8.6	8.5	8.6	8.5	8.4	8.4													
CENTERVILLE AVE SW(8.5R)									FC125M																											
2084183	3.954	11.839	C	2022		0012			CRACKING	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*		10.0													9.0
				(2026)					RIDE	8.5	8.3	8.0	8.0	8.0	8.0	7.9	7.9	8.0	7.9	7.8		8.2													7.8
29060000	0.000	7.350	C	1	1	60			CRACKING	3.5*	3.5*	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.5	8.5	7.0													
100			2	13.0		4600			RIDE	7.9	7.4	8.9	8.4	8.7	8.6	8.6	8.7	8.7	8.7	8.6	8.4	8.4													
CR 242 SE(1.2C)									FC125M																											
4342971	0.000	7.350	C	2019		0012			CRACKING	7.0	5.5*	5.5*	3.5*	3.5*	3.0*		10.0	10.0	10.0	10.0	9.7	10.0													8.5
PREFERRED MATERIALS, INC.				(2021)					SPRIDE	8.4	8.2	8.2	8.1	8.1	8.0		8.8	8.9	8.9	8.9	8.8	8.8													8.4
29060000	7.350	9.989	C	1	1	60			CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.5													
100			2	13.0		4600			RIDE	8.7	8.7	8.7	7.9	8.0	8.1	8.0	8.1	8.2	8.2	8.1	8.0	8.0													
ACADEMIC AVE SE(7.5R)									FC125A																											
4286941	7.354	9.915	C	2015		0012			CRACKING	7.5	7.5	7.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.9	8.0													6.0*
ANDERSON COLUMBIA COMPANY				(2017)					SPRIDE	8.0	7.9	7.8	8.5	8.5	8.3	8.4	8.4	8.3	8.4	8.4	8.3	8.3													7.9
29070000	0.061	0.569	R	1	1	45			CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	5.5*	5.5*	10.0	10.0	10.0	10.0													
25A 441			1	7.6		5200			RIDE	7.9	7.9	7.7	7.4	7.2	7.3	7.2	7.0	7.2	8.4	8.3	7.8	7.9													
SR 25(0.1C)									FC125																											
2084024	0.248	0.544	R	2009		0012			CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.2*	7.0													4.0*
				(2010)					RIDE	7.7	7.3	7.7	7.7	7.6	7.5	7.5	7.3	7.3	7.3	7.2	7.2	7.1													6.7
29070000	0.569	1.045	C	1	1	45			CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.0	6.0*	10.0	10.0	10.0	10.0													
25A 441			2	7.6		5200			RIDE	7.9	7.9	7.7	7.4	7.2	7.3	7.2	8.1	8.1	8.4	8.3	7.8	7.9													
CORONADO ST SW(0.6L)									FC125																											
2084024	0.544	1.086	C	2009		0012			CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.2*	7.0													4.0*
				(2010)					RIDE	7.7	7.3	7.7	7.7	7.6	7.5	7.5	7.3	7.3	7.3	7.2	7.2	7.4													7.0
29070000	1.045	2.652	R	1	1	45			CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	10.0	10.0	10.0	10.0													
25A 441			1	7.6		6300			RIDE	7.9	7.9	7.7	7.4	7.2	7.3	7.2	7.2	7.2	8.4	8.3	7.8	7.9													
BUTLER BLVD SE(1.3R)									FC125																											
2084024	1.086	2.653	R	2009		0012			CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.2*	7.5													4.5*
				(2010)					RIDE	7.7	7.3	7.7	7.7	7.6	7.5	7.5	7.3	7.3	7.3	7.2	7.2	7.0													6.6

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = COLUMBIA

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / SURFTYPE / FY-P / ASTYPE / FY-F	AADT / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
29070000	2.652	3.031	C	1	4	30			CRACKING	1.4*	3.2*	3.0*	2.3*	0.9*	0.5*	1.0*	0.0*	2.4*	2.0*	2.2*	1.2*	0.8*												
25A 441			2	7.6		4800			RIDE	7.2	6.9	7.1	5.8	5.7	5.2*	5.6	5.6	5.9	6.3	6.1	5.7	6.0												
SE CAMP ST(2.7R)								LDG																												
2083861	2.524	3.005	C	1992		0217			CRACKING	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.1*	0.6*	0.0*	0.0*											
ANDERSON COLUMBIA CO., INC(1997)									RIDE	6.1	5.6	6.5	6.4	6.4	6.6	6.2	6.0	5.9	6.0	5.9	5.9	6.0	5.9											
29070000	4.000	6.513	R	1	7	45			CRACKING	9.0	9.0	9.0	9.0	9.0	7.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0												
47 441			2	7.6		6300			RIDE	6.7	6.7	7.6	6.8	6.9	6.4	8.1	8.2	8.1	8.1	8.1	7.9	7.6												
BASCOM NORRIS DR(4.0R)								FC125M																												
4454341	4.000	6.490	R	2024		0012			CRACKING	8.0	6.5	6.5	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.5*	10.0	9.0											
ANDERSON COLUMBIA CO., INC(2026)								SPRIDE	RIDE	7.6	7.2	7.6	7.5	7.4	7.7	7.6	7.5	7.3	7.1	7.0	6.9	8.4	8.0											
29070000	6.513	6.912	R	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	10.0												
47 441			1	13.2		3200			RIDE	8.3	8.3	8.3	7.7	7.7	7.6	7.6	7.6	7.5	7.6	7.5	7.4	8.4												
								FC125M																												
									CRACKING	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	7.5	7.5	7.0	6.5	5.8*	3.0*											
				(2013)					RIDE	8.4	8.2	7.7	7.7	7.6	7.5	7.5	7.6	7.5	7.5	7.4	7.4	7.2	6.8											
2130745	6.490	6.881	C	2029		0012																														
29070000	6.912	15.991	C	1	7	60			CRACKING	10.0	10.0	7.0	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0												
47 441			2	13.2		3200			RIDE	8.6	8.5	8.5	7.7	7.8	7.5	7.4	7.4	8.5	8.4	8.4	8.2	8.0												
FRASER GREEN RD(7.0R)								FC125A																												
2084026	6.881	15.971	C	2023		0012			CRACKING	7.0	7.0	7.0	7.0	6.5	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	10.0	9.0											
				(2026)					RIDE	8.0	7.6	7.8	7.7	7.8	7.8	7.6	7.5	7.5	7.4	7.2	7.2	8.5	8.1											
29070000	15.991	32.016	C	1	1	60			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	7.0												
47 441			2	13.2		950			RIDE	8.7	8.7	8.7	8.2	8.2	8.0	7.9	8.0	7.8	7.8	7.7	7.5	7.4												
NE REGISTER LN(16.2R)								FC125M																												
4244921	15.991	32.016	C	2013		0012			CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.5	6.0*	5.5*	4.7*	2.0*											
ANDERSON COLUMBIA CO., INC(2014)								SPRIDE	RIDE	8.9	8.3	8.3	8.2	8.1	8.1	8.0	7.8	7.9	8.0	7.9	7.8	7.6	7.2											
2083897	15.990	32.016	C	2029		0012																														
29070000	6.513	6.912	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	10.0												
47 441			2	13.2		3200			RIDE	8.1	8.2	8.0	7.6	7.8	7.7	7.6	7.6	7.7	7.6	7.5	7.4	8.4												
								FC125M																												
									CRACKING	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	7.0	7.0	7.0	6.5	5.5*	3.0*											
				(2013)					RIDE	8.4	8.2	7.7	7.7	7.6	7.5	7.5	7.6	6.9	7.1	6.9	6.8	6.6	6.2											
2130745	6.490	6.881	C	2029		0012																														
29070000	4.000	6.513	L	1	7	45			CRACKING	9.0	9.0	9.0	9.0	7.5	6.5	10.0	10.0	10.0	9.0	9.0	9.0	9.0												
47 441			2	7.6		6300			RIDE	7.8	7.7	7.6	7.1	7.0	6.8	8.3	8.4	8.4	8.1	8.1	7.9	7.6												
US-441/SR-100A(4.0L)								FC125M																												
4454341	4.000	6.490	L	2024		0012			CRACKING	8.0	6.5	6.5	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	3.5*	10.0	9.0											
ANDERSON COLUMBIA CO., INC(2026)								SPRIDE	RIDE	7.6	7.2	7.6	7.5	7.4	7.7	7.6	7.5	7.6	7.6	7.4	7.5	8.4	8.0											
29080000	0.000	1.473	C	1	1	55			CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	10.0	10.0	10.0												
238			2	8.8		4400			RIDE	8.5	8.2	8.5	7.8	7.6	7.6	7.4	7.5	7.6	7.0	8.7	8.5	8.3												
SR 25 US 41 US 441(0.0C)								FC125M																												
2083932	0.000	1.472	C	2010		0226			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	6.5	3.5*											
ANDERSON COLUMBIA CO., INC(2011)									RIDE	8.4	8.2	8.2	8.1	8.1	7.9	8.1	8.1	8.0	7.9	7.8	7.8	7.7	7.3											
29090000	0.000	10.245	C	1	1	60			CRACKING	9.0	7.0	7.0	7.0	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	9.0												
247			2	15.4		5200			RIDE	8.1	8.1	8.4	7.8	7.4	7.4	6.6	8.3	8.3	8.0	8.0	7.7	7.7												
RAMP FROM MARKET RD(0.2L)								FC125M																												
2084115	0.000	5.580	C	2007		0012			CRACKING	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	3.5*	3.5*	3.5*	3.5*	3.5*	0.0*											
ANDERSON COLUMBIA CO., INC(2008)									RIDE	7.9	7.7	7.5	7.3	7.4	7.4	7.4	7.3	7.4	7.4	7.2	7.2	7.2	6.8											
2084119	0.000	10.074	C	2027		0012																														
29090000	10.245	11.348	R	1	1	45			CRACKING	9.0		10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.0	8.0												
247			1	4.4		13500			RIDE	8.4		8.2	7.7	7.8	7.6	7.5	7.5	7.5	6.9	7.2	7.3	7.5												
LEISURE DR SW(10.4R)								FC4																												
									CRACKING	8.0	8.0	8.0	8.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	5.5*	3.7*	0.0*											
				(2003)					RIDE	7.5	7.3	7.0	6.9	6.8	6.9	6.8	6.8	6.7	6.6	6.6	6.5	6.5	6.1											
4454351	10.074	11.348	C	2027		0012																														
29090000	10.245	11.348	L	1	1	45			CRACKING	9.0		10.0	10.0	10.0	10.0	8.5	9.0	8.5	8.5	8.5	8.0	8.0												
247			1	4.4		13500			RIDE	8.4		8.2	7.7	7.8	7.6	7.5	7.5	7.7	6.9	7.2	7.3	7.5												
REAL TERR SW(10.4L)								FC4																												
									CRACKING	8.0	8.0	8.0	8.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	5.5*	4.4*	0.5*											
				(2003)					RIDE	7.5	7.3	7.0	6.9	6.8	6.9	6.8	6.8	6.7	6.5	6.5	6.4	6.5	6.1											
4454351	10.074	11.348	C	2027		0012																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW LN / RW FY-P / RW FY-F	SYS / %T / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	TYP	SPD / AADT	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
29110000	0.000	0.837	C 1	1	60		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	7.5	7.5	7.5															
2			2 28.8		400		RIDE	8.4	8.6	8.5	7.7	8.1	7.9	7.5	8.0	7.8	7.9	8.0	7.9	7.9															
				FC125A																																	
4244841	0.000	0.837	C 2015		0012		CRACKING	7.0	7.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.1	6.5	4.0*														
ANDERSON COLUMBIA CO., INC			(2016)				RIDE	7.9	7.8	8.4	8.4	8.4	8.3	8.1	7.9	7.7	7.4	7.1	7.1	6.7	6.3*														
29160000	0.000	2.243	C 1	1	55		CRACKING	6.0*	3.5*	0.0*	0.0*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
136			2 12.1		2600		RIDE	8.0	7.9	7.8	6.2*	6.1*	6.1*	8.4	8.4	8.4	8.4	8.4	8.4	8.2															
NULL DR NW(0.9L)				FC125																																
2083712	0.000	2.243	C 2006		0012		CRACKING	9.0	9.0	9.0	7.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	3.5*	3.5*	3.1*	0.0*														
ANDERSON COLUMBIA CO., INC			(2007)				RIDE	8.2	8.0	8.0	8.0	8.0	7.8	7.8	7.7	7.6	7.6	7.6	7.4	7.6	7.2														
29170000	0.000	0.323	R 4	7	70		CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.0	6.5	6.0*	6.0*	10.0															
8 I10	293.8	294.1	2 27.7		29000		RIDE	9.1	9.0	9.0	8.4	8.5	8.2	8.3	8.1	8.0	7.9	7.7	7.4	8.4															
				FC5M																																	
							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.3	10.0	9.0														
			(2026)				RIDE	8.5	8.4	8.7	8.7	8.6	8.7	8.7	8.9	8.9	8.9	8.8	8.7	8.4	8.3														
29170000	0.323	6.455	R 4	1	70		CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.0	6.5	6.0*	6.0*	10.0															
8 I10	294.1	300.2	2 28.3		24000		RIDE	9.1	9.0	9.0	8.4	8.5	8.2	8.3	8.1	8.0	7.9	7.7	7.4	8.4															
				FC2																																	
2130743	0.000	9.522	C 2011		0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.3	7.8	5.0*														
ANDERSON COLUMBIA CO., INC			(2013)				SPRIDE	8.5	8.4	8.7	8.7	8.6	8.7	8.7	8.9	8.9	8.9	8.8	8.7	8.7	8.6														
29170000	6.455	16.297	R 4	1	70		CRACKING	10.0	9.0	6.5	4.5*	4.5*	3.5*	8.0		10.0	10.0	10.0	10.0	10.0															
8 I10	300.2	310.1	2 27.3		25957		RIDE	9.1	8.9	8.6	7.5	6.7	6.5	7.4		8.1	8.2	8.2	8.0	8.0															
				FC5M																																	
4326411	5.125	16.154	C 2013		0012		CRACKING	10.0		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.3	7.8	5.5*														
			(2016)				RIDE	8.1		8.7	8.7	8.7	8.7	8.7	8.9	8.9	8.8	8.7	8.5	8.7	8.6														
2130745	6.455	16.323	C 2029		0012																															
29170000	16.297	20.690	R 4	1	70		CRACKING	10.0	9.0	6.5	4.5*	4.5*	3.5*	8.0		10.0	10.0	10.0	10.0	10.0															
8 I10	310.1	314.4	2 27.3		25957		RIDE	9.1	8.9	8.6	7.5	6.7	6.5	7.4		8.1	8.2	8.2	8.0	8.0															
				FC5M																																	
4434211	16.323	20.690	C 2022		0012		CRACKING	10.0	9.0	7.5	7.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0															
ANDERSON COLUMBIA CO., INC			(2025)				SPRIDE	8.1	7.7	8.3	8.3	8.2	8.3	8.4	8.5	8.4	8.2	8.0	8.7	8.8	8.7														
29170000	16.297	20.690	L 4	1	70		CRACKING	10.0	10.0	9.0	6.5	6.5	4.5*	3.5*		10.0	10.0	10.0	10.0	10.0															
8 I10	310.1	314.4	2 27.3		25957		RIDE	8.9	8.7	8.7	8.0	7.4	7.1	6.9		8.1	8.2	8.2	8.2	8.1															
				FC5M																																	
4434211	16.323	20.690	C 2022		0012		CRACKING	10.0	10.0	9.0	9.0	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0															
ANDERSON COLUMBIA CO., INC			(2025)				SPRIDE	8.2	8.0	8.5	8.4	8.4	8.5	8.5	8.6	8.5	8.4	8.2	8.9	9.1	9.0														
29170000	6.455	16.297	L 4	1	70		CRACKING	10.0	10.0	9.0	6.5	6.5	4.5*	3.5*		10.0	10.0	10.0	10.0	10.0															
8 I10	300.2	310.1	2 27.3		25957		RIDE	8.9	8.7	8.7	8.0	7.4	7.1	6.9		8.1	8.2	8.2	8.2	8.1															
				FC5M																																	
4326411	5.125	16.154	C 2013		0012		CRACKING	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.6	8.3	6.0*														
			(2016)				RIDE	8.2		8.8	8.7	8.7	8.8	8.8	8.9	8.9	8.9	8.8	8.8	8.8	8.7														
2130745	6.455	16.323	C 2029		0012																															
29170000	0.323	6.455	L 4	1	70		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.5	6.5	10.0															
8 I10	294.1	300.2	2 28.3		24000		RIDE	9.2	9.2	9.1	8.6	8.5	8.4	8.3	8.2	8.2	8.1	7.8	7.7	8.4															
				FC5																																	
2130743	0.000	9.522	C 2011		0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	7.5	7.5	5.0*														
ANDERSON COLUMBIA CO., INC			(2013)				SPRIDE	8.5	8.4	8.7	8.7	8.7	8.8	8.8	8.9	8.9	8.8	8.8	8.8	8.8	8.7														
29170000	0.000	0.323	L 4	7	70		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.5	6.5	10.0															
8 I10	293.8	294.1	2 27.7		29000		RIDE	9.2	9.2	9.1	8.6	8.5	8.4	8.3	8.2	8.2	8.1	7.8	7.7	8.4															
				FC5M																																	
							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0		10.0	9.0														
			(2026)				RIDE	8.5	8.4	8.7	8.7	8.7	8.8	8.8	8.9	8.9	8.8	8.8		8.6	8.5														
29180000	0.000	9.790	R 4	1	70		CRACKING	10.0	10.0	9.0	9.0	9.0	8.0	8.0	7.5	6.5	6.0*	6.0*		10.0															
93 I75	407.9	417.7	3 30.8		58000		RIDE	9.0	9.0	9.0	8.4	7.9	7.6	8.1	7.9	7.7	7.4	6.8		8.2															
				FC5M																																	
2130713	0.000	9.802	C 2011		0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	6.9	6.5	4.0*														
V. E. WHITEHURST & SONS, I			(2013)				SPRIDE	8.3	8.2	8.6	8.6	8.6	8.7	8.8	8.9	8.9	8.8	8.8	8.7	8.7	8.6														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = COLUMBIA ----------

RDWYID / SR / INTERSECT AT / ITMSEG-P / CONTRACTOR / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / (MP|SIDE) / RW	SYS / %T / FY-P / FY-F	TYP SPD / AADT / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2031 (PMRS)
29180000	9.790	15.304	R	4	1 70	CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0	
93 I75	417.7	423.2	3	30.8	53000 FC5M	RIDE	8.9	8.9	8.8	8.2	8.0	7.9	7.9	7.9	8.3	8.3	8.2	8.1	7.9	
4455471	9.802	15.318	C	2023	0012	CRACKING	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.5	6.5	6.5	6.5	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC				(2025)	SPRIDE	RIDE	8.1	7.9	8.4	8.4	8.3	8.4	8.5	8.6	8.6	8.5	8.5	9.0	8.9	8.8
29180000	15.304	19.008	R	4	1 70	CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0	10.0	
93 I75	423.2	426.9	3	30.8	53000 FC5M	RIDE	8.9	8.9	8.8	8.2	8.0	7.9	7.9	8.1	8.2	8.2	8.1	8.1	7.8	
4425811	15.318	19.002	C	2021	0012	CRACKING	10.0	10.0	9.0	9.0	7.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.7	10.0	8.5
ANDERSON COLUMBIA CO., INC				(2023)	SPRIDE	RIDE	7.9	7.7	8.1	8.1	8.1	8.3	8.3	8.4	8.2	9.1	9.1	9.0	9.0	8.9
29180000	19.008	27.352	R	4	1 70	CRACKING	10.0	8.5	7.0	6.0*		10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	
93 I75	426.9	435.2	3	31.7	48915 FC5M	RIDE	9.0	8.7	8.5	8.3		8.3	8.3	8.2	8.1	7.9	7.8	7.8	7.4	
4327331	19.008	27.379	C	2016	0012	CRACKING	7.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.0
ANDERSON COLUMBIA CO., INC				(2018)	SPRIDE	RIDE	7.2	6.8	7.5		8.9	8.9	8.8	8.9	8.9	8.9	8.9	8.8	8.8	8.7
29180000	27.352	30.447	R	4	1 70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	10.0	10.0	10.0	
93 I75	435.2	438.3	3	30.8	48000 FC5M	RIDE	8.9	9.0	8.9	8.5	8.3	8.2	8.2	8.0	7.9	7.8	8.3	8.4	8.4	
4460451	27.379	30.447	C	2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	6.5	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC				(2025)	SPRIDE	RIDE	8.4	8.2	8.5	8.5	8.4	8.6	8.6	8.7	8.6	8.5	8.5	9.0	8.9	8.8
29180000	27.352	30.447	L	4	1 70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	6.5	10.0	10.0	10.0	
93 I75	435.2	438.3	3	30.8	48000 FC5M	RIDE	9.0	9.0	8.9	8.4	8.2	8.2	8.1	7.9	7.7	7.1	8.2	8.3	8.3	
4460451	27.379	30.447	C	2023	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC				(2025)	SPRIDE	RIDE	8.3	8.2	8.5	8.5	8.5	8.7	8.7	8.8	8.7	8.7	8.6	8.8	9.0	8.9
29180000	19.008	27.352	L	4	1 70	CRACKING	10.0	8.5	7.0	6.0*		10.0	10.0	9.0	9.0	9.0	8.5	8.5	8.5	
93 I75	426.9	435.2	3	31.7	48915 FC5M	RIDE	9.0	8.9	8.8	8.1		8.3	8.3	8.2	8.2	8.0	7.9	7.7	7.6	
4327331	19.008	27.379	C	2016	0012	CRACKING	7.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.7	9.0	7.0
ANDERSON COLUMBIA CO., INC				(2018)	SPRIDE	RIDE	7.4	7.2	7.8		8.8	8.8	8.8	8.9	8.9	8.9	8.9	8.9	8.9	8.8
29180000	15.315	19.008	L	4	1 70	CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	6.5	10.0	10.0	10.0	10.0	10.0	
93 I75	423.2	426.9	3	30.8	53000 FC5M	RIDE	9.0	8.5	8.8	8.2	8.1	7.9	7.8	8.2	8.1	8.1	8.1	8.1	7.9	
4425811	15.318	19.002	C	2021	0012	CRACKING	9.0	9.0	9.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	8.5
ANDERSON COLUMBIA CO., INC				(2023)	SPRIDE	RIDE	7.8	7.5	8.1	8.1	8.0	8.3	8.3	8.3	8.1	9.1	9.1	9.1	9.1	9.0
29180000	9.790	15.315	L	4	1 70	CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	10.0	10.0	10.0	10.0	10.0	
93 I75	417.7	423.2	3	30.8	53000 FC5M	RIDE	9.0	8.5	8.8	8.2	8.1	7.9	7.8	7.8	8.2	8.3	8.2	7.9	7.8	
4455471	9.802	15.318	C	2023	0012	CRACKING	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	6.5	4.5*	4.5*	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC				(2025)	SPRIDE	RIDE	7.9	7.7	8.3	8.3	8.3	8.3	8.3	8.6	8.5	8.4	8.4	9.1	9.0	8.9
29180000	0.000	9.790	L	4	1 70	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	6.0*	6.0*	6.0*		10.0	
93 I75	407.9	417.7	3	30.8	58000 FC5M	RIDE	9.1	9.0	8.9	8.4	8.2	8.2	7.8	7.8	7.5	7.0	7.1		8.3	
2130713	0.000	9.802	C	2011	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	7.8	7.3	4.5*
V. E. WHITEHURST & SONS, I				(2013)	SPRIDE	RIDE	8.3	8.2	8.5	8.5	8.5	8.6	8.6	8.6	8.7	8.6	8.6	8.5	8.5	8.4

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).