FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = DIXIE ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	LN	TYP / %T / SURFTYPE / ASTYPE / RW FY-P / RW FY-F	SPD / AADT / WKMX-P / WKMX-F	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
30010000	0.000	15.492	R	1	1	65	CRACKING	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
55 19		2 13.6				6300	RIDE	8.2	8.2	7.9		8.1	8.4	8.5	8.4	8.4	8.3	8.2	8.0	7.8															
SW 37 AVE(1.0R)						FC5M																														
4361721	0.000	14.990	C	2018		0012	CRACKING	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5														
ANDERSON COLUMBIA CO., INC(2020)						SPRIDE	RIDE	7.6	7.4	7.9	7.7	7.8	7.6	8.8	8.6	8.6	8.6	8.6	8.6	8.6	8.4														
30010000	15.492	17.679	R	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5															
55 19		2 13.6				6300	RIDE		8.8	8.7	8.2	8.2	7.6	7.8	7.5	7.7	7.8	7.6	7.5	7.6															
CR 351A(15.7R)						FC125M																														
4393571	15.485	17.084	R	2022		0012	CRACKING	7.5	7.5	7.5	7.5	7.5	7.0	5.5*	5.5*	5.5*		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2024)						SPRIDE	RIDE	7.5	7.2	7.2	7.1	6.5	7.0	6.8	6.8	6.6		8.3	8.2	8.0	7.6														
30010000	17.679	18.256	R	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0															
55 19		2 13.6				11000	RIDE		8.8	8.7	8.2	8.2	8.5	8.5	8.5	8.4	8.3	8.3	8.3	8.2														
SE BEAR LN(18.0R)						FC125M																														
4376191	17.671	25.343	C	2019		0012	CRACKING	7.0	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	9.7	10.0	8.5														
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE	RIDE	8.1	8.0	8.0	7.9	7.9	8.0		8.6	8.5	8.5	8.5	8.3	8.2	7.8														
30010000	18.256	25.344	R	1	1	65	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0															
55 19		2 13.6				15700	RIDE		8.8	8.7	8.2	8.2	8.5	8.5	8.5	8.4	8.3	8.3	8.3	8.2														
HOLLIS CHEWNING RD(18.4R)						FC5M																														
4376191	17.671	25.343	C	2019		0012	CRACKING	7.0	5.5*	5.5*	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	9.7	9.6	7.5														
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE	RIDE	8.1	8.0	8.0	7.9	7.9	8.0		8.6	8.5	8.5	8.5	8.5	8.5	8.3														
30010000	25.344	25.832	R	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5															
55 19		2 13.6				15700	RIDE		8.8	8.6	8.4	8.4	7.9	8.3	8.0	8.4	8.3	8.1	7.9	8.0															
MADISON ST(25.7R)						FC125M																														
2084641	25.450	29.216	C	1999		0221	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.2	8.0	4.0*														
ANDERSON COLUMBIA CO., INC(2002)						SPRIDE	RIDE	8.4	8.3	8.3	8.3	8.3	8.3	8.3	8.1	8.2	8.1	8.1	8.1	8.2	7.8														
30010000	25.832	29.216	R	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	6.5	6.5	6.5	6.5															
55 19		2 13.6				15700	RIDE	8.8	8.8	8.6	8.4	8.4	8.5	8.5	8.5	8.3	8.2	8.1	7.8															
CR-349/SE 349 HWY(25.8R)						FC5M																														
4244831	25.832	29.216	C	2012		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.4	7.9	3.5*														
ANDERSON COLUMBIA CO., INC(2014)							RIDE	8.2	8.2	8.4	8.4	8.4	8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.1														
30010000	25.832	29.216	L	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.0	6.5	6.5	6.5	6.5	6.5															
55 19		2 13.6				15700	RIDE	8.7	8.7	8.7	8.4	8.4	8.6	8.6	8.5	8.5	8.3	8.2	8.1															
CR 349(25.8L)						FC5M																														
4244831	25.832	29.216	C	2012		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.3	7.8	3.5*														
ANDERSON COLUMBIA CO., INC(2014)							RIDE	8.2	8.2	8.5	8.5	8.4	8.5	8.5	8.4	8.4	8.3	8.4	8.3	8.3	8.1														
30010000	25.344	25.832	L	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.5															
55 19		2 13.6				15700	RIDE		8.7	8.7	8.4	8.4	8.0	8.0	7.9	8.0	8.1	7.7	7.7	7.9														
HATCH ST(25.5L)						FC125M																														
2084641	25.450	29.216	C	1999		0221	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	8.0	7.7	7.5	3.5*														
ANDERSON COLUMBIA CO., INC(2002)						SPRIDE	RIDE	8.2	8.3	8.0	8.0	8.1	7.9	8.1	7.9	7.7	7.8	7.8	7.7	7.7	7.3														
30010000	18.256	25.344	L	1	1	65	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
55 19		2 13.6				15700	RIDE		8.7	8.6	8.2	8.2	8.5	8.6	8.5	8.5	8.4	8.4	8.2	8.2															
GEORGIA PACIFIC PLANT EN(18.8L)						FC5M																														
4376191	17.671	25.343	C	2019		0012	CRACKING	9.0	6.5	5.5*	5.5*	5.5*	3.5*		10.0	10.0	10.0	10.0	10.0	9.7	7.5														
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE	RIDE	8.1	8.0	8.2	8.1	8.0	8.1		8.7	8.6	8.6	8.6	8.6	8.6	8.4														
30010000	17.679	18.256	L	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
55 19		2 13.6				11000	RIDE		8.7	8.6	8.2	8.2	8.5	8.6	8.5	8.5	8.4	8.4	8.2	8.2															
BEAR LN SE(18.0L)						FC125M																														
4376191	17.671	25.343	C	2019		0012	CRACKING	9.0	6.5	5.5*	5.5*	5.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	8.5														
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE	RIDE	8.1	8.0	8.2	8.1	8.0	8.1		8.7	8.6	8.6	8.6	8.6	8.1	7.7														
30010000	15.492	17.679	L	1	1	35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5															
55 19		2 13.6				6300	RIDE		8.7	8.6	8.2	8.2	7.3	7.2	7.2	7.7	7.8	7.6	7.5	7.6															
CR-351A/NE 223 AVE(15.7L)						FC125M																														
4393571	15.485	17.084	L	2022		0012	CRACKING	7.5	7.5	7.5	7.5	7.5	7.0	5.5*	5.5*	5.5*		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2024)						SPRIDE	RIDE	7.5	7.2	7.2	7.1	6.5	7.0	6.8	6.4	6.3		8.3	8.2	8.0	7.6														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = DIXIE ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	DISTRESS / RATINGS / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
30010000	0.000	15.492	L	1	1	65	CRACKING	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5															
55 19		13.6		2		6300	RIDE	8.3	8.2	8.0		8.0	8.3	8.5	8.4	8.4	8.3	8.1	7.9	7.7															
JONES RD(0.1L)						FC5M																													
4361721	0.000	14.990	C	2018		0012	CRACKING	6.5	4.5*	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	9.8	9.8	7.5															
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	7.2	7.0	7.7	7.6	7.6	7.6	8.9	8.6	8.7	8.6	8.7	8.7	8.7	8.5															
30030000	23.492	23.640	C	1	1	35	CRACKING	8.5	8.5	6.0*	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	9.5	9.5															
349				2	12.1	6600	RIDE	8.2	8.3	7.9	7.1	7.0	6.9	7.1	6.9	6.7	6.4	6.2															
SHOPPING ENT(23.6R)						FC125M																													
2084472	23.492	23.593	L	2011		0012	CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	8.0	8.0	7.4	7.5	4.5*															
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE													4.2*	3.8*														
2084473	23.507	39.021	C	2031		0012																													
30030000	23.640	39.021	C	1	1	60	CRACKING	8.5	8.5	6.0*	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0															
349				2	12.1	2815	RIDE	8.2	8.3	7.9	7.1	7.0	6.9	7.1	6.9	6.7	6.4*	6.2*	8.3	8.3															
JOHN O GREEN RD(23.7L)						FC125M																													
2084472	29.037	39.021	C	2011		0012	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.5	7.5	6.0*	7.0	6.5	6.2*	3.5*															
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE	8.0	7.9	7.9	7.8	7.8	7.8	7.5	7.5	7.4	7.4	7.3	7.3	7.2	6.8															
2084473	23.507	39.021	C	2031		0012																													
30050000	0.000	1.518	C	1	7	60	CRACKING	8.5	8.0	8.0	7.0	7.0	7.0	6.5	5.5*	5.5*	5.5*		10.0	10.0															
51				2	8.7	600	RIDE	8.0	8.0	7.8	6.9	7.4	7.4	7.3	6.7	7.1	7.0		7.8	7.7															
						FC125M																													
2100853	0.000	1.518	C	2025		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.9	10.0	9.0															
ANDERSON COLUMBIA CO., INC(2026)							RIDE	7.6	7.3	6.8	6.7	6.5	6.6	6.4*	6.4*	6.1*	6.1*	6.2*	6.2*	8.3	7.9															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).