FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = HAMILTON

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW LN / %T / SURFTYPE / RW FY-P / RW FY-F	SYS TYP SPD / AADT / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
32010000 25 41 BOAT RAMP(0.1L) (2014) 2098315	0.000 2 12.9 8.7 0.000	16.601 2000 8.5 16.600	C 1 1 60 FC125M 8.3 C 2029 0012	CRACKING RIDE CRACKING RIDE	10.0 9.1 10.0 8.7	10.0 9.0 10.0 8.5	10.0 8.9 10.0 8.3	10.0 8.7 10.0 8.3	10.0 8.7 10.0 8.2	10.0 8.7 9.0 8.2	9.5 8.7 9.0 8.0	8.5 8.6 8.0 8.1	8.5 8.5 7.0 8.0	8.5 8.5 7.0 8.0	8.5 8.5 7.0 7.9	8.5 8.4 4.6* 8.0	8.5 8.3 4.1* 7.8	8.5 1.5* 7.4												
32010000 25 41 SE 50 DR(16.7R) 4286951 ANDERSON COLUMBIA CO., INC(2016)	16.601 2 12.9 16.625 8.4	18.292 5600 24.681 C 2014	C 1 1 55 FC125M 0012 SPRIDE	CRACKING RIDE CRACKING	10.0 9.0 9.0	10.0 8.8	10.0 8.7	10.0 8.5 10.0 8.3	10.0 8.6 10.0 8.3	10.0 8.6 10.0 8.2	10.0 8.6 10.0 8.1	10.0 8.6 10.0 8.1	10.0 8.6 10.0 8.0	10.0 8.5 10.0 8.0	10.0 8.5 8.5 8.0	10.0 8.4 7.5 8.0	10.0 8.4 4.7* 8.0	9.0 8.3 4.0* 8.0	1.5* 7.6												
32010000 25 41 SE 11TH ST(18.3L) 4286951 ANDERSON COLUMBIA CO., INC(2016)	18.292 2 12.9 16.625 8.2	18.900 5500 24.681 C 2014	C 1 1 35 FC125M 0012 SPRIDE	CRACKING RIDE CRACKING	10.0 8.3 6.0*	10.0 8.0 6.0*	10.0 8.0 10.0 8.0	10.0 7.5 10.0 7.9	9.0 7.5 10.0 7.8	9.0 7.6 10.0 7.8	9.0 7.5 10.0 7.7	8.5 7.4 10.0 7.7	8.5 7.5 8.5 7.6	8.5 7.3 7.5 7.7	7.5 7.3 7.5 7.6	7.0 7.0 5.6* 7.5	7.0 7.2 6.0* 7.9	3.5* 7.5												
32010000 6 41 1ST AVE NE(18.9R) 4286951 ANDERSON COLUMBIA CO., INC(2016)	18.900 2 12.9 16.625 8.2	20.130 7200 24.681 C 2014	C 1 1 35 FC125M 0012 SPRIDE	CRACKING RIDE CRACKING	10.0 8.2 6.0*	10.0 8.0 6.0*	10.0 8.0 10.0 8.0	10.0 7.5 10.0 7.9	9.0 7.5 10.0 7.8	9.0 7.6 10.0 7.8	9.0 7.5 10.0 7.7	8.5 7.4 10.0 7.7	8.5 7.5 8.5 7.6	8.5 7.3 7.5 7.7	7.5 7.3 7.5 7.6	7.0 7.0 5.6* 7.5	7.2 6.0* 7.2	3.5* 6.8												
32010000 6 41 NW 104 PL(20.1R) 4286951 ANDERSON COLUMBIA CO., INC(2016)	20.130 2 12.9 16.625 8.0	25.096 3800 24.681 C 2014	C 1 1 60 FC125M 0012 SPRIDE	CRACKING RIDE CRACKING	10.0 8.6 7.0	10.0 8.4	10.0 8.5 10.0 8.2	10.0 8.2 10.0 8.2	10.0 8.2 10.0 8.0	10.0 8.2 10.0 7.9	9.0 8.3 8.5 7.8	9.0 8.3 8.5 7.8	9.0 8.2 7.5 7.8	8.0 8.2 7.0 7.6	8.0 8.2 4.7* 7.6	7.0 8.1 3.8* 7.6	8.0 1.5* 7.2												
32010000 25 41 NW 34 TRL(25.5R) 2098183 ANDERSON COLUMBIA CO., INC(2008)	25.096 2 12.9 24.949 8.5	30.741 1700 30.741 8.4	C 1 1 60 FC125 C 2006 8.2	CRACKING RIDE CRACKING RIDE	7.5 8.3 10.0 8.5	3.0* 8.0 10.0 8.4	3.0* 8.0 10.0 8.2	3.0* 6.4* 10.0 8.2	2.0* 7.0 10.0 8.2	2.0* 7.1 10.0 8.1	10.0 8.1	10.0 8.6 8.5 8.1	10.0 8.6 8.5 8.1	10.0 8.5 7.5 8.1	10.0 8.5 7.5 8.1	10.0 8.5 6.0* 8.1	10.0 8.4 5.2* 8.0	2.0* 7.6												
32010000 25 41 BEN BATES ST(30.8C) 2098183 ANDERSON COLUMBIA CO., INC(2007)	30.741 4 12.9 30.741 8.1	31.246 1700 31.176 8.1	C 1 1 35 FC125 C 2006 8.0	CRACKING RIDE CRACKING RIDE	7.0 6.6 10.0 8.1	7.0 5.9 10.0 8.1	7.0 5.8 10.0 8.0	7.0 6.5 10.0 8.1	5.5* 5.3* 8.5 7.9	4.0* 5.8 8.5 8.1	10.0 8.8 8.5 8.0	10.0 8.6 8.5 7.9	10.0 8.7 8.5 8.1	10.0 8.3 8.5 7.8	10.0 8.4 8.5 7.7	10.0 8.3 7.5 7.9	10.0 8.3 5.1* 7.8	6.0* 7.4	2.5*											
32010000 25 41 SUWANNEE ST(31.3R) 2098183 ANDERSON COLUMBIA CO., INC(2007)	31.246 2 12.9 31.176 8.2	32.782 1700 32.782 8.1	C 1 1 55 FC125 C 2006 8.0	CRACKING RIDE CRACKING RIDE	7.0 7.9 10.0 8.2	6.0* 7.6 10.0 8.1	6.0* 7.6 10.0 8.0	4.0* 6.9 10.0 8.1	3.0* 6.9 8.5 8.0	2.0* 7.1 8.5 7.9	10.0 8.6 8.5 7.9	10.0 8.6 8.5 7.9	10.0 8.6 8.5 7.7	10.0 8.5 7.5 7.7	10.0 8.4 6.0* 7.7	10.0 8.3 3.8* 7.7	10.0 8.2 3.3* 7.7	0.0* 7.2											
32020000 136 RIVER ST(0.0R) (1999)	0.000 2 12.1 9.5	0.107 2600 9.5	C 1 1 35 FC125 9.5	CRACKING RIDE CRACKING RIDE	10.0 9.5	10.0 9.5	10.0 9.5	10.0 9.5	10.0 9.5	9.5 9.5	9.5 9.5	9.5 7.0	9.5 7.0	9.5 5.5*	9.5 4.0*	9.5 2.7*	9.5 2.4* 5.9	0.0* 5.5											
32030000 51 129 SW 79 TER(0.3L) 4470771 ANDERSON COLUMBIA CO., INC(2025)	0.000 2 3.9 0.926 7.8	3.325 6400 2.681 C 2024	C 1 1 60 FC125M 0012 SPRIDE	CRACKING RIDE CRACKING	3.0* 7.5 9.5	10.0 8.5 9.5	10.0 8.4 8.0	10.0 8.0 7.0	10.0 8.1 7.0	10.0 8.2 7.0	10.0 8.3 6.0*	10.0 8.3 5.5*	9.5 8.0 5.5*	9.5 7.9 5.5*	9.5 7.9 5.5*	9.5 7.9 10.0	9.5 7.8 10.0	9.0											
32030000 51 129 FROM 100101(3.7L) 2098312 ANDERSON COLUMBIA CO., INC(2026)	3.325 2 12.3 3.320 8.2	3.979 4800 4.095 8.0	C 1 7 45 FC125M L 2025 0012 SPRIDE	CRACKING RIDE CRACKING	10.0 8.1 10.0	10.0 8.2 10.0	10.0 8.0 10.0	10.0 6.8 10.0	9.5 7.8 10.0	9.5 7.7 10.0	10.0 7.5 10.0	9.5 7.7 10.0	9.5 8.0 9.0	9.5 7.9 7.0	9.5 7.9 6.0*	9.5 7.9 3.8*	10.0 8.3 10.0	9.0											

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = HAMILTON ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE / FY-P / FY-F	DISTRESS / RATINGS / WKMX-P / ASTYPE / WKMX-F	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
32030000	3.979	6.120	C	1	7	50					CRACKING	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5													
51 129			2	12.3		4800					RIDE	7.3	8.5	8.5	8.1	8.0	8.3	8.3	8.3	8.0	7.9	7.9	7.9	7.4													
SW 55TH DR(5.3L)										FC125M																											
2098312	4.095	5.060	C	2025		0012					CRACKING	9.5	9.5	9.5	9.5	9.5	8.0	7.0	6.0*	6.0*	6.0*	6.0*	5.2*	10.0	9.0												
ANDERSON COLUMBIA CO., INC			(2026)							SPRIDE	RIDE	7.8	7.8	7.6	7.6	7.5	7.5	7.4	7.5	7.3	7.3	7.3	7.3	8.9	8.5												
32030000	6.120	6.398	C	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5													
51 129			2	12.3		4800					RIDE	8.3	8.0	7.7	7.3	7.3	7.9	8.1	8.0	8.0	7.9	7.9	7.9	7.4													
NB EXIT TO SR 25(6.3R)										FC125M																											
											CRACKING	9.5	9.5	9.5	9.5	9.5	8.0	7.0	6.0*	6.0*	6.0*	6.0*	5.2*	5.5*	0.5*												
				(1996)							RIDE	7.8	7.8	7.6	7.6	7.5	7.5	7.4	7.5	7.3	7.3	7.3	7.3	6.9	6.5												
32040000	0.065	7.591	C	1	1	60					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	7.5	6.0*	6.0*	6.0*	6.0*													
100 129			2	30.1		2200					RIDE	8.8	8.8	8.7	8.3	8.3	8.2	8.2	8.0	7.9	7.6	7.8	7.7	7.6													
SHADY OAK DR(0.1R)										FC125M																											
4269671	0.222	7.591	C	2012		0012					CRACKING	10.0	10.0	10.0	10.0	8.5	8.0	7.0	7.0	6.5	6.0*	5.5*	3.9*	3.4*	1.0*												
ANDERSON COLUMBIA CO., INC			(2014)							SPRIDE	RIDE	8.5	8.1	8.1	8.0	8.0	7.8	7.7	7.8	7.6	7.6	7.4	7.3	7.1	6.7												
2098313	0.065	7.591	C	2028		0012																															
32050000	0.000	11.969	C	1	1	60					CRACKING	10.0	9.5	9.5	9.5	8.5	8.5	8.0	8.0	7.0	7.0	7.0	7.0	7.0													
6			2	27.8		1604					RIDE	8.8	8.6	8.5	7.8	7.9	7.9	8.1	7.8	7.8	7.7	7.7	7.5	7.3													
NW 49 TRL(0.8L)										FC125A																											
4311291	0.000	12.011	C	2015		0012					CRACKING	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5	7.0	6.0*	5.5*	5.4*	4.7*	2.5*												
THE SCRUGGS COMPANY			(2016)							SPRIDE	RIDE	7.1	6.7	8.6	8.6	8.6	8.4	8.3	8.3	8.2	7.9	7.8	7.7	7.4	7.0												
4246316	0.000	13.452	C	2029		0012																															
32050000	11.969	12.273	R	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	8.5		9.5													
6			1	18.8		2300					RIDE	8.0	7.8	7.8	7.5	7.4	7.4	7.4	7.4	7.4	7.3	7.3		7.4													
						FC3																															
											CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	8.0	7.0	4.1*	3.6*	1.0*												
				(2013)							RIDE	7.5	7.4	6.6	6.5	6.6	6.3	6.2	6.3	6.2	6.4	6.0	6.0	6.2	5.8												
4246316	0.000	13.452	C	2029		0012																															
32050000	12.273	13.452	C	1	1	55					CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.0	7.0	7.0	7.0	6.0*	6.0*													
6			2	18.8		2300					RIDE	8.3	8.3	7.9	7.7	7.9	7.9	8.1	7.8	7.8	7.8	7.5	7.1	7.1													
SW 78 PL(12.8R)										FC125A																											
4311291	12.233	13.430	C	2015		0012					CRACKING	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	6.0*	5.1*	4.3*	2.0*												
THE SCRUGGS COMPANY			(2016)							SPRIDE	RIDE	7.0	6.7	8.6	8.6	8.6	8.2	8.1	8.1	8.0	7.7	7.6	7.5	7.2	6.8												
4246316	0.000	13.452	C	2029		0012																															
32050000	11.969	12.273	L	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5		9.5													
6			1	18.8		2300					RIDE	8.1	7.8	7.8	7.4	7.5	7.5	7.6	7.6	7.6	7.5	7.4		7.4													
						DGFC																															
											CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	8.0	7.0	6.0*	5.3*	2.5*												
				(2013)							RIDE	7.4	7.3	7.0	6.9	6.8	6.7	6.7	6.6	6.6	6.6	6.3	6.1	6.0	5.6												
4246316	0.000	13.452	C	2029		0012																															
32070000	10.100	10.607	C	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.0*	6.0*	6.0*													
143			2	6.8		1750					RIDE	8.6	8.4	8.1	7.8	7.8	7.9	7.9	7.9	7.7	7.7	7.6	7.4	7.4													
						DGFC																															
											CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	6.7	7.0	4.5*												
				(2014)							RIDE	8.3	8.3	8.0	8.0	7.9	7.9	7.9	7.9	7.8	7.7	7.8	7.8	7.7	7.3												
32070000	10.607	11.669	C	1	1	55					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.0*	6.0*	6.0*													
143			2	6.8		1750					RIDE	8.6	8.4	8.1	7.8	7.8	7.9	7.9	7.9	7.7	7.7	7.6	7.4	7.4													
BERRY ST(11.2L)										FC125M																											
4322621	10.607	11.659	C	2016		0012					CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	7.9	7.3	5.0*												
PREFERRED MATERIALS, INC.			(2017)							SPRIDE	RIDE	7.1	7.1	7.1	8.2	8.1	8.0	8.0	8.0	7.8	7.8	7.7	7.7	7.7	7.3												
32100000	0.000	9.506	R	4	1	70					CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	7.0	7.0	10.0													
93 I75	442.0	451.5	3	31.3		38500					RIDE	9.1	9.1	9.0	8.5	8.5	8.6	8.5	8.5	8.4	8.3	8.2	8.2	8.2													
						FC5M																															
4246312	0.000	9.506	C	2012		0012					CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	7.3	7.3	4.5*												
ANDERSON COLUMBIA CO., INC			(2013)							SPRIDE	RIDE	8.3	8.3	8.6	8.6	8.6	8.8	8.9	8.9	8.9	8.8	8.7	8.7	8.7	8.6												
4234323	0.000	9.506	C	2029		0012																															
32100000	9.506	19.175	R	4	1	70					CRACKING	10.0	10.0	10.0	10.0	9.0	8.0	8.0	8.0	8.0	8.0	7.0		10.0													
93 I75	451.5	461.2	3	31.3		37500					RIDE	9.2	9.1	9.0	8.5	8.4	8.5	8.4	8.2	8.1	7.9	7.8		8.2													
						FC5M																															
4234321	9.506	19.175	C	2011		0012					CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	7.5	7.5	7.0	6.5	4.0*												
ANDERSON COLUMBIA CO., INC			(2013)							SPRIDE	RIDE	8.2	8.2	8.6	8.5	8.5	8.6	8.7	8.8	8.7	8.7	8.6	8.6	8.5	8.4												
4234322	9.506	19.175	C	2029		0012																															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = HAMILTON

RDWYID / SR / US / G_BMP / G_EMP / LN / %T / AADT / RATINGS / INTERSECT AT (MP|SIDE) / SURFTYPE / ITMSEG-P / W_BMP / W_EMP / RW / FY-P / WKMX-P / CONTRACTOR (AGE_ONE YEAR) / ASTYPE / ITMSEG-F / W_BMP / W_EMP / RW / FY-F / WKMX-F	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
32100000	19.175	28.746	R	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	6.5	6.5	6.5	6.5	4.5*													
93 I75	461.2	470.7	3	30.9	47243		RIDE	8.8	8.9	8.7	8.2	8.2	8.2	8.0	7.8	7.6	7.4	7.3	7.1	6.8													
						FC5M																											
4246311	19.175	28.746	C	2012	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	8.0	6.6	6.5	4.0*												
PREFERRED MATERIALS, INC. (2014)							SPRIDE	8.6	8.6	8.9	8.9	8.9	9.1	9.1	9.1	9.1	9.1	9.0	9.0	8.9	8.8												
4246313	19.175	25.061@	C	2027	0012																												
32100000	19.175	28.746	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	9.5	9.0	8.0	8.0	7.5	6.5	4.5*	4.5*	4.5*													
93 I75	461.2	470.7	3	30.9	47243		RIDE	8.9	8.8	8.7	8.1	8.1	8.0	7.9	7.8	7.5	7.2	6.8	6.5	6.3*													
						FC5M																											
4246311	19.175	28.746	C	2012	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.0	7.0	7.0	7.3	6.5	4.0*												
PREFERRED MATERIALS, INC. (2014)							SPRIDE	8.5	8.5	8.8	8.8	8.7	8.9	9.0	9.0	9.0	8.9	8.9	8.8	8.7	8.6												
4246313	19.175	25.061@	C	2027	0012																												
32100000	9.506	19.175	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	9.0	8.0	8.0	7.5	7.5	7.5	6.5		10.0													
93 I75	451.5	461.2	3	31.3	37500		RIDE	8.9	8.6	8.7	8.1	8.3	8.2	8.2	8.1	7.9	7.6	7.4		8.1													
						FC5M																											
4234321	9.506	19.175	C	2011	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	7.5	7.5	6.5	6.5	4.0*												
ANDERSON COLUMBIA CO., INC(2013)							SPRIDE	8.1	8.1	8.5	8.4	8.4	8.5	8.5	8.6	8.6	8.5	8.5	8.4	8.4	8.3												
4234322	9.506	19.175	C	2029	0012																												
32100000	0.000	9.506	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	8.0	10.0													
93 I75	442.0	451.5	3	31.3	38500		RIDE	9.1	9.0	9.1	7.7	8.5	8.6	8.6	8.5	8.4	8.4	8.2	8.2	7.8													
						FC5M																											
4246312	0.000	9.506	C	2012	0012		CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	6.5	6.5	4.0*												
ANDERSON COLUMBIA CO., INC(2013)							SPRIDE	8.0	7.9	8.4	8.5	8.4	8.6	8.7	8.7	8.7	8.6	8.6	8.5	8.4	8.3												
4234323	0.000	9.506	C	2029	0012																												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).