FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE	RW	FY-P	FY-F	WKMX-P	WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
36001000	0.000	8.656	R	1	1	65									CRACKING	7.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
25 301				2	18.6	29000									RIDE	8.9	8.6	8.6	8.0	7.7	8.0	8.2	8.2	8.2	8.2	8.1	8.0	7.9														
CR 25A(0.0C)									FC5HP																															
4411361	0.000	8.656	C	2021		0012			CRACKING	10.0	9.0	7.0	6.0*	6.0*	6.0*	6.0*	4.5*	4.5*		10.0	10.0	9.7	8.5															
ANDERSON COLUMBIA CO., INC(2024)									SPRIDE						RIDE	7.8	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0		8.5	8.5	8.5	8.3												
36001000	8.656	14.221	R	1	1	65									CRACKING	0.0*	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0														
25 441				2	21.3	7700									RIDE	8.6	8.6	8.5	8.0	8.0	7.8	7.9	7.8	7.8	7.7	7.7	7.5	7.5														
NW140 ST(9.7R)									FC5M																															
4272801	8.911	13.788	C	2016		0012			CRACKING	7.0	7.0	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.4	9.7	7.5															
ANDERSON COLUMBIA CO., INC(2018)									SPRIDE						RIDE	7.3	7.2	7.7		8.6	8.6	8.5	8.4	8.3	8.2	8.3	8.2	8.2	8.0												
36001000	8.656	14.221	L	1	1	65									CRACKING	0.0*	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5														
25 441				2	21.3	7700									RIDE	8.5	8.5	8.5	8.0	8.0	7.9	7.9	7.8	7.8	7.7	7.7	7.5	7.5														
NW 142 PL(10.0L)									FC5M																															
4272801	8.911	13.788	C	2016		0012			CRACKING	6.5	6.0*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.3	10.0	8.0															
ANDERSON COLUMBIA CO., INC(2018)									SPRIDE						RIDE	7.4	7.2	7.8		8.6	8.5	8.5	8.4	8.2	8.3	8.3	8.2	8.2	8.0												
36001000	0.000	8.656	L	1	1	65									CRACKING	6.5	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
25 301				2	18.6	29000									RIDE	8.8	8.6	8.5	7.7	7.3	8.3	8.4	8.3	8.4	8.4	7.7	8.0	8.2														
CR 25A(0.0C)									FC5HP																															
4411361	0.000	8.656	C	2021		0012			CRACKING	10.0	10.0	8.5	7.0	7.0	6.5	6.5	3.5*	3.5*		10.0	10.0	9.8	8.5															
ANDERSON COLUMBIA CO., INC(2024)									SPRIDE						RIDE	8.1	8.0	8.2	8.1	8.1	8.2	8.2	8.1	8.1		8.4	8.4	8.4	8.2												
36002000	0.000	4.727	R	1	1	60									CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	6.5	6.5	7.5	6.5	6.5														
200 301				2	25.0	17400									RIDE	8.9	8.9	8.7	8.3	8.2	8.1	7.9	8.0	7.9	7.9	8.0	7.8	7.7														
SR 25(0.0C)									FC5M																															
4272491	0.000	4.774	C	2013		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.7	7.4	4.5*															
				(2014)											RIDE	8.0	8.0	8.4	8.4	8.4	8.5	8.5	8.5	8.4	8.5	8.5	8.5	8.5	8.3												
36002000	0.000	4.727	L	1	1	60									CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	7.5	6.5	6.5														
200 301				2	25.0	17400									RIDE	8.7	8.7	8.6	8.2	8.1	8.1	8.0	7.9	7.8	7.8	7.6	7.5	7.4														
US-441/SR-25(0.0L)									FC5M																															
4272491	0.000	4.774	C	2013		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.9	7.2	4.5*															
				(2014)											RIDE	8.2	8.3	8.5	8.5	8.5	8.6	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.3												
36004000	0.000	0.633	R	1	1	45									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5														
464				2	15.1	32000									RIDE	8.3	8.5	7.7	7.3	7.1	7.2	6.8	7.3	7.8	8.0	7.7	7.7	7.1														
COLLEGE RD SW(0.0C)									FC3																															
2386731	0.000	1.228	C	1993		0012			CRACKING	8.5	8.5	8.5	8.5	8.5	8.0	7.0	7.0	7.0	7.0	7.0	6.8	6.6	3.0*															
CRAGGS CONSTRUCTION COMPAN(1994)									S						RIDE	6.9	7.1	7.0	7.0	7.1	6.9	7.1	7.1	7.8	7.2	7.2	7.1	7.0	6.7												
4526341	0.017	1.210	C	2029		0226																																		
36004000	0.633	1.332	R	1	1	40									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	10.0	10.0	10.0	10.0														
464				2	15.1	32000									RIDE	8.3	8.5	7.7	7.3	7.1	7.2	6.8	7.3	7.8	6.9	6.9	6.9	6.7														
SW 12 AVE(0.7C)									FC95																															
															CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	8.0	8.0	6.0*												
				(2010)											RIDE	6.9	7.0	6.9	6.8	6.4	6.5	6.4	6.4	6.8	7.0	6.7	6.7	6.3	6.0												
4526341	0.017	1.210	C	2029		0226																																		
36004000	1.332	7.213	R	1	8	50									CRACKING	8.0	8.0	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	9.0	9.0	8.5														
464				2	3.8	34532									RIDE	8.5	8.4	8.0	7.6	7.3	7.0	7.0		8.0	8.0	8.0	7.9	7.8														
FIRST AVE SW(1.4C)									FC5																															
4155231	1.242	7.213	C	2007		0012			CRACKING	8.5	8.5	8.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	3.7*																		
ANDERSON COLUMBIA CO., INC(2009)									SPRIDE						RIDE	7.8	7.7	7.8	7.7	7.6	7.6	7.7	7.7	7.6	7.6	7.1	7.0														
4411411	1.335	7.213	C	2023		0012																																		
36004000	1.332	7.213	L	1	8	50									CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	8.5														
464				2	3.8	34532									RIDE	8.6	8.4	8.3	7.8	7.6	7.2	7.1		8.0	7.9	7.6	7.5	7.5														
FIRST AVE SW(1.4C)									FC5																															
4155231	1.242	7.213	C	2007		0012			CRACKING	8.5	8.5	8.5	7.0	7.0	7.0	4.5*	4.5*	4.5*	4.5*	3.5*																		
ANDERSON COLUMBIA CO., INC(2009)									SPRIDE						RIDE	7.4	7.4	7.7	7.6	7.6	7.4	7.5	7.5	7.1	6.9	6.5															
4411411	1.335	7.213	C	2023		0012																																		
36004000	0.633	1.332	L	1	1	40									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
464				2	15.1	32000									RIDE	7.6	7.8	7.9	7.5	7.2	7.5	7.2	7.2	7.3	7.0	7.0	7.2	7.0														
SW 12 AVE(0.7C)									FC95																															
2386731	0.000	1.228	C	1993		0012			CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	7.0	7.0	8.0	8.0	8.4	5.0*															
CRAGGS CONSTRUCTION COMPAN(1994)									S						RIDE	6.9	6.8	6.8	6.7	6.4	6.1	6.5	6.4	6.9	6.8	6.5	6.4	6.2	5.9												
4526341	0.017	1.210	C	2029		0226																																		

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE	WKMX-P	WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
36004000	0.000	0.633	L	1	1	45	1						CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5													
464							2	15.1	32000				RIDE	7.6	7.8	7.9	7.5	7.2	7.5	7.2	7.2	7.3	7.5	7.3	7.2	7.4													
COLLEGE RD SW(0.0C)										FC3																													
2386731	0.000	1.228	C	1993		0012							CRACKING	8.5	8.5	8.5	8.5	8.5	8.0	7.0	7.0	7.0	7.0	7.0	6.1*	7.0	3.5*												
CRAGGS CONSTRUCTION COMPAN(1994)						S							RIDE	7.1	7.4	7.5	7.9	8.0	8.0	7.5	7.7	8.0	7.8	7.5	7.6	7.5	7.2												
4526341	0.017	1.210	C	2029		0226																																
36004001	0.000	0.216	C	1	1								CRACKING													5.5*													
464							2	3.8	300				RIDE													4.8*													
36004002	0.000	0.237	C	1	1								CRACKING													9.0	8.0												
464							2	3.8	600				RIDE													5.2*	4.9*												
36004003	0.000	0.309	C	1	1								CRACKING													8.0													
464							2	3.8	450				RIDE													5.2*													
36008000	0.000	3.737	R	1	1	45							CRACKING	6.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	9.0	9.0	8.5	8.5	8.5	8.5												
492							2	23.3	17000				RIDE	7.5	7.4	6.8	6.0*	5.5*	7.6	7.4	7.8	7.7	7.3	7.5	7.4	7.3												
PINE AVE N(0.0C)										FC125M																													
4306551	0.000	3.719	C	2018		0012							CRACKING	8.5	8.5	8.5	8.5	8.5		10.0	10.0	10.0	10.0	10.0	8.7	8.5	7.0												
ANDERSON COLUMBIA CO., INC(2020)													RIDE	7.5	7.3	7.2	7.1	6.9		8.0	8.0	7.8	7.8	7.7	7.7	7.7	7.4												
36008000	0.000	3.737	L	1	1	45							CRACKING	6.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	8.5	7.0	7.0	7.0												
492							2	23.3	17000				RIDE	7.6	7.5	7.2	6.2*	5.7*	7.8	7.8	7.9	7.8	7.5	7.6	7.1	7.1												
PINE AVE N(0.0C)										FC125M																													
4306551	0.000	3.719	C	2018		0012							CRACKING	7.0	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	8.5	8.1	7.6	6.0*												
ANDERSON COLUMBIA CO., INC(2020)													RIDE	7.0	7.0	6.6	6.7	6.6		7.9	7.9	7.7	7.6	7.7	7.6	7.6	7.3												
36009000	0.000	1.486	C	1	1	55							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0	7.0	7.0	7.0	7.0	5.5*												
35							2	17.3	15000				RIDE	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.7	7.6	7.9	7.8	7.7	7.3												
CR-25/SE 110 ST(0.0R)										FC125M																													
4248851	0.000	1.570	C	2013		0012							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.3	7.8	6.0*												
D.A.B. CONSTRUCTORS, INC				(2014)		SP							RIDE	8.2	8.3	8.2	8.2	8.0	8.0	8.1	8.2	8.1	8.2	8.0	8.0	7.8	7.5												
36009000	1.486	5.269	R	1	1	55							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	6.5	6.5	6.5	6.5												
35							2	10.2	28500				RIDE	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.9	7.4	7.9	7.8	7.8	7.7												
SE 96 PL RD(1.5R)										FC125M																													
2386931	1.486	5.244	C	2015		0213							CRACKING	6.5	6.0*	6.0*				10.0	10.0	10.0	10.0	10.0	9.6	9.2	8.0												
				(2020)									RIDE	7.5	7.3	7.3				7.3	7.3	7.2	7.1	7.2	7.1	7.1	6.8												
36009000	5.269	10.843	R	1	1	45							CRACKING	8.5	8.5	7.0	6.0*	3.5*	3.5*	3.5*		4.5*	4.5*			10.0												
35							2	15.7	22000				RIDE	8.6	8.3	7.8	7.1	6.6	6.2	5.7		5.9	6.4			8.3												
CR-464(5.5R)										FC125R																													
2386771	5.123	10.827	C	2010		0213							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	8.5	7.5	5.5*	3.5*												
				(2013)									RIDE	8.2	8.4	8.2	8.2	8.1	8.0	8.0	8.1	8.0	7.8	7.8	7.6	7.7	7.4												
4542111	5.264	10.829	C	2029		0012																																
36009000	5.269	10.843	L	1	1	45							CRACKING	8.5	8.5	7.0	6.0*	3.5*	3.5*	3.5*		4.5*	4.5*			10.0												
35							2	15.7	22000				RIDE	8.6	8.3	7.8	7.1	6.6	6.2	5.7		5.9	6.4			8.2												
CR 464(5.5L)										FC125R																													
2386771	5.123	10.827	C	2010		0213							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	5.0*	3.0*												
				(2013)									RIDE	8.3	8.3	8.2	8.2	8.2	8.1	8.1	8.1	8.1	8.0	8.0	7.9	7.9	7.6												
4542111	5.264	10.829	C	2029		0012																																
36009000	1.486	5.269	L	1	1	55							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	6.5	6.5	6.5	6.5												
35							2	10.2	28500				RIDE	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.9	7.4	7.9	7.8	7.8	7.7												
SE 92 PL RD(1.8L)										FC125M																													
2386931	1.486	5.244	C	2015		0213							CRACKING	6.5	6.0*	6.0*				10.0	10.0	10.0	10.0	10.0	10.0	9.6	8.0												
				(2020)									RIDE	7.5	7.3	7.3				7.7	7.7	7.6	7.6	7.6	7.5	7.6	7.3												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / ASTYPE / FY-F	TYP SPD / AADT / WKMX-P / WKMX-F	DISTRESS / RATINGS / SURFTYPE	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2031 (PMRS)
36010000 25 27 BASELINE RD(14.3R) 4392381 WESTERN SURETY COMPANY	14.347 3.8 14.347 (2024)	14.711 13200 C 2020	R 1 2 C	1 35 FC125M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 7.3 9.5	10.0 7.5 8.5	10.0 7.2 7.0	8.5 7.0 7.0	8.5 7.1 7.0	8.5 6.9 6.5	8.5 6.1 6.5	6.5	10.0 7.3 6.5	9.5 6.9 6.5	9.5 6.9 10.0	9.5 6.9 10.0	9.5 6.1 9.0	
						RIDE	7.0	6.8	5.9	6.0	5.8	5.6	5.6	5.7	5.7	5.3*	7.1		6.0	5.7
36010000 25 27 OAK RD(14.8R) 4392381 WESTERN SURETY COMPANY	14.711 20.5 23.868 (2024)	23.895 30000 C 2020	R 1 2 C	1 55 FC5M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 8.6 9.0	10.0 8.6 8.0	8.5 8.4 8.0	8.5 8.2 6.5	8.5 8.2 6.5	8.5 8.0 6.5	10.0 8.1 6.5	10.0 8.1 4.5*	10.0 8.1 4.5*	10.0 8.1	10.0 8.1 10.0	10.0 8.1 10.0	9.5 7.9 8.5	
						RIDE	8.0	7.7	8.1	8.0	8.0	8.1	8.1	8.1	8.0		8.2	8.2	8.2	8.0
36010000 25 27 SE 22 PL(24.0R) 4392381 WESTERN SURETY COMPANY	23.895 3.8 23.868 (2024)	24.959 32000 C 2020	R 1 3 C	1 35 FC125M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 8.3 10.0	10.0 8.3 10.0	10.0 7.9 9.0	10.0 7.7 9.0	10.0 7.5 9.0	10.0 7.2 7.5	10.0 7.8 6.5	10.0 7.7 4.5*	10.0 7.8 4.5*	10.0 8.0 4.5*	10.0 7.7 10.0	10.0 7.6 10.0	10.0 7.4 9.0	
						RIDE	7.6	7.3	7.2	7.1	7.1	7.0	6.9	7.0	6.7	6.4	6.8	6.8	6.9	6.6
36010000 25 27 SE 1ST AVE(24.0L) 4392381 WESTERN SURETY COMPANY	23.895 3.8 23.868 (2024)	24.959 32000 C 2020	L 1 3 C	1 35 FC125M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 8.1 10.0	10.0 8.2 8.5	8.5 8.0 7.0	8.5 7.7 6.5	8.5 7.5 6.5	8.5 7.4 6.5	10.0 7.4 6.5	10.0 7.5 4.5*	10.0 7.4 3.5*	10.0 7.5 3.5*	10.0 7.5 10.0	10.0 7.3 10.0	10.0 7.3 9.0	
						RIDE	7.2	7.2	7.1	7.2	7.0	6.8	7.0	7.1	6.6	6.5	7.8	7.8	7.8	7.5
36010000 25 27 SE 57 AVE(14.9C) 4392381 WESTERN SURETY COMPANY	14.711 20.5 23.868 (2024)	23.895 30000 C 2020	L 1 2 C	1 55 FC5M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 8.6 9.0	10.0 8.6 7.0	8.5 8.3 6.5	8.5 8.2 6.5	8.5 8.1 6.5	8.5 7.9 5.5*	10.0 8.2 5.5*	10.0 8.2 3.5*	10.0 8.1 3.5*	10.0 8.1	10.0 8.2 10.0	10.0 8.1 10.0	9.5 8.1 8.5	
						RIDE	8.0	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.8		8.1	8.1	8.1	7.9
36010000 25 27 SE 62ND AVE(14.4L) 4392381 WESTERN SURETY COMPANY	14.347 3.8 14.347 (2024)	14.711 13200 C 2020	L 1 2 C	1 35 FC125M 0012 SPRIDE		CRACKING RIDE CRACKING	10.0 7.3 9.5	10.0 7.5 8.5	10.0 7.2 7.0	8.5 7.0 7.0	8.5 7.1 6.5	8.5 6.9 6.5	8.5 6.1 6.5	6.5	10.0 7.3 6.5	9.5 6.9 6.5	9.5 6.9 10.0	9.5 6.9 10.0	9.5 6.1 9.0	
						RIDE	7.0	6.8	5.9	6.0	5.8	5.6	5.6	5.7	5.7	5.3*	6.0		5.8	5.5
36030000 25 27 OCALA CITY LIMITS(0.0C) 4195851 THE MIDDLESEX CORPORATION (2010) 4526351	0.000 3.8 0.000 0.012	0.292 41500 2.699 0.296	R 1 3 C 2009 C 2027	1 35 FC95 0012 0226		CRACKING RIDE CRACKING RIDE	10.0 7.4 10.0 7.7	10.0 8.1 10.0 7.6	8.5 7.6 10.0 7.5	8.5 6.1 10.0 7.5	7.0 6.8 10.0 7.4	7.0 6.8 8.5 6.9	6.5 5.0* 7.0 7.1	6.5 6.8 7.0 7.1	6.5 6.6 7.0 7.0	10.0 7.9 6.0* 7.1	10.0 7.9 6.0* 6.4	10.0 7.8 3.6* 6.5	10.0 7.8 1.5* 6.2	
36030000 25 27 SW 3 ST(0.3C) 4195851 THE MIDDLESEX CORPORATION (2010) 4542141	0.292 3.8 0.000 0.692	0.652 41500 2.699 1.809	R 1 3 C 2009 C 2028	7 35 FC95 0012 0012		CRACKING RIDE CRACKING RIDE	10.0 7.4 10.0 8.5	10.0 8.1 10.0 8.4	8.5 7.6 10.0 8.3	8.5 6.1 10.0 8.2	7.0 6.8 10.0 8.2	7.0 6.8 8.5 7.9	6.5 5.0* 7.0 8.0	6.5 6.8 7.0 8.0	6.5 6.6 7.0 8.0	10.0 7.9 6.0* 7.9	10.0 7.9 6.0* 7.8	10.0 7.8 10.0 7.7	10.0 7.8 9.0 7.8	4.5* 7.5
36030000 25 27 NW 3 ST(0.7R) 4195851 THE MIDDLESEX CORPORATION (2010) 4542141	0.652 12.2 0.000 0.692	1.805 32500 2.699 1.809	R 1 2 C 2009 C 2028	1 45 FC95 0012 0012		CRACKING RIDE CRACKING RIDE	10.0 9.0 10.0 8.5	10.0 9.0 10.0 8.4	8.5 8.7 10.0 8.3	8.5 8.6 10.0 8.2	7.0 8.4 10.0 8.2	7.0 8.1 10.0 7.9	6.5 8.2 9.0 8.0	6.5 8.2 8.5 8.0	6.5 8.2 8.5 8.0	10.0 8.6 7.5 7.9	10.0 8.6 7.0 7.8	10.0 8.6 7.1 7.7	10.0 8.5 6.8 7.8	4.5* 7.5
36030000 25 301 CR 200A(1.9R) 4542141	1.805 22.7 2.606 0.692	2.606 19500 1.809	R 1 2 C 2028	1 45 FC125M 0012		CRACKING RIDE CRACKING RIDE	10.0 9.0 10.0 8.5	10.0 9.0 10.0 8.4	8.5 8.7 10.0 8.3	8.5 8.6 10.0 8.2	7.0 8.4 10.0 8.2	7.0 8.1 10.0 7.9	6.5 8.2 9.0 8.0	6.5 8.2 8.5 8.0	6.5 8.2 8.5 8.0	10.0 8.6 7.5 7.9	10.0 8.6 10.0 8.2	10.0 8.6 10.0 8.1	10.0 8.5 9.0 8.2	7.9
36030000 25 441 NW 177 PL(16.8R) 4171621 ANDERSON COLUMBIA CO., INC(2009) 4486351	16.463 11.6 16.399 16.399	19.635 8800 22.764 19.572	R 1 2 C 2007 C 2025	1 60 FC5 0012 0012		CRACKING RIDE CRACKING RIDE	10.0 8.8 10.0 7.9	9.0 8.7 10.0 7.8	6.5 8.5 9.0 8.2	6.5 7.8 9.0 8.3	3.5* 7.5 9.0 8.2	3.5* 7.3 7.5 8.3	3.5* 7.1 7.5 8.3	3.5* 6.9 4.5* 8.2	10.0 8.1 4.5* 8.2	10.0 8.0 4.5* 8.1	10.0 8.0 4.5* 8.0	10.0 8.0 3.3* 7.9	10.0 7.9 2.4* 7.6	0.0* 7.4

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / US / W_BMP	EMP / G_BMP / G_EMP / W_EMP	RW / LN / SURFTYPE / RW	SYS / %T / FY-P / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD / ASTYPE	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36030000	19.635	20.075	R	1	1 40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	10.0	10.0	10.0	10.0	10.0															
25 441			4	19.6	8200	RIDE	8.3	8.3	7.8	7.6	7.5	7.2	7.4	7.4	7.9	7.7	7.8	7.8	7.7															
AVE H(19.7C)					FC125																														
4171621	16.399	22.764	C	2007	0012	CRACKING	10.0	8.5	8.5	7.5	7.5	7.5	7.5	6.5	6.0*	6.0*	6.0*	5.5*	6.3*	4.0*														
ANDERSON COLUMBIA CO., INC(2009)						SPRIDE	7.7	7.6	7.6	7.6	7.6	7.5	7.5	7.5	7.4	7.4	7.2	7.4	7.1	6.8												
4452181	19.572	22.718	C	2025	0012																														
36030000	20.075	22.831	R	1	1 65	CRACKING	10.0	10.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
25 441			2	19.6	8200	RIDE	8.7	8.6	8.4	7.4	7.0	6.7	6.8	6.4*	8.2	8.2	8.1	8.0	7.7															
AVE C(20.1C)					FC5																														
4171621	16.399	22.764	C	2007	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	6.5	4.5*	4.5*	4.5*	4.3*	3.9*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)						SPRIDE	7.4	7.7	8.1	8.1	8.2	8.2	8.3	8.3	8.1	8.2	8.2	8.0	7.8	7.6												
4452181	19.572	22.718	C	2025	0012																														
36030000	20.075	22.831	L	1	1 65	CRACKING	9.0	10.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
25 441			2	19.6	8200	RIDE	8.6	8.2	8.2	7.3	7.2	7.0	6.7	6.4*	8.0	7.9	7.9	7.9	7.8															
AVE C(20.1C)					FC5																														
4171621	16.399	22.764	C	2007	0012	CRACKING	10.0	9.5	9.5	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.6*	3.1*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)						SPRIDE	7.8	7.7	8.2	8.2	8.1	8.1	8.2	8.2	8.1	8.1	8.1	8.0	7.8	7.6												
4452181	19.572	22.718	C	2025	0012																														
36030000	19.635	20.075	L	1	1 40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	10.0	10.0	10.0	10.0	10.0															
25 441			2	19.6	8200	RIDE	8.3	8.3	7.8	7.6	7.5	7.2	7.4	7.4	7.9	7.7	7.8	7.8	7.7															
AVE H(19.7C)					FC125																														
4171621	16.399	22.764	C	2007	0012	CRACKING	10.0	8.5	8.5	7.5	7.5	7.5	7.5	6.5	6.0*	6.0*	6.0*	5.5*	5.3*	3.0*												
ANDERSON COLUMBIA CO., INC(2009)						SPRIDE	7.7	7.6	7.6	7.6	7.6	7.5	7.5	7.5	7.4	7.4	7.2	7.4	6.7	6.4												
4452181	19.572	22.718	C	2025	0012																														
36030000	16.463	19.635	L	1	1 60	CRACKING	9.0	6.5	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
25 441			2	11.6	8800	RIDE	8.6	8.6	8.2	7.9	7.4	6.9	6.9	6.5	8.2	8.2	8.1	8.2	8.1															
NW 177 LN(16.8L)					FC5																														
4171621	16.399	22.764	C	2007	0012	CRACKING	10.0	8.5	8.5	8.5	8.5	7.0	7.0	4.5*	4.5*	4.5*	4.5*	4.4*	4.0*	0.5*												
ANDERSON COLUMBIA CO., INC(2009)						SPRIDE	8.0	8.0	8.3	8.3	8.2	8.4	8.3	8.3	8.2	8.2	8.1	8.0	7.7	7.5												
4486351	16.399	19.572	C	2025	0012																														
36030000	1.805	2.606	L	1	1 45	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.0*	10.0	10.0	10.0	10.0															
25 301			2	22.7	19500	RIDE	8.5	8.8	8.7	8.4	8.3	8.0	8.0	7.9	7.6	8.6	8.6	8.6	8.5															
NW 22 ST(2.1C)					FC125M																														
						CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	10.0	10.0	10.0	9.0												
				(2024)		RIDE	8.5	8.5	8.3	8.2	8.2	7.9	8.1	8.1	8.1	8.0	8.4	8.2	8.3	8.0												
36030000	0.652	1.805	L	1	1 45	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.0*	10.0	10.0	10.0	10.0															
25 27			2	12.2	32500	RIDE	8.5	8.8	8.7	8.4	8.3	8.0	8.0	7.9	7.6	8.6	8.6	8.6	8.5															
EIGHTH ST NW(1.0C)					FC95																														
4195851	0.000	2.699	C	2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.5	7.0	5.0*												
THE MIDDLESEX CORPORATION (2010)						RIDE	8.5	8.5	8.3	8.2	8.2	7.9	8.1	8.1	8.1	8.0	7.9	7.7	8.0	7.7												
4542141	0.692	1.809	C	2028	0012																														
36030000	0.292	0.652	L	1	7 35	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	7.0	10.0	10.0	10.0	10.0															
25 27			2	13.4	41500	RIDE	8.5	8.3	8.1	7.8	7.8	7.6	7.1	7.0	6.7	7.8	7.8	7.6	7.6															
SW 3 ST(0.3C)					FC95																														
						CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.0	8.0	7.0	7.0		10.0	9.0												
				(2026)		RIDE	7.5	7.5	7.3	7.3	7.2	7.3	7.3	7.4	7.2	7.3	7.1		7.5	7.2												
36030000	0.000	0.292	L	1	1 35	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	7.0	10.0	10.0	10.0	10.0															
25 27			3	13.4	41500	RIDE	8.5	8.3	8.1	7.8	7.8	7.6	7.1	7.0	6.7	7.8	7.8	7.6	7.6															
OCALA CITY LIMITS(0.0C)					FC95																														
4195851	0.000	2.699	C	2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.0	8.0	7.0	7.0		5.0*	3.0*												
THE MIDDLESEX CORPORATION (2010)						RIDE	7.5	7.5	7.3	7.3	7.2	7.3	7.3	7.4	7.2	7.3	7.1		7.3	7.0												
4526351	0.012	0.296	C	2027	0226																														
36040000	14.143	14.310	R	1	1 55	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
200 301			2	16.2	14800	RIDE	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6	7.7															
FROM CR-200A(14.2R)					FC5																														
4155111	14.161	16.652	C	2006	0012	CRACKING	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	8.3	8.3	4.5*												
ANDERSON COLUMBIA CO., INC(2007)						SPRIDE	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.3	8.3	8.1												
36040000	14.310	15.026	R	1	1 45	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
200 301			2	16.2	14800	RIDE	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6	7.7															
NE 175 ST(14.5C)					FC5																														
4452121	14.290	15.007	R	2023	0012	CRACKING	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0												
				(2025)		RIDE	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.2	8.3	8.1												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / SURFTYPE / FY-P / ASTYPE / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36040000	15.026	15.632	R	1	1	45	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6	7.7														
NE 180 ST(15.0C)					FC125M																													
4452121	15.007	15.605	R	2023	0012		CRACKING	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0														
				(2025)			RIDE	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	7.6	7.6	7.3													
36040000	15.632	16.652	R	1	1	55	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6	7.7														
NE 189 LN(16.0R)					FC5M																													
4452121	15.605	16.652	R	2023	0012		CRACKING	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0														
				(2025)			RIDE	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.5	8.5	8.3													
36040000	15.589	16.652	L	1	1	55	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7	7.7														
NE 189 LN(16.0L)					FC5M																													
4452121	15.605	16.652	L	2023	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	9.0														
				(2025)			RIDE	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.5	8.5	8.3													
36040000	14.957	15.589	L	1	1	45	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7	7.7														
NE 180 ST(15.0C)					FC125M																													
4452121	15.007	15.605	L	2023	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	9.0														
				(2025)			RIDE	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	7.9	7.9	7.6													
36040000	14.300	14.957	L	1	1	45	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7	7.7														
NE 175 ST(14.5C)					FC5																													
4452121	14.290	15.007	L	2023	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	9.0														
V. E. WHITEHURST & SONS, I				(2025)			SPRIDE	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.6	8.6	8.4													
36040000	14.143	14.300	L	1	1	55	CRACKING	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
200 301			2	16.2	14800		RIDE	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7	7.7														
FROM CR 200A(14.2L)					FC5																													
							CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	9.0	8.5	7.5													
				(2025)			RIDE	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.2	8.2	8.0													
36050000	0.000	1.500	R	1	1	55	CRACKING	8.5	8.5	7.0	6.5	4.5*		3.5*	3.5*	3.5*			10.0	10.0														
35 301			2	3.8	30500		RIDE	8.5	8.1	8.3	7.9	7.9		7.7	7.8	7.5			8.4	7.7														
					FC5																													
4112563	0.000	1.404	C	2010	0213		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.5	7.8	4.5*														
D.A.B. CONSTRUCTORS, INC				(2012)			SPRIDE	8.3	8.4	8.3	8.3	8.3	8.0	8.0	8.0	8.0	8.0	8.0	7.9	8.0	7.8													
4526941	0.000	1.540	C	2029	0226																													
36050000	1.500	1.900	R	1	7	55	CRACKING	8.5	8.5	7.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0														
35 301			2	20.3	16200		RIDE	8.5	8.1	8.3	7.9	7.9		7.5	7.6	7.5	7.6	7.6	7.4	6.9														
CR 42(1.5C)					FC125M																													
4453021	1.540	1.904	R	2024	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.5	10.0	9.0														
C. W. ROBERTS CONTRACTING,				(2026)			SPRIDE	7.3	7.4	7.3	7.1	7.2	8.0	8.0	8.0	8.0	8.0	8.0	7.9	8.2	7.9													
36050000	1.900	3.235	C	1	7	55	CRACKING	8.5	8.5	7.0	6.5	4.5*	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0														
35 301			2	20.3	16200		RIDE	8.5	8.1	8.3	7.9	7.9	7.1	7.5	7.5		8.4	8.4	8.3	7.8														
SE 151 ST(2.9L)					FC125M																													
4453021	1.904	2.526	C	2024	0012		CRACKING	10.0	9.5	8.5	8.5	8.5	7.0	6.5	6.5	6.5	6.5	6.5	5.9*	10.0	9.0														
C. W. ROBERTS CONTRACTING,				(2026)			SPRIDE	8.2	8.0	7.9	7.6	7.4	7.1	7.2	7.1	6.9	7.5	7.3	7.1	8.3	8.0													
36050000	3.235	3.744	R	1	7	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0														
35 301			2	20.3	16200		RIDE	8.7	8.8	8.5	8.4	8.2	7.8	7.9	8.0		8.4	8.4	8.3	7.8														
SE 147 ST(3.4C)					FC125M																													
4453021	3.278	3.747	R	2024	0012		CRACKING	10.0	9.5	8.5	8.5	8.5	7.0	6.5	6.5	6.5	6.5	6.5	5.9*	10.0	9.0														
C. W. ROBERTS CONTRACTING,				(2026)			SPRIDE	8.2	8.0	7.9	7.6	7.4	7.1	7.2	7.1	6.9	7.5	7.3	7.1	7.3	7.0													
36050000	3.744	6.866	R	1	1	55	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	7.0	7.0		10.0	10.0	10.0	10.0														
35 301			2	20.3	16200		RIDE	8.9	8.7	8.5	8.3	8.3	8.1	8.2	8.2		8.4	8.4	8.3	7.9														
SE 139 ST(4.2R)					FC5																													
4195571	1.904	6.866	C	2008	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.9	6.5	3.0*														
C. W. ROBERTS CONTRACTING,				(2010)			SPRIDE	8.3	8.4	8.5	8.4	8.4	8.5	8.5	8.5	8.5	8.5	8.4	8.5	8.4	8.2													
4542151	3.747	6.866	C	2029	0012																													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE / FY-P / ASTYPE / FY-F	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36050000	3.744	6.866	L	1	1	55				CRACKING	8.5	8.5	7.0	7.0	6.5	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0													
35 301			2	20.3	16200				WKMX-P	RIDE	8.6	8.5	8.2	8.0	7.9	7.8	7.8	7.7		8.5	8.5	8.4	8.1													
SE 142 PL(3.9L)									FC125																												
4195571	1.904	6.866	C	2008			0012			CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.7	5.9*	3.5*												
C. W. ROBERTS CONTRACTING,(2010)									SPRIDE	RIDE	8.4	8.4	8.5	8.5	8.4	8.5	8.5	8.5	8.5	8.4	8.4	8.4	8.3	8.0												
4542151	3.747	6.866	C	2029			0012																														
36050000	3.235	3.744	L	1	7	40				CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	9.5		10.0	10.0	10.0	10.0													
35 301			2	20.3	16200				WKMX-P	RIDE	8.7	8.8	8.5	8.4	8.2	7.8	7.9	7.6		8.4	8.4	8.3	7.8													
SE 147 ST(3.4C)									FC125																												
4453021	3.278	3.747	L	2024			0012			CRACKING	10.0	9.5	8.5	8.5	8.5	7.0	6.5	6.5	6.5	6.5	6.5	5.9*	10.0	9.0												
C. W. ROBERTS CONTRACTING,(2026)									SPRIDE	RIDE	8.2	8.0	7.9	7.6	7.4	7.1	7.2	7.1	6.9	7.5	7.3	7.1	7.0	6.7												
36050000	1.500	1.900	L	1	7	55				CRACKING	8.5	8.5	7.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0													
35 301			2	20.3	16200				WKMX-P	RIDE	8.5	8.1	8.3	7.9	7.9		7.7	7.8	7.7	7.9	7.9	7.6	6.9													
CR 42(1.5C)									FC5																												
4453021	1.540	1.904	L	2024			0012			CRACKING	10.0	9.5	9.0	9.0	9.0	9.0	9.0	6.5	6.5	6.5	6.5	6.5	10.0	9.0												
C. W. ROBERTS CONTRACTING,(2026)									SPRIDE	RIDE	7.5	7.6	7.3	7.0	7.2	7.9	7.8	7.9	7.8	7.9	7.9	7.8	8.3	8.1												
36050000	0.000	1.500	L	1	1	55				CRACKING	8.5	8.5	7.0	6.5	4.5*		3.5*	3.5*	3.5*			10.0	10.0													
35 301			2	3.8	30500				WKMX-P	RIDE	8.5	8.1	8.3	7.9	7.9		7.7	7.8	7.5			8.3	7.9													
SE 177 PL(0.3L)									FC5																												
4112563	0.000	1.404	C	2010			0213			CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	6.5	6.5	6.5	6.5	6.5	8.2	5.0*												
D.A.B. CONSTRUCTORS, INC (2012)									SPRIDE	RIDE	8.3	8.2	8.2	8.2	8.2	7.9	7.8	7.9	7.8	7.9	7.9	7.8	7.9	7.7												
4526941	0.000	1.540	C	2029			0226																														
36060000	0.000	0.619	R	1	1	35				CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.0	9.0	9.0	8.5													
45 41			2	25.1	22500				WKMX-P	RIDE	8.2	7.7	8.0	7.5	7.6	7.4	7.1	7.5	7.4	7.4	7.2	7.3	7.1													
CR-484/PENN AVE(0.3R)									FC3																												
2386571	0.000	0.735	C	1998			0012			CRACKING	8.5	8.5	8.5	8.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	6.0*	3.0*												
D.A.B. CONSTRUCTORS, INC (2000)									S	RIDE	7.1	7.0	7.5	7.6	7.5	7.4	7.3	7.4	7.4	7.4	7.4	7.3	7.3	7.0												
4485261	0.100	1.410	R	2025			0012																														
36060000	0.619	1.532	R	1	1	35				CRACKING	7.5	7.5	7.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
45 41			2	8.5	23500				WKMX-P	RIDE	8.0	7.8	8.1		7.7	7.5	7.6	7.8	7.8	7.7	7.8	7.8	7.7													
E MCKINNEY AVE(0.6R)									FC125																												
2387401	0.619	1.662	C	2003			0213			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.5	7.1	4.5*												
D.A.B. CONSTRUCTORS, INC (2005)									SPRIDE	RIDE	7.5	7.5	7.3	7.3	7.3	7.1	7.0	7.1	6.9	7.0	6.8	6.9	5.9	5.6												
4485261	0.100	1.410	R	2025			0012																														
36060000	1.532	4.939	C	1	1	55				CRACKING	7.5	7.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	7.0	6.5	10.0	10.0													
45 41			2	8.5	23500				WKMX-P	RIDE	8.0	7.8	8.1	8.0	7.9	7.8	7.8	7.7	7.7	7.8	7.7	8.0	7.8													
SW 108 PL(1.6R)									FC125R																												
4195841	1.621	4.939	C	2011			0012			CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	7.0	7.0	7.0	7.0	4.3*	3.5*	1.5*												
V. E. WHITEHURST & SONS, I(2012)									RIDE	RIDE	7.6	7.5	7.3	7.3	7.3	7.2	7.1	7.1	7.1	7.1	6.9	6.9	6.9	6.6												
2386481	1.438	5.556	C	2030			0213																														
36060000	4.939	11.928	C	1	1	60				CRACKING	9.0	9.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0													
45 41			2	13.4	5900				WKMX-P	RIDE	8.6	8.6	8.5	8.3	8.2	8.1	8.1	8.2	8.7	8.6	8.5	8.4	8.5													
SW 61 ST(5.8R)									FC95																												
4171791	4.939	11.928	C	2008			0012			CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	7.6	7.1	5.0*												
STEVEN COUNTS, INC. (2009)									RIDE	RIDE	8.4	8.4	8.3	8.2	8.3	8.2	8.1	8.1	8.1	8.2	8.0	8.0	8.0	7.7												
36060000	0.619	1.532	L	1	1	35				CRACKING	7.5	7.5	7.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
45 41			2	8.5	23500				WKMX-P	RIDE	8.0	7.8	8.1		7.5	6.9	7.4	7.8	7.7	7.8	7.9	7.7	7.7													
MAGNOLIA AVE(0.6L)									FC125																												
2387401	0.619	1.662	C	2003			0213			CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0	7.0	7.0	7.4	7.0	4.5*												
D.A.B. CONSTRUCTORS, INC (2005)									SPRIDE	RIDE	7.7	7.7	7.3	7.3	7.4	7.1	7.3	7.3	7.2	7.1	7.1	7.3	7.2	6.9												
4485261	0.175	1.431	L	2025			0012																														
36060000	0.000	0.619	L	1	1	35				CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5													
45 41			2	25.1	22500				WKMX-P	RIDE	8.2	8.8	8.6	8.2	8.1	8.2	8.1	7.9	8.0	8.1	7.6	7.6	7.7													
RIVER DR(0.1L)									FC3																												
2386571	0.000	0.735	C	1998			0012			CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	7.0	7.3	7.1	4.0*												
D.A.B. CONSTRUCTORS, INC (2000)									S	RIDE	8.1	8.2	7.8	7.8	7.8	7.7	7.7	7.7	7.7	7.7	7.7	7.6	7.6	7.3												
4485261	0.175	1.431	L	2025			0012																														
36070000	0.000	6.672	R	1	1	65				CRACKING	4.5*	3.5*			10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.0	9.0													
500 27			2	19.9	10700				WKMX-P	RIDE	8.3	8.1			8.3	8.2	8.2	8.0	8.2	8.3	8.2	8.1	8.1													
NW 160 AVE(1.7C)									FC5M																												
4373391	0.000	6.672	C	2019			0012			CRACKING	7.0	7.0	6.0*	6.0*	6.0*	4.5*		10.0	10.0	10.0	10.0	8.9	8.1	6.5													
V. E. WHITEHURST & SONS, I(2021)									RIDE	RIDE	8.0	7.9	8.0	8.0	7.9	7.9		8.8	8.6	8.5	8.4	8.3	8.4	8.2												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / SURFTYPE / FY-P / FY-F	AADT / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36070000	6.672	14.305	R	1	1	65			CRACKING				10.0	10.0	10.0	10.0	10.0	8.5	7.0	6.5	6.5	6.5														
500 27				2	19.9		10700		RIDE				8.2	8.2	8.1	8.1	8.1	7.9	7.8	7.7	7.4	7.2														
CR 326(6.8C)							FC5M																												
4290531	6.683	14.305	C	2015			0012		CRACKING	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.3	8.3	5.5*													
ANDERSON COLUMBIA CO., INC(2016)									RIDE	7.1	6.8	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.5	8.4	8.4	8.4	8.2													
36070000	14.305	17.912	R	1	1	55			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.5	7.5														
500 27				2	25.2		21000		RIDE	8.6	8.7	8.5	8.1	8.1	8.0	8.1	7.9	8.0	8.0	7.9	7.8	7.8														
CR 225A(14.5C)							FC5M																												
4290831	14.305	17.912	C	2015			0012		CRACKING	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.9	8.2	6.0*													
ANDERSON COLUMBIA CO., INC(2017)									RIDE	7.7	7.6		8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.3	8.4	8.2													
36070000	17.912	20.700	R	1	1	45			CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	7.0	7.0	7.0	7.0														
500 27				2	17.1		22000		RIDE	8.7	8.7	8.5	8.3	8.2	8.1	8.1	8.4	8.1	8.1	8.0	7.8	7.8														
NW 35 AVE RD(18.2C)							FC125M																												
4290831	17.912	20.700	C	2015			0012		CRACKING	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	7.5	6.0*													
ANDERSON COLUMBIA CO., INC(2017)									RIDE	7.6	7.6		8.0	8.0	7.8	7.8	7.9	7.8	7.8	7.8	7.8	7.8	7.5													
36070000	17.912	20.700	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	7.0	7.0														
500 27				2	17.1		22000		RIDE	8.4	8.5	8.3	7.9	8.0	7.8	7.9	8.3	7.7	7.9	7.8	7.8	7.6														
FROM NW 35 AVE RD(18.1L)							FC125M																												
4290831	17.912	20.700	C	2015			0012		CRACKING	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.0	7.9	7.5	6.0*													
ANDERSON COLUMBIA CO., INC(2017)									RIDE	7.5	7.5		8.0	7.9	7.6	7.8	7.9	7.8	7.8	7.8	7.8	7.8	7.5													
36070000	14.305	17.912	L	1	1	55			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0														
500 27				2	25.2		21000		RIDE	8.8	8.7	8.6	8.3	8.2	8.2	8.2	8.3	8.1	8.1	8.0	7.9	7.8														
CR 225A(14.5C)							FC5M																												
4290831	14.305	17.912	C	2015			0012		CRACKING	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.3	8.3	6.0*													
ANDERSON COLUMBIA CO., INC(2017)									RIDE	7.3	7.5		8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.3	8.1													
36070000	6.672	14.305	L	1	1	65			CRACKING				10.0	10.0	10.0	10.0	9.0	9.0	8.5	7.5	7.5	7.5														
500 27				2	19.9		10700		RIDE				8.3	8.2	8.1	8.2	8.1	8.1	8.1	8.0	7.8	7.8														
NW 131 CT(6.7L)							FC5M																												
4290531	6.683	14.305	C	2015			0012		CRACKING	6.5	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.9	8.3	5.5*													
ANDERSON COLUMBIA CO., INC(2016)									RIDE	7.3	7.4	8.3	8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.2	8.2	8.2	8.0													
36070000	0.000	6.672	L	1	1	65			CRACKING	4.5*	3.5*			10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5	8.0														
500 27				2	19.9		10700		RIDE	8.3	8.1			8.3	8.2	8.2	8.2	8.1	8.1	8.1	8.0	8.0														
COUNTY ROAD 316(0.1L)							FC5M																												
4373391	0.000	6.672	C	2019			0012		CRACKING	7.0	6.5	6.0*	6.0*	6.0*	5.0*		10.0	10.0	10.0	10.0	9.0	9.0	7.0													
V. E. WHITEHURST & SONS, I(2021)									RIDE	7.8	7.5	7.9	7.9	7.7	7.8		8.9	8.7	8.6	8.4	8.4	8.5	8.3													
36080000	0.000	6.494	R	1	1	45			CRACKING	7.0	6.5	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0														
40				2	6.8		21825		RIDE	7.3	7.2	6.9	6.2*	5.9*		7.7	7.7	7.8	7.8	7.7	7.7	7.7														
OCALA CITY LIMITS(0.0C)							FC125																												
4135701	0.000	6.499	C	2005			0012		CRACKING	10.0	10.0	8.5	8.5	8.5	8.0	8.0	7.0	7.0	7.0	7.0	6.9	6.6	4.0*													
STEVEN COUNTS, INC.		(2007)					SPRIDE		RIDE	7.7	7.7	7.4	7.4	7.4	7.4	7.4	7.4	7.3	7.4	7.3	7.3	7.4	7.1													
4509511	2.356	6.494@	C	2026			0226																												
36080000	6.494	9.640	C	1	1	55			CRACKING	10.0	9.0	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	9.0	9.0	9.0														
40				2	11.3		18700		RIDE	8.6	8.5	8.3	7.6	7.6	7.3	7.2	6.8	6.2*	8.5	8.4	8.3	8.2														
SR 326(7.2L)							FC95																												
4171601	6.494	9.617	C	2007			0012		CRACKING	9.0	9.0	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.5	7.5	7.0	6.8	4.5*													
ANDERSON COLUMBIA CO., INC(2010)							SPRIDE		RIDE	8.2	8.2	7.9	7.9	7.8	7.7	7.7	7.7	7.7	7.8	7.7	7.7	7.7	7.4													
4106742	6.146	11.473	C	2030			0213																												
36080000	10.157	12.615	C	1	1	55			CRACKING	9.0	9.0	6.5		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0														
40				2	6.7		14000		RIDE	8.0	8.2	7.9		8.2	8.2	8.2	8.4	8.4	8.4	8.4	8.3	8.3														
COLBY WOODS CAMPGROUNDS(10.4L)							FC125																												
4116601	10.157	14.112	C	2003			0012		CRACKING	9.0	9.0	8.5	8.5	8.5	7.5	7.5	7.0	6.0*	6.0*	6.0*	5.7*	5.4*	2.5*													
ANDERSON COLUMBIA CO., INC(2005)							SPRIDE		RIDE	8.3	8.2	8.1	8.1	8.1	8.0	8.0	8.0	8.0	7.9	7.9	7.9	7.9	7.6													
4509481	10.148	20.643	C	2026			0012																												
36080000	12.615	13.360	C	1	1	55			CRACKING	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
40				3	6.7		14000		RIDE	7.3	7.6	6.3*		8.3	8.1	8.2	8.3	8.2	8.4	8.3	8.1	8.2														
NE 130 TER(13.3R)							FC4																												
4116601	10.157	14.112	C	2003			0012		CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	7.0	7.0	7.0	6.6	7.0	4.5*													
ANDERSON COLUMBIA CO., INC(2005)							SPRIDE		RIDE	8.2	8.1	8.0	8.0	8.0	7.8	7.8	7.9	7.8	7.9	7.8	7.7	7.7	7.4													
4509481	10.148	20.643	C	2026			0012																												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / ASTYPE / FY-F	TYP SPD / AADT / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36080000	13.360	14.260	C	1	1 50	CRACKING	4.5*	4.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
40			2	6.7	14000	RIDE	7.8	7.5	6.4*		8.3	8.2	8.3	8.3	8.2	8.3	8.2	8.2	8.1															
NE 134 TER(13.7R)						FC125																													
4116601	10.157	14.112	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.0	6.0*	6.0*	6.0*	6.1*	3.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.1	8.2	7.9	7.8	7.8	7.7	7.7	7.8	7.7	7.7	7.7	7.6	7.6	7.3															
4509481	10.148	20.643	C	2026	0012																														
36080000	14.260	15.470	C	1	1 50	CRACKING	10.0	10.0	10.0		10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.5	7.5																
40			2	6.7	14000	RIDE	8.3	8.5	8.6		8.3	8.2	8.3	8.1	8.3	8.4	8.4	8.3	8.2															
NE 14 ST RD(14.5L)						FC125M																													
4344081	14.260	15.120	C	2018	0012	CRACKING	7.5	7.5	7.5	7.0	7.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.3	6.0*															
D.A.B. CONSTRUCTORS, INC	(2019)					RIDE	8.2	8.2	8.1	8.2	8.1	8.0	8.0	8.0	7.9	8.0	8.0	8.0	7.9	7.6															
4509481	10.148	20.643	C	2026	0012																														
36080000	15.470	16.220	C	1	1 55	CRACKING	4.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5																
40			3	6.7	14000	RIDE	7.8	7.9	6.9		8.3	8.3	8.4	8.5	8.4	8.4	8.4	8.3	8.3															
						FC125																													
4116611	14.923	23.528	C	2003	0012	CRACKING	9.0	9.0	9.0	8.0	8.0	8.0	7.5	7.0	6.0*	6.0*	6.0*	5.8*	5.5*	3.0*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.3	8.3	8.0	8.0	8.0	7.9	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.6															
4509481	10.148	20.643	C	2026	0012																														
36080000	16.220	17.440	C	1	1 45	CRACKING	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			2	6.8	8200	RIDE	7.5	7.7	6.9		8.1	8.1	8.1	8.2	8.3	8.3	8.2	8.0	8.2															
CR 314A(16.6C)						FC125																													
4116611	14.923	23.528	C	2003	0012	CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	5.7*	5.4*	2.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.2	8.2	7.6	7.9	7.8	7.6	7.7	7.8	7.7	7.7	7.5	7.5	7.3	7.0															
4509481	10.148	20.643	C	2026	0012																														
36080000	17.440	21.237	C	1	1 55	CRACKING	7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0																
40			2	7.1	5600	RIDE	9.0	9.0	8.5		8.3	8.2	8.3	8.2	8.4	8.4	8.3	8.2	8.3															
SE 167 CT RD(17.7L)						FC4																													
4116611	14.923	23.528	C	2003	0012	CRACKING	9.0	9.0	9.0	9.0	9.0	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	5.6*	3.0*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.2	8.2	8.0	8.0	8.0	7.9	7.9	7.9	7.8	7.8	7.8	7.7	7.7	7.4															
4509481	10.148	20.643	C	2026	0012																														
36080000	21.237	22.297	C	1	1 55	CRACKING	6.0*	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			3	7.1	5600	RIDE	8.5	8.2	7.5		8.4	8.3	8.3	8.4	8.4	8.4	8.5	8.4	8.3															
						FC4																													
4116611	14.923	23.528	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	6.0*	6.0*	4.9*	4.4*	1.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.2	8.2	8.1	8.1	8.0	7.8	7.9	7.9	7.8	7.9	7.8	7.8	7.7	7.4															
4509482	20.643	32.206	C	2028	0226																														
36080000	22.297	22.563	C	1	1 55	CRACKING	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			2	7.1	5600	RIDE	9.1	9.0	9.0		8.3	8.3	8.3	8.4	8.4	8.4	8.4	7.8	8.3															
						FC4																													
4116611	14.923	23.528	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.0*	6.0*	6.0*	6.4*	3.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.3	8.2	8.1	8.1	8.2	8.1	8.0	8.0	7.9	8.0	7.9	7.9	7.5	7.2															
4509482	20.643	32.206	C	2028	0226																														
36080000	22.563	23.528	C	1	1 55	CRACKING	7.0	6.0*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			3	7.1	5600	RIDE	7.7	6.8	5.7*		8.5	8.4	8.5	8.5	8.5	8.6	8.6	8.5	8.3															
FOREST ROAD #97(23.4C)						FC4																													
4116611	14.923	23.528	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	6.0*	6.0*	6.0*	6.1*	3.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.4	8.3	8.2	8.2	8.3	8.2	8.2	8.3	8.2	8.2	8.2	8.1	8.2	7.9															
4509482	20.643	32.206	C	2028	0226																														
36080000	23.528	26.540	C	1	1 55	CRACKING	7.0	7.0	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			2	7.1	5600	RIDE	8.4	7.9	7.0		8.4	8.4	8.5	8.5	8.5	8.5	8.5	8.5	8.4															
FOREST ROAD #11(24.2L)						FC4																													
4116621	23.528	32.206	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	7.0	6.0*	6.0*	6.0*	5.9*	3.0*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.4	8.4	8.2	8.2	8.2	8.1	8.1	8.2	8.1	8.1	8.0	8.0	7.9	7.6															
4509482	20.643	32.206	C	2028	0226																														
36080000	26.540	27.540	C	1	1 55	CRACKING	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			3	7.1	5600	RIDE	8.9	8.6	7.9		8.5	8.5	8.5	8.6	8.6	8.6	8.6	8.5	8.5															
FOREST RD #33(26.7L)						FC4																													
4116621	23.528	32.206	C	2003	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	6.0*	6.0*	5.8*	5.3*	2.5*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.4	8.4	8.3	8.3	8.3	8.1	8.1	8.2	8.0	8.1	8.0	8.0	7.9	7.6															
4509482	20.643	32.206	C	2028	0226																														
36080000	27.540	28.623	C	1	1 55	CRACKING	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
40			2	7.1	5600	RIDE	8.6	7.9	7.8		8.4	8.4	8.4	8.5	8.5	8.5	8.4	8.3	8.4															
JUNIPER SPRINGS(27.6L)						FC4																													
4116621	23.528	32.206	C	2003	0012	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.0	6.0*	6.0*	6.0*	4.8*	4.5*	2.0*															
ANDERSON COLUMBIA CO., INC(2005)						SPRIDE	8.3	8.3	8.2	8.2	8.1	8.0	8.0	8.1	7.9	7.8	7.8	7.7	7.7	7.4															
4509482	20.643	32.206	C	2028	0226																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36080000	28.623	29.627	C	1	1	55	1	3	5600	FC4	CRACKING	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
40								7.1			RIDE	7.9	7.6	6.4*		8.5	8.3	8.4	8.4	8.4	8.4	8.4	8.3	8.1													
4116621	23.528	32.206	C	2003		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0	6.0*	6.0*	6.0*	4.7*	4.3*	1.5*												
ANDERSON COLUMBIA CO., INC				(2005)							SPRIDE	8.2	8.0	7.9	8.1	8.0	7.7	7.9	7.9	7.8	7.8	7.7	7.7	7.6	7.3												
4509482	20.643	32.206	C	2028		0226																															
36080000	29.627	32.206	C	1	1	55					CRACKING	6.5	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
40							2	7.1	5600	RIDE	8.4	8.0	7.7		8.3	8.3	8.3	8.2	8.2	8.2	8.2	8.1	8.0													
SR 19(32.1C)										FC4																											
4116621	23.528	32.206	C	2003		0012					CRACKING	10.0	9.0	9.0	8.5	8.5	8.0	8.0	6.5	6.0*	6.0*	6.0*	5.3*	4.9*	2.0*												
ANDERSON COLUMBIA CO., INC				(2005)							SPRIDE	8.0	7.9	7.7	7.7	7.6	7.6	7.6	7.6	7.4	7.5	7.4	7.4	7.4	7.1												
4509482	20.643	32.206	C	2028		0226																															
36080000	0.000	6.494	L	1	1	45					CRACKING	6.5	4.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	8.5													
40							2	6.8	21825	RIDE	7.8	7.5	7.2	6.7	6.6		7.8	8.1	8.1	8.0	7.9	7.9	7.9													
OCALA CITY LIMITS(0.0C)										FC125																											
4135701	0.000	6.499	C	2005		0012					CRACKING	8.5	8.5	8.5	8.5	8.5	8.0	8.0	7.0	7.0	7.0	7.0	6.8	6.5	4.0*												
STEVEN COUNTS, INC.				(2007)							SPRIDE	7.9	7.9	7.7	7.6	7.5	7.3	7.5	7.6	7.5	7.4	7.5	7.4	7.4	7.1												
4509511	2.356	6.494@	C	2026		0226																															
36090000	0.000	3.057	C	1	1	55					CRACKING	3.5*			10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0													
19							2	15.5	2050	RIDE	8.1			8.6	8.2	8.3	8.2	8.3	8.2	8.0	7.9	7.8	7.5	7.4													
SR 40(0.2C)										FC125																											
2387701	0.000	15.808	C	2001		0012					CRACKING	9.0	9.0	9.0	9.0	9.0	8.5	8.5	8.5	8.5	8.5	8.5	8.3	8.1	5.5*												
THE MIDDLESEX CORPORATION				(2003)							SPRIDE	7.3	7.2	7.4	7.4	7.3	7.1	7.3	7.3	7.2	7.2	7.2	7.2	7.2	6.9												
36090000	3.868	15.780	C	1	1	55					CRACKING	3.5*			10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0													
19							2	22.7	2200	RIDE	8.1			8.6	8.2	8.3	8.2	8.3	8.2	8.0	7.9	7.8	7.6	7.5													
THE YEARLING TR(6.1L)										FC125																											
2387701	0.000	15.808	C	2001		0012					CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	8.5	8.4	5.5*												
THE MIDDLESEX CORPORATION				(2003)							SPRIDE	7.4	7.3	7.4	7.4	7.4	7.3	7.3	7.4	7.3	7.2	7.3	7.3	7.2	6.9												
36090000	15.780	17.448	C	1	1	55					CRACKING	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0													
19							2	9.4	4900	RIDE	8.1	7.6	7.7	7.3	7.1	6.9	6.9	7.1	8.4	8.3	8.3	8.2	8.2													
NE 133 PL(15.8L)										FC125M																											
4195831	15.780	17.448	C	2009		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.7	7.3	5.0*												
P & S PAVING, INC.				(2009)							RIDE	8.2	8.1	7.6	7.6	7.6	7.4	7.5	7.5	7.4	7.4	7.4	7.4	7.4	7.1												
36090100	0.000	0.811	C	1	1	55					CRACKING											10.0	10.0	10.0													
19							2	15.5	2050	RIDE											8.1	8.2	8.0													
3331 FT S/BR 360067(0.0C)										FC125																											
											CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.3	6.8	4.5*												
				(2011)							RIDE	7.8	7.6	7.4	7.5	7.4	7.1	7.0	7.1	7.0	6.9	6.9	6.7	6.9	6.6												
36100000	0.000	3.113	C	1	1	55					CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.0	6.5	6.5													
200							2	10.7	18100	RIDE	8.9	8.9	8.7	8.2	8.1	8.0	8.0	8.1	7.6	7.7	7.4	7.1													
SW 137 CT(0.2R)										FC125M																											
4286871	0.000	5.815	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.0	7.0	7.0	7.0	5.0*												
C. W. ROBERTS CONTRACTING,				(2014)							RIDE	8.8	8.7	8.6	8.6	8.6	8.5	8.5	8.6	8.5	8.5	8.5	8.5	8.5	8.2												
36100000	3.113	3.672	R	1	1	55					CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	6.5	7.5	7.0	6.5	6.5													
200							2	10.7	18100	RIDE	8.9	8.9	8.7	8.2	8.1	8.0	8.0	7.2	7.6	7.7	7.4	7.1													
SW 136 PL(3.2R)										FC125M																											
4286871	0.000	5.815	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.0	7.0	7.0	7.3	5.5*												
C. W. ROBERTS CONTRACTING,				(2014)							RIDE	8.8	8.7	8.6	8.6	8.6	8.5	8.5	8.6	8.5	8.5	8.5	8.5	8.1	7.8												
36100000	3.672	5.795	C	1	1	55					CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.0	6.5	6.5													
200							2	10.7	18100	RIDE	8.9	8.9	8.7	8.2	8.1	8.0	8.0	7.7	7.6	7.7	7.4	7.1													
ROSS PRAIRIE TR(4.4R)										FC125M																											
4286871	0.000	5.815	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.0	7.0	7.0	7.1	5.0*												
C. W. ROBERTS CONTRACTING,				(2014)							RIDE	8.8	8.7	8.6	8.6	8.6	8.5	8.5	8.6	8.5	8.5	8.5	8.5	8.6	8.3												
36100000	5.795	11.983	R	1	1	50					CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0													
200							3	12.6	38000	RIDE				8.7	8.3	8.4	8.2	8.2	8.3	8.2	8.1	7.6	7.9	7.8													
CR 484(6.0C)										FC5M																											
4368791	5.981	11.983	C	2019		0012					CRACKING	8.0	7.5	4.5*	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	9.6	9.4	7.5													
ANDERSON COLUMBIA CO., INC				(2021)							RIDE	7.5	7.4	7.8	7.7	7.6	7.6		8.7	8.6	8.7	8.6	8.6	8.6	8.4													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / G_BMP / G_EMP / LN / %T / AADT / RATINGS	BMP / EMP / RW / SYS / TYP / SPD	DISTRESS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE
INTERSECT AT (MP|SIDE) / SURFTYPE ========																
ITMSEG-P / W_BMP / W_EMP / RW / FY-P / WKMX-P																
CONTRACTOR (AGE_ONE YEAR) / ASTYPE			2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031
ITMSEG-F / W_BMP / W_EMP / RW / FY-F / WKMX-F																(PMRS)
36100000 11.983 14.635	R 1 1 50	CRACKING	10.0	10.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	
200	3 3.6 44005	RIDE	8.6	8.6	8.2		8.0	7.9	8.0	8.0	8.0	7.9	7.9	7.7	7.7	
SW 66 ST(12.2R)	FC5HP															
4373441 11.983 14.750	C 2018 0012	CRACKING	8.0	6.5	4.5*	4.5*	4.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	8.0
D.A.B. CONSTRUCTORS, INC	(2021)	RIDE	7.3	7.1	7.6	7.5	7.3	7.3		8.3	8.2	8.2	8.1	8.1	8.1	7.9
36100000 14.635 15.040	R 1 1 45	CRACKING	10.0	10.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	
200	3 3.6 44005	RIDE	8.6	8.6	8.2		8.0	7.9	8.0	8.0	8.0	7.9	7.9	7.7	7.7	
SW 38 CT(14.7C)	FC5HP															
		CRACKING	8.0	6.5	4.5*	4.5*	4.5*	3.5*			10.0	10.0	10.0	9.0	9.5	8.0
	(2022)	RIDE	7.3	7.1	7.6	7.5	7.3	7.3			7.3	7.4	7.3	7.4	7.3	7.1
36100000 15.040 17.870	R 1 8 45	CRACKING	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	9.5	8.0	
200	3 5.9 35500	RIDE	7.6	7.6	7.5	7.0	6.9	6.3	7.1	7.6	7.5	7.5	7.4	7.3	7.2	
SW 36 AVE(15.1R)	FC125															
4135831 15.074 18.427	C 2005 0012	CRACKING	8.0	7.5	7.0	7.0	7.0	6.5	6.5	6.5	6.0*	6.0*	6.0*	4.6*		
ANDERSON COLUMBIA CO., INC	(2007)	RIDE	7.2	7.1	7.1	7.0	7.0	6.9	6.9	6.9	6.8	6.8	6.6	6.7		
36100000 17.870 18.405	R 1 8 45	CRACKING	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	9.5	9.5	9.0	9.0	
200	2 15.6 28000	RIDE	7.6	7.6	7.5	7.0	6.9	6.3	7.1	6.6	7.8	7.8	7.8	7.4	7.5	
SW 7 RD(18.0R)	FC125															
4135831 15.074 18.427	C 2005 0012	CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	5.4*		
ANDERSON COLUMBIA CO., INC	(2007)	RIDE	7.4	7.2	7.6	7.5	7.5	6.5	7.3	7.4	7.3	7.2	7.0	6.8		
36100000 17.870 18.405	L 1 8 45	CRACKING	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
200	2 15.6 28000	RIDE	7.7	7.8	7.0	7.0	7.0	6.6	7.6	6.7	6.6	6.8	6.8	6.8	6.8	
SW 10 AVE(18.0L)	FC125															
4135831 15.074 18.427	C 2005 0012	CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	4.8*		
ANDERSON COLUMBIA CO., INC	(2007)	RIDE	6.7	6.6	6.8	7.4	7.0	6.8	7.1	6.7	6.6	6.9	6.5	6.3		
4392341 15.070 18.391	L 2024 0012															
36100000 15.060 17.870	L 1 8 45	CRACKING	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	9.0	9.0	8.5	7.5	
200	3 5.9 35500	RIDE	7.7	7.8	7.0	7.0	7.0	6.6	7.6	7.7	7.7	7.7	7.6	7.6	7.5	
SW 36 TER(15.1L)	FC125															
4135831 15.074 18.427	C 2005 0012	CRACKING	7.5	7.5	7.0	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	5.8*		
ANDERSON COLUMBIA CO., INC	(2007)	RIDE	7.5	7.4	7.2	7.1	7.2	6.9	6.9	6.9	6.9	7.0	6.9	6.8		
4392341 15.070 18.391	L 2024 0012															
36100000 14.635 15.060	L 1 1 45	CRACKING	10.0	10.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	8.0	
200	3 3.6 44005	RIDE	8.6	8.6	8.3		8.2	7.8	7.9	7.8	7.8	7.8	7.7	7.6	7.7	
SW 38 CT(14.7C)	FC5HP															
		CRACKING	7.5	4.5*	4.5*	3.5*	3.5*	3.5*			10.0	10.0	10.0	8.8	8.6	7.0
	(2022)	RIDE	7.5	7.3	7.6	7.6	7.2	7.3			7.1	7.1	7.1	7.2	6.8	6.6
36100000 11.983 14.635	L 1 1 50	CRACKING	10.0	10.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	8.0	
200	3 3.6 44005	RIDE	8.6	8.6	8.3		8.2	7.8	7.9	7.8	7.8	7.8	7.7	7.6	7.7	
SW 58 CT(12.2L)	FC5HP															
4373441 11.983 14.750	C 2018 0012	CRACKING	7.5	4.5*	4.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	9.0	8.9	7.0
D.A.B. CONSTRUCTORS, INC	(2021)	RIDE	7.5	7.3	7.6	7.6	7.2	7.3		8.5	8.4	8.4	8.4	8.3	8.4	8.2
36100000 5.795 11.983	L 1 1 50	CRACKING			10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5	
200	3 12.6 38000	RIDE			8.7	8.4	8.3	8.2	8.3	8.2	8.1	8.0	8.0	7.8	7.7	
CR 484(6.0C)	FC5M															
4368791 5.981 11.983	C 2019 0012	CRACKING	6.5	6.5	4.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	9.7	10.0	8.0
ANDERSON COLUMBIA CO., INC	(2021)	RIDE	7.6	7.4	7.7	7.6	7.5	7.4		8.8	8.7	8.7	8.6	8.6	8.7	8.5
36110000 6.600 8.053	C 1 1 55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	
40	2 24.0 8900	RIDE	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	8.0	
SR 45(6.6C)	FC95															
4171821 6.643 19.588	C 2007 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	6.6	5.4*	3.0*
ANDERSON COLUMBIA CO., INC	(2010) SPRIDE	RIDE	7.8	7.9	7.8	7.7	7.7	7.5	7.5	7.6	7.5	7.5	7.4	7.4	6.8	6.5
4526361 6.632 15.750	C 2027 0012															
36110000 8.053 8.649	R 1 1 55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	
40	2 24.0 8900	RIDE	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	8.0	
SW 185 AVE RD(8.1R)	FC4															
4171821 6.643 19.588	C 2007 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	6.6	7.3	5.0*
ANDERSON COLUMBIA CO., INC	(2010) SPRIDE	RIDE	7.8	7.9	7.8	7.7	7.7	7.5	7.5	7.6	7.5	7.5	7.4	7.4	7.2	6.9
4526361 6.632 15.750	C 2027 0012															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	SYS / %T / FY-P / FY-F	TYP / AADT	SPD	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36110000	8.649	15.847	C	1	1	55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0															
40			2	24.0	8900		RIDE	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	8.0															
SW 178 TER(8.7L)					FC95																															
4171821	6.643	19.588	C	2007	0012		CRACKING	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	6.6	5.5*	3.5*															
ANDERSON COLUMBIA CO., INC		(2010)			SPRIDE			7.8	7.9	7.8	7.7	7.7	7.5	7.5	7.6	7.5	7.5	7.4	7.4	7.5	7.2															
4526361	6.632	15.750	C	2027	0012																															
36110000	15.847	19.589	R	1	1	55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0															
40			2	7.3	18500		RIDE	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	8.0															
SW 119 AVE(15.9R)					FC5M																															
2387191	15.847	19.589	C	2014	0213		CRACKING	10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.8	8.2	6.0*														
D.A.B. CONSTRUCTORS, INC		(2017)			SPRIDE			7.8	7.9		8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.2	8.2	8.2	8.0														
36110000	19.589	22.747	R	1	1	55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0															
40			2	3.3	24500		RIDE	8.1	7.9	7.9	7.4	7.2	6.8		8.1	8.1	8.1	8.1	8.1	8.1															
SW 80 AVE(19.9R)					FC5																															
2387621	19.588	22.805	C	2006	0213		CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	6.5	6.5	6.5	5.0*	4.5*	0.5*															
ANDERSON COLUMBIA CO., INC		(2008)			SPRIDE			8.0	7.9	8.2	8.1	8.1	8.1	8.1	8.2	8.0	8.1	8.0	8.0	8.0	7.8															
4506651	19.572	22.776	C	2028	0226																															
36110000	22.747	23.800	R	1	1	50	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0															
40			2	15.6	29500		RIDE	8.6	8.5	8.5	8.3	8.2	8.0	8.2	8.4	8.1	8.3	8.3	8.2	8.1															
SW 49 AVE(23.0R)					FC125M																															
4306561	22.747	24.138	C	2016	0012		CRACKING	9.0	9.0	8.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	5.5*															
MASCI GENERAL CONTRACTORS		(2017)			SPRIDE			8.2	7.9	7.9	8.7	8.7	8.6	8.6	8.5	8.5	8.5	8.4	8.4	8.3	8.0															
36110000	23.800	26.311	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
40			2	15.1	22500		RIDE	8.3	8.2	8.1	7.5	7.5	7.4	7.7	7.5	7.5	7.7	7.8	7.7	7.7															
HOLIDAY TRAVEL PARK(23.8R)					FC95																															
2387571	23.719	26.705	C	1999	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.3	7.0	4.0*															
ANDERSON COLUMBIA CO., INC		(2001)			SPRIDE			7.6	7.5	7.5	7.5	7.3	7.3	7.4	7.4	7.3	7.3	7.2	7.2	7.2	6.9															
36110000	23.800	26.311	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	8.5	7.0	7.0	10.0	9.5	9.5	9.5	9.5	9.5															
40			2	15.1	22500		RIDE	8.2	8.1	7.8	7.3	7.3	7.1	7.1	7.3	7.5	7.5	7.5	7.3	7.0															
OAK TREE DR W(24.4L)					FC95																															
4137191	23.808	26.705	C	2005	0216		CRACKING	9.5	9.0	9.0	9.0	9.0	9.0	9.0	8.5	8.5	8.5	8.5	7.7	7.5	5.0*															
STEVEN COUNTS, INC.		(2008)			SPRIDE			7.4	7.4	7.2	7.1	7.2	7.1	7.1	7.1	6.9	6.9	6.9	6.9	6.9	6.6															
36110000	22.747	23.800	L	1	1	50	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	7.0	7.0	7.0	7.0															
40			2	15.6	29500		RIDE	8.6	8.6	8.4	7.8	7.9	7.8	8.3	8.2	8.2	8.0	8.0	7.9	7.8															
NW 49 AVE(23.0L)					FC125M																															
4306561	22.747	24.138	C	2016	0012		CRACKING	7.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.2	8.5	7.0															
MASCI GENERAL CONTRACTORS		(2017)			RIDE			7.6	7.4	7.7	8.5	8.6	8.5	8.5	8.5	8.4	8.3	8.2	8.3	8.2	7.9															
36110000	19.589	22.747	L	1	1	55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0															
40			2	3.3	24500		RIDE	8.1	7.9	7.9	7.4	7.2	6.8		8.1	8.1	8.1	8.1	8.1	8.1															
NW 82 CT(19.7L)					FC5																															
2387621	19.588	22.805	C	2006	0213		CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	6.5	2.5*															
ANDERSON COLUMBIA CO., INC		(2008)			SPRIDE			8.1	8.0	8.1	8.2	8.1	8.1	8.1	8.2	8.1	8.1	8.0	8.0	8.0	7.8															
4506651	19.572	22.776	C	2028	0226																															
36110000	15.847	19.589	L	1	1	55	CRACKING	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0															
40			2	7.3	18500		RIDE	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	8.0															
CR 328(16.3L)					FC5M																															
2387191	15.847	19.589	C	2014	0213		CRACKING	10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.7	6.5															
D.A.B. CONSTRUCTORS, INC		(2017)			SPRIDE			7.8	7.9		8.3	8.3	8.4	8.3	8.4	8.3	8.3	8.3	8.3	8.3	8.1														
36110500	0.000	0.358	R	1	1	30	CRACKING								3.5*	10.0	10.0	10.0	10.0	10.0															
40			2	3.8	22200		RIDE								5.0*	5.7	5.4*	6.1																	
SW BROADWAY(0.0R)					FC95																															
							CRACKING	10.0	9.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.5	5.7*	3.5*															
						(2009)	RIDE													5.7	5.4*															
36110500	0.000	0.358	L	1	1	30	CRACKING								3.5*	10.0	10.0	10.0	10.0	10.0															
40			2	3.8	22200		RIDE								5.0*	7.7	7.7	7.6																	
BROADWAY AVE W(0.0C)					FC95																															
							CRACKING	9.0	9.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.5	7.5	6.5	5.3*	3.0*															
						(2009)	RIDE													5.9	5.6															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / ASTYPE / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36180000	12.560	14.003	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	10.0															
326			2	6.8	26500		RIDE	8.3	8.0	8.1	7.8	7.5	7.5	7.5	7.7	8.1	8.0	8.1	8.0	7.9															
NW 42ND AVE RD(13.2R)							FC125																												
4170051	12.827	14.003	C	2007		0216	CRACKING	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	6.5	4.0*														
ANDERSON COLUMBIA CO., INC(2009)							RIDE	8.0	7.9	7.5	7.4	7.5	7.3	7.5	7.5	7.3	7.3	7.3	7.4	7.4	7.1														
4542161	12.560	14.003	C	2029		0012																													
36180000	12.560	14.003	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	8.5															
326			2	6.8	26500		RIDE	7.7	8.0	7.7	7.4	7.3	7.3	7.0	7.2	7.9	7.8	7.8	7.5	7.6															
NW 47 AVE(12.7L)							FC125																												
							CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	6.5	6.5	4.5*													
				(2014)			RIDE	8.1	8.1	7.7	7.8	7.4	7.4	7.7	7.6	7.4	7.4	7.4	7.1	7.1	6.8													
4542161	12.560	14.003	C	2029		0012																													
36180001	0.000	1.674	R	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.5	6.0*	10.0	10.0	10.0															
326			2	12.2	11900		RIDE	8.7	8.6	8.6	8.2	7.9	8.1	8.0	8.1	7.9	7.7	7.9	8.0	8.0															
36180 MEDIAN GORE(0.0C)							FC2																												
4233481	0.000	1.674	C	2010		0226	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.3	7.0	3.5*														
ANDERSON COLUMBIA CO., INC(2011)							RIDE	8.1	8.0	8.4	8.4	8.4	8.4	8.5	8.5	8.4	8.5	8.5	8.5	8.5	8.3														
36180001	0.000	1.674	L	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.0*	6.0*	10.0	10.0	10.0															
326			2	12.2	11900		RIDE	8.4	8.5	8.4	7.9	7.8	7.7	7.6	7.4	7.1	6.8	7.8	7.9	7.8															
36180 MEDIAN GORE(0.0C)							FC2																												
4233481	0.000	1.674	C	2010		0226	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.0	7.0	3.5*														
ANDERSON COLUMBIA CO., INC(2011)							RIDE	7.9	7.8	8.3	8.2	8.2	8.2	8.3	8.3	8.2	8.3	8.2	8.1	8.2	8.0														
36210000	0.000	13.905	R	4	1	70	CRACKING	9.0	9.0	7.5	7.5	6.5	6.5	4.5*	10.0	10.0	10.0	10.0	10.0	10.0															
93	I75	334.4	348.3	3	26.4	140500	RIDE	8.9	8.9	8.7	8.1	7.8	7.6	7.5	8.0	8.3	8.3	8.3	8.2	8.1															
							FC5M																														
4431701	0.000	13.993	R	2022		0012	CRACKING	10.0	10.0	9.0	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*	10.0	10.0	9.0															
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.0	7.9	8.4	8.3	8.2	8.4	8.4	8.4	8.4	8.1	8.0	8.7	8.8	8.7														
36210000	13.905	18.482	R	4	1	70	CRACKING	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	6.0*	10.0	10.0	10.0	10.0															
93	I75	348.3	352.9	3	26.4	100500	RIDE	9.0	8.7	8.9	8.4	8.1	8.0	7.9	7.8	7.5	8.2	8.2	8.2	8.2															
							FC5M																														
4194371	13.991	18.436	C	2009		0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	5.5*	4.5*	4.3*	1.5*														
ANDERSON COLUMBIA CO., INC(2010)							SPRIDE	8.1	8.1	8.4	8.4	8.4	8.6	8.6	8.6	8.6	8.5	8.4	8.3	8.3	8.2														
4520741	13.991	22.000	C	2025		0548																													
36210000	18.482	38.282	R	4	1	70	CRACKING	10.0	7.5	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5															
93	I75	352.9	372.7	3	29.7	71000	RIDE	8.6	8.6	8.0	7.3	6.9	7.9	8.0	7.9	7.9	7.8	7.7	7.5	7.5															
ALACHUA CO LINE(38.3C)							FC5M																												
4306431	18.482	38.282	C	2015		0012	CRACKING	7.5	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.6	8.3	6.5														
ANDERSON COLUMBIA CO., INC(2018)							SPRIDE	7.3	6.8	7.6		8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.5														
36210000	18.482	38.282	L	4	1	70	CRACKING	9.0	7.5	6.5	4.5*	1.0*	10.0	10.0	10.0	9.0	8.0	7.5	7.5	6.5															
93	I75	352.9	372.7	3	29.7	71000	RIDE	8.8	8.6	8.2	7.5	7.1	8.0	7.9	7.9	7.6	7.8	7.6	7.4	7.3															
ALACHUA CO LINE(38.3C)							FC5M																												
4306431	18.482	38.282	C	2015		0012	CRACKING	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.4	7.2	5.0*														
ANDERSON COLUMBIA CO., INC(2018)							SPRIDE	6.8	6.2*	7.3		8.6	8.7	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.4														
36210000	13.905	18.482	L	4	1	70	CRACKING	9.0	9.0	9.0	8.0	7.0	6.0*	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0															
93	I75	348.3	352.9	3	26.4	100500	RIDE	8.6	8.9	8.7	8.2	7.9	7.8	7.6	7.6	7.6	8.2	8.3	8.2	8.2															
							FC5M																														
4194371	13.991	18.436	C	2009		0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	6.5	4.5*	4.5*	4.5*	1.5*														
ANDERSON COLUMBIA CO., INC(2010)							SPRIDE	8.2	8.1	8.5	8.4	8.3	8.5	8.5	8.6	8.5	8.4	8.4	8.1	8.0	7.9														
4520741	13.991	22.000	C	2025		0548																													
36210000	0.000	13.905	L	4	1	70	CRACKING	9.0	9.0	9.0	7.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0															
93	I75	334.4	348.3	3	26.4	140500	RIDE	8.9	8.8	8.5	8.0	7.8	7.6	7.5		8.3	8.3	8.3	8.3	8.1															
							FC5M																														
4431701	0.000	13.993	L	2022		0012	CRACKING	10.0	10.0	9.0	7.5	7.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.0															
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.1	7.9	8.3	8.2	8.2	8.4	8.4	8.4	8.3	8.1	7.9	8.6	8.6	8.5														
36220000	0.000	8.760	R	1	1	55	CRACKING	9.0	9.0	7.0	6.5	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
500	27		2	20.3	19100		RIDE	9.0	8.9	8.6	8.2	8.0	7.8	7.7	7.6	8.2	8.3	8.3	8.2	7.7															
SE 178 PL(0.2C)							FC5																												
4155241	0.000	8.760	C	2007		0012	CRACKING	10.0	10.0	10.0	10.0	9.5	9.0	9.0	7.5	6.5	4.5*	4.5*	4.5*	4.5*	1.0*														
ANDERSON COLUMBIA CO., INC(2009)							SPRIDE	8.2	8.2	8.3	8.3	8.3	8.4	8.4	8.4	8.4	8.4	8.3	8.3	8.3	8.1														
4506371	0.228	8.430	C	2026		0226																													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 5 COUNTY = MARION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD / SURFTYPE / ASTYPE	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
36220000	0.000	8.760	L	1	1	55	CRACKING	9.0	9.0	7.0	6.5	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
500	27		2	20.3	19100		RIDE	9.0	8.9	8.7	8.3	8.1	7.8	7.6	7.6	8.3	8.3	8.3	8.3	7.9															
SE 178 PL(0.2C)							FC5																												
4155241	0.000	8.760	C	2007		0012	CRACKING	10.0	10.0	10.0	10.0	9.5	9.0	8.5	6.5	6.5	4.5*	4.5*	4.5*	4.4*	0.5*															
ANDERSON COLUMBIA CO., INC				(2009)			SPRIDE	8.3	8.2	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.2	8.3	8.1															
4506371	0.228	8.430	C	2026		0226																													
36518000	0.000	0.288	R	1	7	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	10.0	10.0	10.0															
326			2	0.0	12200		RIDE	8.0	8.0	7.4	7.4	7.6	6.8	6.2	6.5	6.5	6.4	7.3	7.1	7.1															
SR 200(0.0C)							FC125M																												
4452171	0.024	0.288	R	2023		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	6.5	6.3*	10.0	9.0															
C. W. ROBERTS CONTRACTING,				(2026)			SPRIDE	7.1	7.1	7.6	7.7	7.4	7.4	7.5	7.5	7.6	7.9	7.4	7.1	8.2	7.9													
36518000	0.288	8.460	C	1	7	55	CRACKING	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.0	8.5															
326			2	6.8	12900		RIDE	6.8	6.2*	8.3	8.3	8.2	8.1	8.1	8.2	8.1	8.1	8.1	8.0	8.0															
NW 8 AVE(0.5R)							FC125M																												
							CRACKING	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	3.5*		10.0	9.0															
				(2026)			RIDE	7.9	7.9	7.7	7.6	7.6	7.6	7.6	7.6	7.4	7.4	7.4		8.2	7.9															
36518000	0.000	0.288	L	1	7	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	10.0	10.0	10.0															
326			2	0.0	12200		RIDE	7.8	8.1	7.7	6.6	6.8	6.5	7.4	6.5	7.2	6.8	6.9	7.0	6.7															
SR 200(0.0C)							FC125M																												
4452171	0.024	0.288	L	2023		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5	5.5*	10.0	9.0															
C. W. ROBERTS CONTRACTING,				(2026)			SPRIDE	6.8	6.9	7.2	7.3	6.9	6.8	6.7	7.1	7.3	6.7	6.7	6.3	7.8	7.5													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).