FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = SUWANNEE

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE	DISTRESS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
37010000 / 10 /	0.000 / 0.000 / 0.000	4.983 / 4.952 / 4.963	C / 2 / 2	1 / 7.2 / 6.5	1 / 2019 / 2026	60 / (2021) / 0012		3200 / 0012 /	FC125M / SPRIDE /	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0												
										RIDE	8.8	8.8	8.6	7.9	8.1	8.0	7.9	8.0	7.8	7.9	7.8	7.6	7.6												
OLD LOCATION OF SR 10(0.1L)										CRACKING	6.5	6.0*	6.0*	6.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	8.5	7.0												
ANDERSON COLUMBIA CO., INC										RIDE	7.6	7.4	7.5	7.4	7.5	7.4	7.3	8.7	8.4	8.3	8.1	8.0	7.9	7.5												
37010000 / 10 /	4.983 / 6.252 / 6.272	6.252 / 10.165 / 10.177	R / 2 / 2	1 / 7.2 / 6.261	1 / 2019 / 2026	45 / (2020) / 0012		3200 / 8700 / 0012	FC125M / FC125M / SPRIDE	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	10.0												
										RIDE	8.2	8.3	8.3	7.9	8.0	7.9	7.8	7.8	7.8	7.9	7.8	7.8	8.7												
161 RD(6.4R)										CRACKING	10.0	10.0	10.0	10.0	9.5		10.0	7.5	7.0	7.0	6.0*	4.0*	4.0*	2.5*												
4342961 / ANDERSON COLUMBIA CO., INC										RIDE	8.5	8.4	8.3	8.3	8.2		8.4	8.3	8.1	8.0	8.0	7.8	7.9	7.5												
37010000 / 10 /	10.165 / 10.686 / 10.700		R / 1 / 2	1 / 7.2 / 6.261	1 / 2019 / 2026	60 / (2021) / 0012		8700 / 0012 /	FC125M / SPRIDE /	CRACKING	10.0		10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5												
										RIDE	8.7		8.6	8.1	8.1	8.0	7.9	8.1	7.8	8.0	7.8	7.7	7.5												
MITCHELL RD(10.3R)										CRACKING	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	9.5	8.0												
4342961 / ANDERSON COLUMBIA CO., INC										RIDE	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	7.6	7.2												
37010000 / 10 /	10.686 / 12.270 / 12.277		C / 2 / 2	1 / 7.2 / 6.261	1 / 2019 / 2026	55 / (2021) / 0012		9700 / 0012 /	FC125M / SPRIDE /	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5												
										RIDE	8.7	8.5	8.6	7.9	7.8	7.6	7.5	7.6	7.8	8.0	7.8	7.7	7.5												
MADISON ST(11.0R)										CRACKING	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	9.5	8.0												
4342961 / ANDERSON COLUMBIA CO., INC										RIDE	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	8.0	7.6												
37010000 / 10 /	12.270 / 13.320 /		C / 2 /	1 / 7.2 /	1 / 2026 /	35 / (2021) /		9700 / 0012 /	FC125M / SPRIDE /	CRACKING	3.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5												
										RIDE	6.7		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4	7.3												
GREEN AVE(12.4R)										CRACKING	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	8.0	6.5												
										RIDE	7.4	7.3	7.3	7.3	7.3	7.2	7.2	7.7	7.3	7.1	7.1	6.9	6.5	6.1												
37010000 / 10 /	13.320 / 15.090 /		C / 2 /	1 / 5.6 /	1 / 2026 /	45 / (2021) /		5700 / 0012 /	FC125M / SPRIDE /	CRACKING	4.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5												
										RIDE	7.9		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4	7.3												
CONNER ST(13.3C)										CRACKING	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.5	9.2	7.5												
										RIDE	7.4	7.3	7.3	7.3	7.3	7.2	7.2	8.4	8.3	8.1	8.0	7.8	7.8	7.4												
37010000 / 10 /	15.090 / 26.152 / 26.152		C / 2 / 2	1 / 5.6 / 6.035	1 / 2022 / 2024	60 / (2024) / 0012		9400 / 0012 /	FC125M / SPRIDE /	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5												
										RIDE	8.7	8.7	8.7	8.4	8.3	8.2	8.1	8.0	7.9	8.0	7.8	7.7	7.6												
97TH LN(15.3L)										CRACKING	7.0	7.0	6.0*	6.0*	4.5*	4.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	10.0	9.0												
4432831 / ANDERSON COLUMBIA CO., INC										RIDE	7.6	7.5	7.6	7.6	7.7	7.7	7.7	7.7	7.6	7.6	8.9	8.9	8.8	8.4												
37010000 / 10 /	4.983 / 6.252 / 6.272		L / 2 / 2	1 / 7.2 / 6.261	1 / 2026 / 2026	45 / (2013) / 0012		3200 / 0012 /	FC125M / SPRIDE /	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	10.0												
										RIDE	8.2	8.6	8.6	7.8	8.0	8.0	7.9	7.9	7.8	7.8	7.5	7.6	8.8												
169 RD(5.3L)										CRACKING	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.0	7.0	7.0	6.0*	6.0*	3.9*	1.0*												
2135604										RIDE	8.5	8.5	8.3	8.3	8.3	8.2	8.4	8.4	8.2	8.2	8.0	8.0	7.8	7.4												
37030000 / 20 /	0.000 / 8.555 /		C / 2 /	1 / 7.3 /	7 / 2026 /	60 / (2026) /		6200 / 0012 /	FC125M / SPRIDE /	CRACKING	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0												
										RIDE	8.1	7.8	7.6	8.5	8.5	8.5	8.5	8.6	8.4	8.3	8.2	8.1	8.1												
SR 249(0.1L)										CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*	10.0	9.0												
										RIDE	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6	8.8	8.4												
37030000 / 20 /	8.555 / 8.623 /		C / 2 /	1 / 7.3 /	8 / 2004 /	60 / (2004) /		6200 / 0012 /	DGFC / SPRIDE /	CRACKING	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0												
										RIDE	8.3	7.8	7.8	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.2	8.1	8.1												
										CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*													
										RIDE	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = SUWANNEE ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
37040000	0.000	0.438	C		1		1		30		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	10.0	10.0	10.0	10.0													
249 129				4	15.4				6200		RIDE	6.5	6.5	6.5	6.6	6.0	5.8	6.2	6.0	6.4	8.2	7.8	7.9	7.9													
US-27/US-129/SR-20(0.0R)										FC125M																												
2108063	0.000	0.347	C	2008					0221		CRACKING	10.0	9.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	7.0	7.0	6.5	6.5	3.5*												
ANDERSON COLUMBIA CO., INC(2010)										SPRIDE		7.8	7.6	7.6	7.5	7.5	7.5	7.4	7.5	7.4	7.5	7.1	7.1	7.2	6.8												
37040000	0.438	12.889	C		1		1		60		CRACKING	8.5	8.5	7.0	5.5*	5.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	10.0													
249 129				2	15.4				3412		RIDE	8.7	8.6	8.5	7.9	7.8	7.5	7.4	7.2		8.5	8.4	8.3	8.2													
HENRY AVE NW(0.4C)										FC125M																												
2108063	0.438	12.889	C	2008					0221		CRACKING	9.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.5	3.5*												
ANDERSON COLUMBIA CO., INC(2010)										SPRIDE		8.1	8.1	8.1	8.0	8.1	7.9	7.9	7.9	7.8	7.8	7.6	7.6	7.4	7.0												
37040000	12.889	23.138	C		1		1		60		CRACKING	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	7.5	7.5													
249 129				2	15.4				5200		RIDE	8.1	7.7	8.9	8.4	8.4	8.4	8.3	8.5	8.4	8.4	8.4	8.2	8.2													
OLD ALIGN RD(13.0L)										FC125M																												
4454011	12.851	22.495	C	2023					0012		CRACKING	7.0	7.0	6.0*	6.0*	5.5*	5.5*	4.0*	4.0*	1.5*	1.5*	10.0	10.0	10.0	9.0												
ANDERSON COLUMBIA CO., INC(2024)										SPRIDE		8.0	8.0	8.0	7.9	7.9	7.7	7.9	7.9	7.7	7.8	8.5	8.4	8.4	8.0												
37040000	23.138	24.685	R		1		1		35		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	6.0*													
249 129				1	15.4				7200		RIDE	7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.1	7.0	6.7	6.8	6.2	6.1													
MANOR ST(23.3R)										FC125M																												
4305571	23.141	24.178	R	2016					0012		CRACKING	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.0	8.0	7.5	4.7*	2.5*												
ANDERSON COLUMBIA CO., INC(2018)										SPRIDE		6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6	7.4	7.2	7.2	6.9	6.4	6.0												
37040000	24.685	25.200	R		1		3		35		CRACKING	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	8.5													
51 129				2	3.9				15500		RIDE	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	7.6													
HAINES ST(24.7C)										DGFC																												
2107502	24.651	25.322	C	2008					0012		CRACKING	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.5	6.9	6.5	6.4	6.0												
2107503	24.685	27.201	C	2025					0012																													
37040000	25.200	25.610	R		1		3		45		CRACKING	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	8.5	8.5	8.5	8.5	8.5													
51 129				2	3.9				14400		RIDE	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	7.6	7.5	7.6	7.5	7.5													
HAMILTON ST(25.3R)										DGFC																												
2107502	25.322	25.610	C	2008					0012		CRACKING	7.5	7.5	6.0*	6.0*	5.5*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		7.2	7.1	6.4	6.4	6.5	7.7	7.4	7.6	7.5	7.5	7.6	7.3	7.4	7.0												
2107503	24.685	27.201	C	2025					0012																													
37040000	25.610	27.579	R		1		1		45		CRACKING	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0													
51 129				2	3.9				13600		RIDE	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	8.5	8.3	8.2	8.3	8.2													
GRAND ST(25.8R)										FC125M																												
2107502	25.610	27.579	C	2008					0012		CRACKING	9.0	8.5	8.5	8.5	7.5	6.5	6.5	5.5*	5.5*	5.5*	5.5*	3.5*	2.6*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		8.3	8.1	8.1	8.1	8.1	8.0	8.1	8.0	7.8	7.9	7.8	7.8	7.7	7.3												
2107503	24.685	27.201	C	2025					0012																													
37040000	27.579	32.407	C		1		1		60		CRACKING	7.0	7.0	7.0	5.5*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
51 129				2	3.9				6400		RIDE	8.2	8.3	8.2	7.8	7.7	7.5	8.3	8.4	8.4	8.5	8.4	8.4	8.3													
58TH ST(28.6R)										FC125																												
											CRACKING	9.0	8.5	8.5	8.5	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	2.3*	0.0*												
										(2007)	RIDE	8.3	8.3	8.1	8.1	8.1	8.0	8.1	8.0	7.9	8.0	7.9	8.0	7.9	7.5												
2107814	27.925	32.407	C	2026					0012																													
37040000	25.610	27.579	L		1		1		45		CRACKING	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	9.0	8.5													
51 129				2	3.9				13600		RIDE	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.3	8.2	8.3	8.0	8.1													
72ND TRACE(26.4C)										FC125M																												
2107502	25.610	27.579	C	2008					0012		CRACKING	8.5	8.5	8.5	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	2.1*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		8.0	8.1	7.9	8.0	7.9	7.8	7.9	7.8	7.6	7.8	7.7	7.7	7.6	7.2												
2107503	24.685	27.201	C	2025					0012																													
37040000	25.200	25.610	L		1		1		45		CRACKING	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	8.5	8.5	7.5	7.5	7.5													
51 129				2	3.9				14400		RIDE	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.0	7.8	7.9	7.7	7.5													
HAMILTON ST(25.3L)										FC4																												
2107502	25.322	25.610	C	2008					0012		CRACKING	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	1.3*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		7.4	7.5	7.4	7.3	7.1	7.1	7.2	7.1	7.0	6.8	6.9	6.8	6.6	6.2												
2107503	24.685	27.201	C	2025					0012																													
37040000	24.685	25.200	L		1		3		35		CRACKING	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	8.5													
51 129				2	3.9				15500		RIDE	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	7.6													
HAINES ST(24.7C)										FC125M																												
2107502	24.651	25.322	C	2008					0012		CRACKING	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	6.0*	6.0*	5.5*	0.0*	0.0*												
ANDERSON COLUMBIA CO., INC(2009)										SPRIDE		7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.8	7.2	6.7	6.4	6.0												
2107503	24.685	27.201	C	2025					0012																													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = SUWANNEE ----------

RDWYID / SR / US / G_BMP / G_EMP / LN / %T / AADT / INTERSECT AT (MP|SIDE) / SURFTYPE / ITMSEG-P / W_BMP / W_EMP / RW / FY-P / WKMX-P / CONTRACTOR (AGE_ONE YEAR) / ASTYPE / ITMSEG-F / W_BMP / W_EMP / RW / FY-F / WKMX-F	DISTRESS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
37040000 23.138 24.685 L 1 1 35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5		7.5	7.5	7.5	6.0*													
249 129 1 15.4 7200	RIDE	7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.5		6.7	6.8	6.2	6.1													
LAVONIA ST(23.2L) FC125M																											
4305571 23.141 24.178 L 2016 0012	CRACKING	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.5	8.5	7.0	5.2*	3.0*												
ANDERSON COLUMBIA CO., INC(2018) SPRIDE	RIDE	6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6	7.4	7.6	7.6	7.3	7.3	6.9												
37050000 0.000 0.424 C 1 1 45	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	10.0	10.0	10.0	10.0													
136 2 12.1 2400	RIDE	8.2	8.0	7.9	7.4	7.4	7.3	7.2	7.4	7.4	8.3	8.2	8.2	7.8													
DGFC																											
CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.0	7.0	7.0	10.0	10.0	9.0													
(2025) RIDE	8.1	8.1	7.7	7.5	7.6	7.3	7.6	7.5	7.3	7.1	7.1	7.6	7.7	7.3													
37050000 0.424 1.046 C 1 1 55	CRACKING	7.0	7.0	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.0													
136 2 12.1 2400	RIDE	8.3	8.3	8.2	7.1	6.7	6.3*	8.0	8.5	8.3	8.2	8.3	8.2	8.1													
EXIT FARMERS MARKET(0.5R) FC125																											
2107752 0.424 0.789 C 2006 0012	CRACKING	8.5	8.5	7.5	7.0	7.0	6.5	6.5	6.0*	6.0*	6.0*	5.5*	5.5*	1.9*	0.0*												
ANDERSON COLUMBIA CO., INC(2007)	RIDE	8.3	8.2	8.0	7.9	7.9	7.8	7.9	7.9	7.8	7.8	7.7	7.6	7.6	7.2												
37060000 0.000 17.455 C 1 1 60	CRACKING	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0													
51 2 6.6 5000	RIDE	8.3	8.3	8.8	8.5	8.4	8.4	8.4	8.4	8.3	8.3	8.2	8.0	8.0													
COUNTY LINE INSPECTION S(1.3C) FC125M																											
4322611 0.000 16.658 C 2016 0012	CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	6.5	4.5*												
ANDERSON COLUMBIA CO., INC(2017) SPRIDE	RIDE	7.9	7.8	7.8	8.6	8.5	8.3	8.0	7.8	7.8	7.7	7.6	7.6	7.4	7.0												
37060000 17.455 17.491 C 1 6 35	CRACKING	0.0*	0.0*		10.0	10.0	10.0	10.0	10.0																		
51 1 6.6 9200	RIDE	8.3	8.3																								
S WALKER AVE(17.5R) FC95																											
CRACKING					8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	8.3	7.6	3.5*												
(2004) RIDE																											
37060000 17.491 17.994 C 1 1 35	CRACKING	9.0	9.0	6.5	6.5	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0	10.0													
51 2 6.6 9200	RIDE	6.7	6.8	6.1	5.8	7.3	6.9	6.6	6.2	5.5	7.7	7.5	7.3	7.2													
BYNUM AVE SW(17.6R) DGFC																											
CRACKING	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	6.0*			10.0	10.0	9.0													
(2025) RIDE	7.0	6.9	6.4	6.3	6.2	6.0	6.0	6.1	5.8			7.2	6.8	6.4													
37070000 0.000 2.755 C 1 1 60	CRACKING	8.5	8.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	10.0	10.0	8.5	8.5													
49 129 2 11.3 3600	RIDE	8.6	8.5	8.4	8.1	8.0	7.9	7.6	7.4	7.4	8.7	8.2	8.2	8.2													
SANDY POINT RD(0.0L) FC125																											
2107762 0.000 2.648 C 2009 0012	CRACKING	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.8*	0.5*												
ANDERSON COLUMBIA CO., INC(2010)	RIDE	8.3	8.2	8.2	8.1	8.0	7.9	7.9	7.8	7.7	7.7	7.6	7.4	7.4	7.0												
2107763 0.000 2.276 C 2029 0012																											
37080000 0.000 0.600 C 1 1 35	CRACKING	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0													
247 2 7.2 3664	RIDE	8.4	8.3	8.3	7.8	7.6	7.4	7.2	6.5	6.8	8.4	7.9	7.8	8.0													
SR 249(0.0C) FC125M																											
2107192 0.000 0.600 C 2008 0221	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.5	6.8	3.5*												
ANDERSON COLUMBIA CO., INC(2010)	RIDE	8.0	8.0	7.8	7.8	7.8	7.8	7.8	7.8	7.7	7.5	7.5	7.4	7.1	6.7												
37080000 0.600 10.700 C 1 1 60	CRACKING	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.0*		10.0	10.0	10.0	10.0													
247 2 15.4 5200	RIDE	8.4	8.3	8.3	7.8	7.6	7.4	7.2	7.1		8.7	8.6	8.5	8.4													
SIDE ROAD(1.2C) FC125M																											
2107192 0.690 10.700 C 2008 0221	CRACKING	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.7	6.6	3.5*												
ANDERSON COLUMBIA CO., INC(2010)	RIDE	8.1	8.1	8.2	8.1	8.1	7.9	7.9	7.8	7.8	7.7	7.6	7.4	7.3	6.9												
37120000 0.000 5.861 R 4 1 70	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0													
8 I10 268.2 274.1 2 26.0 28000	RIDE	8.9	8.9	8.9	8.4	8.4	8.0	8.3	8.0	8.1	8.2	8.2	8.1	8.1													
FC5M																											
4413371 0.000 5.861 C 2021 0012	CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5		10.0	10.0	9.7	10.0	8.5												
ANDERSON COLUMBIA CO., INC(2023)	SPRIDE	8.1	8.0	8.3	8.3	8.5	8.4	8.4	8.4		8.8	8.8	8.7	8.8	8.7												
37120000 5.861 15.099 R 4 1 70	CRACKING	10.0	10.0	10.0	10.0	9.0	8.0	7.5	7.5	7.5	6.5	6.0*		10.0													
8 I10 274.1 283.3 2 27.7 24000	RIDE	8.9	8.9	8.9	8.3	8.2	8.0	8.0	7.7	7.6	7.3	7.0		8.7													
FC5M																											
2135603 5.861 15.099 C 2011 0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	4.0*												
PREFERRED MATERIALS, INC. (2013)	SPRIDE	8.7	8.6	8.9	8.9	9.1	9.0	9.0	9.1	9.1	8.9	8.8	8.7	8.6	8.5												
2135604 5.861 15.132 C 2026 0012																											

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = SUWANNEE ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / SURFTYPE / ASTYPE / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS / RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
37120000	15.099	25.508	R	4	8	70	CRACKING	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
8 I10	283.3	293.8	2	27.7	30110		RIDE	9.0	8.6	8.3	7.7	6.8	6.4*	8.4	8.5	8.5	8.5	8.5	8.4	8.3														
					FC5M																														
2135202	15.144	25.523	C	2006	0012		CRACKING	9.0	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.5*	1.0*	1.0*															
ANDERSON COLUMBIA CO., INC(2007)							RIDE	8.1	7.9	8.3	8.3	8.6	8.5	8.5	8.5	8.4	8.2	8.0	8.0															
37120000	15.099	25.508	L	4	8	70	CRACKING	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0														
8 I10	283.3	293.8	2	27.7	30110		RIDE	8.9	8.7	8.3	7.4	7.0	6.7	8.5	8.5	8.5	8.5	8.4	8.3	8.2														
					FC5M																														
2135202	15.144	25.523	C	2006	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	4.5*	4.5*	4.5*	4.5*	4.5*	1.0*																
ANDERSON COLUMBIA CO., INC(2007)							RIDE	8.1	7.9	8.4	8.3	8.7	8.5	8.5	8.4	8.1	7.8	7.8																
37120000	5.861	15.099	L	4	1	70	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.5	7.5	6.5	6.0*	6.0*		10.0														
8 I10	274.1	283.3	2	27.7	24000		RIDE	8.8	8.8	8.8	8.2	8.1	7.9	7.7	7.4	7.4	7.1	6.6		8.7														
					FC5M																														
2135603	5.861	15.099	C	2011	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	6.5	6.5	6.5	4.0*													
PREFERRED MATERIALS, INC. (2013)							SPRIDE	8.7	8.6	8.8	8.8	9.0	8.9	8.9	9.1	9.0	8.8	8.8	8.6	8.5	8.4													
2135604	5.861	15.132	C	2026	0012																													
37120000	0.000	5.861	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0														
8 I10	268.2	274.1	2	26.0	28000		RIDE	8.8	8.9	8.9	8.4	8.3	8.2	8.2	8.1	8.1	8.2	8.2	8.1	8.1														
					FC5M																														
4413371	0.000	5.861	C	2021	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5		10.0	10.0	9.6	10.0	8.5														
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.0	7.8	8.3	8.2	8.5	8.4	8.4	8.4		8.9	8.8	8.8	8.8	8.7														
37130000	0.000	3.656	R	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	10.0	10.0	10.0	10.0														
93 I75	438.3	442.0	3	31.3	38500		RIDE	8.5	8.9	8.9	8.3	8.3	8.1	7.9	7.7	7.5	8.7	8.7	8.6	8.6														
					FC5M																														
4455451	0.000	3.656	R	2022	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5	7.5	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.5	8.3	8.7	8.6	9.0	8.8	8.9	8.9	8.8	8.6	8.6	8.9	9.0	8.9													
37130000	0.000	3.656	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0	10.0														
93 I75	438.3	442.0	3	31.3	38500		RIDE	8.9	8.9	8.8	8.4	8.3	8.2	8.1	8.0	7.7	8.6	8.6	8.5	8.5														
					FC5M																														
4455451	0.000	3.656	L	2022	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	6.5	4.5*	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.4	8.2	8.5	8.5	8.7	8.6	8.6	8.6	8.3	8.2	8.1	8.7	8.8	8.7													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).