FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = TAYLOR ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
38010000	0.000	7.831	R	1	1	65					CRACKING	8.5	8.5	7.0	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0													
55 19				2	13.0		5700			RIDE		8.9	8.4	8.9	8.4	8.4		8.6	8.3	8.5	8.4	8.3	8.2	8.1													
SR 51(0.2C)						FC5M																															
4376181	0.000	7.831	C	2019		0012					CRACKING	10.0	9.0	9.0	7.5	7.5	4.5*		10.0	10.0	10.0	10.0	9.6	9.7	7.5													
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE						8.1	7.9	8.1	7.9	8.0	8.0		8.9	8.9	8.9	8.7	8.7	8.6	8.4													
38010000	7.831	24.844	R	1	1	65					CRACKING	6.5	4.5*	4.5*	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0														
55 19				2	13.0		5700			RIDE		8.7	8.6	8.5	7.8	7.8	7.6		8.3	8.4	8.4	8.3	8.3	8.2														
JOSH MCCALL(8.8R)						FC5HP																															
4410591	7.831	24.844	R	2021		0012					CRACKING	10.0	10.0	9.0	7.5	7.5	4.5*	4.5*	4.5*		10.0	10.0	9.7	10.0	8.5													
ANDERSON COLUMBIA CO., INC(2023)						SPRIDE						8.1	7.9	8.1	8.1	8.3	8.2	8.1	8.0		8.9	8.9	8.8	8.8	8.6													
38010000	24.844	27.458	R	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0														
55 19				2	13.0		9600			RIDE		8.3	8.3	8.4	8.2	8.2	7.8	8.0	8.1	8.1	8.0	7.9	7.8	7.8														
CARLTON CEMETERY RD(24.9R)						FC125M																															
4361651	24.832	27.395	C	2018		0012					CRACKING	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	9.0	9.5	8.0													
CAPITAL ASPHALT INC				(2020)		SPRIDE						7.7	7.7	7.7	7.7	7.9	7.7	8.5	8.5	8.4	8.4	8.4	8.3	8.2	7.8													
38010000	24.844	27.458	L	1	1	45					CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	6.0*														
55 19				2	13.0		9600			RIDE		8.3	8.5	8.4	8.1	8.0	7.8	7.9	8.1	8.2	8.0	8.0	7.9	7.8														
UNSIGNED(24.9L)						FC125M																															
4361651	24.832	27.395	C	2018		0012					CRACKING	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	8.7	9.5	8.0													
CAPITAL ASPHALT INC				(2020)		SPRIDE						7.8	7.7	7.8	7.7	7.9	7.7	8.5	8.4	8.4	8.4	8.3	8.2	8.2	7.8													
38010000	7.831	24.844	L	1	1	65					CRACKING	6.5	6.5	4.5*	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0														
55 19				2	13.0		5700			RIDE		8.7	8.9	8.8	8.3	8.2	8.0		8.3	8.4	8.4	8.4	8.3	8.3														
FISH CREEK RD(9.4L)						FC5HP																															
4410591	7.831	24.844	L	2021		0012					CRACKING	10.0	9.0	9.0	8.0	8.0	7.5	6.5	4.5*	10.0	10.0	10.0	9.8	8.9	7.0													
ANDERSON COLUMBIA CO., INC(2022)						SPRIDE						8.2	8.1	8.4	8.4	8.6	8.5	8.5	8.4	9.0	8.9	8.9	8.9	8.9	8.7													
38010000	0.000	7.831	L	1	1	65					CRACKING	8.5	8.5	7.0	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0													
55 19				2	13.0		5700			RIDE		8.8	8.5	8.8	8.3	8.2		8.6	8.2	8.6	8.6	8.5	8.5	8.4													
SR 51(0.2C)						FC5M																															
4376181	0.000	7.831	C	2019		0012					CRACKING	10.0	10.0	9.0	9.0	9.0	7.5		10.0	10.0	10.0	10.0	9.7	9.5	7.5													
ANDERSON COLUMBIA CO., INC(2021)						SPRIDE						8.4	8.3	8.4	8.4	8.4	8.3		8.8	8.8	8.8	8.7	8.7	8.7	8.5													
38020000	0.000	1.784	R	1	1	40					CRACKING	7.5	7.5	5.5*	5.5*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0														
30 19				2	10.2		11500			RIDE		8.0	8.0	7.7	7.0	7.2	6.5	6.5	8.4	8.3	8.3	8.0	8.0	7.9														
US-221/SR-55/JEFFER(0.0R)						FC125M																															
2108782	0.000	1.784	C	2007		0012					CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.0	7.0	7.0	6.0*	4.9*	4.4*	1.0*													
ANDERSON COLUMBIA CO., INC(2008)						SPRIDE						7.9	7.9	7.9	7.8	7.9	7.8	7.7	7.7	7.6	7.6	7.6	7.5	7.5	7.1													
2108784	0.000	1.784	C	2028		0012																															
38020000	1.784	2.005	R	1	1	45					CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0														
20 19				2	10.2		11300			RIDE		8.9	8.8	8.8	8.4	8.3	8.1	8.1	7.9	7.7	7.5	8.5	8.5	8.5														
CR 356(2.0C)						FC125M																															
2108783	1.784	17.387	R	2009		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.1	6.5	3.5*													
ANDERSON COLUMBIA CO., INC(2011)						SPRIDE						8.5	8.5	8.7	8.7	8.8	8.7	8.7	8.7	8.7	8.7	8.6	8.6	7.6	7.2													
38020000	2.005	17.387	R	1	2	65					CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0														
20 19				2	10.2		5800			RIDE		8.9	8.8	8.8	8.4	8.3	8.1	8.1	7.9	7.7	7.5	8.5	8.5	8.5														
ASH RD W(2.3C)						FC5M																															
2108783	1.784	17.387	R	2009		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.1	7.0	2.0*													
ANDERSON COLUMBIA CO., INC(2011)						SPRIDE						8.5	8.5	8.7	8.7	8.8	8.7	8.7	8.7	8.7	8.7	8.6	8.6	8.6	8.4													
38020000	4.657	17.387	L	1	1	65					CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	6.0*	6.0*	6.0*	10.0	10.0	10.0														
20 19				2	10.2		5800			RIDE		8.8	8.8	8.8	8.3	8.3	8.0	7.9	8.3	8.2	7.9	8.6	8.6	8.5														
PISGAH CHURCH RD(5.3L)						FC5M																															
2108783	1.784	17.387	L	2009		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.0	6.9	2.0*													
ANDERSON COLUMBIA CO., INC(2011)						SPRIDE						8.6	8.5	8.8	8.8	8.9	8.9	8.8	8.9	8.8	8.8	8.8	8.7	8.7	8.5													
38020000	2.855	4.657	L	1	8	55					CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0														
20 19				2	10.2		8600			RIDE		8.8	8.8	8.8	8.3	8.3	8.0	7.9	7.3	7.1	7.0	8.6	8.6	8.5														
ANDREW REAMS RD(3.1L)						FC5M																															
2108783	1.784	17.387	L	2009		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.0															
ANDERSON COLUMBIA CO., INC(2011)						SPRIDE						8.6	8.5	8.8	8.8	8.9	8.9	8.8	8.9	8.8	8.8	8.8	8.7															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = TAYLOR ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
38020000	2.005	2.855	L	1	1	55				CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0													
20 19			2	10.2		8600				RIDE	8.8	8.8	8.8	8.3	8.3	8.0	7.9	7.3	7.1	7.0	8.6	8.6	8.5													
ASH RD W(2.3C)									FC5M																											
2108783	1.784	17.387	L	2009		0012				CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.0	6.5	1.5*												
ANDERSON COLUMBIA CO., INC(2011)									SPRIDE	RIDE	8.6	8.5	8.8	8.8	8.9	8.9	8.8	8.9	8.8	8.8	8.8	8.7	8.6	8.4												
38020000	1.784	2.005	L	1	1	45				CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0													
20 19			2	10.2		11300				RIDE	8.8	8.8	8.8	8.3	8.3	8.0	7.9	7.3	7.1	7.0	8.6	8.6	8.5													
CR 356(2.0C)									FC125M																											
2108783	1.784	17.387	L	2009		0012				CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.0	6.5	3.5*												
ANDERSON COLUMBIA CO., INC(2011)									SPRIDE	RIDE	8.6	8.5	8.8	8.8	8.9	8.9	8.8	8.9	8.8	8.8	8.8	8.7	7.8	7.4												
38020000	0.000	1.784	L	1	1	40				CRACKING	7.5	7.5	5.5*	5.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0													
30 19			2	10.2		11500				RIDE	8.3	8.0	7.7	7.0	6.6	6.4	6.1	8.2	8.1	8.1	8.1	7.8	7.8													
CR-361A PUCKETT RD(0.0L)									FC125M																											
2108782	0.000	1.784	C	2007		0012				CRACKING	10.0	10.0	9.0	9.0	6.5	6.5	6.5	6.0*	6.0*	6.0*	5.5*	4.4*	3.9*	0.5*												
ANDERSON COLUMBIA CO., INC(2008)									SPRIDE	RIDE	7.8	7.9	7.6	7.7	7.7	7.6	7.6	7.5	7.4	7.4	7.4	7.1	7.3	6.9												
2108784	0.000	1.784	C	2028		0012																														
38030000	0.000	0.334	C	1	1	30				CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	7.0													
20 27			2	7.1		5100				RIDE	7.0	7.5	7.3	6.8	6.6	6.3	6.4	6.3	6.4	6.5	5.8	5.6	5.6													
US-19/27A/98/SR-30(0.0R)									FC125M																											
4305491	0.020	0.683	C	2015		0012				CRACKING	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	6.5	4.0*												
ROBERTS AND ROBERTS, INC. (2016)									SPRIDE	RIDE	6.0	6.0	7.6	7.6	7.4	7.1	6.8	7.0	7.0	6.9	6.6	6.5	6.4	6.0												
38030000	0.334	0.686	R	1	1	30				CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	7.0													
20 27			1	7.1		5200				RIDE	7.0	7.5	7.3	6.8	6.6	6.3	6.4	6.3	6.4	6.5	5.8	5.6	5.6													
QUINCY ST S(0.4C)									FC125M																											
4305491	0.020	0.683	C	2015		0012				CRACKING	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	6.5	4.0*												
ROBERTS AND ROBERTS, INC. (2016)									SPRIDE	RIDE	6.0	6.0	7.6	7.6	7.4	7.1	6.8	7.0	7.0	6.9	6.6	6.5	6.3	5.9												
38030000	0.686	1.104	R	1	1	40				CRACKING	7.0	7.0	7.0	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
20 27			1	7.1		3700				RIDE	7.6	7.6	7.2	6.8	6.7	6.5	8.5	8.5	8.6	8.6	8.5	8.4	8.4													
MAPLE AVE(0.7C)									FC125M																											
2108652	0.686	6.704	C	2006		0012				CRACKING	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.5	6.0*	6.0*	4.0*	3.5*	2.3*	0.0*												
ANDERSON COLUMBIA CO., INC(2007)									SPRIDE	RIDE	8.1	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.7	7.9	7.7	7.7	7.5	7.1												
2108656	0.686	3.979	C	2027		0012																														
38030000	1.104	3.756	C	1	1	50				CRACKING	6.5	6.5	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
20 27			4	7.1		3900				RIDE	8.0	7.9	7.8	7.3	7.2	6.9	8.5	8.5	8.6	8.6	8.5	8.4	8.4													
BISHOP BLVD(1.4L)									FC125M																											
2108652	0.686	6.704	C	2006		0012				CRACKING	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.5	6.0*	6.0*	4.0*	3.5*	3.1*	0.0*												
ANDERSON COLUMBIA CO., INC(2007)									SPRIDE	RIDE	8.1	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.7	7.9	7.7	7.7	7.8	7.4												
2108656	0.686	3.979	C	2027		0012																														
38030000	3.756	4.040	C	1	1	50				CRACKING	6.5	6.5	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
20 27			4	7.1		2400				RIDE	8.0	7.9	7.8	7.3	7.2	6.9	8.5	8.5	8.6	8.6	8.5	8.4	8.4													
WELDON POPPELL RD(3.8L)									DGFC																											
										CRACKING	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.5	6.0*	6.0*	4.0*	3.5*	9.6	8.5												
						(2026)				RIDE	8.1	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.7	7.9	7.7	7.7	8.0	7.6												
2108656	0.686	3.979	C	2027		0012																														
38030000	4.040	4.625	C	1	7	50				CRACKING	6.5	6.5	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
20 27			2	7.1		2400				RIDE	7.6	7.7	7.7	7.1	6.9	6.7	8.2	8.2	8.2	8.1	7.9	7.5	7.6													
CONNEL RD(4.0L)									FC125M																											
2108655	4.036	4.613	C	2024		0012				CRACKING	8.5	8.5	8.5	7.5	7.5	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	3.5*	10.0	9.0												
ANDERSON COLUMBIA CO., INC(2026)									SPRIDE	RIDE	7.7	7.7	7.8	7.7	7.4	7.8	7.7	7.7	7.6	7.7	7.6	7.6	8.5	8.1												
38030000	4.625	4.983	R	1	7	50				CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5													
20 27			1	7.1		3500				RIDE	8.7	8.7	8.6	8.1	7.9	7.8	8.4	8.4	8.4	8.5	8.4	8.2	8.1													
CR 30(4.7R)									FC125M																											
2108655	4.613	4.979	R	2024		0012				CRACKING	9.0	9.0	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.5*	10.0	9.0												
ANDERSON COLUMBIA CO., INC(2026)									SPRIDE	RIDE	8.0	8.0	8.1	8.1	8.2	8.0	8.0	8.0	8.0	8.1	8.0	8.0	8.3	7.9												
38030000	4.983	6.660	C	1	7	60				CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5													
20 27			2	7.1		3500				RIDE	8.8	8.8	8.8	8.0	7.9	7.7	8.5	8.6	8.5	8.5	8.4	8.2	8.1													
CR 356(5.5L)									FC125M																											
2108655	4.979	6.649	C	2024		0012				CRACKING	9.0	9.0	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.5*	10.0	9.0												
ANDERSON COLUMBIA CO., INC(2026)									SPRIDE	RIDE	8.0	8.0	8.1	8.1	8.2	8.0	8.0	8.0	8.0	8.1	8.0	8.0	8.6	8.2												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = TAYLOR ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / SURFTYPE / FY-P / ASTYPE / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
38030000	6.660	14.697	C	1	1	60	CRACKING	9.0	9.0	7.0	6.5	6.5	6.5	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
20 27			2	7.1	3500		RIDE	9.0	8.9	8.9	8.1	7.9	7.5	7.2	7.2	8.8	8.8	8.7	8.6	8.4															
SIDE ROAD(7.1C)						FC125M																													
2108653	6.704	14.697	C	2008		0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	6.5	6.5	3.5*														
ANDERSON COLUMBIA CO., INC					(2009)		SPRIDE	8.5	8.4	8.4	8.3	8.3	8.1	8.2	8.2	8.1	8.1	8.1	8.0	8.0	7.6													
2108657	6.704	14.697	C	2029		0012																													
38040000	0.000	0.358	R	1	1	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	5.5*	10.0	10.0															
55 221			2	2.1	9700		RIDE	8.1	7.7	7.6	7.1	7.1	7.1	7.4	7.6	7.4	7.1	6.9	8.1	7.3															
CR 361A(0.0C)						FC3																													
							CRACKING	10.0	8.5	8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	5.5*	5.5*	4.9*	4.6*	2.0*													
					(2012)		RIDE	7.6	7.0	7.0	6.5	6.9	6.6	6.8	7.2	6.5	6.5	6.1	6.5	5.9	5.5													
38040000	0.358	0.933	R	1	1	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	5.5*	7.0	5.5*															
55 221			2	2.1	9300		RIDE	8.1	7.7	7.6	7.1	7.1	7.1	7.4	7.6	7.4	7.1	6.9	6.2	6.2															
E JONES ST(0.4R)						FC125M																													
4323101	0.351	0.872	R	2018		0012	CRACKING	5.5*	5.0*	3.5*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	9.0	8.0	8.0	6.0*														
PREFERRED MATERIALS, INC.					(2019)		SPRIDE	5.7	6.5	6.6	6.4	6.6	8.5	8.0	8.3	8.1	7.8	7.8	7.6	7.7	7.3													
38040000	3.210	14.620	C	1	1	60	CRACKING	6.0*	6.0*	5.5*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
55 221			2	11.3	3000		RIDE	8.5	8.2	8.0	7.2		8.6	8.5	8.4	8.4	8.4	8.4	8.2	8.1															
CR 359A(3.4L)						FC125H																													
4410581	3.447	13.387	C	2023		0012	CRACKING	8.5	8.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	5.5*		10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC					(2025)		SPRIDE	7.9	7.9	7.9	7.7	7.9	7.7	7.7	7.7	7.6	7.5		8.4	8.3	7.9													
38070000	0.346	1.940	C	1	1	30	CRACKING	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.5															
51			2	8.7	1100		RIDE	7.2	7.2	7.0	6.4	8.1	7.9	7.8	7.7	7.8	7.6	7.4	7.3	7.2															
FIRST AVE S(0.3L)						FC95																													
4088671	0.000	1.906	C	2004		0012	CRACKING	7.0	7.0	7.0	7.0	7.0	5.5*	5.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	0.0*														
ANDERSON COLUMBIA CO., INC					(2005)		RIDE	7.0	6.9	6.9	6.8	6.8	6.6	6.5	6.4	6.4	6.2	6.2	6.3	6.0	5.6													
4088672	0.336	1.933	C	2027		0012																													
38070000	1.940	11.853	C	1	7	60	CRACKING	7.0	7.0	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.5															
51			2	8.7	1100		RIDE	8.1	8.0	8.0	7.1	7.1	6.7	6.8	6.5	8.5	8.4	8.3	7.9	7.8															
1ST AVE S(2.0R)						FC125M																													
4470761	1.933	11.853	C	2023		0012	CRACKING	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0														
					(2026)		RIDE	7.5	7.3	7.6	7.4	7.4	7.3	7.2	7.1	7.0	7.0	7.0	6.9	8.5	8.1													
38090000	0.259	11.687	C	1	1	60	CRACKING	10.0	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0															
30 98			2	28.6	2329		RIDE	8.8	8.8	8.8	8.4	8.2	8.0	7.9	7.9	7.7	7.5	8.6	8.6	8.5															
AUCILLA LANDING RD(0.3L)						FC125M																													
2108832	0.000	11.861	C	2009		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	7.0	7.0	7.3	7.0	4.0*														
ANDERSON COLUMBIA CO., INC					(2011)		RIDE	8.5	8.5	8.4	8.3	8.3	8.2	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.6													
2108833	0.000	11.861	C	2029		0012																													
38090000	11.687	24.698	C	1	1	60	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
30 98			2	2.1	2200		RIDE		8.8	8.8	8.5	8.4	8.3	8.2	8.0	8.2	8.4	8.3	8.1	8.2															
CABBAGE GROVE(12.3L)						FC125M																													
4433111	11.825	24.682	C	2022		0012	CRACKING	8.5	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC					(2024)		SPRIDE	8.1	8.1	7.9	7.9	7.9	7.8	7.7	7.6	7.6		8.5	8.4	8.3	7.9													
38501000	0.000	1.346	C	1	1	45	CRACKING																												
359A 221			2	2.1	1400		RIDE																												
						DGFC																													
4410581	0.000	1.346	C	2023		0012	CRACKING							8.5	8.5	8.5	8.5	8.5	10.0	10.0	9.0														
ANDERSON COLUMBIA CO., INC					(2025)		SPRIDE							7.6	7.2	7.2	7.2	7.3	8.3	8.3	7.9														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).