FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = UNION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
39010000	0.000	3.423	C	1	1	60			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	7.0	7.0	7.0														
100			2	14.1		6100			RIDE	8.1	8.6	8.6	8.4	8.3	8.3	8.5	8.5	8.3	8.3	8.3	8.3	8.2														
SE 206 PL(0.3L)									FC125A																												
4342951	0.000	3.399	C	2017		0012			CRACKING	7.0	7.0	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.0	6.0*														
V. E. WHITEHURST & SONS, I			(2018)						SPRIDE	8.2	7.9	8.1	8.0	8.7	8.7	8.6	8.6	8.5	8.4	8.3	8.3	8.3	7.9													
39010000	3.423	3.765	R	1	1	40			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	6.0*	5.5*	5.5*														
100			1	14.1		6100			RIDE	7.6	7.9	6.8	7.2	6.9	6.9	6.9	6.9	7.2	6.8	6.7	6.4	6.2														
RAMP TO SR 121(3.5R)									FC125M																												
									CRACKING	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.0	5.5*													
			(2016)						RIDE	6.2	6.4		7.0	7.4	8.0	8.0	7.9	7.9	7.8	7.9	7.9	7.1	6.7													
39010000	3.765	4.265	R	1	1	40			CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	6.0*	5.5*	5.5*														
100			1	14.1		6100			RIDE	8.0	8.4	8.2	7.8	7.8	7.7	7.9	7.8	7.7	7.7	7.4	7.3	7.3														
EPPERSON ST(4.0R)									FC125A																												
4234271	3.782	14.012	C	2016		0012			CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.7	6.5														
ANDERSON COLUMBIA CO., INC			(2017)						SPRIDE	7.1	7.1	7.1	8.2	8.2	8.0	8.0	7.9	7.9	7.8	7.9	7.9	7.9	7.5													
39010000	4.265	4.573	C	1	1	30			CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	6.0*	5.5*	5.5*														
100			2	14.1		7000			RIDE	8.0	8.4	8.2	7.8	7.8	7.7	7.9	7.8	7.7	7.7	7.4	7.3	7.3														
NE 1ST AVE/ CHURCH S(4.3R)									FC125A																												
4234271	3.782	14.012	C	2016		0012			CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	6.5														
ANDERSON COLUMBIA CO., INC			(2017)						SPRIDE	7.1	7.1	7.1	8.2	8.2	8.0	8.0	7.9	7.9	7.8	7.9	7.9	8.3	7.9													
39010000	4.573	5.048	R	1	1	30			CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.0	6.0*	5.5*	5.5*														
100			1	14.1		5000			RIDE	8.0	8.4	8.2	7.8	7.8	7.7	7.9	7.8	7.7	7.7	7.4	7.3	7.3														
NW 4TH AVE/DEKLE ST(4.6R)									FC125A																												
4234271	3.782	14.012	C	2016		0012			CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.4	5.5*														
ANDERSON COLUMBIA CO., INC			(2017)						SPRIDE	7.1	7.1	7.1	8.2	8.2	8.0	8.0	7.9	7.9	7.8	7.9	7.9	7.7	7.3													
39010000	5.048	5.338	C	1	1	40			CRACKING	3.0*	3.0*	3.0*		10.0	10.0	10.0	10.0	9.5	9.5	7.5	7.5	7.5														
100			2	14.1		5000			RIDE	7.6	7.0	6.5		8.5	8.4	8.6	8.6	8.4	8.4	8.3	8.3	8.1														
NINTH AVE SW(5.1L)									FC125A																												
4234271	3.782	14.012	C	2016		0012			CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.2	6.0*														
ANDERSON COLUMBIA CO., INC			(2017)						SPRIDE	8.1	8.1	8.1	8.2	8.2	8.0	8.0	7.9	7.9	7.8	7.9	7.9	8.1	7.7													
39010000	5.338	14.012	C	1	1	60			CRACKING	3.0*	3.0*	3.0*		10.0	10.0	10.0	10.0	9.5	9.5	7.5	7.5	7.5														
100			2	13.0		3800			RIDE	7.6	7.0	6.5		8.5	8.4	8.6	8.6	8.4	8.4	8.3	8.3	8.1														
CR 231(5.6R)									FC125A																												
4234271	3.782	14.012	C	2016		0012			CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	6.5													
ANDERSON COLUMBIA CO., INC			(2017)						SPRIDE	8.1	8.1	8.1	8.6	8.6	8.6	8.5	8.5	8.4	8.4	8.2	8.3	8.2	7.8													
39020000	0.029	0.874	C	1	1	35			CRACKING	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.0	7.0	7.0	7.0	6.0*	6.0*														
121			2	15.5		7000			RIDE	7.4	7.0	6.9	8.2	8.0	8.1	8.3	8.3	8.1	8.1	8.0	7.9	7.8														
SW 33 TRL(0.3R)									FC125M																												
4323071	0.029	8.600	C	2016		0012			CRACKING	6.0*	6.0*	4.5*	10.0	10.0	10.0	10.0	9.5	9.5	9.0	9.0	8.3	7.8	5.5*													
V. E. WHITEHURST & SONS, I			(2017)						SPRIDE	7.8	7.7	7.5	8.4	8.5	8.4	8.4	8.3	8.2	8.3	8.2	8.2	8.1	7.7													
39020000	0.874	2.300	C	1	1	50			CRACKING	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.0	7.0	7.0	7.0	6.0*	6.0*														
121			2	15.5		7000			RIDE	7.4	7.0	6.9	8.2	8.0	8.1	8.3	8.3	8.1	8.1	8.0	7.9	7.8														
LITTLE SPRINGS RD(1.1R)									FC125M																												
4323071	0.029	8.600	C	2016		0012			CRACKING	6.0*	6.0*	4.5*	10.0	10.0	10.0	10.0	9.5	9.5	9.0	9.0	8.3	7.4	5.5*													
V. E. WHITEHURST & SONS, I			(2017)						SPRIDE	7.8	7.7	7.5	8.4	8.5	8.4	8.4	8.3	8.2	8.3	8.2	8.2	8.2	7.8													
39020000	2.300	8.600	C	1	1	60			CRACKING	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.0	7.0	7.0	7.0	6.0*	6.0*														
121			2	15.5		7000			RIDE	7.4	7.0	6.9	8.2	8.0	8.1	8.3	8.3	8.1	8.1	8.0	7.9	7.8														
SW 50 ST(2.4R)									FC125M																												
4323071	0.029	8.600	C	2016		0012			CRACKING	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	8.4	8.0	6.0*													
V. E. WHITEHURST & SONS, I			(2017)						SPRIDE	7.8	7.7	8.0	8.4	8.5	8.5	8.5	8.5	8.5	8.5	8.4	8.5	8.4	8.0													
39020000	8.600	10.367	R	1	1	35			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.0	7.0	7.0	6.0*	6.0*	6.0*														
121			1	15.5		7700			RIDE	8.2	8.3	8.1	7.8	7.4	7.4	7.4	7.1	7.0	6.8	6.7	6.7	6.7														
SR 231(8.9C)									FC125M																												
4305581	8.613	10.356	R	2015		0012			CRACKING	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	8.0	7.0	4.5*													
PREFERRED MATERIALS, INC.			(2016)						SPRIDE	6.5	6.8	8.6	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.4	8.4	7.9	7.5													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 2 COUNTY = UNION ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	AADT / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
39020000 121 SB OFF(10.4L) 4305581 PREFERRED MATERIALS, INC. (2016)	10.367 2 17.4 10.356	23.410 16.560	C C 2015	1	1	60 6600 FC125M 0012	CRACKING RIDE CRACKING SPRIDE		10.0 8.8 8.5 8.4	10.0 8.8 8.5 8.4	10.0 8.6 10.0 8.6	10.0 8.6 10.0 8.5	10.0 8.3 10.0 8.5	10.0 8.7 10.0 8.5	10.0 8.7 9.5 8.5	10.0 8.6 9.5 8.5	10.0 8.6 8.5 8.5	10.0 8.5 8.5 8.4	9.5 8.5 8.0 8.4	9.5 8.5 7.5 8.5	9.5 8.5 5.0* 8.1
39040000 16 S.R. 121(0.0C) 2109492 ANDERSON COLUMBIA CO., INC(2008) 4382122	0.000 2 9.7 0.000 0.000	2.605 1.770 2.605	C C 2007 C 2029	1	1	45 2900 FC125M 0012 0012	CRACKING RIDE CRACKING RIDE	6.0* 8.0 9.0 8.0	5.5* 8.0 8.0 7.9	5.5* 7.4 8.0 7.8	5.5* 6.6 8.0 7.7	3.5* 6.1* 8.0 7.8	3.5* 5.9 7.5 7.7	1.0* 6.0 7.5 7.6	10.0 8.4 7.5 7.6	10.0 8.2 6.5 7.5	10.0 8.1 4.5* 7.5	10.0 8.2 4.5* 7.3	10.0 8.0 4.6* 7.2	9.0 8.0 4.3* 7.2	1.0* 6.8
39050000 238 31ST LN SW(0.2R) 2109553 ANDERSON COLUMBIA CO., INC(2011) 2109554	0.000 2 10.3 0.000 0.000	13.850 13.887 13.983	C C 2010 C 2029	1	1	60 3300 FC125M 0012 0012	CRACKING RIDE CRACKING RIDE	10.0 8.2 8.5 8.0	9.5 8.7 8.5 7.7	9.5 8.7 8.5 7.7	9.5 8.3 8.5 7.4	9.5 8.2 8.5 7.6	7.0 8.1 7.5 7.5	6.5 8.0 7.5 7.5	6.5 7.8 7.0 7.4	6.5 7.5 6.5 7.3	10.0 7.4 6.0* 7.2	10.0 8.6 6.0* 7.2	10.0 8.3 4.8* 7.2	8.2 4.3* 7.1	1.5* 6.7
39050000 238 SR 231(13.9R) 2109554	13.850 2 10.3 (2010) 0.000	13.986 13.983	C C 2029	1	1	35 6000 UNKW 0012	CRACKING RIDE CRACKING RIDE	10.0 5.9* 10.0	10.0 5.7 10.0	10.0 6.1 10.0	9.5 5.4* 10.0	8.0 4.3* 10.0	8.0 4.8* 10.0	6.5 4.9* 10.0	6.5 4.6* 8.5	6.5 3.9* 8.5	10.0 7.0 7.5	10.0 6.5	10.0 6.5	10.0 6.5 6.5	3.5* 6.1
39070000 18 SR 121(0.0C) 2109622 ANDERSON COLUMBIA CO., INC(2009)	0.000 2 8.0 0.000	0.892 0.892	C C 2007	1	1	40 900 FC125 0221	CRACKING RIDE CRACKING SPRIDE	5.5* 7.2 10.0 7.5	5.5* 6.8 10.0 7.2	5.5* 6.1 10.0 7.4	5.5* 6.1 10.0 7.0	3.5* 6.5 10.0 6.6	3.5* 6.3 10.0 6.9	3.5* 6.4 10.0 6.7	1.0* 6.5 8.5 6.3	10.0 8.0 7.5 6.2	10.0 8.0 7.0 6.1	10.0 8.0 7.5 6.3	10.0 7.6 7.2 6.1	10.0 7.8 6.8 6.2	3.5* 5.8
39090000 231 SW 73 ST(0.0L) 2109522 V. E. WHITEHURST & SONS, I(2010) 2109555	0.000 2 2.8 0.000 0.000	2.739 2.739 2.739	C C 2008 C 2028	1	1	55 4200 FC125M 0012 0012	CRACKING RIDE CRACKING RIDE	7.0 8.5 10.0 7.5	7.0 8.5 9.0 7.4	7.0 8.4 9.0 7.1	7.0 8.1 8.5 6.9	7.0 7.8 8.5 6.9	7.0 7.8 8.0 6.3*	6.5 8.0 8.0 6.3*	3.5* 7.8 7.0 6.2*	3.5* 7.7 6.5 6.0*	10.0 8.0 6.0* 5.7*	10.0 8.0 6.0* 5.8*	10.0 7.7 5.0* 5.7*	10.0 7.6 4.6* 5.9*	1.5* 5.5*

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).