FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP SPD / AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46001000	0.000	3.576	R	1	1 45	CRACKING	6.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0																
368			2	2.9	30000	RIDE	7.1		8.1	7.9	7.8	7.7	7.7	7.8	7.7	7.2	7.5	7.3	7.3																
BECK AVE(0.0R)					FC125																															
2179851	0.000	2.900	C	2001	0012	CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	7.0	4.5*																
GRANGER ASPHALT PAVING INC(2003)					SPRIDE		7.2	7.4	7.4	7.4	7.0	7.2	7.3	7.2	7.2	7.1	7.1	7.0	7.1	6.7																
4508181	0.098	3.567	C	2026	0012																															
46001000	0.000	3.576	L	1	2 45	CRACKING	6.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0																
368			2	2.9	30000	RIDE	7.1		8.3	7.6	7.8	7.6	7.7	7.8	7.8	7.7	7.6	7.4	7.4																
ST ANDREWS BLVD(0.0L)					FC125																															
2179851	0.000	2.900	C	2001	0012	CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	6.8	4.5*																
GRANGER ASPHALT PAVING INC(2003)					SPRIDE		7.4	7.4	7.4	7.4	7.3	7.3	7.3	7.3	7.2	7.1	7.1	7.1	7.1	6.7																
4508181	0.098	3.567	C	2026	0012																															
46002000	1.001	1.590	C	1	1 35	CRACKING	9.0	7.0	7.0	7.0	6.5	6.5	6.5	4.5*	10.0	10.0	10.0	10.0	8.5																	
327			2	2.3	3900	RIDE	6.9	7.0	6.4	6.3	5.8	5.1*	5.2*	5.3*	7.6	7.3	7.3	7.1	7.3																
SR 368(1.0C)					FC95M																															
4134281	1.019	1.513	C	2008	0012	CRACKING	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	7.0	5.0*																
ANDERSON COLUMBIA CO., INC(2009)						RIDE	7.1	7.2	7.0	6.9	6.9	6.6	6.9	6.2	6.6	6.4	6.3	6.2	5.7	5.3*																
4508181	1.007	1.552	C	2026	0012																															
46003000	0.000	3.423	C	1	1 45	CRACKING																														
28			2	7.9	8600	RIDE																														
					DGFC																															
						CRACKING																														
		(2023)				RIDE																														
46010000	0.000	0.451	R	1	1 45	CRACKING	10.0	10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
30 98			2	5.3	28000	RIDE	8.7	8.7	8.7		8.4	8.0	8.2	8.3	8.3	8.3	8.3	8.3	8.3																
					FC5M																															
4377591	0.000	0.451	R	2021	0012	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	6.5	6.5	6.5	4.5*	10.0	10.0	8.5																
ANDERSON COLUMBIA CO., INC(2025)					SPRIDE		8.2	8.2	8.2	8.2	8.1	8.1	8.1	8.2	8.0	8.1	8.0	8.5	8.5	8.3																
46010000	0.850	1.106	R	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																	
30 98			2	5.3	28000	RIDE	8.7	8.6	8.5	7.8	7.7	7.8	7.8	7.9	7.9	7.8	7.9	7.9	7.8																	
					FC5M																															
4377591	0.850	1.106	R	2021	0012	CRACKING	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	4.5*	4.5*	3.5*	10.0	10.0	8.5																
ANDERSON COLUMBIA CO., INC(2025)						RIDE	7.8	7.7	7.8	7.8	7.8	7.8	7.9	7.7	7.7	7.6	7.5	8.4	8.6	8.4																
46010000	9.178	10.408	C	1	1 35	CRACKING	5.5*	5.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.5	8.5	8.5																	
30			2	3.4	12500	RIDE	7.7	7.6	7.4	6.4	6.4	6.0	7.4	7.6	7.0	6.9	6.9	6.8	6.8																
YOUNG ST(9.4L)					DGFC																															
4063191	7.253	13.743	C	2005	0012	CRACKING	8.5	8.5	7.5	6.0*	6.0*	6.0*	3.5*	3.5*	3.5*	3.5*	6.0*	6.3*	6.1*	4.0*																
ANDERSON COLUMBIA CO., INC(2007)						RIDE	6.7	6.7	6.5	6.5	6.3	6.2	6.2	6.0	5.8	5.7	5.9	5.8	5.7	5.3*																
46010000	10.649	12.370	C	1	1 35	CRACKING	5.5*	5.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	8.5	8.5	8.5	8.5																	
30			2	3.4	12000	RIDE	7.7	7.6	7.4	6.4	6.4	6.0	7.4	8.0	7.7	7.7	7.7	7.0	7.6																
AZALEA ST(10.6L)					DGFC																															
4063191	7.253	13.743	C	2005	0012	CRACKING	7.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	6.0*	6.6	6.4*	4.5*																
ANDERSON COLUMBIA CO., INC(2007)						RIDE	7.5	7.5	7.4	7.6	7.6	7.1	7.0	7.0	6.8	6.8	6.7	6.6	6.4	6.0																
46010000	13.694	15.769	R	1	1 45	CRACKING	8.5	7.0	5.0*	5.0*	5.0*	5.0*	5.0*	5.0*	5.0*	10.0	10.0	10.0	10.0																	
30			2	3.4	30000	RIDE	8.0	7.9	7.8	7.5	7.2	6.9	7.3	7.3	7.3	8.4	8.3	8.3	8.2																
RAMP FROM THOMAS DR(13.7R)					FC125M																															
4090231	13.743	15.554	C	2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.9	7.6	5.5*																
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE		8.2	8.2	8.0	8.0	7.7	7.8	7.8	7.7	7.7	7.7	7.7	7.4	7.6	7.2																
46010000	13.694	15.769	L	1	1 45	CRACKING	8.5	7.5	7.0	7.0	5.0*	5.0*	5.0*	5.0*	5.0*	10.0	10.0	10.0	10.0																	
30			2	3.4	30000	RIDE	7.9	7.6	7.7	6.9	6.6	6.4	6.4	6.7	6.7	8.3	8.3	8.2	8.1																
FLAGG AVE(13.8L)					FC125M																															
4090231	13.743	15.554	C	2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	7.0	7.0	7.5	7.3	5.5*																
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE		8.2	8.1	8.0	8.1	8.0	8.0	7.9	7.9	7.8	7.8	7.6	7.7	7.7	7.3																
46010000	0.836	1.106	L	1	1 45	CRACKING	10.0	10.0	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																	
30 98			2	5.3	28000	RIDE	8.4	8.7	8.5	7.7	6.9	7.9	8.2	8.2	8.2	8.2	8.2	8.1	8.1																
					FC5M																															
4377591	0.836	1.106	L	2021	0012	CRACKING	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	6.5	6.5	6.0*	10.0	10.0	8.5																
ANDERSON COLUMBIA CO., INC(2025)						RIDE	8.1	8.1	8.2	8.2	8.1	8.3	8.2	8.2	8.2	8.0	8.0	8.6	8.7	8.5																

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN / %T / FY-P / FY-F	AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46010000	0.000	0.451	L	2	1	1	1	45	CRACKING	10.0	10.0	8.5		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.5													
30 98			2	5.3				28000	RIDE	9.1	9.0	8.9		8.4	8.1	8.2	8.3	8.2	8.2	8.4	8.3	8.3													
								FC5M																											
4377591	0.000	0.451	L	2021				0012	CRACKING	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	8.5													
ANDERSON COLUMBIA CO., INC				(2025)					SPRIDE	8.2	8.2	8.2	8.2	8.1	8.1	8.1	8.1	8.1	7.9	7.9	8.5	8.7	8.5												
46010001	0.000	0.440	R	2	1	1	1	45	CRACKING	9.0	9.0	6.5	6.5	6.5	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.5													
30 98			2	5.3				28000	RIDE	8.1	8.0	7.1	6.9	6.1*	7.7	7.2	7.9	7.9	7.5	7.5	7.4	7.4													
SR 30(0.0C)								FC5M																											
4377591	0.000	0.440	R	2021				0012	CRACKING	8.5	9.0	8.0	8.0	8.0	6.5	6.5	6.5	6.5	6.5	5.5*	10.0	10.0	8.5												
ANDERSON COLUMBIA CO., INC				(2025)					RIDE	7.4	7.9	8.0	8.1	8.0	8.0	8.1	7.8	7.9	8.0	7.9	8.8	8.7	8.5												
46010001	0.000	0.440	L	2	1	1	1	45	CRACKING	9.0	9.0	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5													
30 98			2	5.3				28000	RIDE	7.6	7.3	7.5	6.7	6.0*	7.5	6.7	8.2	8.2	7.7	7.8	7.6	7.5													
SR 30(0.0C)								FC5M																											
4377591	0.000	0.440	L	2021				0012	CRACKING	8.5	8.5	8.5	8.5	8.5	6.5	6.5	6.5	5.5*	5.5*	3.5*	10.0	10.0	8.5												
ANDERSON COLUMBIA CO., INC				(2025)					RIDE	7.5	7.9	8.0	7.3	7.7	7.9	7.9	7.9	7.8	7.8	7.7	8.9	8.8	8.6												
46010002	0.166	3.283	R	2	1	8	1	45	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	8.5	7.0													
392A			2	3.9				10400	RIDE	7.3	8.7	8.5	8.1	8.1	7.6	7.9	8.1	7.8	7.8	7.8	7.7	7.6													
AZALEA ST(0.2C)								FC125																											
2179861	0.135	3.265	C	2001				0012	CRACKING	6.5	6.5	6.5	6.0*	6.0*	5.5*	5.5*	5.5*	5.5*	5.5*	5.5*	3.5*														
ANDERSON COLUMBIA CO., INC				(2002)					SPRIDE	7.4	7.2	7.3	7.3	7.1	7.1	7.1	7.1	6.8	6.7	6.6	6.5														
2179862	0.153	3.222	C	2022				0012																											
46010002	0.166	3.283	L	2	1	8	1	45	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	8.5	8.5													
392A			2	3.9				10400	RIDE	7.2	8.1	8.5	8.1	8.0	7.5	7.7	7.8	7.7	7.7	7.7	7.5	7.2													
LANTANA ST(0.2L)								FC125																											
2179861	0.135	3.265	C	2001				0012	CRACKING	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*	5.5*	5.5*	5.5*	5.5*	3.5*														
ANDERSON COLUMBIA CO., INC				(2002)					SPRIDE	7.2	7.1	7.1	7.0	6.8	6.8	6.9	6.7	6.6	6.6	6.5	6.5														
2179862	0.153	3.222	C	2022				0012																											
46010005	0.000	0.254	C	2	1	1	1	35	CRACKING								10.0	10.0	10.0	10.0	8.5	8.5													
30			2	3.9				10400	RIDE								6.9																		
CRANE ST(0.0L)								DGFC																											
									CRACKING	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.1	7.0	5.0*												
				(2008)					RIDE													5.3*	4.9*												
46010100	0.000	0.243	R	2	1	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0													
30			2	5.2				19800	RIDE																										
BULLNOSE OF 46160104(0.0C)								FC125																											
									CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	3.8*	1.5*												
				(2008)					RIDE													7.3	6.9												
46010100	0.725	1.208	R	2	1	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0													
30 98			2	5.4				69029	RIDE								8.4	7.7	8.5	8.5	8.5	8.4													
RAMP FROM FRONT BCH(0.9R)								FC125																											
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.3	8.3	6.5												
				(2010)					RIDE	8.4	8.4	8.2	8.1	8.0	8.0	8.1	8.0	8.0	7.6	7.7	7.6	7.8	7.4												
2178385	0.737	1.214	R	2026				0213																											
46010100	1.849	1.953	R	1	1	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0													
30 98			4	5.4				69029	RIDE										8.4	8.5	8.4	8.2													
BULLNOSE OF BRIDGE(2.0C)								FC95M																											
2179763	1.856	1.953	C	2015				0213	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5												
SUPERIOR CONSTRUCTION COMP				(2021)					SPRIDE	8.4	8.2	8.1	8.1	7.9	7.8	7.7	8.4	8.5				8.1	7.7												
46010100	1.885	1.953	L	1	1	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0													
30 98			4	5.4				69029	RIDE											8.5															
BULLNOSE OF BRIDGE(2.0C)								FC95M																											
2179763	1.856	1.953	C	2015				0213	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.7	10.0	8.5												
SUPERIOR CONSTRUCTION COMP				(2021)					SPRIDE													7.3	6.9												
46010100	0.320	1.169	L	1	1	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0													
30 98			4	5.4				69029	RIDE								8.3	7.8	7.5	7.6	7.9	7.9													
CR 3031(0.4L)								FC125																											
									CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	7.5	7.0	7.0	7.0	8.0	6.8	6.5	4.5*												
				(2008)					RIDE	7.9	7.8	7.9	7.8	7.7	7.5	7.6	7.5	7.6	7.6	7.6	7.7	7.8	7.4												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 3 COUNTY = BAY

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / FY-P / FY-F	AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46010100 30 98 UNSIGNED(0.0L)	0.000 2	0.320 5.2	L	1	1	45 19800 FC125			CRACKING RIDE														10.0 8.3	10.0 7.8	10.0 7.5	10.0 7.6	10.0 7.9	10.0 7.9							
								(2008)	CRACKING RIDE	9.5 7.9	9.5 7.8	9.5 7.9	9.5 7.8	9.5 7.7	9.5 7.5	7.5 7.6	7.0 7.5	7.0 7.6	7.0 7.6	6.0* 6.9	4.5* 7.0	3.5* 6.8	1.5* 6.4											
46020000 30 98 N BAY RD(0.8R)	0.742 3	1.703 4.8	R	1	1	45 41500 FC95MR			CRACKING RIDE	10.0 8.4	10.0 8.2	10.0 8.1	10.0 7.7	10.0 7.4	8.5 7.0	8.5 7.2	9.0 7.3	7.0 7.1	10.0 8.2	10.0 8.0	10.0 7.7	10.0 7.7												
								(2022)	CRACKING RIDE	10.0 7.5	10.0 7.5	10.0 6.9	9.0 6.7					10.0 7.5	10.0 7.1	10.0 7.1	9.1 7.1	10.0 7.4	8.5 7.0										
46020000 30 98 DANFORD AVE(1.9C) 4169171 GAC CONTRACTORS, INC 4475941	1.703 2 1.263 (2010) 1.735	2.950 4.8 2.962 3.004	R C C	1 2009 2024	8 SP 0012	45 41500 FC95M 0012 0012			CRACKING RIDE CRACKING RIDE	10.0 8.4 10.0 7.8	10.0 8.2 10.0 7.8	10.0 8.1 10.0 7.8	10.0 7.7 10.0 7.8	10.0 7.4 10.0 7.8	8.5 7.0 9.0 7.7	8.5 7.2 8.5 7.7	9.0 7.3 7.5 7.6	7.0 7.1 7.0 7.5	10.0 8.2 7.0 7.3	10.0 8.2 7.0 7.4	10.0 8.0 7.0 7.2	10.0 8.2													
46020000 30 98 BECK AVE(3.0L) 4373681	2.950 2 3.676 (2023)	6.016 4.0 5.928	C C	1 2022	1 0012	35 11500 FC125M			CRACKING RIDE CRACKING RIDE	3.5* 6.5 6.5 6.7	3.5* 6.4 6.0* 6.6	0.0* 6.3 6.0* 6.5	3.0*	3.0*	10.0 7.6 3.0* 6.2	10.0 7.6 3.0* 6.2	8.5 7.7 3.0* 5.9	7.0 7.3 3.0* 5.8	7.0 7.4 3.0* 7.0	7.0 7.1 10.0 6.8	7.0 6.7 10.0 6.9	7.0 6.8 9.5 6.9	8.0 6.5											
46020000 30 MULBERRY AVE(6.1C) 4373681	6.016 2 6.002 (2023)	6.266 4.0 6.326	R R	1 2022	1 0012	35 12300 FC125M			CRACKING RIDE CRACKING RIDE	3.5* 5.6* 6.5 5.2*	3.5* 5.5 6.0* 5.0*	0.0* 5.3* 6.0* 4.7*	3.0* 4.4*	3.0* 4.1*	10.0 6.7 3.0* 4.1*	8.5 6.3 3.0* 4.1*	8.5 5.5 3.0* 4.0*	7.0 6.0 3.0* 4.0*	7.0 5.8 3.0* 5.2*	7.0 5.5 10.0 5.2*	7.0 5.5 10.0 4.7*	7.0 5.6 9.5 4.9*	8.0 4.5*											
46020000 30 B98 GRACE AV(6.3C) 4287381 ANDERSON COLUMBIA CO., INC(2016) 4546401	6.266 2 6.446 6.326	6.739 5.9 6.747 13.285	R R C	1 2015 2028	1 0012 0012	35 13800 FC95MR			CRACKING RIDE CRACKING RIDE	3.5* 5.6* 6.5 5.2*	3.5* 5.5 6.0* 5.0*	0.0* 5.3* 10.0	10.0	10.0	10.0 6.7 10.0	8.5 6.3 8.5	8.5 5.5 7.5	7.0 6.0 7.0	7.0 5.8 7.0	7.0 5.5 7.0	7.0 5.5 6.5	7.0 5.6 7.0 5.4*	5.5* 5.0*											
46020000 30 B98 MASSALINA AVE R(6.8R) 4546401	6.739 4 6.326	9.628 4.4 13.285	C C	1 2028	1 0012	35 20200 FC95MR			CRACKING RIDE CRACKING RIDE	10.0 8.5 6.0* 5.9	10.0 8.4 6.0* 5.7	8.5 7.7 10.0 7.7	8.5 7.7 10.0 7.7	8.5 7.5 10.0 7.5	8.5 7.4 10.0 7.4	8.5 7.4 8.5 7.3	8.5 6.9 7.5 7.1	7.0 6.7 7.0 6.9	7.0 6.6 7.0 6.6	7.0 6.2 7.0 6.6	7.0 5.8 7.2 6.6	7.0 5.4* 6.8 6.7	5.0* 6.3											
46020000 30 B98 MILLER CT(9.9L) 4287381 ANDERSON COLUMBIA CO., INC(2016) 4546401	9.628 2 10.193 6.326	12.177 7.5 11.382 13.285	C C C	1 2015 2028	1 0012 0012	35 9100 FC95MR			CRACKING RIDE CRACKING RIDE	6.0* 7.1	10.0 8.6 5.5* 6.9	10.0 8.5 10.0 8.6	10.0 8.1 10.0 8.5	10.0 8.0 10.0 8.3	10.0 7.8 9.0 8.3	10.0 7.8 8.5 8.3	8.0 7.8 7.0 8.1	7.0 7.8 7.0 8.0	7.0 7.7 7.0 7.9	7.0 7.6 7.0 7.7	7.0 7.4 7.1 7.6	7.0 7.2 6.8 7.6	5.0* 7.2											
46020000 30 98 R V PARK(12.3R) 4134291 ANDERSON COLUMBIA CO., INC(2009) 4546401	12.177 2 12.172 6.326	13.694 6.8 13.694 13.285	R C C	1 2007 2028	1 0012 0012	45 24000 FC95M			CRACKING RIDE CRACKING RIDE	7.0 8.2 8.5 8.4	6.5 8.2 8.5 8.2	4.5* 8.2 8.5 8.2	3.5* 7.5 8.5 8.1	3.5* 7.4 8.5 8.2	3.5* 7.0 8.5 8.0	3.5* 7.1 8.5 8.0	1.0* 7.1 7.0 7.8	10.0 8.6 7.0 7.8	10.0 8.5 7.0 7.7	10.0 8.6 7.0 7.5	10.0 8.5 7.2 7.4	10.0 8.4 6.9 7.4	5.0* 7.0											
46020000 30 98 WALLACE RD(12.3L) 4134291 ANDERSON COLUMBIA CO., INC(2009) 4546401	12.177 2 12.172 6.326	13.694 6.8 13.694 13.285	L C C	1 2007 2028	1 0012 0012	45 24000 FC95M			CRACKING RIDE CRACKING RIDE	8.5 8.0 9.5 8.3	7.0 8.1 9.5 8.2	5.5* 7.9 9.5 8.2	5.5* 7.2 9.5 8.1	5.5* 6.9 9.5 7.9	5.5* 6.8 8.5 8.1	3.5* 6.8 8.5 8.0	3.5* 7.2 7.0 8.0	10.0 8.6 7.0 7.9	10.0 8.6 7.0 7.8	10.0 8.6 8.0 7.7	10.0 8.5 7.6 7.6	10.0 8.4 7.2 7.6	5.0* 7.2											
46020000 30 98 BALTIMORE AVE(1.8L) 4169171 GAC CONTRACTORS, INC 4475941	1.703 2 1.263 (2010) 1.735	2.950 4.8 2.962 3.004	L C C	1 2009 2024	8 SP 0012	45 41500 FC95M 0012 0012			CRACKING RIDE CRACKING RIDE	10.0 8.4 10.0 8.1	10.0 8.4 10.0 7.7	10.0 8.2 10.0 8.0	10.0 7.8 10.0 7.9	10.0 7.4 10.0 7.6	10.0 7.0 9.0 7.9	10.0 6.7 9.0 7.8	9.5 7.3 7.5 7.7	7.5 7.2 7.0 7.7	10.0 8.0 7.0 7.4	10.0 8.3 7.0 7.6	10.0 8.2 7.0 7.6	10.0 8.0 7.5											

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN / %T / RW / FY-P / FY-F	AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46020000	0.742	1.703	L	1	1	45	1		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	7.5	10.0	10.0	10.0	10.0													
30 98							2 4.8	41500	RIDE	8.4	8.4	8.2	7.8	7.4	7.0	6.7	7.3	7.2	8.3	7.9	7.9	7.9													
COLLEGIATE DR(1.1L)								FC95MR																											
									CRACKING	10.0	10.0	10.0	10.0					10.0	10.0	10.0	9.1	10.0	8.5												
							(2022)		RIDE	7.7	7.7	7.4	7.2					7.6	7.6	7.5	7.5	7.5	7.1												
46020003	0.000	2.347	R	1	8	45			CRACKING	7.5	7.0	7.0	6.0*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	9.0													
30A 98							2 4.7	37500	RIDE	6.8	7.5	6.7	6.2*	6.1*	5.9	5.4*	8.2	8.1	8.2	8.3	8.0	8.0													
US BUS 98/SR-30(0.0R)								FC95M																											
4114011	0.000	2.375	C	2006		0012			CRACKING	9.0	9.0	9.0	8.5	8.5	7.0	6.5	6.0*	6.0*	6.0*	6.0*	5.5*														
ANDERSON COLUMBIA CO., INC(2008)									RIDE	7.9	7.9	7.6	7.4	7.4	7.4	7.4	7.3	7.2	6.8	7.1	6.9														
4475941	0.000	2.408	C	2024		0012																													
46020003	2.347	4.695	R	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.5	5.5*													
30A 98							2 7.8	28000	RIDE	8.8	8.7	8.2	7.5	7.6	7.3	7.4	7.1	7.1	7.2	6.7	6.7	6.3													
JENKS AVE(2.4C)								FC95MR																											
4307771	2.480	4.695	C	2015		0012			CRACKING	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.1	7.6	6.0*												
ANDERSON COLUMBIA CO., INC(2017)									RIDE	6.5	6.3	6.6	8.2	7.9	8.1	8.1	8.0	7.9	7.5	7.6	7.5	7.4	7.0												
46020003	4.695	5.721	R	1	1	45			CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	10.0	10.0	10.0	10.0													
30A 98							2 7.8	27500	RIDE	8.2	8.6	8.3	8.2	8.0	7.8	7.8	7.8	7.8	8.5	8.5	7.8	8.2													
KRAFT AVE(4.8R)								FC125M																											
4134321	4.630	5.783	C	2009		0012			CRACKING	10.0	10.0	10.0	9.5	9.5	9.0	9.0	7.5	7.5	7.5	8.0	8.5	8.1	6.0*												
ANDERSON COLUMBIA CO., INC(2010)						SP			RIDE	7.8	7.7	8.2	8.3	8.1	8.1	7.9	7.8	7.6	7.5	7.5	7.5	7.3	6.9												
46020003	5.721	9.813	R	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.5	7.5													
30A 98							2 5.4	33500	RIDE	8.8	8.6	8.7	8.3	8.0	7.8	7.9	8.2	7.9	7.8	7.7	7.7	7.8													
DAVID AVE(5.8R)								FC95MR																											
4288441	5.721	9.813	R	2018		0012			CRACKING	7.5	7.0	6.0*	3.5*	3.5*			10.0	10.0	10.0	9.0	8.6	8.4	7.0												
ROBERTS AND ROBERTS, INC. (2021)									RIDE	7.5	7.7	7.7	7.7	7.6			8.3	8.2	8.1	8.1	8.0	8.0	7.6												
46020003	5.721	9.813	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5													
30A 98							2 5.4	33500	RIDE	8.6	8.6	8.5	8.2	8.0	7.9	7.9	8.0	8.0	8.0	7.9	7.7	7.6	7.5												
SPRING GATE DR(6.3L)								FC95MR																											
4288441	5.721	9.813	L	2018		0012			CRACKING	7.0	7.0	6.0*	3.5*	3.5*			10.0	10.0	10.0	10.0	8.7	8.6	7.0												
ROBERTS AND ROBERTS, INC. (2021)									RIDE	7.5	7.6	7.6	7.6	7.6			8.4	8.4	8.3	8.2	8.2	8.2	7.8												
46020003	4.695	5.721	L	1	1	45			CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	10.0	10.0	10.0	10.0													
30A 98							2 7.8	27500	RIDE	8.1	8.4	8.3	7.7	7.7	7.2	7.1	7.3	7.3	8.4	8.0	8.2	8.2													
JAMES AVE L(4.7L)								FC125M																											
4134321	4.630	5.783	C	2009		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.0	8.0	8.3	7.9	6.0*												
ANDERSON COLUMBIA CO., INC(2010)						SP			RIDE	8.1	8.2	8.2	8.1	8.0	8.1	8.0	7.8	7.7	7.7	7.7	7.6	7.5	7.1												
46020003	2.347	4.695	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.5	7.5	5.5*													
30A 98							2 7.8	28000	RIDE	8.7	8.7	8.0	7.3	7.5	7.1	7.1	7.0	6.5	6.6	6.4	6.2	6.1													
OAK AVE(2.4L)								FC95MR																											
4307771	2.480	4.695	C	2015		0012			CRACKING	5.5*	5.5*	4.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.7	7.0	5.5*												
ANDERSON COLUMBIA CO., INC(2017)									RIDE	6.3	6.2	6.4	8.1	7.9	7.9	8.0	7.9	7.8	7.4	7.6	7.3	7.4	7.0												
46020003	0.000	2.347	L	1	8	45			CRACKING	7.5	7.5	7.0	7.0	6.5	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	9.0													
30A 98							2 4.7	37500	RIDE	7.1	6.9	6.7	5.8*	5.6*	5.3*	4.9*	7.6	8.1	8.0	7.9	7.8	7.5													
SR-390/BECK AVE(0.0L)								FC95M																											
4114011	0.000	2.375	C	2006		0012			CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	6.0*	6.0*	6.0*	6.0*	4.6*														
ANDERSON COLUMBIA CO., INC(2008)									RIDE	7.5	7.2	7.6	7.7	7.4	7.4	7.5	7.1	7.1	6.8	6.8	6.6														
4475941	0.000	2.408	C	2024		0012																													
46020100	0.000	0.451	C	1	1				CRACKING																											
384							1 4.7	800	RIDE																											
								FC95MR																												
									CRACKING													10.0	10.0	9.2	10.0	8.5									
							(2023)		RIDE															5.9*	5.9*	5.5*									
46020200	0.000	0.451	C	1	1				CRACKING																											
384							1 4.7	750	RIDE																											
								FC95MR																												
									CRACKING													10.0	10.0	8.8	8.6	7.0									
							(2023)		RIDE															6.6	6.2*	5.8*									

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP SPD / AADT / WKMX-P / WKMX-F	DISTRESS RATINGS / SURFTYPE / ASTYPE	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46020400	0.000	0.043	C	1	1	CRACKING																														
385			4	8.8	3000	RIDE																														
						CRACKING																														
				(2023)		RIDE																													5.3*	4.9*
46030000	0.000	1.956	R	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	7.0	7.0	7.0	7.0	7.0	6.0*																
30 98			2	6.8	24000	RIDE		8.6	8.6	8.3	8.2	8.0	7.9	8.1	8.1	7.9	7.9	7.7	7.6																
BRIDGE #19(0.0C)					FC5M																															
4269501	0.330	1.956	R	2017	0012	CRACKING	6.0*	6.0*	6.0*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	8.7	8.5	6.0*															
ANDERSON COLUMBIA CO., INC				(2019)		RIDE	7.6	7.5	7.4	7.3		8.5	8.5	8.5	8.5	8.4	8.3	8.4	8.4	8.2													
46030000	1.956	2.539	R	1	7 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	7.0	7.0	7.0	7.0	7.0	6.0*																
30 98			3	6.8	24000	RIDE		8.6	8.6	8.3	8.2	8.0	7.9	8.1	8.1	7.9	7.9	7.7	7.6																
					FC1																															
						CRACKING	6.0*	6.0*	6.0*	5.5*		3.0*	3.0*						10.0	8.5																
				(2026)		RIDE	7.6	7.5	7.4	7.3		6.9	7.1						8.2	7.8																
46030000	2.539	3.291	C	1	7 45	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			2	15.0	7000	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
TYNDALL DR(2.7C)					FC3																															
						CRACKING	7.0	7.0	6.0*	6.0*		6.0*	6.0*						10.0	8.5																
				(2026)		RIDE	7.5	7.4	7.6	7.5		7.5	7.4						8.5	8.1																
46030000	3.291	3.846	R	1	1 45	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			1	15.0	7000	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
OHIO AVE(3.8R)					FC95MR																															
						CRACKING	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0		10.0	10.0	8.5																
				(2025)		RIDE	7.5	7.4	7.6	7.5		8.5	8.5	8.4	8.4	8.4		7.6	7.8	7.4																
46030000	3.846	14.763	C	1	1 60	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			2	15.0	7000	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
AMMO RD(4.7L)					FC95MR																															
4269501	4.776	15.316	C	2017	0012	CRACKING	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.1	7.5															
ANDERSON COLUMBIA CO., INC				(2019)		RIDE	7.5	7.4	7.6	7.5		8.5	8.5	8.4	8.4	8.4	8.3	8.3	8.1	7.7															
46030000	14.763	15.555	R	1	7 35	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			1	15.0	7000	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
CANAL PKWY(15.4R)					FC95MR																															
4269502	14.748	15.316	C	2024	0012	CRACKING	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5															
C. W. ROBERTS CONTRACTING,				(2026)		SPRIDE	7.5	7.4	7.6	7.5		8.5	8.5	8.4	8.4	8.4	8.3	8.3	8.1	7.7															
46030000	15.555	18.433	C	1	7 35	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			2	6.6	7600	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
39TH ST(15.6R)					FC95MR																															
4269502	15.425	18.431	C	2024	0012	CRACKING	7.0	7.0	6.0*	6.0*	6.0*	10.0		9.0	9.0	9.0	9.0	9.0	10.0	8.5															
C. W. ROBERTS CONTRACTING,				(2026)		SPRIDE	7.5	7.4	7.6	7.5	7.5	8.4		7.9	7.9	7.8	7.8	7.8	8.0	7.6															
46030000	3.291	3.846	L	1	1 45	CRACKING	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	7.0																
30 98			2	15.0	7000	RIDE	8.7	8.7	8.7	8.3	8.1	8.0	8.0	8.1	8.0	8.0	7.9	7.8	7.7																
					FC95MR																															
						CRACKING	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0		10.0	10.0	8.5																
				(2025)		RIDE	7.5	7.4	7.6	7.5		8.5	8.5	8.4	8.4	8.4		7.6	7.3	6.9																
46030000	2.273	2.539	L	1	7 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	7.5	7.5	6.5																
30 98			1	6.8	24000	RIDE		8.6	8.6	8.3	8.0	8.0	7.9	7.9	7.8	7.8	7.6	7.4	7.5																
DIXIE RD(2.3L)					FC3																															
						CRACKING	6.5	6.0*	6.0*	5.5*		3.0*	3.0*	3.0*	3.0*	3.0*			10.0	8.5																
				(2026)		RIDE	7.5	7.4	7.4	7.4		7.1	7.1	6.9	6.8	6.4			8.6	8.2																
46030000	1.956	2.273	L	1	7 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	7.5	7.5	6.5																
30 98			2	6.8	24000	RIDE		8.6	8.6	8.3	8.0	8.0	7.9	7.9	7.8	7.8	7.6	7.4	7.5																
					FC1																															
						CRACKING	6.5	6.0*	6.0*	5.5*		3.0*	3.0*	3.0*	3.0*	3.0*			10.0	8.5																
				(2026)		RIDE	7.5	7.4	7.4	7.4		7.1	7.1	6.9	6.8	6.4			8.3	7.9																

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 3 COUNTY = BAY

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW LN / %T / SURFTYPE / RW FY-P / ASTYPE / RW FY-F	SYS / AADT / WKMX-P / WKMX-F	TYP	SPD	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46030000	0.000	1.956	L	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	7.5	7.5	6.5														
30 98			2	6.8	24000		RIDE		8.6	8.6	8.3	8.0	8.0	7.9	7.9	7.8	7.8	7.6	7.4	7.5														
BRIDGE #19(0.0C)					FC5M																														
4269501	0.330	1.956	L	2017	0012		CRACKING	6.5	6.0*	6.0*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.4	5.5*													
ANDERSON COLUMBIA CO., INC			(2019)				RIDE	7.5	7.4	7.4	7.4		8.5	8.5	8.5	8.4	8.4	8.4	8.4	8.3	8.1													
46040000	0.000	1.120	R	1	1	30	CRACKING	8.5	6.5	6.5	6.5	6.5	3.5*	3.5*	3.5*	10.0	8.5	7.5	7.5	7.5															
75 231			4	3.6	8600		RIDE	7.8	7.4	7.2	6.7	6.3	6.0	5.8	6.8	7.2	6.9	6.6	6.9	6.6														
BUS US 98(0.0C)					FC125M																														
							CRACKING	6.0*	6.0*	6.0*	3.5*	3.5*	3.0*	3.0*	3.0*	3.0*	3.0*	10.0	9.0	10.0	8.5													
			(2024)				RIDE	7.0	6.5	5.9	6.0	5.9	5.9	5.9	6.1	5.7	5.4*	7.3	6.9	7.1	6.7													
46040000	1.120	1.552	R	1	1	45	CRACKING	10.0	7.5	7.0	7.0	6.0*	6.0*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0															
75 231			2	6.0	16500		RIDE	8.8	8.6	8.4	8.0	7.9	7.6	7.2	7.2	7.0	7.0	8.7	8.6	8.4														
SR 30A(1.1C)					FC95M																														
4134331	1.193	4.050	C	2009	0012		CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	5.7*	4.1*	2.0*													
GAC CONTRACTORS, INC			(2011)			SPRIDE		8.4	8.3	8.2	8.2	7.9	7.9	7.9	7.7	7.6	7.4	7.3	7.1	6.1	5.7													
4508101	1.130	4.058	C	2026	0012																														
46040000	1.552	1.880	R	1	1	45	CRACKING	10.0	7.5	7.0	7.0	6.0*	6.0*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0															
75 231			2	6.0	16500		RIDE	8.8	8.6	8.4	8.0	7.9	7.6	7.2	7.2	7.0	7.0	8.7	8.6	8.4														
						DGFC																														
4134331	1.193	4.050	C	2009	0012		CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	5.7*	8.0	6.0*													
GAC CONTRACTORS, INC			(2011)			SPRIDE		8.4	8.3	8.2	8.2	7.9	7.9	7.9	7.7	7.6	7.4	7.3	7.1	6.9	6.5													
4508101	1.130	4.058	C	2026	0012																														
46040000	1.880	4.050	R	1	1	45	CRACKING	10.0	7.5	7.0	7.0	6.0*	6.0*	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0															
75 231			2	4.1	35000		RIDE	8.8	8.6	8.4	8.0	7.9	7.6	7.2	7.2	7.0	7.0	8.7	8.6	8.4														
RAMP TO SR-77(1.9R)					FC95M																														
4134331	1.193	4.050	C	2009	0012		CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.0*	5.7*	5.2*	3.0*													
GAC CONTRACTORS, INC			(2011)			SPRIDE		8.4	8.3	8.2	8.2	7.9	7.9	7.9	7.7	7.6	7.4	7.3	7.1	7.2	6.8													
4508101	1.130	4.058	C	2026	0012																														
46040000	4.050	10.440	R	1	1	55	CRACKING	10.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.0*		10.0	10.0	10.0															
75 231			2	9.9	38500		RIDE	8.6	8.5	8.8	8.1	8.1	7.8	7.7	7.8	7.6		8.5	8.5	8.4															
RAMP TO CR-2327(5.2R)					FC5M																														
4134331	6.004	10.541	C	2009	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	7.5	7.0	7.0	7.0	7.0	7.0	6.6	6.1*	1.5*													
GAC CONTRACTORS, INC			(2011)			SPRIDE		8.4	8.4	8.6	8.6	8.6	8.7	8.7	8.6	8.6	8.6	8.6	8.5	8.5	8.3													
46040000	10.440	16.313	R	1	7	65	CRACKING	9.0	7.0	4.5*	3.5*	1.0*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0															
75 231			2	12.2	29500		RIDE	9.1	8.4	8.9	8.1	7.7	7.5	7.3	8.4	8.4	8.5	8.5	8.4	8.4														
BAYOU GEORGE DR(11.5R)					FC5M																														
4456311	10.438	16.288	R	2023	0012		CRACKING	10.0	10.0	10.0	8.0	8.0	6.5	6.5	4.5*	4.5*	4.5*	3.5*	3.5*	10.0	9.0													
ANDERSON COLUMBIA CO., INC			(2026)				RIDE	8.3	8.2	8.5	8.5	8.5	8.6	8.6	8.6	8.5	8.5	8.5	8.4	9.0	8.8													
46040000	16.313	20.152	R	1	1	65	CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5	4.5*															
75 231			2	14.4	14900		RIDE	9.0	9.0	9.0	8.6	8.5	8.3	8.3	8.1	8.0	7.8	7.4	7.4	7.1														
BEAR CREEK RD S R(16.6R)					FC5M																														
4230601	16.930	25.245	C	2013	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.8	6.9	3.0*													
GAC CONTRACTORS, INC			(2014)			SPRIDE		8.2	8.3	8.6	8.6	8.6	8.7	8.7	8.6	8.6	8.7	8.7	8.6	8.7	8.5													
46040000	20.152	21.282	R	1	1	45	CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5	4.5*															
75 231			2	11.7	16013		RIDE	9.0	9.0	9.0	8.6	8.5	8.3	8.3	8.1	8.0	7.8	7.4	7.4	7.1														
GRIFFIN RD(20.2R)					FC95MR																														
4230601	16.930	25.245	C	2013	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.8	7.9	6.0*													
GAC CONTRACTORS, INC			(2014)			SPRIDE		8.2	8.3	8.6	8.6	8.6	8.7	8.7	8.6	8.6	8.7	8.7	8.6	8.0	7.6													
46040000	21.282	25.245	R	1	1	65	CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	6.5	4.5*															
75 231			2	11.7	16013		RIDE	9.1	9.0	8.9	8.6	8.5	8.3	8.2	8.0	7.8	7.7	7.4	7.2	7.1														
E LINGER LONGER RD(23.2R)					FC5M																														
4230601	16.930	25.245	C	2013	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.8	7.5	3.5*													
GAC CONTRACTORS, INC			(2014)			SPRIDE		8.2	8.3	8.6	8.6	8.6	8.7	8.7	8.6	8.6	8.7	8.7	8.6	8.7	8.5													
46040000	25.245	34.764	R	1	1	65	CRACKING	10.0	8.5	7.0	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0															
75 231			2	8.8	11891		RIDE	8.9	8.9	8.8	8.3	8.1	7.8	7.7	7.3	8.8	8.5	8.5	8.4	8.4														
MONCLAIR RD R(25.6R)					FC5M																														
							CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	2.0*													
			(2009)				RIDE	8.4	8.4	8.6	8.6	8.5	8.5	8.7	8.7	8.7	8.7	8.7	8.6	8.6	8.4													
4529371	25.056	34.764	C	2027	0012																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46040000	25.245	34.764	L	1	1	65					CRACKING	8.5	7.0	4.5*	4.5*	4.5*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0													
75 231			2	8.8	11891					RIDE	8.9	8.9	8.9	8.2	8.1	7.8	7.4	7.3	8.8	8.4	8.4	8.3	8.3													
CHAPEL RD(25.7L)						FC5M																															
											CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	6.5	7.0	6.5	6.5	1.5*												
							(2009)				RIDE	8.3	8.2	8.6	8.5	8.5	8.5	8.6	8.6	8.6	8.6	8.6	8.6	8.5	8.3												
4529371	25.056	34.764	C	2027		0012																															
46040000	21.282	25.245	L	1	1	65					CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	6.5	4.5*													
75 231			2	11.7	16013					RIDE	9.0	9.1	9.0	8.6	8.6	8.4	8.3	8.3	8.0	8.0	7.8	7.6	7.3													
WALDEN RD(22.9L)						FC5M																															
4230601	16.930	25.245	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.5	7.6	7.1	3.5*												
GAC CONTRACTORS, INC				(2014)		SPRIDE					RIDE	8.1	8.3	8.6	8.6	8.5	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.5	8.3												
46040000	20.152	21.282	L	1	1	45					CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*													
75 231			2	11.7	16013					RIDE	9.0	9.0	8.9	8.2	8.2	8.0	8.0	7.9	7.6	7.6	7.4	7.2	7.0													
CR 388(20.4L)						FC95MR																															
4230601	16.930	25.245	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.5	7.6	8.6	7.0												
GAC CONTRACTORS, INC				(2014)		SPRIDE					RIDE	8.1	8.3	8.6	8.6	8.5	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.3	7.9												
46040000	16.313	20.152	L	1	1	65					CRACKING	10.0	10.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*													
75 231			2	14.4	14900					RIDE	9.0	9.0	8.9	8.2	8.2	8.0	8.0	7.9	7.6	7.6	7.4	7.2	7.0													
CAMP FLOWERS RD N L(16.4L)						FC5M																															
4230601	16.930	25.245	C	2013		0012					CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.5	7.6	6.8	3.0*												
GAC CONTRACTORS, INC				(2014)		SPRIDE					RIDE	8.1	8.3	8.6	8.6	8.5	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.6	8.4												
46040000	10.440	16.313	L	1	7	65					CRACKING	10.0	7.0	4.5*	3.5*	3.5*	1.0*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0													
75 231			2	12.2	29500					RIDE	9.0	9.0	8.8	7.6	7.2	6.9	6.4*	8.3	8.3	8.4	8.3	8.2	8.2													
JOLEE RD(10.6L)						FC5M																															
4456311	10.438	16.288	L	2023		0012					CRACKING	10.0	9.0	9.0	8.0	8.0	6.5	4.5*	4.5*	4.5*	4.5*	3.5*	2.9*	10.0	9.0												
ANDERSON COLUMBIA CO., INC				(2026)		SPRIDE					RIDE	8.1	8.0	8.4	8.4	8.4	8.5	8.5	8.5	8.5	8.4	8.4	8.3	8.8	8.6												
46040000	4.050	10.440	L	1	1	55					CRACKING	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	6.5		10.0	10.0	10.0													
75 231			2	9.9	38500					RIDE	8.8	8.7	8.8	8.3	8.3	8.1	8.1	8.2	8.1		8.6	8.5	8.5													
WAKULLA AVE(4.1L)						FC5M																															
4134331	6.004	10.541	C	2009		0012					CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	7.2	6.5	2.0*												
GAC CONTRACTORS, INC				(2011)		SPRIDE					RIDE	8.4	8.4	8.7	8.6	8.6	8.8	8.7	8.8	8.7	8.7	8.6	8.6	8.7	8.5												
46040000	1.880	4.050	L	1	1	45					CRACKING	10.0	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0													
75 231			2	4.1	35000					RIDE	8.7	8.5	8.3	7.8	7.1	7.3	7.4	7.3	6.7	6.9	8.6	7.8	8.5													
COVE BLVD(1.9C)						FC95M																															
4134331	1.193	4.050	C	2009		0012					CRACKING	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.5	5.6*	3.5*												
GAC CONTRACTORS, INC				(2011)		SPRIDE					RIDE	8.2	8.4	8.3	8.3	8.1	8.2	8.0	7.9	7.9	7.7	7.6	7.5	7.5	7.1												
4508101	1.130	4.058	C	2026		0012																															
46040000	1.552	1.880	L	1	1	45					CRACKING	10.0	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0													
75 231			2	6.0	16500					RIDE	8.7	8.5	8.3	7.8	7.1	7.3	7.4	7.3	6.7	6.9	8.6	7.8	8.5													
WILSON AVE(1.7L)						DGFC																															
											CRACKING	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.5	8.5	7.0												
							(2026)				RIDE	8.2	8.4	8.3	8.3	8.1	8.2	8.0	7.9	7.9	7.7	7.6	7.5	8.0	7.6												
46040000	1.120	1.552	L	1	1	45					CRACKING	10.0	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0													
75 231			2	6.0	16500					RIDE	8.7	8.5	8.3	7.8	7.1	7.3	7.4	7.3	6.7	6.9	8.6	7.8	8.5													
SR 30A(1.1C)						FC95M																															
4134331	1.193	4.050	C	2009		0012					CRACKING	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	6.5	6.5	4.5*												
GAC CONTRACTORS, INC				(2011)		SPRIDE					RIDE	8.2	8.4	8.3	8.3	8.1	8.2	8.0	7.9	7.9	7.7	7.6	7.5	5.8	5.4*												
4508101	1.130	4.058	C	2026		0012																															
46040000	0.000	1.120	L	1	1	30					CRACKING	8.5	6.5	6.5	6.5	6.5	3.5*	3.5*	3.5*	10.0	8.5	7.5	7.5	7.5													
75 231			2	3.6	8600					RIDE	7.8	7.4	7.2	6.7	6.3	6.0	5.8	6.8	7.2	6.9	6.6	6.9	6.6													
BUS US 98(0.0C)						FC125M																															
											CRACKING	6.0*	6.0*	6.0*	3.5*	3.5*	3.0*	3.0*	3.0*	3.0*	3.0*	10.0	9.1	10.0	8.5												
							(2024)				RIDE	7.0	6.5	5.9	6.0	5.9	5.9	5.9	6.1	5.7	5.4*	7.3	7.0	7.3	6.9												
46050000	0.000	7.716	C	1	1	60					CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.0	9.0	9.0	8.0													
20			2	20.3	5400					RIDE	9.1	9.1	9.1	8.7	8.7	8.5	8.6	8.5	8.5	8.5	8.5	8.4	8.3													
AMETHYST LN(6.5L)						FC95MR																															
4397441	0.000	7.567	C	2023		0012					CRACKING	7.5	7.5	7.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	8.5												
C. W. ROBERTS CONTRACTING,				(2024)		SPRIDE					RIDE	8.2	8.1	8.2	8.2	8.0	8.1	8.1	8.0	8.0	8.0	9.0	9.0	9.0	8.6												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP SPD / AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46050000	7.716	23.462	C	1	1 60	CRACKING	5.5*	3.0*	3.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5															
20			2	15.6	3234	RIDE	7.8	7.5	7.3		8.7	8.6	8.6	8.5	8.4	8.4	8.3	7.9	7.9															
CHIPLEY(7.7C)					FC125M																														
4362661	7.908	16.355	C	2021	0012	CRACKING	7.0	7.0	5.5*	3.0*	3.0*	3.0*	3.0*	3.0*	3.0*		10.0	10.0	10.0	8.5															
				(2024)		RIDE	7.5	7.6	7.9	7.8	7.6	7.6	7.6	7.6	7.4		8.6	8.6	8.4	8.0															
46050000	23.462	25.871	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	8.5	7.0	7.0	3.5*	3.5*	3.5*	10.0	10.0	10.0																
20			2	16.2	6400	RIDE	8.5	8.8	8.3	7.7	7.7	6.8	7.4	7.3	7.1	7.0	8.4	8.1	8.2																
PARK N RIDE(23.5L)					FC95MR																														
4192991	23.462	25.871	C	2010	0012	CRACKING	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.0*	6.0*	6.0*	6.0*	5.4*	4.8*	3.0*															
ANDERSON COLUMBIA CO., INC				(2011)		SPRIDE	8.5	8.3	8.4	8.2	8.0	8.1	8.0	8.0	7.9	7.7	7.7	7.6	7.5	7.1															
4508051	23.480	25.871	C	2026	0012																														
46060000	0.000	1.766	R	1	1 40	CRACKING	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	5.1	26000	RIDE	5.2*		8.7	8.0	7.5	7.6	7.7	7.5	7.6	7.5	7.3	7.5	7.3																
BUS US 98 / SR30(0.0C)					FC125M																														
4307791	0.029	1.200	C	2015	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	6.7	7.0	5.5*															
ANDERSON COLUMBIA CO., INC				(2016)		SPRIDE	7.3	7.0	8.0	7.9	7.9	8.0	7.9	7.8	7.7	7.6	7.6	7.6	7.4	7.0															
4565901	0.029	1.732	C	2029	0012																														
46060000	1.766	6.490	R	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5																
77			2	5.2	30098	RIDE	8.4	8.4	8.2	8.0	7.9	7.7	7.7	7.7	7.6	7.4	7.3	7.3	7.1																
CR 368(2.2C)					FC95MR																														
4216391	1.766	6.490	C	2014	0012	CRACKING	7.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0															
ANDERSON COLUMBIA CO., INC				(2016)		RIDE	7.0		8.5	8.4	8.4	8.3	8.3	8.2	8.2	8.1	8.0	8.0	8.0	7.6															
46060000	7.731	9.901	R	1	1 45	CRACKING	10.0	10.0	10.0	10.0	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	5.2	29000	RIDE	8.3	8.1	8.0	7.4	7.3		8.4	8.4	8.4	8.4	8.4	8.3	8.3																
GRASSY POINT RD(7.9R)					FC125																														
2179471	7.553	10.219	C	2004	0213	CRACKING	10.0	10.0	7.5	7.5	7.5	6.5	6.5	7.0	7.0	7.0	8.0	8.5	7.9	6.0*															
C. W. ROBERTS CONTRACTING,				(2007)		SPRIDE	8.3	8.2	8.1	8.1	8.0	8.0	7.9	7.7	7.7	7.5	7.5	7.5	7.6	7.2															
4570471	7.731	9.901	C	2029	0012																														
46060000	9.901	20.116	R	1	1 65	CRACKING	10.0	9.0	6.5	6.5			10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	18.5	15700	RIDE	9.0	8.9	8.9	8.5			8.4	8.4	8.4	8.4	8.4	8.3	8.3																
BOZY DR(11.8R)					FC5M																														
4397251	9.901	20.116	R	2020	0012	CRACKING	10.0	10.0	7.5	7.5	7.5	6.5	6.5			10.0	10.0	9.5	10.0	8.5															
ANDERSON COLUMBIA CO., INC				(2023)		SPRIDE	8.3	8.2	8.1	8.1	8.0	8.0	7.9			8.9	8.9	8.9	8.9	8.7															
46060000	20.116	20.440	R	1	7 55	CRACKING	10.0	9.0	6.5	6.5			10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	15.8	10500	RIDE	9.0	8.9	8.9	8.5			8.4	8.4	8.4	8.4	8.4	8.3	8.3																
					FC5																														
						CRACKING	10.0	10.0	7.5	7.5	7.5	6.5	6.5	7.0	7.0				10.0	9.0															
				(2026)		RIDE	8.3	8.2	8.1	8.1	8.0	8.0	7.9						8.4	8.2															
46060000	20.030	20.440	L	1	7 55	CRACKING	10.0	9.0	6.5	6.5			10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	15.8	10500	RIDE	9.0	8.9	8.9	8.5			8.2	8.3	8.4	8.4	8.4	8.3	8.3																
					FC5M																														
						CRACKING	9.0	8.5	7.0	7.0	7.0	6.5	6.5	7.0	7.0				10.0	9.0															
				(2026)		RIDE	8.3	8.2	8.1	8.0	7.9	7.8	7.8						8.4	8.2															
46060000	9.901	20.030	L	1	1 65	CRACKING	10.0	9.0	6.5	6.5			10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	18.5	15700	RIDE	9.0	8.9	8.9	8.5			8.2	8.3	8.4	8.4	8.4	8.3	8.3																
CR 2300(10.4L)					FC5M																														
4397251	9.901	20.116	L	2020	0012	CRACKING	9.0	8.5	7.0	7.0	7.0	6.5	6.5			10.0	10.0	9.8	10.0	8.5															
ANDERSON COLUMBIA CO., INC				(2023)		SPRIDE	8.3	8.2	8.1	8.0	7.9	7.8	7.8			8.9	8.9	8.9	8.9	8.7															
46060000	7.731	9.901	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0																
77			2	5.2	29000	RIDE	8.3	8.1	8.0	7.4	7.3		8.2	8.3	8.4	8.4	8.4	8.3	8.3																
MCKENZIE RD(8.1L)					FC125																														
2179471	7.553	10.219	C	2004	0213	CRACKING	9.0	8.5	7.0	7.0	7.0	6.5	6.5	7.0	7.0	7.0	8.0	8.1	7.4	5.5*															
C. W. ROBERTS CONTRACTING,				(2007)		SPRIDE	8.3	8.2	8.1	8.0	7.9	7.8	7.8	7.3	7.3	7.1	7.1	7.0	7.1	6.7															
4570471	7.731	9.901	C	2029	0012																														
46060000	1.766	6.490	L	1	1 45	CRACKING	10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*																
77			2	5.2	30098	RIDE	8.8	8.8	8.6	8.2	8.1	7.9	7.8	7.8	7.7	7.8	7.6	7.5	7.4																
CR 368(2.2C)					FC95MR																														
4216391	1.766	6.490	C	2014	0012	CRACKING	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.9	8.6	7.0															
ANDERSON COLUMBIA CO., INC				(2016)		RIDE	7.4		8.5	8.4	8.1	8.3	8.3	8.2	8.1	8.1	8.0	8.0	8.0	7.6															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 3 COUNTY = BAY

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / SURFTYPE / FY-P / FY-F	AADT / WKMX-P / WKMX-F	DISTRESS / RATINGS / ASTYPE	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
46060000	0.000	1.766	L	1	1	40			CRACKING	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0													
77			2	5.1				26000	RIDE	5.2*		8.3	8.3	8.3	7.7	7.8	7.6	7.3	7.6	7.7	7.5	7.8												
BUS US 98 / SR30(0.0C)								FC125M																										
4307791	0.029	1.200	C	2015				0012	CRACKING	9.0	9.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	7.5	7.5	7.2	6.7	5.0*											
ANDERSON COLUMBIA CO., INC(2016)									SPRIDE	7.5	7.2	8.2	8.2	8.0	8.0	8.0	7.8	7.8	7.8	7.7	7.7	7.7	7.3											
4565901	0.029	1.732	C	2029				0012																										
46060001	0.000	0.133	R	1	1	35			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5												
77			2	5.2				29000	RIDE	7.3	7.8	7.7	7.3	6.7	6.8	7.1	7.3	7.2	7.3	7.2	7.2	7.1												
E 4TH ST(0.0R)								FC95MR																										
4216391	0.000	0.132	C	2014				0012	CRACKING	7.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	9.5	9.0	7.0											
ANDERSON COLUMBIA CO., INC(2015)									RIDE	7.1	8.9	8.4	8.3	8.3	8.2	8.2	8.1	8.1	7.9	7.9	7.9	7.9	7.5											
46060001	0.818	1.238	R	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
77			2	5.2				29000	RIDE	8.3	8.5	8.2	7.9	8.0	7.7	8.4	8.6	8.6	8.6	8.5	8.5	8.6												
HOUSE OF SEAFOOD DR(1.0R)								FC125																										
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.6	8.5	6.5											
		(2007)							RIDE	8.6	8.7	8.3	8.3	8.3	8.3	8.2	8.2	8.2	8.1	8.1	8.1	8.2	7.8											
4570471	0.817	1.238	C	2029				0012																										
46060001	0.818	1.238	L	1	1	45			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
77			2	5.2				29000	RIDE	8.5	8.6	8.3	8.0	7.7	7.5	8.5	8.7	8.7	8.8	8.7	8.7	8.6												
HOUSE OF SEAFOOD DR(1.0L)								FC125																										
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.8	7.7	5.5*											
		(2007)							RIDE	8.6	8.7	8.1	8.0	8.0	7.9	7.9	7.7	7.7	7.5	7.4	7.5	7.5	7.1											
4570471	0.817	1.238	C	2029				0012																										
46060001	0.000	0.133	L	1	1	35			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5												
77			2	5.2				29000	RIDE	7.8	7.7	7.4	7.0	6.9	6.8	6.7	6.8	6.7	6.7	6.8	6.6	6.6												
W 4TH ST(0.0L)								FC95MR																										
4216391	0.000	0.132	C	2014				0012	CRACKING	7.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.9	9.4	7.5											
ANDERSON COLUMBIA CO., INC(2015)									RIDE	6.6	8.9	8.1	8.0	7.5	7.6	7.7	7.6	7.6	7.3	7.2	7.0	7.2	6.8											
46070000	4.440	4.672	R	1	1	60			CRACKING																										
388			1	11.2				9400	RIDE																										
								FC95MR																												
									CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	8.0		10.0	10.0	8.5											
		(2025)							RIDE	8.4	8.4	8.4	8.4	8.5	8.4	8.3	8.2	8.1	8.1		7.6	7.5	7.1											
46070000	4.672	12.339	C	1	1	60			CRACKING																										
388			2	11.2				9400	RIDE																										
BURNT MILL CREEK RD N(6.0L)								DGFC																										
									CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	8.0	9.5	9.1	9.5	8.0											
		(2024)							RIDE	8.4	8.4	8.4	8.4	8.5	8.4	8.3	8.2	8.1	8.1	8.4	8.4	8.3	7.9											
46070000	4.440	4.672	L	1	1	60			CRACKING																										
388			2	11.2				9400	RIDE																										
								FC95MR																												
									CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	8.0		10.0	10.0	8.5											
		(2025)							RIDE	8.4	8.4	8.4	8.4	8.5	8.4	8.3	8.2	8.1	8.1		7.8	8.0	7.6											
46070001	0.000	3.417	R	1	1	60			CRACKING																										
388			2	10.2				1900	RIDE																										
									CRACKING																										
		(2025)							RIDE																										
46070001	3.417	4.036	R	1	1	25			CRACKING																										
388			2	10.2				1900	RIDE																										
									CRACKING																										
		(2025)							RIDE																										
46070001	3.417	4.036	L	1	1	25			CRACKING																										
388			2	10.2				1900	RIDE																										
									CRACKING																										
		(2025)							RIDE																										

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	LN	%T	AADT	SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46070001 388	0.000	3.417	L	1	1	60	2	10.2	1900	CRACKING RIDE																												
								(2025)		CRACKING RIDE													10.0 8.7	10.0 8.5	8.5 8.1												
46080000 22 SR 30(0.0C)	0.000	1.813	C	1	1	45	2	6.0	9800	CRACKING RIDE FC125	10.0 8.0	10.0 7.5	10.0 7.6	10.0 7.3	10.0 7.1	8.5 7.0	8.5 6.7	8.5 7.1	8.5 6.5	7.5 7.2	6.5 6.5	6.5 6.8	6.5 6.2													
								(2016)		CRACKING RIDE	6.5 6.6	6.0* 5.9	10.0 7.8	10.0 7.9	10.0 7.2	10.0 7.6	10.0 7.7	10.0 7.4	9.5 7.6	9.5 7.6	8.0 7.4	7.6 7.4	7.3 7.4	5.5* 7.0											
46080000 22 KIMBREL AVE N(2.1R)	1.813	2.765	C	1	1	45	2	6.8	19500	CRACKING RIDE FC125	10.0 8.6	10.0 8.6		10.0 7.8	10.0 7.7	10.0 7.3	10.0 7.4	9.0 7.6	8.5 7.3	8.5 7.4	7.5 7.3	7.5 7.3	7.5 6.9													
4307881 C. W. ROBERTS CONTRACTING,(2017)	2.171	2.762	C	2015		0012				CRACKING RIDE	7.0 7.3	7.0 7.2		10.0 8.4	10.0 8.4	10.0 8.3	10.0 8.3	10.0 8.2	10.0 8.3	10.0 8.2	10.0 8.2	9.0 8.2	8.4 8.2	8.2 8.2	6.5 7.8											
46080000 22 CR 22A(2.8C)	2.765	13.681	C	1	1	60	2	6.0	4300	CRACKING RIDE FC125M	8.5 8.7	8.5 8.6	8.5 8.4	8.5 8.1	8.5 7.8	7.0 7.4	7.0 7.3	7.0 7.3	7.0 6.9	6.0* 6.9	6.0* 6.7	6.0* 6.6													
4216401 C. W. ROBERTS CONTRACTING,(2014)	7.500	12.616	C	2012		0012				CRACKING SPRIDE	10.0 8.4	10.0 8.4	10.0 8.3	10.0 8.3	10.0 8.3	10.0 8.2	9.0 8.2	9.0 8.0	8.5 8.0	8.5 7.9	8.5 7.7	8.7 7.8	8.3 7.6	6.5 7.2											
46090000 79 RAMP US 98(0.5R)	0.483	0.980	R	1	1	45	2	7.9	17300	CRACKING RIDE FC125	3.5* 7.2	10.0 8.7	10.0 8.5			10.0 8.0	10.0 7.8	10.0 7.9	10.0 8.0	10.0 8.1	10.0 7.9	10.0 7.9	10.0 8.0													
4377631 ANDERSON COLUMBIA CO., INC(2024)	0.558	5.655	R	2022		0012				CRACKING RIDE	10.0 7.7	8.5 7.7	8.5 7.9	7.5 7.8	7.0 7.7	6.5 7.8	6.5 7.7	4.5* 7.6	4.5* 7.4	4.5* 7.3	10.0 8.5	9.2 8.4	10.0 7.3	8.5 6.9											
46090000 79 BAY PARKWAY(1.5R)	0.980	5.140	R	1	1	65	2	7.9	17300	CRACKING RIDE FC5M	3.5* 7.2	10.0 8.7	10.0 8.5			10.0 8.0	10.0 7.8	10.0 7.9	10.0 8.0	10.0 8.1	10.0 7.9	10.0 7.9	10.0 8.0													
4377631 ANDERSON COLUMBIA CO., INC(2024)	0.558	5.655	R	2022		0012				CRACKING RIDE	10.0 7.7	8.5 7.7	8.5 7.9	7.5 7.8	7.0 7.7	6.5 7.8	6.5 7.7	4.5* 7.6	4.5* 7.4	4.5* 7.3	10.0 8.5	9.2 8.4	10.0 8.6	8.5 8.4											
46090000 79 OLD HWY 79(5.7R)	5.648	5.924	R	1	7	45	2	7.9	24000	CRACKING RIDE FC125M	10.0 8.7	10.0 8.7	8.5 8.7	8.5 8.4	8.5 8.3	7.0 8.1	6.5 8.1	6.5 8.2		10.0 8.7	10.0 8.6	10.0 8.6	10.0 8.6													
4377632 C. W. ROBERTS CONTRACTING,(2026)	5.648	14.302	R	2024		0012				CRACKING RIDE	10.0 8.6	10.0 8.5	10.0 8.6	10.0 8.5	9.5 8.5	7.0 8.6	7.0 8.6	6.0* 8.5	6.0* 8.4	6.0* 8.3	6.0* 8.2		10.0 8.1	8.5 7.7											
46090000 79 FC5M	5.924	7.241	R	1	7	55	2	7.9	17000	CRACKING RIDE	10.0 8.7	10.0 8.7	8.5 8.7	8.5 8.4	8.5 8.3	7.0 8.1	6.5 8.1	6.5 8.2		10.0 8.7	10.0 8.6	10.0 8.6	10.0 8.6													
4377632 C. W. ROBERTS CONTRACTING,(2026)	5.648	14.302	R	2024		0012				CRACKING RIDE	10.0 8.6	10.0 8.5	10.0 8.6	10.0 8.5	9.5 8.5	7.0 8.6	7.0 8.6	6.0* 8.5	6.0* 8.4	6.0* 8.3	6.0* 8.2		10.0 8.5	9.0 8.3											
46090000 79 PATE ST(7.6R)	7.241	8.292	R	1	7	55	2	7.9	17000	CRACKING RIDE FC125M	10.0 8.7	10.0 8.7	8.5 8.7	8.5 8.4	8.5 8.3	7.0 8.1	6.5 8.1	6.5 8.2		10.0 8.7	10.0 8.6	10.0 8.6	10.0 8.6													
4377632 C. W. ROBERTS CONTRACTING,(2026)	5.648	14.302	R	2024		0012				CRACKING RIDE	10.0 8.6	10.0 8.5	10.0 8.6	10.0 8.5	9.5 8.5	7.0 8.6	7.0 8.6	6.0* 8.5	6.0* 8.4	6.0* 8.3	6.0* 8.2		10.0 8.4	8.5 8.0											
46090000 79 VINSON RD(9.4R)	8.292	14.348	R	1	7	65	2	7.9	17000	CRACKING RIDE FC5M	10.0 8.7	10.0 8.7	8.5 8.7	8.5 8.4	8.5 8.3	7.0 8.1	6.5 8.1	6.5 8.2		10.0 8.5	10.0 8.5	10.0 8.5	10.0 8.5													
4377632 C. W. ROBERTS CONTRACTING,(2026)	5.648	14.302	R	2024		0012				CRACKING RIDE	10.0 8.4	10.0 8.3	10.0 8.5	10.0 8.5	10.0 8.4	9.0 8.5	9.0 8.5	6.5 8.5	6.5 8.5	6.5 8.4	6.0* 8.4		10.0 8.8	9.0 8.6											
46090000 79 CR 2296(12.4L)	8.292	14.348	L	1	7	65	2	7.9	17000	CRACKING RIDE FC5M	10.0 8.7	10.0 8.7	8.5 8.7	8.5 8.4	8.5 8.3	7.0 8.1	6.5 8.1	6.5 8.2		10.0 8.6	10.0 8.6	10.0 8.5	10.0 8.5													
4377632 C. W. ROBERTS CONTRACTING,(2026)	5.648	14.302	L	2024		0012				CRACKING SPRIDE	10.0 8.4	10.0 8.3	10.0 8.6	10.0 8.6	10.0 8.5	9.0 8.6	7.5 8.4	6.5 8.4	6.5 8.4	6.5 8.4	5.5* 8.2		10.0 8.8	9.0 8.6											

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / US / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	DISTRESS / RATINGS / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46090000	7.241	8.292	L	1	7	55	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	6.5	6.5		10.0	10.0	10.0	10.0															
79		7.9	2	17000			RIDE	8.7	8.7	8.7	8.4	8.3	8.1	8.1	8.2		8.7	8.6	8.6	8.6															
MARILYN RD(7.3L)							FC125M																												
4377632	5.648	14.302	L	2024		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.0	6.5	6.5	6.5	6.0*		10.0	8.5															
C. W. ROBERTS CONTRACTING,(2026)							SPRIDE	8.6	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.2	8.1	8.1		8.3	7.9															
46090000	5.924	7.241	L	1	7	55	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	6.5	6.5		10.0	10.0	10.0	10.0															
79		7.9	2	17000			RIDE	8.7	8.7	8.7	8.4	8.3	8.1	8.1	8.2		8.7	8.6	8.6	8.6															
							FC5M																													
4377632	5.648	14.302	L	2024		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.0	6.5	6.5	6.5	6.0*		10.0	9.0															
C. W. ROBERTS CONTRACTING,(2026)							SPRIDE	8.6	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.2	8.1	8.1		8.6	8.4															
46090000	5.648	5.924	L	1	7	45	CRACKING	10.0	10.0	8.5	8.5	8.5	7.0	6.5	6.5		10.0	10.0	10.0	10.0															
79		7.9	2	24000			RIDE	8.7	8.7	8.7	8.4	8.3	8.1	8.1	8.2		8.7	8.6	8.6	8.6															
							FC125M																													
4377632	5.648	14.302	L	2024		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.0	6.5	6.5	6.5	6.0*		10.0	8.5															
C. W. ROBERTS CONTRACTING,(2026)							SPRIDE	8.6	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.2	8.1	8.1		8.4	8.0															
46090000	0.980	5.140	L	1	1	65	CRACKING	3.5*	10.0	10.0			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
79		7.9	2	17300			RIDE	7.2	8.7	8.5			8.2	8.0	8.2	8.1	8.0	8.2	7.9	7.9															
UNSIGNED(4.5L)							FC5M																												
4377631	0.558	5.655	L	2022		0012	CRACKING	9.0	7.0	6.5	6.0*	6.0*	5.5*	5.5*	5.5*	3.5*	3.5*	10.0	10.0	10.0	8.5															
ANDERSON COLUMBIA CO., INC(2024)							SPRIDE	8.0	8.1	8.1	8.0	8.0	8.0	8.0	7.9	7.9	7.8	8.6	8.5	8.7	8.5															
46090000	0.483	0.980	L	1	1	45	CRACKING	3.5*	10.0	10.0			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
79		7.9	2	17300			RIDE	7.2	8.7	8.5			8.2	8.0	8.2	8.1	8.0	8.2	7.9	7.9															
BACK BEACH RD(0.6C)							FC125M																												
4377631	0.558	5.655	L	2022		0012	CRACKING	9.0	7.0	6.5	6.0*	6.0*	5.5*	5.5*	5.5*	3.5*	3.5*	10.0	10.0	10.0	8.5															
ANDERSON COLUMBIA CO., INC(2024)							SPRIDE	8.0	8.1	8.1	8.0	8.0	8.0	8.0	7.9	7.9	7.8	8.6	8.5	7.2	6.8															
46130000	0.000	1.243	C	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.0	7.0	7.0	6.5															
389		6.4	2	7300			RIDE	7.4	7.8	7.1	7.4	7.4	7.1	7.0	6.4	7.0	6.9	6.3	6.4	6.8															
SR 30(0.0C)							FC95MR																												
4287441	0.078	0.664	C	2014		0012	CRACKING	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.4	8.1	6.5															
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE	6.5	8.6	8.1	8.0	7.6	8.1	8.0	8.1	8.0	8.0	8.0	7.8	7.1	6.7															
46130000	1.243	2.100	C	1	1	35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	7.0	7.0	6.5															
389		8.7	2	10500			RIDE	8.6	8.3	8.5	8.1	7.5	7.1	7.9	7.7	7.9	7.9	7.9	7.8	7.3															
SR 30A(1.2C)							FC95MR																												
4287441	1.323	1.848	C	2014		0012	CRACKING	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.2	7.8	6.0*															
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE	7.3	8.1	8.3	8.2	8.3	8.0	8.1	8.0	8.1	7.9	8.0	7.9	8.0	7.6															
46130000	2.100	3.030	C	1	1	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	7.0	7.0	6.5															
389		11.2	2	14000			RIDE	8.6	8.3	8.5	8.1	7.5	7.1	7.9	7.7	7.9	7.9	7.9	7.8	7.3															
E 22ND CT(2.2L)							FC95MR																												
4287441	2.028	2.749	C	2014		0012	CRACKING	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.2	8.6	7.0															
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE	7.3	8.1	8.3	8.2	8.3	8.0	8.1	8.0	8.1	7.9	8.0	7.9	8.4	8.0															
46140000	1.198	2.021	R	1	2	45	CRACKING	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
368		4.5	2	39000			RIDE	8.1	8.0	8.0	7.2		8.1	8.1	8.3	8.0	8.0	7.8	7.7	7.4															
GRANT AVE(1.3C)							FC125																												
4039252	1.206	2.015	C	2004		0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.5	7.5	8.0	8.6	8.4	6.0*															
C. W. ROBERTS CONTRACTING,(2006)							RIDE	7.9	7.9	7.8	7.5	7.2	7.2	7.5	7.3	7.4	7.4	7.2	7.2	7.4	7.0															
4570481	1.198	1.917	C	2028		0012																													
46140000	2.021	2.569	R	1	8	45	CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0															
390		5.6	2	16800			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.6	8.4	8.7	8.4	8.5	8.5															
BECK AVE(2.0R)							FC125M																												
4134381	2.046	2.547	C	2007		0012	CRACKING	8.5	8.5	8.5	8.5	8.5																								
C. W. ROBERTS CONTRACTING,(2008)							RIDE	8.4	8.4	8.2	8.4	8.1																								
46140000	2.569	4.480	R	1	7	45	CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0															
390		5.6	3	22500			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.6	8.4	8.7	8.4	8.5	8.5															
CR 385(2.7C)							FC95MR																												
2178752	2.021	4.447	C	2020		0213	CRACKING	8.5	8.5	8.5	8.5	8.5																					10.0	8.5	
				(2026)			RIDE	8.4	8.4	8.2	8.4	8.1																					8.2	7.8	

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 3 COUNTY = BAY

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	%T / FY-P / FY-F	AADT / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	DISTRESS RATINGS	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	FUTURE 2031 (PMRS)
46140000	4.480	7.053	R	1	2	45			CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0												
390			3	5.6		20400			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.5	8.4	8.7	8.4	8.5	8.5												
34TH PL(4.5R)								FC95MR																										
									CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0			10.0	10.0	8.5											
							(2025)		RIDE	8.4	8.4	8.2	8.4	8.1	8.0	8.1	7.4	7.5			7.8	8.2	7.8											
46140000	4.448	7.053	L	1	1	45			CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0												
390			3	5.6		20400			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.5	8.4	8.7	8.4	8.5	8.5												
FDOT ENT(4.7L)								FC95MR																										
									CRACKING	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0			10.0	10.0	8.5											
							(2025)		RIDE	8.4	8.4	8.2	8.4	8.1	8.0	8.1	7.4	7.5			7.6	7.6	7.2											
46140000	2.569	4.448	L	1	7	45			CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0												
390			3	5.6		22500			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.6	8.4	8.7	8.4	8.5	8.5												
CR 385(2.7C)								FC95MR																										
2178752	2.021	4.447	C	2020		0213			CRACKING	8.5	8.5	8.5	8.5	8.5								10.0	8.5											
				(2026)					RIDE	8.4	8.4	8.2	8.4	8.1								8.2	7.8											
46140000	2.021	2.569	L	1	8	45			CRACKING	9.0	9.0	7.0	6.0*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0												
390			3	5.6		16800			RIDE	7.8	7.9	7.7	6.4*	6.3*	5.8	5.9	8.6	8.4	8.7	8.4	8.5	8.5												
ISLAND VIEW DR(2.5L)								FC125M																										
4134381	2.046	2.547	C	2007		0012			CRACKING	8.5	8.5	8.5	8.5	8.5																				
C. W. ROBERTS CONTRACTING,(				2008)					RIDE	8.4	8.4	8.2	8.4	8.1																				
46140000	1.198	2.021	L	1	1	45			CRACKING	9.0	8.5	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
368			2	4.5		39000			RIDE	6.8	6.9	7.2	6.4*		7.7	7.7	7.7	7.9	7.7	7.6	7.3	7.4												
MOUND AVE(1.2L)								FC125																										
4039252	1.206	2.015	C	2004		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	7.5	7.5	7.5	7.6	7.2	5.0*											
C. W. ROBERTS CONTRACTING,(				2006)					RIDE	6.9	7.0	7.2	7.1	6.8	6.6	6.5	6.4	6.2	6.1	6.1	6.0	6.2	5.8											
4570481	1.198	1.917	C	2028		0012																												
46140001	0.141	0.702	R	1	1	45			CRACKING	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
368			2	4.7		35500			RIDE	7.6	8.2	8.6	6.0*		8.1	7.6	8.3	8.3	8.3	8.1	8.2	8.1												
ACCESS TO 20TH ST(0.3R)								FC95MR																										
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	10.0	10.0	10.0	10.0	9.5	10.0	8.5											
							(2021)		RIDE	8.1	8.0	7.8	7.7	7.4	7.4	7.4	7.8	8.3	8.3	8.3	8.3	8.1	7.7											
4570481	0.141	0.989	C	2028		0012																												
46140001	0.702	0.989	R	1	1	45			CRACKING	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
368			2	4.7		35500			RIDE	7.6	8.2	8.6	6.0*		8.1	7.6	8.3	8.3	8.3	8.1	8.2	8.1												
MOUND AVE(1.0C)								FC125																										
4039251	0.013	0.838	C	2004		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	8.7	9.2	7.0											
C. W. ROBERTS CONTRACTING,(				2006)					RIDE	8.1	8.0	7.8	7.7	7.4	7.4	7.4	7.7	7.8	7.4	7.3	7.3	7.6	7.2											
4570481	0.141	0.989	C	2028		0012																												
46140001	0.702	0.989	L	1	1	45			CRACKING	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
368			2	4.7		35500			RIDE	7.6	7.4	7.5	7.0		7.5	7.6	8.0	8.0	7.8	8.0	7.9	7.9												
MOUND AVE(1.0L)								FC125																										
4039251	0.013	0.838	C	2004		0012			CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	8.7	8.9	6.5											
C. W. ROBERTS CONTRACTING,(				2006)					RIDE	7.9	7.9	7.6	7.1	7.0	7.0	6.6	7.4	7.3	7.0	6.8	6.8	7.4	7.0											
4570481	0.141	0.989	C	2028		0012																												
46140001	0.141	0.702	L	1	1	45			CRACKING	10.0	10.0	8.5	8.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0												
368			2	4.7		35500			RIDE	7.6	7.4	7.5	7.0		7.5	7.6	8.0	8.0	7.8	8.0	7.9	7.9												
COLLEGE(0.3L)								FC95MR																										
									CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5											
							(2021)		RIDE	7.9	7.9	7.6	7.1	7.0	7.0	6.6	7.8	7.4	7.3	7.6	7.5	7.5	7.1											
4570481	0.141	0.989	C	2028		0012																												
46140003	0.000	0.690	C	1	1	35			CRACKING												8.5	7.5												
368A			2	8.8		3400			RIDE												7.5	7.5												
COLLEGIATE DR(0.0R)								FC125M																										
									CRACKING	7.0	7.0	7.0	7.0	7.0	6.5	6.5	10.0	10.0	10.0	10.0	8.9	8.6	7.0											
							(2021)		RIDE	7.3	7.3	7.1	7.1	7.1	7.0	6.3	7.0	7.0	6.7	6.2	6.4	6.3	5.9											
46140005	0.000	0.631	C	1	2	35			CRACKING	6.5	6.5	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0												
390			2	4.6		3400			RIDE	6.3*	6.7	6.2	5.2*	7.6	7.4	7.7	7.8	7.5	7.4	7.5	7.7	7.6												
US-98/SR-30A(0.0R)								FC125																										
2179991	0.000	0.821	C	2004		0012			CRACKING	9.0	9.0	8.5	7.5	7.5	7.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	4.0*											
C. W. ROBERTS CONTRACTING,(				2005)				SP	RIDE	6.9	7.1	6.8	6.8	6.2	6.6	6.8	6.3	6.4	6.0	6.3	6.4	6.1	5.7											
4508181	0.047	0.629	C	2026		0012																												

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR / US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / SURFTYPE / FY-P / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS / RATINGS / ASTYPE	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46140005	0.631	0.824	C	1	8	35	CRACKING	6.5	6.5	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
390			2	4.1	5000		RIDE	6.3*	6.7	6.2	5.2*	7.6	7.4	7.7	7.8	7.5	7.4	7.5	7.7	7.6															
BRIARWOOD APTS(0.7L)							FC125																												
2179991	0.000	0.821	C	2004	0012		CRACKING	9.0	9.0	8.5	7.5	7.5	7.5	7.5	7.5	7.0	7.0	6.0*	6.0*																
C. W. ROBERTS CONTRACTING,(2005)							SPRIDE	6.9	7.1	6.8	6.8	6.2	6.6	6.8	6.3	6.4	6.0	6.3	6.4															
46140006	0.000	0.348	R	1	1	35	CRACKING																												
368			2	3.4	35000		RIDE																												
GORE AT US-98/SR-30(0.0C)							FC95MR																												
							CRACKING																												
		(2023)					RIDE																												
46140006	0.000	0.348	L	1	1	35	CRACKING																												
368			2	3.4	35000		RIDE																												
GORE AT US-98/SR-30(0.0C)																																			
							CRACKING																												
		(2023)					RIDE																												
46160000	0.303	5.679	R	1	1	55	CRACKING	7.5	7.0	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5															
30A 98			2	5.4	30000		RIDE	8.6	8.6	8.5	7.5	7.2	8.1	7.9	8.2	8.1	8.1	8.1	8.0	7.9															
RAMP FROM FRONT BCH(0.3R)							FC5M																												
4377591	0.303	5.534	R	2021	0012		CRACKING	8.5	7.0	5.5*	3.0*	3.0*	3.0*	3.0*	3.0*	3.0*	3.0*		10.0	10.0	8.5															
ANDERSON COLUMBIA CO., INC(2025)							RIDE	7.8	7.7	7.8	7.7	7.6	7.6	7.5	7.4	7.4	7.4		8.8	8.7	8.5															
46160000	5.679	6.685	R	1	2	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	6.0*	6.0*	6.0*	6.0*	4.5*															
30A 98			3	5.4	42000		RIDE	8.6	8.8	8.6	7.7	7.5	7.8	8.0	7.8	7.5	7.3	6.9	6.7	6.5															
SAN VINCENTE ST(5.9R)							FC95MR																												
4193121	5.679	6.760	C	2013	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0	8.0	7.9	6.0*															
C. W. ROBERTS CONTRACTING,(2014)							SPRIDE	8.8	8.6	8.4	8.3	8.3	8.1	8.2	8.2	8.1	8.1	8.1	8.0	8.1	7.7															
46160000	6.685	10.724	R	1	8	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.5	6.0*	6.0*	4.5*	4.5*	4.5*															
30A 98			2	5.4	51000		RIDE	8.6	8.8	8.5	8.4	8.4	8.3	8.2	8.2	8.1	8.1	7.9	7.7	7.6															
PIER PARK DR(7.2C)							FC5M																												
4193121	6.760	10.968	C	2013	0012		CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5																	
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE		8.3	8.5	8.5	8.4	8.6	8.6	8.6	8.5	8.5	8.4																	
2178383	6.760	9.006@	C	2023	0213																														
46160000	10.724	11.491	R	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.5	6.0*	6.0*	4.5*	4.5*	4.5*															
30A 98			3	5.4	51000		RIDE	8.6	8.8	8.5	8.4	8.4	8.3	8.2	8.2	8.1	8.1	7.9	7.7	7.6															
JACKSON BLVD(11.3C)							FC5M																												
4193121	10.968	11.491	C	2013	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.0	6.5	2.5*														
C. W. ROBERTS CONTRACTING,(2014)							SPRIDE	8.7	8.1	8.5	8.5	8.5	8.5	8.6	8.6	8.6	8.5	8.5	8.6	8.4	8.2														
2178384	8.879	11.390	C	2023	0213																														
46160000	11.491	13.395	R	1	1	55	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.5	6.0*	6.0*	4.5*	4.5*	4.5*															
30A 98			2	5.4	44000		RIDE	8.6	8.8	8.5	8.4	8.4	8.3	8.2	8.2	8.1	8.1	7.9	7.7	7.6															
GLADES TR N(12.0C)							FC5M																												
4193121	11.491	13.677	C	2013	0012		CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	6.8	6.4*	3.0*														
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE		8.2	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.4														
2178385	11.297	13.937	C	2026	0213																														
46160000	13.395	13.677	R	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.5	6.0*	6.0*	4.5*	4.5*	4.5*															
30A 98			2	5.4	44000		RIDE	8.6	8.8	8.5	8.4	8.4	8.3	8.2	8.2	8.1	8.1	7.9	7.7	7.6															
CAULEY AVE(13.5R)							DGFC																												
							CRACKING																												
		(2026)					RIDE																												
46160000	13.677	13.937	R	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	6.5	6.0*	6.0*	4.5*	4.5*	4.5*															
30A 98			2	5.4	44000		RIDE	8.6	8.8	8.5	8.4	8.4	8.3	8.2	8.2	8.1	8.1	7.9	7.7	7.6															
							FC125																												
							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.3	8.2	6.5													
		(2014)					RIDE	7.8	7.3	7.6	7.5	7.4	7.3	7.3	7.4	7.4	7.3	7.4	7.4	7.1	6.7													
2178385	11.297	13.937	C	2026	0213																														
46160000	13.677	13.937	L	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5															
30A 98			2	5.4	44000		RIDE	8.9	8.5	8.8	8.4	8.3	8.2	8.3	8.4	8.3	8.3	8.2	8.1	8.0															
HERITAGE CIR(13.8L)							FC125																												
							CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	8.5	8.5	8.5	7.2	7.0	5.0*													
		(2014)					RIDE	8.3	8.4	8.1	8.2	8.1	7.9	7.9	8.0	8.0	8.0	8.0	8.0	8.0	7.6													
2178385	11.297	13.937	C	2026	0213																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 01/30/2026

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = BAY ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW	SYS	TYP	SPD	DISTRESS / SURFTYPE / ASTYPE / WKMX-P / WKMX-F	SURVEYED YEAR 2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	FUTURE 2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2031 (PMRS)
46160000	13.395	13.677	L	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5															
30A 98			2	5.4	44000		RIDE	8.9	8.5	8.8	8.4	8.3	8.2	8.3	8.4	8.3	8.3	8.2	8.1	8.0															
CHIP SEAL PKWY(13.5L)							DGFC																												
							CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.4	8.9	7.5														
		(2026)					RIDE		8.1	8.6	8.5	8.6	8.6	8.6	8.5	8.5	8.5	8.5	8.5	7.8	7.4														
46160000	11.491	13.395	L	1	1	55	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5															
30A 98			2	5.4	44000		RIDE	8.9	8.5	8.8	8.4	8.3	8.2	8.3	8.4	8.3	8.3	8.2	8.1	8.0															
GLADES TR N(12.0C)							FC5M																												
4193121	11.491	13.677	C	2013		0012	CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.4	6.5	3.0*														
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE		8.1	8.6	8.5	8.6	8.6	8.6	8.5	8.5	8.5	8.5	8.5	8.6	8.4														
2178385	11.297	13.937	C	2026		0213																													
46160000	10.724	11.491	L	1	1	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5															
30A 98			3	5.4	51000		RIDE	8.9	8.5	8.8	8.4	8.3	8.2	8.3	8.4	8.3	8.3	8.2	8.1	8.0															
JACKSON BLVD(11.3C)							FC5M																												
4193121	10.968	11.491	C	2013		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.3	7.0	3.0*														
C. W. ROBERTS CONTRACTING,(2014)							SPRIDE	8.5	8.0	8.5	8.3	8.5	8.6	8.5	8.7	8.6	8.3	8.6	8.5	8.5	8.3														
2178384	8.879	11.390	C	2023		0213																													
46160000	6.760	10.724	L	1	8	45	CRACKING	10.0	10.0	10.0	9.0	7.0	7.0	7.0	7.0	7.0	6.5	6.5	6.5	6.5															
30A 98			2	5.4	51000		RIDE	8.9	8.5	8.8	8.4	8.3	8.2	8.3	8.4	8.3	8.3	8.2	8.1	8.0															
BALL PARK RD(6.8L)							FC5M																												
4193121	6.760	10.968	C	2013		0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5																	
C. W. ROBERTS CONTRACTING,(2015)							SPRIDE		8.3	8.7	8.6	8.5	8.7	8.7	8.7	8.7	8.7	8.7																	
2178383	6.760	9.006@	C	2023		0213																													
46160000	5.679	6.760	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0															
30A 98			3	5.4	42000		RIDE	8.4	8.8	8.4	7.5	7.4	8.0	7.8	8.2	8.0	8.1	8.0	7.8	7.7															
HEATHER(5.7L)							FC95MR																												
4193121	5.679	6.760	C	2013		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.6	7.0	5.0*														
C. W. ROBERTS CONTRACTING,(2014)							SPRIDE	8.9	8.8	8.7	8.6	8.5	8.5	8.4	8.5	8.4	8.5	8.5	8.5	8.5	8.1														
46160000	0.303	5.679	L	1	1	55	CRACKING	6.0*	5.5*	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
30A 98			2	5.4	30000		RIDE	8.7	8.5	8.4	6.8	6.3*	8.2	8.2	8.2	8.2	8.2	8.2	8.1	8.1															
LAKE POWELL DR(0.6L)							FC5M																												
4377591	0.303	5.534	L	2021		0012	CRACKING	8.5	8.5	8.5	6.5	6.5	3.5*	3.5*	3.5*	3.5*	3.5*		10.0	10.0	8.5															
ANDERSON COLUMBIA CO., INC(2025)							RIDE	8.1	8.0	8.1	8.0	8.0	8.0	8.0	7.9	7.8	7.7		8.7	8.7	8.5															
46160101	0.000	0.314	C	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0															
30A 98			1	4.7	16000		RIDE								8.3	8.4	8.3	8.2	8.2	8.1															
PHYSICAL GORE(0.0C)							FC125																												
							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	8.5	8.5	9.0	8.9	7.0														
		(2008)					RIDE	8.2	8.0	7.6	7.8	7.6	7.5	7.6	7.6	7.3	7.3	7.3	7.4	7.6	7.2														
2178385	0.000	0.223	C	2026		0213																													
46160102	0.000	0.296	C	1	1	45	CRACKING								10.0	10.0	10.0	10.0	10.0	10.0															
30A 98			2	5.4	22000		RIDE								8.3	8.3	8.3	8.3	8.2	8.0															
SR-30/FRONT BEACH RD(0.0L)							FC125																												
							CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.4	6.7	4.5*														
		(2008)					RIDE	8.2	8.2	7.9	7.9	7.4	7.6	7.6	7.5	7.5	7.6	7.6	7.5	7.4	7.0														
2178385	0.000	0.296	C	2026		0213																													
46600000	0.000	3.028	C	1	1	45	CRACKING																												
390			2	8.8	17000		RIDE																												
OHIO AVE(0.0C)							FC125M																												
							CRACKING				0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	10.0	10.0	10.0	8.5														
		(2024)					RIDE				6.9	6.8	6.7	6.8	6.6	6.4	7.3	8.0	7.9	7.6	7.2														
46600000	3.028	3.315	C	1	8	45	CRACKING																												
390			2	8.8	9400		RIDE																												
BROOK FOREST DR(3.0R)							DGFC																												
							CRACKING				0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*																	
							RIDE				6.9	6.8	6.7	6.8	6.6	6.4	7.3	4.4*	4.4*																
46600000	3.315	4.308	C	1	1	45	CRACKING																												
390			2	8.8	9400		RIDE																												
CATO RD(3.3R)							FC125M																												
4401491	3.397	4.137	C	2021		0012	CRACKING				0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	10.0	9.6	10.0	8.5													
ROBERTS AND ROBERTS, INC. (2024)							SPRIDE				6.9	6.8	6.7	6.8	6.6	6.4	7.3	7.9	7.9	7.8	7.4													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2031 FORECASTED BY PAVEMARS (PMRS).