FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / SURFTYPE / W_BMP / ASTYPE / W_EMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53002000	0.000	10.256	R	4	1	70	CRACKING	10.0	9.0	8.5	7.0	5.5*	3.5*	1.0*	0.0*		10.0	10.0	10.0	10.0															
8 I10	126.8	137.1	2	29.5	26187		RIDE	9.0	8.9	8.7	8.7	7.9	7.6	7.3	7.0		8.6	8.5	8.5	8.5															
					FC5M																														
4152581	3.073	9.623	C	2006	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	6.5	6.5	6.5	6.5	6.5	3.5*														
ANDERSON COLUMBIA CO., INC(2009)							SPRIDE	8.5	8.4	8.3	8.6	8.6	8.6	8.8	8.8	8.9	8.8	8.7	8.7	8.7	8.6														
4506911	0.000	9.684	C	2026	0012																														
53002000	10.256	19.468	R	4	7	70	CRACKING	8.5	8.5	7.5	7.0	6.5	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0															
8 I10	137.1	146.3	2	34.5	23500		RIDE	8.9	8.9	8.9	8.8	8.2	8.2	8.0	8.0	8.6	8.7	8.6	8.6	8.6															
					FC5M																														
4456351	10.260	19.486	R	2023	0012		CRACKING	10.0	10.0	9.0	9.0	8.0	8.0	6.5	4.5*	3.5*	3.5*	3.5*	3.5*	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.6	8.5	8.5	8.7	8.7	8.7	8.9	9.0	9.0	8.9	8.9	8.7	8.8	8.7														
53002000	19.468	27.046	R	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
8 I10	146.3	153.8	2	31.6	21500		RIDE			9.0	8.9	8.4	8.6	8.5	8.6	8.5	8.5	8.3	8.3	8.1															
					FC5M																														
4327401	19.468	25.224	C	2017	0012		CRACKING	9.0	9.0	7.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	10.0	8.8	7.0														
ANDERSON COLUMBIA CO., INC(2019)							SPRIDE	8.3	8.0	7.9	8.2	8.2		8.9	8.9	9.0	9.0	8.9	8.9	8.9	8.8														
53002000	27.046	33.260	R	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
8 I10	153.8	160.1	2	33.0	23500		RIDE			9.0	8.9	8.4	8.6	8.5	8.6	8.6	8.6	8.5	8.4	8.4															
					FC5M																														
4327402	27.018	33.260	C	2017	0012		CRACKING	10.0	10.0	9.0	9.0	8.0	8.0		10.0	10.0	10.0	10.0	10.0	9.5	8.0														
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	8.3	8.2	8.2	8.4	8.4	8.4		9.0	9.1	9.0	9.0	9.0	9.0	8.9														
53002000	27.046	33.260	L	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
8 I10	153.8	160.1	2	33.0	23500		RIDE			9.0	9.0	8.4	8.5	8.4	8.6	8.6	8.5	8.4	8.3	8.3															
					FC5M																														
4327402	27.018	33.260	C	2017	0012		CRACKING	10.0	8.5	7.0	7.0	6.5	6.5		10.0	10.0	10.0	10.0	10.0	9.0	7.5														
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	8.3	8.2	8.0	8.3	8.3	8.3		9.1	9.1	9.1	9.1	9.1	9.1	9.0														
53002000	19.468	27.046	L	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
8 I10	146.3	153.8	2	31.6	21500		RIDE			9.0	9.0	8.4	8.5	8.4	8.4	8.4	8.3	8.2	8.0	7.9															
					FC5M																														
4327401	19.468	25.224	C	2017	0012		CRACKING	9.0	8.0	8.0	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5														
ANDERSON COLUMBIA CO., INC(2019)							SPRIDE	7.8	7.8	7.5	8.0	8.0		9.0	8.9	9.0	9.0	9.0	8.9	8.9	8.8														
53002000	13.609	19.468	L	4	7	70	CRACKING	8.5	8.5	7.5	7.0	6.5	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0															
8 I10	140.4	146.3	2	31.6	21500		RIDE	8.7	8.8	8.9	8.6	8.4	8.3	8.2	8.1	8.4	8.7	8.7	8.6	8.5															
					FC5M																														
4456351	10.260	19.486	L	2023	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	7.5	6.5	6.5	4.5*	4.5*	4.5*	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.5	8.4	8.3	8.6	8.6	8.6	8.9	8.9	9.0	8.9	8.7	8.6	8.9	8.8														
53002000	10.256	13.609	L	4	7	70	CRACKING	9.0	9.0	7.5	7.0	7.0	5.5*	5.5*	3.5*		10.0	10.0	10.0	10.0															
8 I10	137.1	140.4	2	34.5	23500		RIDE	8.6	8.4	8.1	8.2	7.7	7.2	7.0	7.1		8.7	8.6	8.6	8.5															
					FC5M																														
4456351	10.260	19.486	L	2023	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	6.5	6.5	4.5*	4.5*	4.5*	10.0	9.0														
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	8.5	8.5	8.3	8.7	8.7	8.6	9.0	9.0	9.0	8.9	8.8	8.7	8.9	8.8														
53002000	0.000	10.256	L	4	1	70	CRACKING	10.0	9.0	8.5	7.0	5.5*	3.5*	1.0*	0.0*		10.0	10.0	10.0	10.0															
8 I10	126.8	137.1	2	29.5	26187		RIDE	9.1	9.0	8.8	8.7	7.7	7.2	6.7	6.5		8.5	8.5	8.5	8.4															
					FC5M																														
4152581	3.073	9.623	C	2006	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	6.5	6.5	6.5	6.5	6.5	3.5*														
ANDERSON COLUMBIA CO., INC(2009)							SPRIDE	8.4	8.5	8.3	8.6	8.6	8.6	8.8	8.9	8.9	8.9	8.7	8.7	8.7	8.6														
4506911	0.000	9.684	C	2026	0012																														
53010000	0.000	4.369	C	1	1	55	CRACKING	3.5*	3.5*	3.5*	10.0	10.0	9.5	9.5	9.5	9.5	9.5	9.5	8.5	8.5															
10 90			2	9.3	3300		RIDE	8.2	8.2	7.6	8.6	8.4	8.3	8.4	8.5	8.5	8.5	8.3	8.5	8.4															
AYCOCK RD(0.9L)					FC95MR																														
4436572	0.000	4.390	C	2022	0012		CRACKING	8.5	8.5	7.5	7.5	7.5	7.0	7.0	5.5*	5.5*	3.5*	10.0	10.0	10.0	8.5														
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.4	8.3	8.3	8.0	8.0	8.0	8.0	8.0	7.9	7.8	8.6	8.5	8.5	8.1														
53010000	4.369	4.681	C	1	4	45	CRACKING	7.4	7.5	7.1	7.1	7.6	7.6	7.4	7.2	6.8	6.8	6.7	6.6	6.6															
10 90			2	7.5	4200		RIDE	6.3*	6.6	6.4*	6.3*	5.7*	5.7*	5.6	5.9	5.5	5.5	5.5	5.8	5.8															
					B																														
							CRACKING	6.6	6.5	6.5	6.5	6.5	6.4*	6.4*	7.4	6.5	6.8	7.4	7.9	7.7	6.0*														
				(1987)			RIDE	5.8	5.8	5.7	5.5	5.4*	5.2*	5.1*	5.2*	4.8*	5.1*	5.2*	5.1*	4.8*	4.6*														
4456331	4.369	11.758	C	2023	0012																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / AADT / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	SPD	DISTRESS RATINGS ========	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53010000	4.681	4.970	C	1	6	35	CRACKING	7.0	4.5*	4.5*	10.0	10.0	10.0	10.0	6.5	6.5	6.5	6.5	6.5	6.5															
10 90			2	7.1	4600		RIDE	7.9	7.8	7.4	8.6	8.3	8.3	7.5	7.6	7.4	7.2	6.9	6.6	6.5														
CARTLEDGE RD(4.7R)					FC125																														
2193791	4.316	11.732	C	2001	0012		CRACKING	6.5	6.5	6.5	6.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	3.5*	1.0*	1.0*	0.0*														
ANDERSON COLUMBIA CO., INC(2003)					SPRIDE		RIDE	6.3	6.3	6.2																									
4456331	4.369	11.758	C	2023	0012																														
53010000	4.970	11.758	C	1	1	55	CRACKING	7.0	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
10 90			2	7.1	4600		RIDE	7.9	7.8	7.4	8.6	8.3	8.3	8.4	8.6	8.5	8.4	8.3	8.3	8.2														
ZION ST(5.0C)					FC125																														
2193791	4.316	11.732	C	2001	0012		CRACKING	9.0	9.0	7.5	7.5	7.5	7.5	7.0	6.0*	6.0*	5.5*	5.5*	3.5*	4.2*	2.0*														
ANDERSON COLUMBIA CO., INC(2003)					SPRIDE		RIDE	8.0	8.0	7.9	7.8	7.8	7.6	7.6	7.6	7.6	7.3	7.4	7.3	7.1	6.7														
4456331	4.369	11.758	C	2023	0012																														
53010000	11.758	14.076	R	1	1	35	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	7.0	7.0	6.5	6.5	6.5	6.5	6.5															
10 90			2	6.6	14313		RIDE	6.4*	8.3	7.3	7.6	7.4	7.5	7.5	7.6	7.5	7.4	7.1	7.0	7.1														
HALL ST(11.9R)					FC95MR																														
4246211	11.878	13.580	C	2015	0012		CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	7.0	7.1	5.5*														
ANDERSON COLUMBIA CO., INC(2016)							RIDE	7.2	6.8	7.0	8.6	8.5	8.4	8.3	8.3	8.1	7.9	7.7	7.7	7.5	7.1														
53010000	11.758	14.076	L	1	1	35	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5	6.5															
10 90			2	6.6	14313		RIDE	5.9*	8.3	7.6	7.6	7.4	7.3	7.0	7.1	7.0	7.4	7.1	7.0	7.1														
SR 73(12.1L)					FC95MR																														
4246211	11.878	13.580	C	2015	0012		CRACKING	6.5	6.5	6.5	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	7.0	7.4	5.5*														
ANDERSON COLUMBIA CO., INC(2016)							RIDE	7.2	6.8	7.0	8.6	8.5	8.4	8.3	8.3	8.1	7.9	8.1	8.0	7.7	7.3														
53020000	0.000	0.685	R	1	1	45	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0															
10 90			2	4.1	19900		RIDE	5.0*	8.4	8.1	8.1	7.9	7.5	7.5	7.9	7.6	7.7	7.6	7.7	7.8														
CR 167(0.0C)					FC95MR																														
4246211	0.182	0.604	C	2015	0012		CRACKING	9.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.9	6.0*														
ANDERSON COLUMBIA CO., INC(2016)							RIDE	7.6	7.4	7.1	8.4	8.3	8.4	8.2	8.2	8.2	8.0	7.3	7.6	7.5	7.1														
53020000	0.685	3.305	R	1	8	45	CRACKING	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	8.0	8.0	8.0															
10 90			2	6.3	21500		RIDE	7.2	8.7	8.6	8.4	8.1	8.3	8.0	8.0	8.1	8.0	7.7	7.9	7.8														
RACE LN(1.2R)					FC3																														
2193741	0.000	3.236	C	2000	0012		CRACKING	8.0	8.0	8.0	8.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*	5.5*	3.5*																
ANDERSON COLUMBIA CO., INC(2001)					SPRIDE		RIDE	7.8	7.6	7.5	7.6	7.4	7.3	7.4	7.3	7.4	7.1	7.3	7.1																
4455411	0.687	3.310	C	2023	0012																														
53020000	3.305	4.166	R	1	1	55	CRACKING	10.0	10.0	8.5	7.5	7.0	5.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0															
10 90			1	8.9	9200		RIDE	8.9	8.9	8.8	8.6	8.1	8.1	8.0	8.1	8.0		8.7	8.6	8.6															
SIDE ROAD(3.4C)					FC125M																														
							CRACKING	10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	3.5*														
				(2010)			RIDE	8.4	8.4	8.3	8.4	8.4	8.3	8.2	8.1	8.0	7.8	7.5	7.4	7.4	7.0														
4153752	3.297	12.829	C	2025	0012																														
53020000	4.166	12.811	C	1	1	55	CRACKING	10.0	10.0	8.5	7.5	7.0	5.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0															
10 90			2	8.9	5400		RIDE	8.9	8.9	8.8	8.6	8.1	8.1	8.0	8.1	8.0		8.7	8.6	8.6															
CILE LN(4.4L)					FC125M																														
4153751	4.168	12.811	C	2008	0012		CRACKING	10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.0*	6.0*	3.5*	3.6*	1.5*														
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE		RIDE	8.4	8.4	8.3	8.4	8.4	8.3	8.2	8.1	8.0	7.8	8.0	8.0	7.9	7.5														
4153752	3.297	12.829	C	2025	0012																														
53020000	12.811	15.586	R	1	1	55	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.0	7.0	7.0	7.0	7.0	7.0															
10 90			2	8.9	6300		RIDE	8.7	8.7	8.5	8.3	8.1	8.2	8.1	8.2	8.2	8.0	7.9	8.0	7.9															
PORTER AVE(13.5C)					FC95MR																														
4169441	13.079	15.360	C	2015	0012		CRACKING	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	7.2	5.5*														
CAPITAL ASPHALT INC				(2016)			SPRIDE	7.9	7.8	7.6	8.6	8.5	8.4	8.4	8.3	8.2	8.0	8.1	8.1	8.2	7.8														
53020000	15.586	18.617	C	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	10.0															
10 90			2	9.5	5700		RIDE	8.8	8.9	8.7	8.5	8.1	8.1	8.0	8.3	8.3	8.3	8.2	8.2	8.2															
CR 69A(16.3L)					FC95M																														
4134421	15.561	18.625	C	2006	0012		CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.5	7.5	5.5*	3.5*	1.5*														
ANDERSON COLUMBIA CO., INC(2007)							RIDE	8.2	8.1	8.1	8.0	8.0	7.9	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.5														
4531511	15.571	23.661	C	2027	0012																														
53020000	18.617	19.446	R	1	1	45	CRACKING	10.0	10.0	9.0	9.0	9.0	8.5	8.5	7.5	7.0	7.0	6.5	6.5	6.5															
10 90			2	8.9	7800		RIDE	7.9	8.1	7.9	7.6	7.3	7.4	7.6	7.7	7.7	7.5	7.4	7.2	6.8															
O HARA AVE(18.7C)					FC95MR																														
4246151	18.679	19.456	C	2013	0012		CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	6.0*	6.1*	4.5*														
JONES CONSTRUCTION OF NORT(2014)					SPRIDE		RIDE	6.6	8.1	8.0	7.9	7.8	7.7	7.6	7.5	7.4	7.3	7.2	7.0	6.9	6.5														
4531511	15.571	23.661	C	2027	0012																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / SURFTYPE / W_BMP / ASTYPE / W_EMP	EMP / G_EMP / W_EMP	RW / RW	SYS / LN / FY-P / FY-F	TYP / %T / WKMX-P / WKMX-F	SPD / AADT	DISTRESS RATINGS	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53020000	19.446	20.302	R	1	1	45	CRACKING	7.5	7.0	8.5	3.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5																
10 90				1	8.9	6600	RIDE	8.4	8.3	8.0	7.8	6.8	8.3	8.3	8.4	8.2	8.1	8.1	8.1	8.0															
THIRD AVE(19.6C)						FC125																														
4063241	19.454	23.352	C	2004		0012	CRACKING	9.5	9.5	9.5	9.5	9.5	8.5	8.5	7.5	7.5	7.5	6.0*	6.0*	4.9*	2.5*															
ANDERSON COLUMBIA CO., INC(2005)							RIDE	8.0	8.0	7.9	7.8	7.8	7.7	7.8	7.7	7.7	7.6	7.5	7.4	7.3	6.9															
4531511	15.571	23.661	C	2027		0012																														
53020000	20.302	22.655	C	1	1	55	CRACKING	7.5	7.0	8.5	3.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5																
10 90				2	8.3	6100	RIDE	8.4	8.3	8.0	7.8	6.8	8.3	8.3	8.4	8.2	8.1	8.1	8.1	8.0															
DAIRY RD(20.7L)						FC125																														
4063241	19.454	23.352	C	2004		0012	CRACKING	9.5	9.5	9.5	9.5	9.5	8.5	8.5	7.5	7.5	7.5	7.0	6.0*	5.5*	3.0*															
ANDERSON COLUMBIA CO., INC(2005)							RIDE	8.0	8.0	7.9	7.8	7.8	7.7	7.8	7.7	7.7	7.6	7.8	7.7	7.7	7.3															
4531511	15.571	23.661	C	2027		0012																														
53020000	19.446	20.302	L	1	1	45	CRACKING	7.5	7.0	8.5	3.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5																
10 90				1	8.9	6600	RIDE	8.4	8.3	8.0	7.8	6.8	8.3	8.3	8.4	8.2	8.1	8.1	8.1	8.0															
THIRD AVE(19.6C)						FC125																														
4063241	19.454	23.352	C	2004		0012	CRACKING	9.5	9.5	9.5	9.5	9.5	8.5	8.5	7.5	7.5	7.5	6.0*	6.0*	4.6*	2.5*															
ANDERSON COLUMBIA CO., INC(2005)							RIDE	8.0	8.0	7.9	7.8	7.8	7.7	7.8	7.7	7.7	7.6	7.1	7.1	7.0	6.6															
4531511	15.571	23.661	C	2027		0012																														
53020000	18.617	19.446	L	1	1	45	CRACKING	10.0	10.0	9.0	8.5	8.5	8.5	8.5	7.5	6.5	7.0	6.5	6.5	6.5																
10 90				2	8.9	7800	RIDE	8.2	8.2	8.1	7.9	7.6	7.5	7.3	7.4	7.2	7.5	7.4	7.2	6.8															
O HARA AVE(18.7C)						FC95MR																														
4246151	18.679	19.456	C	2013		0012	CRACKING	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	6.0*	6.0*	4.7*	3.0*															
JONES CONSTRUCTION OF NORT(2014)							SPRIDE	6.6	8.1	8.0	7.9	7.8	7.7	7.6	7.5	7.4	7.3	7.3	7.3	7.3	6.9															
4531511	15.571	23.661	C	2027		0012																														
53020000	12.811	15.586	L	1	1	55	CRACKING	10.0	10.0	9.0	9.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.0*																
10 90				2	8.9	6300	RIDE	7.9	8.5	8.2	8.2	7.9	7.9	7.8	7.9	7.8	7.7	7.5	7.6	7.5															
JOLIE AVE(13.1L)						FC95MR																														
4169441	13.079	15.360	C	2015		0012	CRACKING	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	6.9	5.0*															
CAPITAL ASPHALT INC				(2016)			SPRIDE	7.4	7.2	7.0	8.4	8.3	8.1	8.1	8.0	7.9	7.7	7.9	7.9	7.9	7.5															
53020000	3.305	4.166	L	1	1	55	CRACKING	10.0	10.0	8.5	7.5	7.0	5.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0																
10 90				1	8.9	9200	RIDE	8.9	8.9	8.8	8.6	8.1	8.1	8.0	8.1	8.0		8.7	8.6	8.6																
SIDE ROAD(3.4C)						FC125M																														
							CRACKING	10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	5.0*	3.0*															
				(2010)			RIDE	8.4	8.4	8.3	8.4	8.4	8.3	8.2	8.1	8.0	7.8	7.6	7.5	7.4	7.0															
4153752	3.297	12.829	C	2025		0012																														
53020000	0.685	3.305	L	1	8	45	CRACKING	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	8.0																
10 90				2	6.3	21500	RIDE	6.3*	8.7	8.7	8.5	8.0	8.2	8.1	8.4	8.3	8.3	8.2	8.2	8.1																
OLD US RD(0.9L)						FC3																														
2193741	0.000	3.236	C	2000		0012	CRACKING	8.0	8.0	8.0	8.0	8.0	7.0	6.0*	6.0*	6.0*	6.0*	5.5*	5.5*																	
ANDERSON COLUMBIA CO., INC(2001)							SPRIDE	8.0	8.0	7.7	7.9	7.8	7.7	7.7	7.7	7.6	7.6	7.6	7.6																	
4455411	0.687	3.310	C	2023		0012																														
53020000	0.000	0.685	L	1	1	45	CRACKING	7.5	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.0	9.0	9.0	9.0	9.0																
10 90				2	4.1	19900	RIDE	4.7*	8.5	8.3	7.9	7.6	7.7	7.0	7.2	7.1	7.7	7.6	7.7	7.8																
SR-166/JEFFERSON ST(0.0L)						FC95MR																														
4246211	0.182	0.604	C	2015		0012	CRACKING	9.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.4	5.5*															
ANDERSON COLUMBIA CO., INC(2016)							RIDE	7.6	7.4	7.1	8.4	8.3	8.4	8.2	8.2	8.2	8.0	7.4	7.4	7.3	6.9															
53030000	0.000	0.586	R	1	1	65	CRACKING	6.0*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0																
75 231				2	11.1	6700	RIDE	7.8	8.3	8.5	8.8	8.4	6.7	8.5	8.5	8.4	8.6	8.3	8.3	8.3																
						FC5M																														
4397401	0.000	0.586	R	2021		0012	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	10.0	10.0	9.8	8.0															
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.4	8.3	8.2	8.4	8.5	8.4	8.5	8.5	8.4	8.5	8.7	8.8	8.7	8.5															
53030000	5.014	7.292	R	1	1	55	CRACKING	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5																
75 231				2	22.7	6500	RIDE	7.3	7.3	8.8	8.8	8.4	8.4	8.3	8.6	8.6	8.6	8.4	8.1	8.3																
SHERRY CIR(5.2R)						FC5																														
4377491	5.014	7.446	R	2019		0012	CRACKING	9.5	9.5	7.0	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	9.2	7.0															
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	8.2	8.1	7.9	8.1	8.0	8.0	8.1	8.9	8.9	8.9	8.9	8.9	8.9	8.7															
53030000	7.292	8.965	R	1	1	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	8.0	8.0	5.5*	5.5*																
75 231				2	22.7	6500	RIDE	8.7	8.7	8.8	8.7	8.2	8.2	8.3	8.2	8.2	8.0	7.8	7.7	7.5																
DANIELS RD(7.5C)						FC5M																														
4287351	7.445	9.987	C	2014		0012	CRACKING	5.5*	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.5	7.5	7.0	3.5*															
ANDERSON COLUMBIA CO., INC(2014)							SPRIDE	7.4	8.5	8.5	8.6	8.5	8.5	8.3	8.5	8.5	8.4	8.5	8.6	8.5	8.3															
4475882	7.446	9.982	C	2029		0012																														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 3 COUNTY = JACKSON

RDWYID BMP EMP RW SYS TYP SPD SR US G_BMP G_EMP LN %T AADT INTERSECT AT (MP|SIDE) SURFTYPE ITMSEG-P W_BMP W_EMP RW FY-P WKMX-P CONTRACTOR (AGE_ONE YEAR) ASTYPE ITMSEG-F W_BMP W_EMP RW FY-F WKMX-F	DISTRESS RATINGS ========	SURVEYED YEAR 2000 2013	2001 2014	2002 2015	2003 2016	2004 2017	2005 2018	2006 2019	2007 2020	2008 2021	2009 2022	2010 2023	2011 2024	2012 2025	FUTURE 2030 (PMRS)
53030000 8.965 9.997 R 1 7 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	7.5	6.5	5.5*	5.5*	
75 231 2 18.8 8100	RIDE	8.8	8.8	8.6	8.6	8.1	8.0	8.1	8.3	8.2	8.0	7.9	7.8	7.4	
FIFTH AVE(9.1R) FC95MR															
	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	10.0	9.0
(2025)	RIDE	6.9	8.0	8.5	8.5	8.4	8.4	8.4	8.3	8.3	8.2	8.2	8.2	8.6	8.2
4475882 7.446 9.982 C 2029 0012															
53030000 9.997 12.840 R 1 7 65	CRACKING	10.0	10.0	9.0	7.5	7.0	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0	
75 231 2 22.7 7700	RIDE	9.0	9.0	8.8	8.8	7.9	7.6	7.1	6.9		8.5	8.4	8.4	8.4	
LITTLE VALLEY RD(10.1R) FC5M															
4475881 9.982 12.843 R 2024 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	6.5	4.5*	4.5*	3.5*	3.5*	10.0	9.0
ANDERSON COLUMBIA CO., INC(2025)	SPRIDE	8.4	8.3	8.2	8.5	8.4	8.4	8.5	8.5	8.5	8.4	8.5	8.5	8.6	8.4
53030000 12.840 13.905 R 1 1 45	CRACKING	10.0	7.5	7.5	7.5	6.5	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.5 9900	RIDE	8.7	8.7	8.1	8.4	7.6	7.4	7.2	8.1	8.3	8.3	8.3	8.3	8.3	
DILMORE RD(13.1C) FC95MR															
4397311 12.843 15.982 R 2021 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	7.5	6.5	4.5*	4.5*	3.5*	10.0	10.0	9.6	8.5
ANDERSON COLUMBIA CO., INC(2023)	SPRIDE	8.3	8.3	8.2	8.2	8.2	8.1	8.2	8.2	8.1	8.1	8.5	8.2	8.2	7.8
53030000 13.905 15.990 R 1 1 65	CRACKING	10.0	7.5	7.5	7.5	6.5	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.5 9900	RIDE	8.7	8.7	8.1	8.4	7.6	7.4	7.2	8.1	8.3	8.3	8.3	8.3	8.3	
BARBER RD(14.2R) FC5M															
4397311 12.843 15.982 R 2021 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	7.5	6.5	4.5*	4.5*	3.5*	10.0	10.0	10.0	8.5
ANDERSON COLUMBIA CO., INC(2023)	SPRIDE	8.3	8.3	8.2	8.2	8.2	8.1	8.2	8.2	8.1	8.1	8.8	8.8	8.8	8.6
53030000 15.990 17.381 R 1 1 45	CRACKING	10.0	8.0	8.0	8.0	8.0	8.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.7 9300	RIDE	7.5	7.6	8.1	8.1	7.6	7.6	7.7	7.0	7.1	7.3	7.1	7.1	7.0	
THOMAS ST(16.2R) FC125M															
4090101 16.465 17.230 C 2005 0012	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.0*	5.4*	3.0*
ANDERSON COLUMBIA CO., INC(2006)	RIDE	7.1	7.0	6.8	7.2	6.9	7.0	6.8	6.9	7.0	6.9	6.6	6.7	6.7	6.3
4529331 15.982 17.381 C 2027 0012															
53030000 17.381 20.217 R 1 1 65	CRACKING	9.0	6.5	5.5*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	
75 231 2 30.1 7800	RIDE	8.8	8.8	8.6	8.6		8.3	8.3	8.4	8.4	8.4	8.2	8.1	8.1	
LOVEWOOD RD(17.8R) FC5M															
4377471 17.381 20.217 R 2019 0012	CRACKING	8.0	8.0	7.0	6.5	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	9.4	7.5
ANDERSON COLUMBIA CO., INC(2020)	RIDE	7.9	7.7	7.5	8.2	8.0	7.9	8.1	9.1	9.1	9.0	9.0	9.0	8.9	8.7
53030000 17.381 20.217 L 1 1 65	CRACKING	9.0	6.5	5.5*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	
75 231 2 30.1 7800	RIDE	8.5	8.6	8.2	8.2		8.3	8.3	8.5	8.4	8.4	8.2	8.0	7.7	
COUNTRY OAKS DR(17.5L) FC5M															
4377471 17.381 20.217 L 2019 0012	CRACKING	7.5	7.5	4.5*	3.5*	0.0*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	9.0	7.0
ANDERSON COLUMBIA CO., INC(2020)	RIDE	7.5	7.1	6.7	7.6	8.5	8.5	8.5	9.1	9.1	9.0	9.0	9.0	9.0	8.8
53030000 15.990 17.381 L 1 1 45	CRACKING	10.0	8.0	8.0	8.0	8.0	8.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.7 9300	RIDE	7.1	7.3	7.7	7.9	7.2	7.5	7.7	7.8	7.8	7.7	7.5	7.3	7.3	
LEVY ST(16.2C) FC125M															
4090101 16.465 17.230 C 2005 0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	6.5	5.5*	5.0*	2.5*
ANDERSON COLUMBIA CO., INC(2006)	RIDE	7.2	6.9	7.2	7.1	7.0	6.8	6.8	7.0	6.7	6.7	6.7	6.6	6.5	6.1
4529331 15.982 17.381 C 2027 0012															
53030000 13.905 15.990 L 1 1 65	CRACKING	10.0	9.0	7.5	7.5	7.5	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.5 9900	RIDE	8.9	8.9	8.0	8.5	7.8	7.6	7.3	8.4	8.5	8.4	8.4	8.4	8.4	
OBERT RD(15.4L) FC5M															
4397311 12.843 15.982 L 2021 0012	CRACKING	10.0	10.0	9.0	9.0	7.5	7.5	7.5	6.5	4.5*	3.5*	10.0	10.0	9.8	8.0
ANDERSON COLUMBIA CO., INC(2023)	SPRIDE	8.4	8.4	8.3	8.3	8.4	8.4	8.4	8.4	8.4	8.3	8.9	8.8	8.8	8.6
53030000 12.840 13.905 L 1 1 45	CRACKING	10.0	9.0	7.5	7.5	7.5	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
75 231 2 28.5 9900	RIDE	8.9	8.9	8.0	8.5	7.8	7.6	7.3	8.4	8.5	8.4	8.4	8.4	8.4	
DILMORE RD(13.1C) FC95MR															
4397311 12.843 15.982 L 2021 0012	CRACKING	10.0	10.0	9.0	9.0	7.5	7.5	7.5	6.5	4.5*	3.5*	10.0	10.0	10.0	8.5
ANDERSON COLUMBIA CO., INC(2023)	SPRIDE	8.4	8.4	8.3	8.3	8.4	8.4	8.4	8.4	8.4	8.3	8.3	8.2	8.1	7.7
53030000 9.997 12.840 L 1 7 65	CRACKING	10.0	9.0	7.5	7.5	7.5	6.5	3.5*	1.0*		10.0	10.0	10.0	10.0	
75 231 2 22.7 7700	RIDE	9.0	9.0	9.0	8.9	8.2	7.9	7.3	6.8		8.3	8.3	8.3	8.2	
HALLMAN LN(10.5L) FC5M															
4475881 9.982 12.843 L 2024 0012	CRACKING	10.0	10.0	9.0	7.5	7.5	7.5	7.5	6.5	4.5*	4.5*	3.5*	3.5*	10.0	9.0
ANDERSON COLUMBIA CO., INC(2025)	SPRIDE	8.2	8.2	8.1	8.5	8.5	8.4	8.6	8.6	8.6	8.5	8.5	8.4	8.6	8.4

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / SURFTYPE / WKMX-P / ASTYPE / WKMX-F	SPD / AADT	DISTRESS RATINGS	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53030000	8.965	9.997	L	1	7	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	7.5	6.5	4.5*	4.5*															
75 231			2	18.8		8100	RIDE	9.1	9.0	8.9	8.8	8.3	8.3	8.2	8.4	8.3	8.1	7.8	7.4	7.3														
CR 1656(9.3L)						FC95MR																													
							CRACKING	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	10.0	9.0													
					(2025)		RIDE	6.5	8.4	8.7	8.5	8.5	8.5	8.5	8.5	8.4	8.3	8.4	8.3	8.6	8.2													
4475882	7.446	9.982	C	2029		0012																													
53030000	7.292	8.965	L	1	1	65	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	8.0	8.0	6.5	5.5*	5.5*															
75 231			2	22.7		6500	RIDE	8.8	9.0	9.0	9.0	8.4	8.5	8.3	8.4	8.3	8.0	7.8	7.6	7.3														
DANIELS RD(7.5C)						FC5M																													
4287351	7.445	9.987	C	2014		0012	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.9	4.5*													
ANDERSON COLUMBIA CO., INC(2014)							SPRIDE	7.0	8.7	8.6	8.7	8.6	8.6	8.4	8.6	8.6	8.5	8.6	8.6	8.5	8.3													
4475882	7.446	9.982	C	2029		0012																													
53030000	5.014	7.292	L	1	1	55	CRACKING	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5															
75 231			2	22.7		6500	RIDE	8.4	8.2	8.8	8.8	8.3	8.4	8.3	8.4	8.4	8.4	8.2	8.2	8.0														
BLOSSOM LOOP S(5.7L)						FC5																													
4377491	5.014	7.446	L	2019		0012	CRACKING	7.5	7.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	9.4	7.5													
ANDERSON COLUMBIA CO., INC(2020)							SPRIDE	7.9	7.7	7.5	7.8	7.7	7.6	7.8	8.9	9.0	8.9	8.9	8.9	8.9	8.7													
53030000	0.000	0.586	L	1	1	65	CRACKING	3.0*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0															
75 231			2	11.1		6700	RIDE	7.6	6.8	8.9	9.0	8.3	8.5	8.5	8.6	8.6	8.6	8.3	8.4	8.2														
						FC5M																													
4397401	0.000	0.586	L	2021		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	10.0	10.0	10.0	8.5													
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.2	8.0	8.1	8.4	8.2	8.3	8.3	8.4	8.3	8.3	8.6	8.7	8.7	8.5													
53030035	0.708	4.979	R	1	1	65	CRACKING	3.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
75 231			2	21.0		6100	RIDE	8.2	8.2	8.9	9.0	8.5	8.5	8.5	8.7	8.7	8.6	8.5	8.5	8.5														
C/D 0.586 53030000(0.7C)						FC5M																													
4397401	1.579	4.806	R	2021		0012	CRACKING	9.0	9.0	9.0	7.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	8.5													
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.4	8.5	8.3	8.4	8.4	8.3	8.4	8.4	8.4	8.4	8.7	8.7	8.7	8.5													
53030035	0.708	4.979	L	1	1	65	CRACKING	3.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5															
75 231			2	21.0		6100	RIDE	8.0	7.9	9.0	9.0	8.4	8.5	8.5	8.6	8.6	8.5	8.5	8.4	8.4														
C/D 0.586 53030000(0.7C)						FC5M																													
4397401	1.567	4.806	L	2021		0012	CRACKING	9.5	9.5	9.0	7.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	9.4	8.0													
ANDERSON COLUMBIA CO., INC(2023)							SPRIDE	8.3	8.3	8.2	8.4	8.3	8.2	8.3	8.4	8.4	8.3	8.6	8.6	8.6	8.4													
53040000	0.000	7.369	C	1	1	55	CRACKING	10.0	10.0	10.0	10.0	9.5	9.5	8.0	7.0	7.0	5.5*	5.5*	5.5*	5.5*															
71			2	9.6		5300	RIDE	8.6	8.6	8.4	8.4	8.0	8.0	8.0	8.1	8.0	7.8	7.7	7.6	7.6														
BIG BONE LN(0.1L)						FC95MR																													
4230651	0.000	7.356	C	2013		0012	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	5.5*													
ANDERSON COLUMBIA CO., INC(2014)							SPRIDE	7.4	8.8	8.6	8.4	8.3	8.2	8.2	8.0	8.0	7.9	8.1	8.0	7.8	7.4													
53040000	7.369	7.940	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	8.5	5.5*	5.5*	5.5*	5.5*															
71			1	12.0		8200	RIDE	8.6	8.6	8.4	8.4	8.0	8.0	8.1	8.0	7.9	7.8	7.7	7.6	7.6														
CR-280/ROCKY CRK RD(7.5R)						FC95MR																													
4230651	7.356	7.780	C	2013		0012	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	5.5*													
ANDERSON COLUMBIA CO., INC(2014)							RIDE	7.4	8.8	8.6	8.4	8.3	8.2	8.2	8.0	8.0	7.9	7.9	8.0	7.9	7.5													
53040000	7.940	8.526	R	1	4	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	10.0															
71			2	9.6		19700	RIDE	8.4	8.3	8.3	8.1	7.8	7.8	7.6	7.8	7.6	7.5	7.3	7.3	8.2														
SIDE ROAD(8.0C)						LGD																													
4230651	8.044	8.861	C	2013		0012	CRACKING	10.0	10.0		9.4	9.4	9.4	9.3	9.4	9.4	9.2	9.1	9.1	8.9	8.5													
ANDERSON COLUMBIA CO., INC(2016)							RIDE	8.2	8.1		8.1	7.9	7.5	8.0	8.1	8.2	8.1	7.7	8.0	8.2	8.0													
53040000	8.526	8.853	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5															
71			2	9.6		19700	RIDE	8.4	8.3	8.4	8.3	8.3	8.4	8.2	7.8	7.6	7.5	7.3	7.3	7.6														
WHITE TAIL RD(8.5C)						FC95MR																													
4457601	8.528	9.301	R	2024		0012	CRACKING	8.5	8.5		8.5	7.5	7.5	7.0	7.0	7.0	6.0*	6.0*	5.5*	8.7	7.5													
ANDERSON COLUMBIA CO., INC(2025)							SPRIDE	7.6	7.5		7.4	7.6	7.5	7.3	7.4	7.4	7.2	7.1	7.2	8.2	7.8													
53040000	8.853	10.216	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5															
71			2	7.2		17500	RIDE	8.5	8.5	8.4	8.3	8.3	8.4	8.2	7.6	8.0	7.3	7.6	7.6	7.6														
ANDERSON COLUMBIA(9.1R)						FC3																													
2193491	8.138	10.217	C	1997		0213	CRACKING	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	6.0*	6.0*	5.5*	3.5*	1.0*													
ANDERSON COLUMBIA CO., INC(2000)							S RIDE	7.6	7.5	7.6	7.4	7.6	7.5	7.3	7.4	7.4	7.2	7.1	7.2	7.1	6.7													
4457601	9.334	10.216	R	2024		0012																													

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / SURFTYPE / W_BMP / ASTYPE / W_EMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / AADT / WKMX-P / WKMX-F	SPD	DISTRESS RATINGS ========	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53040000	8.853	10.216	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5															
71			2	7.2	17500		RIDE	8.5	8.6	8.5	8.4	8.3	8.3	8.2	8.2	8.3	8.1	7.7	8.1	8.0															
					FC3																														
2193491	8.138	10.217	C	1997	0213		CRACKING	8.5	8.5	8.5	8.5	7.5	7.5	7.0	6.0*	5.5*	5.5*	3.5*	3.5*	3.5*	1.0*														
ANDERSON COLUMBIA CO., INC(2000)					S		RIDE	8.0	8.0	7.7	7.7	7.8	7.8	7.8	7.6	7.5	7.5	7.4	7.4	7.3	6.9														
4457601	8.528	10.216	L	2024	0012																														
53040000	8.600	8.853	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	8.5															
71			2	9.6	19700		RIDE	8.5	8.6	8.5	8.4	8.3	8.3	8.2	7.6	7.6	7.5	7.4	7.3	8.0															
					FC95MR																														
4457601	8.608	9.301	L	2024	0012		CRACKING	8.5	8.5		8.5	7.5	7.5	7.0	6.0*	5.5*	5.5*	3.5*	3.5*	9.0	8.0														
ANDERSON COLUMBIA CO., INC(2025)					SPRIDE		RIDE	8.0	8.0		7.7	7.8	7.8	7.8	7.6	7.5	7.5	7.4	7.4	7.6	7.2														
53040000	7.940	8.600	L	1	4	45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	10.0															
71			2	9.6	19700		RIDE	8.5	8.5	8.2	8.0	7.7	7.8	7.6	7.6	7.6	7.5	7.4	7.3	8.5															
SIDE ROAD(8.0C)					LGD																														
4230651	8.044	8.861	C	2013	0012		CRACKING	10.0	10.0		9.4	9.4	9.4	9.3	9.3	9.4	9.5	9.5	9.5	9.4	9.0														
ANDERSON COLUMBIA CO., INC(2016)							RIDE	8.5	8.4		8.0	7.7	7.7	8.1	8.0	8.0	8.0	7.5	7.8	8.0	7.8														
53040000	7.369	7.940	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5	8.5	5.5*	5.5*	5.5*	5.5*															
71			1	12.0	8200		RIDE	8.6	8.6	8.4	8.4	8.0	8.0	7.7	7.6	7.6	7.8	7.7	7.6	7.6															
DOVE REST DR(7.4L)					FC95MR																														
4230651	7.356	7.780	C	2013	0012		CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	5.5*														
ANDERSON COLUMBIA CO., INC(2014)							RIDE	7.4	8.8	8.6	8.4	8.3	8.2	8.2	8.0	8.0	7.9	7.6	7.6	7.5	7.1														
53050000	0.000	6.075	C	1	1	55	CRACKING	10.0	10.0	8.5	7.5	6.5	5.0*	5.0*	5.0*	5.0*	3.5*	10.0	10.0	10.0															
73			2	19.0	6100		RIDE	8.7	8.6	8.5	8.3	8.2	8.2	7.9	8.1	7.9	7.8	8.7	8.6	8.5															
LAFAYETTE ST(0.0C)					FC95M																														
4153831	0.079	6.075	C	2008	0012		CRACKING	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.0	6.5	6.5	7.1	5.0*														
PREFERRED MATERIALS, INC. (2010)							RIDE	8.5	8.5	8.4	8.3	8.3	8.2	8.1	8.2	8.0	8.0	8.0	7.9	7.8	7.4														
53050000	6.971	10.560	R	1	1	65	CRACKING	10.0	8.5	8.5	7.5	6.5	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0															
75 231			2	27.3	12200		RIDE	8.9	8.9	8.8	8.7	7.9	7.6	7.0	6.5		8.6	8.5	8.5	8.4															
SPRINGFIELD RD(8.9C)					FC5M																														
4397221	7.018	10.495	R	2020	0012		CRACKING	10.0	10.0	8.5	8.5	7.5	7.0	5.5*	4.0*	10.0	10.0	10.0	10.0	9.6	7.5														
ANDERSON COLUMBIA CO., INC(2021)							RIDE	8.4	8.4	8.2	8.5	8.5	8.3	8.4	8.5	9.0	8.9	8.9	8.8	8.8	8.6														
53050000	10.560	18.365	R	1	1	65	CRACKING	6.5	6.5	6.5	6.5		10.0	10.0	10.0	9.5	9.5	9.5	7.5	7.5															
75 231			2	20.9	12300		RIDE	8.5	8.6	8.2	8.3		8.2	8.2	8.4	8.3	8.2	7.9	7.7	7.4															
CECIL RD(11.1R)					FC5M																														
							CRACKING	7.5	7.5	4.5*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.2	4.5*														
				(2016)			RIDE	7.3	6.8	6.3*	8.8	8.7	8.7	8.7	8.8	8.7	8.7	8.6	8.6	8.6	8.4														
4565831	10.445	18.365	C	2029	0012																														
53050000	10.560	18.365	L	1	1	65	CRACKING	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	10.0	7.5	6.5															
75 231			2	20.9	12300		RIDE	8.3	8.4	8.1	8.0		8.3	8.3	8.5	8.4	8.3	8.1	7.9	7.6															
SIDE ROAD(13.3C)					FC5M																														
							CRACKING	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.2	4.5*														
				(2016)			RIDE	7.5	7.1	6.5	8.7	8.7	8.6	8.7	8.7	8.7	8.6	8.6	8.5	8.6	8.4														
4565831	10.445	18.365	C	2029	0012																														
53050000	6.971	10.560	L	1	1	65	CRACKING	10.0	10.0	10.0	8.5	6.5	3.5*	1.0*	1.0*		10.0	10.0	10.0	10.0															
75 231			2	27.3	12200		RIDE	8.9	8.9	8.7	8.7	8.0	7.4	7.0	6.6		8.6	8.5	8.5	8.4															
DOUGLAS RD(7.8L)					FC5M																														
4397221	7.018	10.495	L	2020	0012		CRACKING	10.0	10.0	8.5	7.0	6.5	6.5	4.5*	3.5*	10.0	10.0	10.0	10.0	9.3	7.5														
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE		RIDE	8.5	8.5	8.3	8.6	8.5	8.5	8.5	8.5	9.0	8.9	8.9	8.8	8.8	8.6														
53050001	0.000	0.566	C	1	1	55	CRACKING	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.5	6.0*	6.0*	10.0	10.0	10.0															
73			2	16.1	4900		RIDE	8.7	7.9	8.7	8.3	7.2	8.1	8.1	7.7	7.7	7.5	8.5	8.1	8.2															
MP 6.075 OF 53050000(0.0C)					FC95M																														
4153831	0.000	0.548	C	2008	0012		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	8.5	6.5														
PREFERRED MATERIALS, INC. (2010)					SPRIDE		RIDE	7.4	7.1	6.8	8.1	7.9	7.4	7.6	7.9	7.6	7.3	7.9	7.8	7.7	7.3														
53050001	0.566	0.939	R	1	1	65	CRACKING					10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0															
75 231			2	27.3	12200		RIDE					8.0	7.2	7.3	8.1	7.9	7.9	7.7	7.6	7.6															
					FC5M																														
4377471	0.566	0.939	C	2019	0012		CRACKING	7.5	7.5	7.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.0														
ANDERSON COLUMBIA CO., INC(2020)							RIDE	7.2	7.2	6.8	8.1	8.1	8.1	7.5	8.5	8.4	8.3	8.2	8.3	8.4	8.2														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

```
RDWYID       BMP    EMP RW SYS TYP SPD DISTRESS SURVEYED YEAR                                                                                FUTURE
 SR   US   G_BMP  G_EMP LN   %T   AADT RATINGS  2000  2001  2002  2003  2004  2005  2006  2007  2008  2009  2010  2011  2012
INTERSECT AT (MP|SIDE)        SURFTYPE ========
ITMSEG-P   W_BMP  W_EMP RW FY-P WKMX-P
CONTRACTOR (AGE_ONE YEAR)       ASTYPE          2013  2014  2015  2016  2017  2018  2019  2020  2021  2022  2023  2024  2025  2030
ITMSEG-F   W_BMP  W_EMP RW FY-F WKMX-F                                                                                                (PMRS)

53050001   0.566  0.939  L   1   1  65 CRACKING                          10.0  10.0  10.0  10.0  10.0  10.0  10.0  10.0   9.0
75   231                2 27.3  12200 RIDE                               8.0   7.2   7.3   8.0   8.1   8.0   8.3   8.3   8.1
SR 73( 0.6L)                    FC5M
4377471    0.566  0.939  C 2019   0012 CRACKING  9.0   9.0   7.5  10.0  10.0  10.0  10.0  10.0  10.0  10.0  10.0  10.0   9.3   7.0
ANDERSON COLUMBIA CO., INC(2020)       RIDE      8.0   7.6   7.6   8.5   8.4   8.4   8.5   9.0   8.7   8.7   8.9   8.7   8.5   8.3
-----------------------------------------------------------------------------------------------------------------------------------
53060000   0.000  8.363  C   1   1  55 CRACKING 10.0  10.0  10.0  10.0  10.0   9.5   9.5   9.5   8.5   8.0   8.0   7.0   7.0
77                     2  9.4   3600 RIDE      9.1   8.9   9.0   9.0   8.6   8.6   8.5   8.6   8.6   8.5   8.3   8.2   8.1
CR 164( 0.5C)                   FC95MR
4307801    0.346  7.965  C 2016   0012 CRACKING  7.0   7.0   6.0*  6.0* 10.0  10.0  10.0  10.0  10.0  10.0  10.0   9.5   8.3   6.5
ANDERSON COLUMBIA CO., INC(2017)     SPRIDE      7.9   7.9   7.7   8.0   8.6   8.6   8.5   8.4   8.3   8.2   8.1   8.0   8.0   7.6

53060000   8.363 10.726  C   1   1  35 CRACKING 10.0  10.0   8.5   8.5   8.5   6.5   6.5   6.5   5.5*  5.5*  3.5*  3.5* 10.0
77                     2  7.4   2952 RIDE      8.4   8.3   8.2   8.0   7.5   7.4   7.1   7.3   7.1   6.8   6.6   6.4   7.9
BROWN ST( 8.4R)                 FC95M
4193061    8.363 10.724  C 2010   0012 CRACKING 10.0  10.0  10.0   8.5   8.5   8.5   7.5   7.0   7.0   5.5*  4.0*  4.0*  3.3*  1.5*
JONES CONSTRUCTION OF NORT(2012)     SPRIDE      7.7   7.7   7.6   7.8   7.7   7.6   7.4   7.5   7.4   7.3   7.1   7.1   7.0   6.6
2193462    8.363 10.726  C 2025   0012

53060000  10.726 12.705  C   1   1  55 CRACKING  5.5*  5.5* 10.0  10.0  10.0   9.0   9.0   9.0   9.0   7.5   7.5   7.5   7.5
77                     2  7.4   2952 RIDE      8.4   8.3   8.5   8.6   8.2   8.4   8.2   8.4   8.4   8.3   8.1   8.0   8.0
JOHNS RD(11.0L)                 FC125M
4325531   10.726 12.705  C 2017   0226 CRACKING  6.0*  6.0*  5.5*  4.0* 10.0  10.0  10.0  10.0  10.0  10.0  10.0  10.0   8.6   7.0
ANDERSON COLUMBIA CO., INC(2017)     SPRIDE      7.8   7.7   7.4   7.6   8.6   8.5   8.4   8.4   8.3   8.2   8.2   8.1   8.1   7.7
-----------------------------------------------------------------------------------------------------------------------------------
53070000   0.000  0.959  C   1   1  35 CRACKING  8.5   8.5   8.5  10.0  10.0  10.0  10.0  10.0  10.0   8.5   8.5   8.5   8.5
2                      2 13.8   4700 RIDE      7.3   6.7   6.4   8.1   7.9   8.0   7.9   8.1   8.0   8.0   7.9   7.9   7.9
MILL CREEK RD( 0.1L)            FC95MR
4436461    0.045  0.958  C 2022   0012 CRACKING  8.5   8.5   8.5   8.5   8.5   7.5   7.0   6.0*  6.0*  6.0* 10.0  10.0  10.0   8.5
ANDERSON COLUMBIA CO., INC(2023)     SPRIDE      7.9   7.8   7.6   7.4   7.3   7.2   7.3   7.2   7.2   7.1   8.3   8.3   8.3   7.9

53070000   1.323  7.643  C   1   1  55 CRACKING       10.0  10.0  10.0  10.0   8.5   7.5   7.0   5.5*  5.0*  3.0*  3.0* 10.0
2                      2 15.0   2200 RIDE            8.9   8.7   8.6   8.2   8.2   8.1   8.2   8.0   7.8   7.3   7.5   8.6
COTTON ST( 1.3C)                FC95MR
4230701    1.332  8.116  C 2011   0226 CRACKING 10.0  10.0  10.0  10.0  10.0   9.0   8.5   7.5   7.5   7.0   6.0*  5.5*  4.8*  3.0*
JONES CONSTRUCTION OF NORT(2012)     SPRIDE      8.5   8.5   8.2   8.2   7.9   7.8   7.6   7.7   7.5   7.4   7.3   7.2   7.1   6.7
4508061    1.323  7.643  C 2026   0012

53070000   8.231 13.000  C   1   1  55 CRACKING 10.0  10.0   8.0   8.0   7.0   5.5*  5.5* 10.0  10.0  10.0  10.0  10.0  10.0
2                      2 25.1   1650 RIDE      8.5   8.6   8.4   8.3   8.1   7.9   7.8   8.6   8.6   8.6   8.5   8.5   8.5
CAMPBELLTON CITY LIMITS( 8.2C)  FC95M
4113971    8.152 12.946  C 2006   0012 CRACKING 10.0  10.0  10.0  10.0   9.0   8.5   8.5   7.5   7.5   7.0   6.0*  5.5*  3.9*  1.5*
ANDERSON COLUMBIA CO., INC(2007)       RIDE      8.2   8.3   8.2   8.1   8.0   7.9   7.7   7.9   7.7   7.7   7.9   7.7   7.6   7.2
4508061    8.237 13.075  C 2026   0012

53070000  13.000 17.451  C   1   1  55 CRACKING 10.0   9.0   9.0   9.0   9.0   8.5   7.5   7.0   5.5*  5.5*  5.5*  5.5* 10.0
2                      2 22.6   1600 RIDE      8.6   8.5   8.5   8.4   8.0   7.9   7.9   7.9   7.9   7.7   7.5   7.6   8.7
ST PHILLIPS RD(13.1R)           FC95M
4216421   14.929 17.177  C 2011   0012 CRACKING 10.0  10.0  10.0  10.0   9.5   9.5   9.5   8.5   8.5   8.5   7.0   6.0*  5.3*  3.5*
ANDERSON COLUMBIA CO., INC(2012)     SPRIDE      8.7   8.6   8.4   8.1   8.0   7.9   7.7   7.8   7.6   7.3   7.5   7.3   7.0   6.6
4529431   13.094 17.445  C 2027   0012

53070000  17.451 23.102  C   1   1  55 CRACKING  6.5   6.5   5.5*  5.5* 10.0  10.0  10.0  10.0  10.0   9.0   9.0   9.0   9.0
2                      2 22.6   1600 RIDE      8.7   8.6   8.4   8.3   8.0   8.4   8.1   8.4   8.4   8.4   8.3   8.3   8.4
CR 167(18.4C)                   FC95M
4307931   17.451 23.102  C 2016   0012 CRACKING  9.0   9.0   9.0   9.0  10.0  10.0  10.0  10.0  10.0  10.0  10.0   9.5   8.5   7.0
ANDERSON COLUMBIA CO., INC(2017)     SPRIDE      8.3   8.3   8.2   8.0   8.7   8.7   8.5   8.6   8.3   8.3   8.3   8.2   8.0   7.6

53070000  23.102 26.145  C   1   1  55 CRACKING  8.5   8.5   7.5   7.5   7.0   6.5  10.0  10.0  10.0   9.0   9.0   9.0   8.5
2                      2 24.1   1650 RIDE      8.0   8.2   7.8   7.5   7.1   6.9   8.1   8.3   8.2   8.1   7.9   7.9   8.0
SR 71(23.1C)                    FC125M
4456321   23.115 26.139  C 2023   0012 CRACKING  8.5   8.5   7.5   7.5   7.5   7.0   7.0   5.5*  5.5*  4.0*  3.5* 10.0  10.0   8.5
ANDERSON COLUMBIA CO., INC(2024)     SPRIDE      7.8   7.7   7.6   7.6   7.5   7.3   7.3   7.4   7.3   7.2   7.2   8.5   8.4   8.0

53070000  26.145 32.614  C   1   1  55 CRACKING 10.0  10.0  10.0  10.0  10.0  10.0  10.0   9.0   8.5   8.5   8.5   7.5   7.0
2                      2 24.1   2208 RIDE      8.5   8.5   8.4   8.4   8.0   8.0   8.1   8.3   8.2   8.1   8.0   8.1   7.9
GROVE RD(26.4L)                 FC125M
4325481   26.145 32.614  C 2016   0012 CRACKING  7.0   6.0*  5.5*  5.5* 10.0  10.0  10.0  10.0  10.0  10.0  10.0   8.0   8.0   6.5
ANDERSON COLUMBIA CO., INC(2017)       RIDE      7.9   7.8   7.6   7.6   8.4   8.4   8.2   8.3   8.1   7.9   8.0   7.9   7.7   7.3
-----------------------------------------------------------------------------------------------------------------------------------
```

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / W_BMP	EMP / G_EMP / W_EMP	RW / LN / RW	SYS / %T / FY-P / FY-F	TYP / SURFTYPE / WKMX-P / WKMX-F	SPD / AADT	DISTRESS RATINGS ======== / ASTYPE	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	FUTURE 2030 (PMRS)
53070001	0.000	0.506	C	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.0*	10.0															
2			2	28.7		1800	RIDE		8.3	8.4	8.2	7.9	6.7	8.2	7.9	8.2	8.2	8.0	7.7	8.6														
CR-2A(0.0R)						FC95MR																													
4230701	0.000	0.499	C	2011		0226	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	6.5	5.5*	3.5*	3.2*	1.5*														
				(2012)			RIDE	8.6	8.4	8.2	8.1	8.0	7.8	7.7	7.8	7.5	7.2	7.3	7.0	6.7	6.3													
4508061	0.000	0.484	C	2026		0012																													
53090000	0.000	7.667	C	1	1	55	CRACKING	4.0*	4.0*	3.5*		10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	8.5															
71			2	10.7		6200	RIDE	7.7	7.5	7.1		8.0	8.1	8.0	8.2	8.1	8.1	8.0	8.0	7.9															
SR 10(0.0C)						FC125																													
							CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	6.0*	5.5*	3.5*	3.1*	0.5*													
				(2004)			RIDE	7.9	7.9	7.7	7.4	7.4	7.3	7.1	7.2	7.1	6.9	7.0	6.9	6.8	6.4*													
4455421	0.000	8.377	C	2023		0012																													
53090000	7.667	13.097	C	1	1	55	CRACKING	4.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
71			2	9.5		3200	RIDE	7.7	7.5	7.1	7.4	8.1	8.2	8.2	8.4	8.4	8.2	8.2	8.2	8.2															
ALBERNATHY ST(7.7L)						FC125																													
2193781	4.531	14.076	C	2001		0012	CRACKING	9.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.0*														
ANDERSON COLUMBIA CO., INC				(2004)			SPRIDE	8.1	8.1	7.9	7.7	7.7	7.6	7.5	7.5	7.5	7.4	7.3	7.4	7.3	6.9														
4307822	8.377	14.047	C	2025		0012																													
53090000	13.097	14.073	R	1	1	35	CRACKING	4.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
71			1	10.7		3800	RIDE	7.7	7.5	7.1	7.4	8.1	8.2	8.2	8.1	8.0	8.2	8.2	8.2	8.2															
THIRTEENTH AVE(13.2C)						FC125																													
2193781	4.531	14.076	C	2001		0012	CRACKING	9.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	6.0*	6.0*	3.5*	3.5*	1.0*														
ANDERSON COLUMBIA CO., INC				(2004)			SPRIDE	8.1	8.1	7.9	7.7	7.7	7.6	7.5	7.5	7.5	7.4	7.5	7.4	7.4	7.0														
4307822	8.377	14.047	C	2025		0012																													
53090000	14.073	17.840	C	1	1	55	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	6.0*															
71			2	14.0		2100	RIDE	8.9	8.8	8.7	8.5	8.0	8.1	8.0	8.1	7.9	7.7	7.4	7.5	7.0															
FOURTH AVE(14.1L)						FC95MR																													
4307821	14.091	17.887	C	2015		0226	CRACKING	5.5*	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.8	6.0*														
OXFORD CONSTRUCTION COMPAN				(2016)			SPRIDE	6.3*	6.1*	5.9*	8.6	8.4	8.4	8.2	8.2	8.1	8.0	7.9	7.8	7.6	7.2														
53090000	13.097	14.073	L	1	1	35	CRACKING	4.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0															
71			1	10.7		3800	RIDE	7.7	7.5	7.1	7.4	8.1	8.2	8.2	8.1	7.9	8.2	8.2	8.2	8.2															
THIRTEENTH AVE(13.2C)						FC125																													
2193781	4.531	14.076	C	2001		0012	CRACKING	9.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	6.0*	6.0*	3.5*	3.0*	0.5*														
ANDERSON COLUMBIA CO., INC				(2004)			SPRIDE	8.1	8.1	7.9	7.7	7.7	7.6	7.5	7.5	7.5	7.4	7.1	7.2	7.1	6.7														
4307822	8.377	14.047	C	2025		0012																													
53110000	6.555	7.572	R	1	1	45	CRACKING	5.5*	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.0	9.0	9.0	9.0															
276			1	10.1		5600	RIDE	7.4	9.1	8.8	8.8	8.3	8.2	8.0	8.2	8.1	8.0	7.9	7.9	7.5															
CR 167(6.6R)						FC95MR																													
4397231	6.901	7.576	R	2020		0012	CRACKING	9.0	9.0	8.0	8.0	7.0	6.0*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5														
ANDERSON COLUMBIA CO., INC				(2021)			RIDE	7.4	7.8	7.4	7.5	7.4	7.3	6.9	6.9	8.2	8.2	8.1	8.1	8.0	7.6														
53110000	7.572	9.950	C	1	1	45	CRACKING	6.0*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	8.0	8.0															
276			2	13.0		9200	RIDE	7.5	8.9	8.7	8.4	8.2	8.1	7.9	7.6	7.3	7.2	7.4	6.9	6.9															
MASHBURN RD(7.8C)						FC95MR																													
							CRACKING	8.0	8.0	8.0	7.0	7.0	6.0*	5.5*	3.5*	10.0	10.0	10.0	10.0	10.0	8.5														
				(2021)			RIDE	7.4	6.8	7.2	7.4	7.4	7.2	7.1	7.1	8.3	8.3	8.2	8.2	8.1	7.7														
53110000	6.555	7.572	L	1	1	45	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5															
276			1	10.1		5600	RIDE	7.2	8.8	8.7	8.6	8.2	8.1	7.8	8.2	8.1	7.9	8.1	8.0	7.9															
NEW HOPE RD(6.7L)						FC95MR																													
4397231	6.555	7.576	L	2020		0012	CRACKING	9.5	9.5	8.0	8.0	7.0	6.0*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5														
ANDERSON COLUMBIA CO., INC				(2021)			RIDE	7.9	7.6	7.6	7.3	7.2	7.2	7.0	6.9	8.2	8.1	8.1	8.1	8.0	7.6														
53120000	0.000	15.793	C	1	1	55	CRACKING	10.0	10.0	10.0	9.5	9.5	8.5	8.5	8.5	8.5	8.5	8.5	7.0	7.0															
73			2	9.9		3200	RIDE	8.9	9.0	8.8	8.7	8.2	8.3	8.1	8.0	8.1	7.9	7.7	7.6	7.3															
HASTY POND RD(1.5L)						FC95MR																													
4325721	0.000	12.555	C	2016		0012	CRACKING	7.0	7.0	6.0*	6.0*		10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.7	7.0														
ANDERSON COLUMBIA CO., INC				(2018)			SPRIDE	7.0	6.8	6.5	7.1		8.4	8.3	8.2	7.8	7.7	7.6	7.2	6.9	6.5														
53120000	15.793	17.591	C	1	1	35	CRACKING	7.5	7.0		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0															
166			2	3.3		9100	RIDE	7.7	7.7		8.3	7.9	7.9	7.8	7.8	7.9	7.5	7.4	7.3	7.3															
FRANKLIN ST(15.9C)						FC95MR																													
							CRACKING	8.0	8.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.0	6.0*													
				(2015)			RIDE	7.1	7.3	8.2	7.8	7.6	7.4	7.4	7.4	7.2	7.1	6.8	6.9	6.9	6.5														

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION

ALL SYSTEM PAVEMENT CONDITION FORECAST

PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN -- 2026 - 2031, EXTRACTED ON 08/28/2025

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

---------- DISTRICT = 3 COUNTY = JACKSON ----------

RDWYID / SR US / INTERSECT AT (MP|SIDE) / ITMSEG-P / CONTRACTOR (AGE_ONE YEAR) / ITMSEG-F	BMP / G_BMP / SURFTYPE / W_BMP / ASTYPE / W_EMP	EMP / G_EMP / W_EMP	RW / RW	SYS / LN / FY-P / FY-F	TYP / %T / WKMX-P / WKMX-F	SPD / AADT	DISTRESS RATINGS ========	SURVEYED YEAR 2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	FUTURE 2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030 (PMRS)
53120000	17.591	21.173	C	1	1	55	CRACKING	7.5	7.0		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0	8.0																
166			2	6.5		4900	RIDE	7.7	7.7		8.3	7.9	7.9	7.8	7.8	8.0	7.5	7.4	7.3	7.3															
LODGE DR(17.9R)							FC125																													
2193851	17.614	20.860	C	2001		0012	CRACKING	8.0	8.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	6.0*	5.5*	5.5*	4.3*	2.0*														
ANDERSON COLUMBIA CO., INC(2003)							SPRIDE	7.1	7.3	7.4	7.2	7.1	7.0	6.9	7.0	6.9	6.9	6.9	6.8	6.8	6.4*														
4397381	17.470	21.173	C	2025		0012																														
53130000	0.000	3.373	C	1	1	55	CRACKING	10.0	10.0	9.0	9.0	8.5	7.0	7.0	7.0	5.5*	5.5*	3.5*		10.0																
69			2	17.1		2000	RIDE	8.5	8.6	8.3	8.2	7.8	7.5	7.5	7.4	7.3	7.2	6.9		8.6															
BONE YARD RD(0.8R)							FC95MR																													
4192941	0.000	3.373	C	2010		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.1	6.0*														
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE	8.5	8.5	8.3	8.3	8.2	8.2	8.1	8.0	7.9	7.7	7.7	7.6	7.4	7.0														
4546191	0.000	8.432	C	2028		0012																														
53130000	3.373	4.210	R	1	1	45	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.5	7.5	7.0	7.0	7.0		10.0																
69			1	17.1		2600	RIDE	8.8	8.8	8.6	8.3	7.9	7.8	7.7	7.5	7.4	7.5	7.2		8.6															
CHIPS DR(4.0R)							FC95MR																													
4192941	3.374	4.209	C	2010		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	7.9	6.0*														
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE	8.5	8.5	8.3	8.1	8.2	8.2	8.1	7.9	7.9	7.8	7.8	7.6	7.6	7.2														
4546191	0.000	8.432	C	2028		0012																														
53130000	4.210	8.555	C	1	1	55	CRACKING	10.0	10.0	9.0	9.0	8.5	7.0	7.0	7.0	5.5*	4.0*	3.5*		10.0																
69			2	17.1		2600	RIDE	8.7	8.7	8.4	8.0	7.8	7.6	7.6	7.7	7.6	7.3	7.1		8.2															
BRUSHEY POND RD(5.3C)							FC95MR																													
4192941	4.210	8.555	C	2010		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.3	5.5*														
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE	8.3	8.2	8.0	8.0	8.0	7.9	7.8	7.8	7.7	7.6	7.4	7.4	7.3	6.9														
4546191	0.000	8.432	C	2028		0012																														
53130000	8.555	24.069	C	1	1	55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.0	6.0*	6.0*	6.0*																
69			2	11.9		2200	RIDE	8.8	8.8	8.7	8.6	8.3	8.3	8.2	7.7	8.3	8.2	8.0	8.0	8.0															
PARK ST(8.6R)							FC95MR																													
4230661	8.564	24.062	C	2013		0012	CRACKING	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.5	7.5	7.5	7.0	5.0*														
ANDERSON COLUMBIA CO., INC(2014)							SPRIDE	7.9	8.9	8.8	8.6	8.5	8.3	8.2	8.0	7.8	7.6	7.5	7.3	7.1	6.7														
4566061	8.432	24.069	C	2029		0012																														
53130000	3.373	4.210	L	1	1	45	CRACKING	10.0	10.0	10.0	10.0	9.0	8.5	8.5	6.5	6.5	6.5	6.5		10.0																
69			1	17.1		2600	RIDE	8.6	8.4	8.5	8.3	7.4	7.7	7.6	7.6	7.6	7.2	6.8		8.4															
							FC95MR																													
4192941	3.374	4.209	C	2010		0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0	6.5	4.5*														
ANDERSON COLUMBIA CO., INC(2012)							SPRIDE	8.3	8.3	8.1	7.9	7.8	7.7	7.6	7.5	7.3	7.2	7.1	6.9	6.8	6.4														
4546191	0.000	8.432	C	2028		0012																														
53220000	0.000	10.709	C	1	1	55	CRACKING	4.5*	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0																
273			2	17.6		3400	RIDE	7.4	8.6	8.4	8.4	8.2	8.1	8.1	8.2	8.2	8.0	8.0	8.0	8.0															
CR 164(0.5C)							FC95MR																													
4397241	0.000	10.687	C	2020		0012	CRACKING	8.0	8.0	8.0	7.0	7.0	5.5*	5.5*	5.5*		10.0	10.0	10.0	10.0	8.5															
ANDERSON COLUMBIA CO., INC(2022)							SPRIDE	7.9	7.9	7.8	7.7	7.5	7.5	7.4	7.4		8.4	8.3	8.4	8.3	7.9															

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
"@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
2030 FORECASTED BY PAVEMARS (PMRS).