FDOT

Florida Department of Transportation

RON DESANTIS
GOVERNOR

605 Suwannee Street
Tallahassee, FL 32399-0450

JARED W. PERDUE, P.E.
SECRETARY

October 24, 2023

Khoa Nguyen
Director, Office of Technical Services
Federal Highway Administration
3500 Financial Plaza, Suite 400
Tallahassee, Florida 32312

Re: State Specifications Office
        Section: 527
        Proposed Specification: **5270500 Detectable Warnings.**

Dear Mr. Nguyen:

We are submitting, for your approval, two copies of the above referenced Supplemental
Specification.

The changes are proposed by Olivia Townsend to clarify the removal of existing detectable
warnings and include the language in surface preparation.

Please review and transmit your comments, if any, within two weeks (10 business days).
Comments should be sent via email daniel.strickland@dot.state.fl.us.

If you have any questions relating to this specification change, please call me at (850) 414-4130.

                    Sincerely,

                    Signature on File

                    Daniel Strickland, P.E.
                    State Specifications Engineer

DS/dh
Attachment
cc: Florida Transportation Builders' Assoc.
        State Construction Engineer

DETECTABLE WARNINGS.
(REV 8-25-23)

ARTICLE 527-5 is deleted and the following substituted:

527-5 Basis of Payment.
Price and payment will be full compensation for all work specified in this Section, including all labor, surface preparation, including removal of existing removable or surface applied detectable warnings, materials, equipment, and incidentals necessary to complete the work.

Payment will be made under:
Item No. 527- 2-   Detectable Warnings - per square foot.

DETECTABLE WARNINGS
(REV 8-25-23)

ARTICLE 527-5 is deleted and the following substituted:

527-5 Basis of Payment.
Price and payment will be full compensation for all work specified in this Section, including all labor, surface preparation including removal of existing removable or surface applied detectable warnings, materials, equipment, and incidentals necessary to complete the work.

Payment will be made under:

Item No. 527- 2-   Detectable Warnings - per square foot.