


SIGNAL ATTACHMENT

## Notes:

1. With the approval of the resident engineer, the service head hole for joint use poles may be drilled by the utility company at an angle of 90° but not less than 45° to the face of the pole.

2. Use only span wire mounting assemblies listed on the APL.




Detail A

TWO POINT ATTACHMENT

12/17/2015 3:03:48 PM

| LAST REVISION | REVISION | DESCRIPTION | FDOT | | INDEX NO. | SHEET NO. |
|---|---|---|---|---|---|---|
| 12/17/15 | | Deleted the Pivotal Hanger Assembly; Changed the Upper and Lower Reinforcement Plates to Tri-Stud Wire Clamps; Changed the Message Cable Clamp; Deleted Notes #1, 3-5 and added new note; Deleted the Vertical Clearance Information; Changed Bottom Tether Clamp to a Tri-Stud Clamp. | | 2016 DESIGN STANDARDS | 17727 | 2 of 2 |

SIGNAL CABLE & SPAN WIRE INSTALLATION DETAILS