ORIGINATION FORM

THE INFORMATION BELOW IS TO BE PROVIDED BY THE ORIGINATOR

✦ Modify Specification _____6490000_____.
Section/File number

☐ New Section _____.
Section number

Subject: Steel Strain Poles Mast Arms and Monotube Assemblies

Origination date: 5/17/2007

Originator: Paul Vinik
Office/Phone: 352-955-6649
Email address/ paul.vinik@dot.state.fl.us
Userid: RT820PV

Problem statement: These structures have an alarming coating system failure rate that is very expensive to the department.

Information source: Don Roberts, Randall Borgersen, Brian Blanchard, Ananth Prasad, Bob Burleson, Carboline, Sherwin Williams, PPG.

Background data: The solution was to implement a bond and warranty for these structures.

Recommended Usage Note: Use on all contracts containing signal mast arm structures let after implementation.

Estimated fiscal impact, if implemented: These modifications are intended to save the department money through reduction of coating repairs needed on failing structures.

Implementation of these changes, if and when approved, will begin with the January 2008 letting.