

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Letting: 01230119 Call Order: 007 Proposal: E1W05-R0 District:01
Counties: GLADES, HENDRY
Road Name: Guardrail Repair
Limits: Midpoint
Project(s): 43274417265(*) Federal Aid No: N/A
Total Roadway Length: 0.000 Miles Contract Days: 365
Total Bridge Length: 0.000 Miles Letting Date: 01/19/23
Total Proposal Length: 0.000 Miles Contract Execution Days: 10
Special Start Date: N/A
Aquis/Flexible Start Time:

Proposal Budget Estimate: \$260,000.00

Please read the full advertisement

Description:

The work under this Contract consists of Guardrail Repair.

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Call Order: 007 Proposal: E1W05-R0

ALT	Item	Description	Unit	Quantity
Section 0001 ASPHALT REPAIR (MANUAL) (TN)				
	0339- 1-	MISCELLANEOUS ASPHALT PAVEMENT	TN	20.000
	0515- 2-311	PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,42" TYPE 1	LF	200.000
	0515- 2-321	PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,54" TYPE 1	LF	50.000
	0536- 7- 1	SPECIAL GUARDRAIL POST- DEEP POST FOR SLOPE BREAK CONDITION- TIMBER OR STEEL	EA	4.000
	0536- 7- 3	SPECIAL GUARDRAIL POST- ENCASED POST FOR SHALLOW MOUNT	EA	50.000
	0538- 1-	GUARDRAIL RESET	LF	100.000
	0544- 3- 1	CRASH CUSHION, TL-3, NARROW	EA	2.000
	E536- 3-141	GUARDRAIL STANDARD PANEL (REPLACE) (SHOP BENT)	LF	100.000
	E536- 3-142	GUARDRAIL STANDARD PANEL (REPLACE) (0' - 50')	LF	700.000
	E536- 3-143	GUARDRAIL STANDARD PANEL (REPLACE) (51' - 200')	LF	150.000
	E536- 3-144	GUARDRAIL STANDARD PANEL (REPLACE) (> 200')	LF	250.000
	E536- 3-242	GUARDRAIL THRIE BEAM (REPLACE) (0' - 50')	LF	100.000
	E536- 6-424	END ANCHORAGE ASSEM (REPLACE) (PARALLEL)	EA	21.000
	E536- 6-425	GUARDRAIL END TREATMENT-FLARED APPROACH TERMINAL, REPLACE, MASH	EA	21.000
	E536- 12-604	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN CONC.)	EA	5.000
	E536- 12-605	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN ASPH.)	EA	10.000
	E536- 12-606	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN SOIL)	EA	10.000
	E536- 12-608	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN ASPH.)	EA	50.000
	E536- 12-609	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN SOIL)	EA	10.000
	E536- 12-615	GUARDRAIL REPAIRS (REPLACE) (FILLER BLOCKS)	EA	100.000
	E536- 15-	MISCELLANEOUS GUARDRAIL MAINTENANCE	LF	100.000
	E536-322-502	END ANCHOR ASSEM FLARED (REPL ROUND END SECT)	EA	3.000
	E536-322-506	END ANCHOR ASSEM FLARED (REPL GUARDRAIL BEAM)	EA	1.000
	E536-322-508	END ANCHOR ASSEM FLARED (REPL TIMBER BREAK POST)	EA	1.000
	E536-322-515	END ANCHOR ASSEM FLARED (REPL AMBER REFLECT SHEET)	EA	10.000
	E536-322-517	END ANCHOR ASSEM FLARED (REPL SHORT TIMBR BREAK POST)	EA	1.000
	E536-324-515	END ANCHOR ASSEM PARALLEL (REPL AMBER REFLECT SHEET)	EA	10.000