

Florida Department of Transportation

RON DESANTIS GOVERNOR 1109 S. Marion Avenue Lake City, FL 32025-5874 KEVIN J. THIBAULT, P.E. SECRETARY

October 26, 2020

To: Prospective Bidders

Maintenance: Jim Brown, Gaye Lynn Norman, Yongman Roberts, Ian Middlemas, Mark Kuhn

Addendum No.: 1, E20G2, FIN# 44503125220, FCO Contract Provide sufficient work force, equipment, component parts, materials, oversight, shop drawings (as needed), permitting, safety, clean-up, as-builts, and all incidentals necessary to remove existing security/surveillance system components and install a new fully integrated and functioning security/ surveillance system as depicted and specified in contract documents in St. Johns County.

In Response to Bid Questions and Answers:

Question: Please let us know the make of Camera with model number? Answer: Contractor shall provide detailed information regarding proposed cameras for the Department's review/approval. Cameras must meet all specifications and be compatible with the overall system. The final decision on any substitution will be at the Department's discretion.

Question: Where will be location of MDF/IDF for cabling? Answer: The MDF/IDF location will be in main hallway utility closet in Bldg. 2396 at 3600 DOT Road St. Augustine Florida.

Question: Are all the cameras wall mount?

Answer: All cameras are wall mount with the exception of the camera at the main office entrance (ceiling mount dome camera) and the vehicle wash (can be wall mount but the structure is a metal structure). A site visit may be necessary to verify conditions.

Question: As we can see all the cameras are outdoor So, do we need to install Surge protection for all the cameras Answer: Please refer to Scope and Plans. One surge protector is required at each camera.

> Improve Safety, Enhance Mobility, Inspire Innovation www.fdot.gov

Question: What kind of cabling do we need to install (Underground / in conduit)? Answer: All cabling should be suitable for the conditions it is installed in. Any underground cable will be installed in conduit.

Question: For clarification, is Gate 1 and Gate 5 being replace with two (2) 31ftx7ft at each opening. The scope calls for one gate operator at each gate. Answer: Please refer to the schematic. Gates 1 and 5 will have the gates replaced with 31 x 7 ft gates. All 5 gates will have new gate openers installed.

Question: The current card access system is a Siemen proprietary system; can we provide the cabling and pathway for the additional card readers and the owner to self-preformed the installation.

Answer: All new cabling shall be provided to the point of connection with the existing Siemen system.

Question: For the 90-degree camera field of view can we provide one 5 mp camera in lieu of 20 mp (4x5mp) camera.

Answer: The intent is to provide high definition camera capable of providing the specified field of view. The Department will consider any equivalent or better. Contractor shall provide detailed information for any substitution for review/ approval. The final decision on any substitution will be at the Department's discretion.

Question: The video management server BCD212-MVR-P-110-64T-8 is no longer available, can we provide a Milestone approved management server as an equal. Answer: The Department will consider any equivalent or better server. Contractor shall provide detailed information for any substitution for review/approval. The final decision on any substitution will be at the Department's discretion.

Question: Are we able to cut and patch concrete if necessary, for underground conduit installation.

Answer: Yes, but patches shall meet FDOT standards.

You must sign, date and fax a copy of this addendum back to me by close of business today to indicate receipt. The bidder is required to acknowledge the addendum in the space provided on the proposal.

All PROPOSAL HOLDERS must acknowledge receipt of this addendum on the first page of the Bid Proposal in the space provided.

Company Name

Signature

Date

Thank you, Jim Brown District Contracts Administrator Phone: 386-758-3798 Fax: 386-758-3791