

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Call Order: 004 Proposal: E4W33-R0

ALT	Item	Description	Unit	Quantity
Section 0001 TRAFFIC CONTROL DEVICES CONTROL (MH)				
	0102- 14-	TRAFFIC CONTROL OFFICER	HR	21.000
	0400-145-	CLEANING CONCRETE SURFACE	SF	20.000
	0400-153-	NON SHRINK GROUT, F&I, MISCELLANEOUS- STRUCTURES REHAB	CF	4.000
	0401- 70- 3	RESTORE SPALLED AREAS, LATEX MODIFIED MORTAR- ACRYLIC	CF	8.000
	0411- 1-	EPOXY MATERIAL FOR CRACK INJECTION- STRUCTURES REHAB	GA	3.000
	0411- 2-	CRACKS INJECT & SEAL- STRUCTURES REHAB	LF	11.000
	0460- 1- 13	STRUCTURAL STEEL REHAB- BOLTS, NUTS, WASHERS & PLATES	LB	703.000
	0460- 94-	STRUCTURAL STEEL REPAIR- WELDS	LF	4.000
	0561- 2-	COATING EXISTING STRUCTURAL STEEL	SF	270.000
	0649- 26- 1	STEEL MAST ARM ASSEMBLY, REMOVE, POLE ONLY- ENTIRE FOUNDATION REMAINS	EA	1.000
	0649- 26- 3	STEEL MAST ARM ASSEMBLY, REMOVE, SHALLOW FOUNDATION- BOLT ON ATTACHMENT	EA	1.000
	0649- 26- 7	STEEL MAST ARM ASSEMBLY, REMOVE, REMOVE ARM AND ATTACHMENTS; POLE REMAINS	EA	1.000
	0649- 40- 1	STEEL MAST ARM ASSEMBLY- REPLACE SCREEN ON EXISTING POLE	EA	45.000
	0649- 40- 2	STEEL MAST ARM ASSEMBLY- REPLACE HAND HOLE COVER ON EXISTING POLE	EA	3.000
	0649- 40- 3	STEEL MAST ARM ASSEMBLY- REPLACE POLE CAP ON EXISTING POLE	EA	25.000
	0649- 40- 4	STEEL MAST ARM ASSEMBLY- REPLACE STRUCTURAL GROUT PAD ON EXISTING POLE	EA	40.000
	0649- 40- 5	STEEL MAST ARM ASSEMBLY- REPAIR/REPLACE BROKEN WELD ON EXISTING POLE	EA	3.000
	0649- 40- 8	STEEL MAST ARM ASSEMBLY- FURNISH & INSTALL BIRD SCREEN ON EXISTING POLE	EA	35.000
	0700- 4-611	OVERHEAD STATIC SIGN STRUCTURE, SHALLOW FOUNDATION REMOVAL, CANTILEVER	EA	1.000
	0700- 4-621	OVERHEAD STATIC SIGN STRUCTURE, SHALLOW FOUNDATION REMOVAL, SPAN	EA	1.000
	0715- 19- 61	HIGH MAST LIGHT POLE, REMOVE POLE- FOUNDATION REMAINS	EA	1.000
	0715- 19- 62	HIGH MAST LIGHT POLE, SHALLOW FOUNDATION REMOVAL	EA	1.000
	E101- 72-	MOBILIZATION (EMERGENCY RESPONSE)	EA	1.000
	E460- 82-	BOLT TIGHTENING	EA	203.000