

Index 649-031 Mast Arm Assemblies

ORIGINATION

Date: May 13, 2013

Name: Cheryl Hudson

Phone: 850-414-5332

Email: cheryl.hudson@dot.state.fl.us

COMMENTARY

Sheet 2, Change Note 3: Half-height anchor 'jam' nut.

Sheet 4: Match splice length to Sheet 3.

Sheet 5: Clarify that luminaire arms are to be galvanized steel not aluminum.

COMMENTS AND RESPONSES

BLACK = Industry Review Comments **RED** = Standard Plans Response

Name: Ravi Kannan, P.E.

Date: August 20, 2019

COMMENT:

I noticed that on Sheet 4 of 6 of the 2019/2020 Standard Plans Index 649-031, the arm splice length is shown at 2'-0". Should that value be 3'-0"?

RESPONSE:

Date: August 20, 2019

Yes, It should be the same as the splice on Sheet 3 (3' nominal, 2' Min.)

