Index 654-001 Rectangular Rapid Flashing Beacon Assembly

ORIGINATION

Date: May 25, 2023 **Name:** Rick Jenkins **Phone:** (850) 414-4355

Email: Rick.Jenkins@dot.state.fl.us

COMMENTARY

Note 4 and callouts were updated at the request of the TERL to allow for various sign options.

Note 12 was added because of new spread footing design option in Standard Plans Index 700-120.

COMMENTS AND RESPONSES

BLACK = Industry Review Comments **BLUE** = Standard Plans Response **GREEN** = Change Made to Index

Name: Sid Whichard Date: 8/24/2023

COMMENT: Recommend reference to meet requirements of Specification 346 for the concrete foundation since not referenced in Specification 646, or update Specification 646 to include meet requirements of Specification 346.

RESPONSE: Thanks for the comment. Specification 646 is referenced in Note 7 and Section 646-2 Materials, references Section 346 and specifies Class II concrete.

CHANGE MADE TO INDEX: No.

Response Date: 8/24/2023