
Index 654-001 Rectangular Rapid Flashing Beacon Assembly

ORIGINATION

Date: 7/7/25

Name: Dibakar Saha

Phone: (850)410-5417

Email: dibakar.saha@dot.state.fl.us

COMMENTARY

Updated W16-7P and Rectangular Rapid Flashing Beacon (RRFB) depiction to more accurately represent dimensions. As W16-7P dimensions depend on the size of W11-2 sign panel, a note 13 was added to send the user to Standard Plans Index 700-010 for the appropriate dimensions.

COMMENTS AND RESPONSES

BLACK = Industry Review Comments **BLUE** = Standard Plans Response **GREEN** = Change Made to Index

Name: Chad Lingenfelter

Date: 8/20/25

COMMENT: Index 654-001 - Recommend the proposed Note 13, "See Standard Plans Index 700-010 for sign dimensions" replace Note 4, "W11-2 sign panel shown ..." instead of added to avoid confusion and contradiction.

RESPONSE: Note 4 and the new Note 13 are related but do not cancel out or replace one another. Note 4 is in reference to the sign panel that may vary, while Note 13 is in reference to the W16-7P sign specifically.

CHANGE MADE TO INDEX: No.

Response Date: 8/25/25