

**State of Florida Department of Transportation  
PAVEMENT EVALUATION AND CONDITION DATA SHEET**

Project No.:		432416-1		Cored By:		Ardaman		Date:		6/3/2014		Page No.:		1 of 1							
County:		Osceola		Highway Sect. No.:		92130		From:		I-4 Collector Ramps		To:		World Dr. Interchange							
Road No.:		SR 400 (I-4 Ramp 92130)		Begin MP:		3.630		End MP:		5.239		Length:		1.609 Miles							
Core No.	MP	Distance from left edge of lane (ft.)	Lane	Wheel Path	Pavement Layers (in.)				Core Length (in.)	Base		Crack				Pavt Cond.	Rut Depth (in)	Cross Slope (%)	Comments		
					FC-2	Type S						Depth (in)	Type	Class	Extent						
1	0.297	3.0	Ramp	X	0.5	5.0					5.5	LR	9.5	1.6	BR	III	S	P			Ramp 001/EB Collector. Top down crack.
2	0.297	5.0	Shoulder	---		2.1					2.1	LR	5.9	---	---	---	---	F			Ramp 001/EB Collector
3	0.607	5.5	Ramp	---	0.5	6.0					6.5	LR	10.0	3.0	BR	III	S	P			Ramp 001/EB Collector Top down crack. Outside Lane
4	0.607	5.0	Shoulder	---		2.8					2.8	LR	6.7	---	---	---	---	F			Ramp 001/EB Collector
5	0.960	6.0	Ramp	---	0.7	5.1					5.8	LR	10.2	3.3	BR	III	S	P			Ramp 001/EB Collector Top down crack. Outside Lane
6	0.960	5.5	Shoulder	---		1.9					1.9	LR	3.6	---	---	---	---	F			Ramp 001/EB Collector
7	1.277	3.5	Ramp	X	0.5	5.0					5.5	LR	10.3	1.9	BR	II	S	P			Ramp 001/EB Collector Top down crack.
8	1.277	7.0	Shoulder	---		2.0					2.0	LR	5.0	---	---	---	---	F			Ramp 001/EB Collector
9	0.234	8.5	Ramp	X	1.0	5.0					6.0	LR	10.0	0.7	BR	II	M	F			Ramp 002/WB Collector.
10	0.234	5.5	Shoulder	---		1.8					1.8	LR	6.0	---	---	---	---	F			Ramp 002/WB Collector.
11	0.358	5.0	Ramp	---	0.4	5.1					5.5	LR	10.5	1.3	BR	III	S	F			Ramp 002/WB Collector Top down crack. Outside Lane
12	0.358	4.5	Shoulder	---		2.2					2.2	LR	6.3	---	---	---	---	F			Ramp 002/WB Collector.
13	0.808	7.5	Ramp	---	0.6	5.4					6.0	LR	10.3	3.0	BR	III	S	F			Ramp 002/WB Collector Top down crack. Outside Lane
14	0.808	2.5	Shoulder	---		2.4					2.4	LR	8.1	---	---	---	---	F			Ramp 002/WB Collector.
15	1.109	5.0	Ramp	---	1.4	4.5					5.9	LR	10.1	1.4	BR	II	L	F			Ramp 002/WB Collector Top down crack.
16	1.109	5.0	Shoulder	---		2.3					2.3	LR	5.2	---	---	---	---	F			Ramp 002/WB Collector.
17	0.092	10.0	Ramp	X	0.6	4.0					4.6	LR	10.4	0.1	BR	I	M	F			Ramp 003/EB Decel
18	0.092	3.0	Shoulder	---		4.4					4.4	LR	10.6	---	---	---	---	F			Ramp 003/EB Decel
19	0.998	12.5	Ramp	X	0.7	4.0					4.7	LR	10.3	2.2	BR	III	S	F			Ramp 004/EB Decel. Top down crack.
20	0.998	3.0	Shoulder	---		2.1					2.1	LR	6.4	---	---	---	---	F			Ramp 004/EB Decel
21	0.102	9.5	Ramp	X	0.4	3.8					4.2	LR	10.8	---	---	---	---	F			Ramp 005/EB Accel
22	0.102	4.0	Shoulder	---		2.4					2.4	LR	5.9	---	---	---	---	F			Ramp 005/EB Accel
23	0.181	10.0	Ramp	X	0.4	4.4					4.8	LR	12.2	2.3	BR	II	S	F			Ramp 006/WB Decel
24	0.181	2.5	Shoulder	---		2.1					2.1	LR	14.4	---	---	---	---	F			Ramp 006/WB Decel
25	0.998	12.5	Ramp	X	0.5	3.3					3.8	LR	11.2	1.8	BR	II	S	F			Ramp 007/WB Decel
26	0.998	4.0	Shoulder	---		1.5					1.5	LR	5.0	---	---	---	---	F			Ramp 007/WB Decel
27	0.258	15.0	Ramp	X	0.5	3.7					4.2	LR	10.8	2.0	BL	III	S	P			Ramp 008/WB Accel
28	0.258	3.0	Shoulder	---		2.0					2.0	LR	4.8	---	---	---	---	F			Ramp 008/WB Accel
29	0.101	7.0	Ramp	X	0.9	4.8					5.7	LR	10.6	1.5	BR	III	S	F			Ramp 012/EB Accel
30	0.101	3.5	Shoulder	---		2.3					2.3	LR	12.7	---	---	---	---	F			Ramp 012/EB Accel