

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = HAMILTON																					
RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	RATINGS	SURVEYED YEAR									
INTERSECT	AT	(MP)	(SIDE)									2000	2001	2002	2003	2004	2005	2006	2007	2008	2009
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKMX-P							2013	2014	2015	2016	2017	2018	2019	2020	2021	2022
CONTRACTOR	(AGE_ONE	YEAR)			ASTYPE																
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKMX-F																
																					FUTURE
																					2030
																					(PMRS)
32010000	0.000	16.601	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
25 41			2	8.8	1900	RIDE	9.1	9.1	9.0	8.9	8.7	8.7	8.7	8.7	8.7	8.7	8.7	8.6	8.5	8.5	8.5
BOAT RAMP(	0.1L)				FC125M																
					(2014)	CRACKING	8.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
2098315	0.000	16.600	C	2029	0012	RIDE	8.3	8.7	8.5	8.3	8.3	8.2	8.2	8.0	8.1	8.1	8.0	8.0	8.0	8.0	8.4
32010000	16.601	18.292	C	1	1 55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
25 41			2	11.2	6000	RIDE	8.9	9.0	8.8	8.7	8.5	8.6	8.6	8.6	8.6	8.6	8.6	8.5	8.5	8.5	8.4
SE 50 DR(16.7R)					FC125M																
4286951	16.625	24.681	C	2014	0012	CRACKING	9.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5
ANDERSON COLUMBIA CO., INC(2016)					SPRIDE		8.3	8.4		8.3	8.3	8.2	8.1	8.1	8.0	8.0	8.0	8.0	8.0	8.0	8.0
32010000	18.292	20.130	C	1	1 35	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	8.5	8.5	8.5	7.5	7.0
6 41			2	8.8	7000	RIDE	8.1	8.3	8.0	8.0	7.5	7.5	7.6	7.5	7.4	7.5	7.3	7.3	7.3	7.0	7.0
SE 11TH ST(18.3L)					FC125M																
4286951	16.625	24.681	C	2014	0012	CRACKING	7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	5.6*
ANDERSON COLUMBIA CO., INC(2016)					SPRIDE		7.2	7.2	6.9	8.0	7.9	7.8	7.8	7.7	7.7	7.6	7.7	7.6	7.6	7.5	7.1
32010000	20.130	25.096	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
6 41			2	8.8	4200	RIDE	8.7	8.6	8.4	8.5	8.2	8.2	8.2	8.3	8.3	8.2	8.2	8.2	8.2	8.2	8.1
NW 104 PL(20.1R)					FC125M																
4286951	16.625	24.681	C	2014	0012	CRACKING	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	4.7*
ANDERSON COLUMBIA CO., INC(2016)					SPRIDE		8.0	8.0		8.2	8.2	8.0	7.9	7.8	7.8	7.8	7.6	7.6	7.6	7.6	7.2
32010000	25.096	30.741	C	1	1 60	CRACKING	7.5	7.5	3.0*	3.0*	3.0*	2.0*	2.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0
25 41			2	8.8	1600	RIDE	8.2	8.3	8.0	8.0	6.4*	7.0	7.1		8.6	8.6	8.5	8.5	8.5	8.5	8.5
NW 34 TRL(25.5R)					FC125																
2098183	24.949	30.741	C	2006	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	6.0*
ANDERSON COLUMBIA CO., INC(2008)					RIDE		8.4	8.5	8.4	8.2	8.2	8.2	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	7.7
32010000	30.741	31.246	C	1	1 35	CRACKING	7.0	7.0	7.0	7.0	7.0	5.5*	4.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
25 41			4	8.8	1600	RIDE	6.7	6.6	5.9	5.8	6.5	5.3*	5.8	8.8	8.6	8.7	8.3	8.3	8.4	8.3	8.3
BEN BATES ST(30.8C)					FC125																
2098183	30.741	31.176	C	2006	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	5.1*
ANDERSON COLUMBIA CO., INC(2007)					RIDE		8.3	8.1	8.1	8.0	8.1	7.9	8.1	8.0	7.9	8.1	7.8	7.7	7.7	7.9	7.5
32010000	31.246	32.782	C	1	1 55	CRACKING	7.0	7.0	6.0*	6.0*	4.0*	3.0*	2.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
25 41			2	8.8	1600	RIDE	8.0	7.9	7.6	7.6	6.9	6.9	7.1	8.6	8.6	8.6	8.6	8.5	8.4	8.3	8.3
SUWANNEE ST(31.3R)					FC125																
2098183	31.176	32.782	C	2006	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	6.0*	3.8*
ANDERSON COLUMBIA CO., INC(2007)					RIDE		8.2	8.2	8.1	8.0	8.1	8.0	7.9	7.9	7.9	7.9	7.7	7.7	7.7	7.7	7.3
32020000	0.000	0.107	C	1	6 35	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5
136			2	7.2	2600	RIDE	7.3														
RIVER ST(0.0R)					FC125																
					(1999)	CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5
						RIDE															
32030000	0.000	3.325	C	1	7 60	CRACKING	5.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5
51 129			2	4.9	6100	RIDE	7.7	7.5	8.5	8.4	8.0	8.1	8.2	8.3	8.3	8.3	8.0	7.9	7.9	7.9	7.9
SW 79 TER(0.3L)					FC125																
4470771	0.926	2.681	C	2024	0012	CRACKING	9.5	9.5	9.5	8.0	7.0	7.0	7.0	6.0*	5.5*	5.5*	5.5*	5.5*	5.5*	10.0	9.0
ANDERSON COLUMBIA CO., INC(2025)					SPRIDE		7.8	7.8	7.7	7.5	7.5	7.5	7.3	7.3	7.3	7.2	7.3	7.3	7.3	8.6	8.2
32030000	3.325	3.979	C	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5	9.5
51 129			2	8.8	6100	RIDE	8.1	8.2	7.9	8.1	6.8	7.8	7.7	7.8	7.7	7.8	7.7	7.7	7.9	7.9	7.9
FROM 100101(3.7L)					FC125M																
					(2013)	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0
2098312	3.287	6.126	C	2025	0012	RIDE	8.3	8.2	8.0	7.7	7.6	7.5	7.6	7.4	7.3	7.1	7.2	7.2	7.1	6.0*	3.8*
																					1.5*
32030000	3.979	6.398	C	1	1 50	CRACKING	5.5*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5
51 129			2	8.8	6100	RIDE	7.4	7.3	8.5	8.5	8.1	8.0	8.3	8.3	8.3	8.3	8.0	7.9	7.9	7.9	7.9
SW 55TH DR(5.3L)					FC125																
2098311	0.050	6.080	C	2001	0012	CRACKING	9.5	9.5	9.5	9.5	9.5	9.5	8.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	5.2*	1.5*
ANDERSON COLUMBIA CO., INC(2002)					SPRIDE		7.4	7.8	7.8	7.6	7.6	7.5	7.5	7.4	7.5	7.3	7.3	7.3	7.3	7.3	6.9
2098312	3.287	6.126	C	2025	0012																

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

----- DISTRICT = 2 COUNTY = HAMILTON -----																									
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR																	FUTURE
SR US	G BMP	G_EMP	LN	%T	AADT		RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012					
INTERSECT	AT (MP SIDE)						=====																		
ITMSEG-P	W BMP	W_EMP	RW	FY-P	WKMX-P																				
CONTRACTOR	(AGE ONE YEAR)				ASTYPE			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025					
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKMX-F																				2030 (PMRS)
32100000	9.506	19.175	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	8.0	8.0	7.5	7.5	7.5	6.5						
93 I75	451.5	461.2	3	29.4	43000		RIDE	8.9	8.9	8.6	8.7	8.1	8.3	8.2	8.2	8.1	7.9	7.6	7.4						
						FC5M																			
4234321	9.506	19.175	C	2011	0012		CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	7.5	7.5	6.5					
ANDERSON	COLUMBIA CO., INC(2013)						SPRIDE	8.1	8.1	8.1	8.5	8.4	8.4	8.5	8.5	8.6	8.6	8.5	8.5	8.4					4.0*
																									8.3
32100000	0.000	9.506	L	4	1	70	CRACKING	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0						
93 I75	442.0	451.5	3	29.4	43000		RIDE	9.1	9.1	9.0	9.1	7.7	8.5	8.6	8.6	8.5	8.4	8.4	8.2	8.2					
						FC5M																			
4246312	0.000	9.506	C	2012	0012		CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	6.5					4.0*
ANDERSON	COLUMBIA CO., INC(2013)						SPRIDE	7.8	8.0	7.9	8.4	8.5	8.4	8.6	8.7	8.7	8.7	8.6	8.6	8.5					8.4

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 "**" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 "@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).