

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)																						
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P																	
CONTRACTOR (AGE ONE YEAR)					ASTYPE																	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																2030 (PMRS)	
36001000	0.000	8.656	R	1	1 65	CRACKING		7.5	7.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
25 301			2	3.5	29500	RIDE		8.9	8.9	8.6	8.6	8.0	7.7	8.0	8.2	8.2	8.2	8.2	8.1	8.0		
CR 25A(0.0C)					FC5HP																	
4411361	0.000	8.656	C	2021	0012	CRACKING		10.0	10.0	9.0	7.0	6.0*	6.0*	6.0*	6.0*	4.5*	4.5*		10.0	10.0	9.0	
ANDERSON COLUMBIA CO., INC(2024)					SPRIDE			7.9	7.8	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0		8.5	8.5	8.3	
36001000	8.656	14.221	R	1	1 65	CRACKING		3.5*	0.0*	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0		
25 441			2	21.3	7500	RIDE		8.7	8.6	8.6	8.5	8.0	8.0	8.0	7.8	7.9	7.8	7.7	7.7	7.5		
NW140 ST(9.7R)					FC5M																	
4272801	8.911	13.788	C	2016	0012	CRACKING		8.0	7.0	7.0	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.4	7.0	
ANDERSON COLUMBIA CO., INC(2018)					SPRIDE			7.5	7.3	7.2	7.7		8.6	8.6	8.5	8.4	8.3	8.2	8.3	8.2	8.0	
36001000	8.656	14.221	L	1	1 65	CRACKING		3.5*	0.0*	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5		
25 441			2	21.3	7500	RIDE		8.8	8.5	8.5	8.5	8.0	8.0	7.9	7.9	7.8	7.8	7.7	7.7	7.5		
NW 142 PL(10.0L)					FC5M																	
4272801	8.911	13.788	C	2016	0012	CRACKING		6.5	6.5	6.0*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.3	7.0	
ANDERSON COLUMBIA CO., INC(2018)					SPRIDE			7.5	7.4	7.2	7.8		8.6	8.5	8.5	8.4	8.2	8.3	8.3	8.2	8.0	
36001000	0.000	8.656	L	1	1 65	CRACKING		7.5	6.5	4.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
25 301			2	3.5	29500	RIDE		8.9	8.8	8.6	8.5	7.7	7.3	8.3	8.4	8.3	8.4	8.4	7.7	8.0		
CR 25A(0.0C)					FC5HP																	
4411361	0.000	8.656	C	2021	0012	CRACKING		10.0	10.0	10.0	8.5	7.0	7.0	6.5	6.5	3.5*	3.5*		10.0	10.0	9.0	
ANDERSON COLUMBIA CO., INC(2024)					SPRIDE			8.2	8.1	8.0	8.2	8.1	8.1	8.2	8.2	8.1	8.1		8.4	8.4	8.2	
36002000	0.000	4.727	R	1	1 60	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	6.5	6.5	7.5	6.5		
200 301			2	25.0	16800	RIDE		8.7	8.9	8.9	8.7	8.3	8.2	8.1	7.9	8.0	7.9	7.9	8.0	7.8		
SR 25(0.0C)					FC5M																	
4272491	0.000	4.774	C	2013	0012	CRACKING		6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.7	4.5*	
(2014)					RIDE			7.7	8.0	8.0	8.4	8.4	8.4	8.5	8.5	8.5	8.4	8.5	8.5	8.5	8.3	
36002000	0.000	4.727	L	1	1 60	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	7.5	6.5		
200 301			2	25.0	16800	RIDE		8.1	8.7	8.7	8.6	8.2	8.1	8.1	8.0	7.9	7.8	7.8	7.6	7.5		
US-441/SR-25(0.0L)					FC5M																	
4272491	0.000	4.774	C	2013	0012	CRACKING		6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.9	5.0*	
(2014)					RIDE			7.4	8.2	8.3	8.5	8.5	8.5	8.6	8.6	8.6	8.6	8.6	8.6	8.5	8.3	
36004000	0.000	0.633	R	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5		
464			2	15.1	31000	RIDE		8.3	8.3	8.5	7.7	7.3	7.1	7.2	6.8	7.3	7.8	8.0	7.7	7.7		
COLLEGE RD SW(0.0C)					FC3																	
2386731	0.000	1.228	C	1993	0012	CRACKING		8.5	8.5	8.5	8.5	8.5	8.5	8.0	7.0	7.0	7.0	7.0	7.0	6.8	3.0*	
CRRGGS CONSTRUCTION COMPAN(1994)					S RIDE			7.1	6.9	7.1	7.0	7.0	7.1	6.9	7.1	7.1	7.8	7.2	7.2	7.1	6.8	
4526341	0.017	1.210	C	2029	0226																	
36004000	0.633	1.242	R	1	1 40	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	10.0	10.0	10.0		
464			2	15.1	31000	RIDE		8.3	8.3	8.5	7.7	7.3	7.1	7.2	6.8	7.3	7.8	6.9	6.9	6.9		
SW 12 AVE(0.7C)					FC95																	
(2010)					CRACKING			10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	8.0	6.0*	
4526341	0.017	1.210	C	2029	0226			6.7	6.9	7.0	6.9	6.8	6.4	6.5	6.4	6.4	6.8	7.0	6.7	6.7	6.4	
36004000	1.242	7.213	R	1	1 50	CRACKING		8.0	8.0	8.0	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	9.0	9.0		
464			2	4.1	33581	RIDE		8.5	8.5	8.4	8.0	7.6	7.3	7.0	7.0		8.0	8.0	8.0	7.9		
SECOND AVE SW(1.3C)					FC5																	
4155231	1.242	7.213	C	2007	0012	CRACKING		8.5	8.5	8.5	8.5	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	4.5*	3.7*	0.0*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.8	7.8	7.7	7.8	7.7	7.6	7.6	7.7	7.7	7.6	7.6	7.1	7.0	6.8	
4411411	1.335	7.213	C	2023	0012																	
36004000	1.242	7.213	L	1	8 50	CRACKING		9.0	9.0	9.0	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	10.0		
464			2	4.1	33581	RIDE		8.6	8.6	8.4	8.3	7.8	7.6	7.2	7.1		8.0	7.9	7.6	7.5		
SW 3 AVE(1.3L)					FC5																	
4155231	1.242	7.213	C	2007	0012	CRACKING		8.5	8.5	8.5	8.5	7.0	7.0	7.0	4.5*	4.5*	4.5*	4.5*	3.5*			
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.5	7.4	7.4	7.7	7.6	7.6	7.4	7.5	7.5	7.1	6.9	6.5			
4411411	1.335	7.213	C	2023	0012																	
36004000	0.633	1.242	L	1	1 40	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
464			2	15.1	31000	RIDE		7.7	7.6	7.8	7.9	7.5	7.2	7.5	7.2	7.2	7.3	7.0	7.0	7.2		
SW 12 AVE(0.7C)					FC95																	
2386731	0.000	1.228	C	1993	0012	CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.0	7.0	7.0	8.0	8.0	4.5*	
CRRGGS CONSTRUCTION COMPAN(1994)					S RIDE			7.0	6.9	6.8	6.8	6.7	6.4	6.1	6.5	6.4	6.9	6.8	6.5	6.4	6.1	
4526341	0.017	1.210	C	2029	0226																	

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	RATINGS	SURVEYED YEAR										FUTURE				
INTERSECT AT (MP SIDE)												2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	W_KMX-P							2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
CONTRACTOR (AGE ONE YEAR)					ASTYPE																			(PMRS)		
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	W_KMX-F																					
36004000	0.000	0.633	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
464			2	15.1	31000	RIDE	7.7	7.6	7.8	7.9	7.5	7.2	7.5	7.2	7.5	7.2	7.5	7.2	7.2	7.3	7.5	7.3	7.2	7.2		
COLLEGE RD SW(0.0C) FC3																										
2386731	0.000	1.228	C	1993	0012	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5		
CRAGGS CONSTRUCTION COMPAN(1994)					S	RIDE	7.4	7.1	7.4	7.5	7.9	8.0	8.0	7.5	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0		
4526341	0.017	1.210	C	2029	0226																					
36008000	0.000	3.737	R	1	1 45	CRACKING	6.5	6.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
492			2	23.3	16400	RIDE	7.5	7.5	7.4	6.8	6.0*	5.5*	7.6	7.4	7.8	7.7	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8		
PINE AVE N(0.0C) FC125M																										
4306551	0.000	3.719	C	2018	0012	CRACKING	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5	8.5		
ANDERSON COLUMBIA CO., INC(2020)					S	RIDE	7.3	7.5	7.3	7.2	7.1	6.9		8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0	8.0		
36008000	0.000	3.737	L	1	1 45	CRACKING	7.5	6.5	6.5	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
492			2	23.3	16400	RIDE	7.7	7.6	7.5	7.2	6.2*	5.7*	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8	7.8		
PINE AVE N(0.0C) FC125M																										
4306551	0.000	3.719	C	2018	0012	CRACKING	7.0	7.0	6.5	6.5	6.5	6.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
ANDERSON COLUMBIA CO., INC(2020)					S	RIDE	7.1	7.0	7.0	6.6	6.7	6.6		7.9	7.9	7.7	7.6	7.6	7.6	7.6	7.6	7.6	7.6	7.6		
36009000	0.000	1.486	C	1	1 55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
35			2	17.3	14500	RIDE	8.6	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7		
CR-25/SE 110 ST(0.0R) FC125M																										
4248851	0.000	1.570	C	2013	0012	CRACKING	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
D.A.B. CONSTRUCTORS, INC (2014)					SPRIDE		7.3	8.2	8.3	8.2	8.2	8.0	8.0	8.1	8.2	8.1	8.2	8.1	8.2	8.1	8.2	8.1	8.2	8.1		
36009000	1.486	5.269	R	1	1 55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
35			2	10.2	27500	RIDE	8.6	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7		
SE 96 PL RD(1.5R) FC125M																										
2386931	1.486	5.244	C	2015	0213	CRACKING	6.5	6.5	6.0*	6.0*				10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
(2020)					RIDE		7.7	7.5	7.3	7.3				7.3	7.3	7.2	7.1	7.2	7.1	7.2	7.1	7.2	7.1	7.2		
36009000	5.269	10.843	R	1	1 45	CRACKING	8.5	8.5	8.5	7.0	6.0*	3.5*	3.5*	3.5*						4.5*	4.5*					
35			2	15.7	21400	RIDE	8.6	8.6	8.3	7.8	7.1	6.6	6.2	5.7						5.9	6.4					
CR-464(5.5R) FC125R																										
2386771	5.123	10.827	C	2010	0213	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
(2013)					RIDE		8.3	8.2	8.4	8.2	8.2	8.1	8.0	8.0	8.1	8.0	8.1	8.0	8.1	8.0	8.1	8.0	8.1	8.0		
36009000	5.269	10.843	L	1	1 45	CRACKING	8.5	8.5	8.5	7.0	6.0*	3.5*	3.5*	3.5*						4.5*	4.5*					
35			2	15.7	21400	RIDE	8.6	8.6	8.3	7.8	7.1	6.6	6.2	5.7						5.9	6.4					
CR 464(5.5L) FC125R																										
2386771	5.123	10.827	C	2010	0213	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
(2013)					RIDE		8.2	8.3	8.3	8.2	8.2	8.2	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1		
36009000	1.486	5.269	L	1	1 55	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
35			2	10.2	27500	RIDE	8.6	8.4	8.3	8.2	7.8	7.8	7.5	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7	7.7		
SE 92 PL RD(1.8L) FC125M																										
2386931	1.486	5.244	C	2015	0213	CRACKING	6.5	6.5	6.0*	6.0*				10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
(2020)					RIDE		7.7	7.5	7.3	7.3				7.7	7.7	7.6	7.6	7.6	7.6	7.6	7.6	7.6	7.6	7.6		
36010000	14.347	14.711	R	1	6 35	CRACKING	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5						10.0	9.5	9.5	9.5	9.5		
25 27			2	16.4	12800	RIDE	6.3*	7.3	7.5	7.2	7.0	7.1	6.9	6.1						7.3	6.9	6.9	6.9	6.9		
BASELINE RD(14.3R) FC125M																										
4392381	14.347	14.711	C	2020	0012	CRACKING	9.5	9.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5		
WESTERN SURETY COMPANY					SPRIDE		6.1	7.0	6.8	5.9	6.0	5.8	5.6	5.6	5.7	5.7	5.7	5.7	5.7	5.7	5.7	5.7	5.7	5.7		
36010000	14.711	23.895	R	1	1 55	CRACKING	7.0	10.0	10.0	8.5	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
25 27			2	20.5	29000	RIDE	8.4	8.6	8.6	8.4	8.2	8.2	8.0	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1		
OAK RD(14.8R) FC5M																										
4392381	14.711	23.868	C	2020	0012	CRACKING	9.5	9.0	8.0	8.0	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5		
WESTERN SURETY COMPANY					SPRIDE		7.9	8.0	7.7	8.1	8.0	8.0	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1	8.1		
36010000	23.895	24.959	R	1	1 35	CRACKING	8.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
25 27			3	16.4	31000	RIDE	7.4	8.3	8.3	7.9	7.7	7.5	7.2	7.8	7.7	7.8	7.7	7.8	7.7	7.8	7.7	7.8	7.7	7.6		
SE 22 PL(24.0R) FC125M																										
4392381	23.868	24.959	C	2020	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5		
WESTERN SURETY COMPANY					SPRIDE		7.4	7.6	7.3	7.2	7.1	7.1	7.0	6.9	7.0	6.7	6.4	6.7	6.4	6.8	6.8	6.8	6.8	6.5		

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS		2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)							=====															
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
CONTRACTOR (AGE ONE YEAR)					ASTYPE																(PMRS)	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																	
36010000	23.895	24.959	L	1	1 35	CRACKING		9.0	10.0	10.0	8.5	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0		
25 27			3	16.4	31000	RIDE		7.4	8.1	8.2	8.0	7.7	7.5	7.4	7.4	7.5	7.4	7.5	7.5	7.3		
SE 1ST AVE(24.0L)					FC125M																	
4392381	23.868	24.959	C	2020	0012	CRACKING		10.0	10.0	8.5	7.0	6.5	6.5	6.5	6.5	4.5*	3.5*	3.5*	10.0	10.0	9.0	
WESTERN SURETY COMPANY				(2024)	SPRIDE			7.3	7.2	7.2	7.1	7.2	7.0	6.8	7.0	7.1	6.6	6.5	7.8	7.8	7.5	
36010000	14.711	23.895	L	1	1 55	CRACKING		4.5*	10.0	10.0	8.5	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	10.0		
25 27			2	20.5	29000	RIDE		8.0	8.6	8.6	8.3	8.2	8.1	7.9	8.2	8.2	8.1	8.1	8.2	8.1		
SE 57 AVE(14.9C)					FC5M																	
4392381	14.711	23.868	C	2020	0012	CRACKING		9.5	9.0	7.0	6.5	6.5	6.5	5.5*	5.5*	3.5*	3.5*		10.0	10.0	9.0	
WESTERN SURETY COMPANY				(2024)	SPRIDE			8.1	8.0	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.8		8.1	8.1	7.9	
36010000	14.347	14.711	L	1	6 35	CRACKING		10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5		10.0	9.5	9.5	9.5		
25 27			2	16.4	12800	RIDE		6.3*	7.3	7.5	7.2	7.0	7.1	6.9	6.1		7.3	6.9	6.9	6.9		
SE 62ND AVE(14.4L)					FC125M																	
4392381	14.347	14.711	C	2020	0012	CRACKING		9.5	9.5	8.5	7.0	7.0	7.0	6.5	6.5	6.5	6.5	6.5	10.0	10.0	9.0	
WESTERN SURETY COMPANY				(2024)	SPRIDE			6.1	7.0	6.8	5.9	6.0	5.8	5.6	5.6	5.7	5.7	5.3*	6.0			
36030000	0.000	0.652	R	1	8 35	CRACKING		10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.5	10.0	10.0	10.0		
25 27			3	11.9	41500	RIDE		8.3	7.4	8.1	7.6	6.1	6.8	6.8	5.0*	6.8	6.6	7.9	7.9	7.8		
OCALA CITY LIMITS(0.0C)					FC95																	
4195851	0.000	2.699	C	2009	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	6.0*	6.0*			
THE MIDDLESEX CORPORATION				(2010)	RIDE			7.8	7.7	7.6	7.5	7.5	7.4	6.9	7.1	7.1	7.0	7.1	6.4			
36030000	0.652	1.805	R	1	1 45	CRACKING		10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.5	10.0	10.0	10.0		
25 27			2	11.9	31500	RIDE		9.0	9.0	9.0	8.7	8.6	8.4	8.1	8.2	8.2	8.2	8.6	8.6	8.6		
NW 3 ST(0.7R)					FC95																	
4195851	0.000	2.699	C	2009	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.5	7.0	7.1	5.0*	
THE MIDDLESEX CORPORATION				(2010)	RIDE			8.5	8.5	8.4	8.3	8.2	8.2	7.9	8.0	8.0	8.0	7.9	7.8	7.7	7.4	
4542141	0.692	1.809	C	2028	0012																	
36030000	1.805	2.606	R	1	1 45	CRACKING		10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.5	10.0	10.0	10.0		
25 301			2	22.7	18700	RIDE		9.0	9.0	9.0	8.7	8.6	8.4	8.1	8.2	8.2	8.2	8.6	8.6	8.6		
CR 200A(1.9R)					FC125M																	
				(2024)	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.5	7.5	10.0	10.0	9.0	
					RIDE			8.5	8.5	8.4	8.3	8.2	8.2	7.9	8.0	8.0	8.0	7.9	8.2	8.1	7.8	
36030000	16.463	19.572	R	1	1 60	CRACKING		10.0	10.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0		
25 441			2	12.9	8500	RIDE		8.9	8.8	8.7	8.5	7.8	7.5	7.3	7.1	6.9	8.1	8.0	8.0	8.0		
NW 177 PL(16.8R)					FC5																	
4171621	16.399	22.764	C	2007	0012	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.3*	0.0*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.9	7.9	7.8	8.2	8.3	8.2	8.3	8.3	8.2	8.2	8.1	8.0	7.9	7.7	
4486351	16.399	19.572	C	2025	0012																	
36030000	19.572	20.075	C	1	1 40	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	10.0	10.0	10.0	10.0		
25 441			4	19.6	8000	RIDE		8.4	8.3	8.3	7.8	7.6	7.5	7.2	7.4	7.4	7.9	7.7	7.8	7.8		
AVE I(19.6L)					FC125																	
4171621	16.399	22.764	C	2007	0012	CRACKING		10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.5	6.5	6.0*	6.0*	6.0*	5.5*	3.0*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.7	7.7	7.6	7.6	7.6	7.6	7.5	7.5	7.5	7.4	7.4	7.2	7.4	7.1	
4452181	19.572	22.718	C	2025	0012																	
36030000	20.075	22.831	R	1	1 65	CRACKING		10.0	10.0	10.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0		
25 441			2	19.6	8000	RIDE		8.7	8.7	8.6	8.4	7.4	7.0	6.7	6.8	6.4*	8.2	8.2	8.1	8.0		
AVE C(20.1C)					FC5																	
4171621	16.399	22.764	C	2007	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	6.5	4.5*	4.5*	4.5*	4.3*	0.5*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.7	7.4	7.7	8.1	8.1	8.2	8.2	8.3	8.3	8.1	8.2	8.2	8.0	7.8	
4452181	19.572	22.718	C	2025	0012																	
36030000	20.075	22.831	L	1	1 65	CRACKING		9.0	9.0	10.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0		
25 441			2	19.6	8000	RIDE		8.4	8.6	8.2	8.2	7.3	7.2	7.0	6.7	6.4*	8.0	7.9	7.9	7.9		
AVE C(20.1C)					FC5																	
4171621	16.399	22.764	C	2007	0012	CRACKING		10.0	10.0	9.5	9.5	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.6*	0.0*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.8	7.8	7.7	8.2	8.2	8.1	8.1	8.2	8.2	8.1	8.1	8.1	8.0	7.8	
4452181	19.572	22.718	C	2025	0012																	
36030000	16.463	19.572	L	1	1 60	CRACKING		9.0	9.0	6.5	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0		
25 441			2	12.9	8500	RIDE		8.7	8.6	8.6	8.2	7.9	7.4	6.9	6.9	6.5	8.2	8.2	8.1	8.2		
NW 177 LN(16.8L)					FC5																	
4171621	16.399	22.764	C	2007	0012	CRACKING		10.0	10.0	8.5	8.5	8.5	8.5	7.0	7.0	4.5*	4.5*	4.5*	4.5*	4.4*	0.5*	
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			8.1	8.0	8.0	8.3	8.3	8.2	8.4	8.3	8.3	8.2	8.2	8.1	8.0	7.8	
4486351	16.399	19.572	C	2025	0012																	

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012			
INTERSECT AT (MP SIDE)	W BMP	W EMP	RW	FY-P	WKMX-P	ASTYPE																
CONTRACTOR (AGE ONE YEAR)	W BMP	W EMP	RW	FY-F	WKMX-F		2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030		
ITMSEG-F																				(PMRS)		
36030000	1.805	2.606	L 1	1 45	CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.0*	10.0	10.0	10.0				
25 301			2 22.7	18700	RIDE	8.9	8.5	8.8	8.7	8.4	8.3	8.0	8.0	7.9	7.6	8.6	8.6	8.6				
NW 22 ST(2.1C)				FC125M																		
			(2024)		CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	10.0	10.0	9.0		
					RIDE	8.5	8.5	8.5	8.3	8.2	8.2	7.9	8.1	8.1	8.1	8.0	8.4	8.2		7.9		
36030000	0.652	1.805	L 1	1 45	CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	6.0*	10.0	10.0	10.0				
25 27			2 11.9	31500	RIDE	8.9	8.5	8.8	8.7	8.4	8.3	8.0	8.0	7.9	7.6	8.6	8.6	8.6				
EIGHTH ST NW(1.0C)				FC95																		
4195851	0.000	2.699	C 2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.5	7.5	7.5	5.5*			
THE MIDDLESEX CORPORATION (2010)					RIDE	8.5	8.5	8.5	8.3	8.2	8.2	7.9	8.1	8.1	8.1	8.0	7.9	7.7	7.4			
4542141	0.692	1.809	C 2028	0012																		
36030000	0.000	0.652	L 1	8 35	CRACKING	10.0	10.0	10.0	8.5	8.5	7.0	7.0	6.5	6.5	7.0	10.0	10.0	10.0				
25 27			3 11.9	41500	RIDE	8.5	8.5	8.3	8.1	7.8	7.8	7.6	7.1	7.0	6.7	7.8	7.8	7.6				
OCALA CITY LIMITS(0.0C)				FC95																		
4195851	0.000	2.699	C 2009	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.5	8.0	8.0	7.0	7.0					
THE MIDDLESEX CORPORATION (2010)					RIDE	7.6	7.5	7.5	7.3	7.3	7.2	7.3	7.3	7.4	7.2	7.3	7.1					
36040000	14.143	14.310	R 1	1 55	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.6	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6				
FROM CR-200A(14.2R)				FC5																		
4155111	14.161	16.652	C 2006	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	8.3	4.0*			
ANDERSON COLUMBIA CO., INC(2007)				SPRIDE		7.7	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.3	8.1			
36040000	14.310	15.026	R 1	7 45	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.6	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6				
NE 175 ST(14.5C)				FC5																		
4452121	14.290	15.007	R 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0			
(2025)					RIDE	7.7	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.2	8.0			
36040000	15.026	15.632	R 1	7 45	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.6	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6				
NE 180 ST(15.0C)				FC125M																		
4452121	15.007	15.605	R 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0			
(2025)					RIDE	7.7	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	7.6	7.3			
36040000	15.632	16.652	R 1	7 55	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.6	8.7	8.5	8.1	7.4	7.2	6.9	7.6	7.8	7.8	7.8	7.7	7.6				
NE 189 LN(16.0R)				FC5M																		
4452121	15.605	16.652	R 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	8.0	7.0	4.5*	4.5*	4.5*	4.5*	4.5*	10.0	9.0			
(2025)					RIDE	7.7	7.7	7.7	7.8	7.7	7.7	7.7	7.7	7.7	7.6	7.9	7.9	8.5	8.3			
36040000	15.589	16.652	L 1	7 55	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.5	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7				
NE 189 LN(16.0L)				FC5M																		
4452121	15.605	16.652	L 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	9.0			
(2025)					RIDE	7.7	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.5	8.3			
36040000	14.957	15.589	L 1	7 45	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.5	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7				
NE 180 ST(15.0C)				FC125M																		
4452121	15.007	15.605	L 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	9.0			
(2025)					RIDE	7.7	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	7.9	7.6			
36040000	14.300	14.957	L 1	7 45	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.5	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7				
NE 175 ST(14.5C)				FC5																		
4452121	14.290	15.007	L 2023	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	10.0	9.0			
V. E. WHITEHURST & SONS, I(2025)				SPRIDE		7.7	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.6	8.4			
36040000	14.143	14.300	L 1	1 55	CRACKING	9.0	9.0	6.5	4.5*	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0				
200 301			2 45.1	15800	RIDE	8.5	8.7	8.6	8.1	7.9	7.5	7.3	7.7	7.8	7.8	7.7	7.8	7.7				
FROM CR 200A(14.2L)				FC5																		
			(2025)		CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*	9.0	8.0			
					RIDE	7.7	7.6	7.6	7.7	7.6	7.6	7.6	7.6	7.6	7.5	7.8	7.8	8.2	8.0			

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT		RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)							=====															
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-X-P	ASTYPE																
CONTRACTOR (AGE ONE YEAR)								2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-X-F																(PMRS)	
36050000	0.000	1.904	R	1	1 55	CRACKING		8.5	8.5	8.5	7.0	6.5	4.5*		3.5*	3.5*	3.5*				10.0	
35 301			2	16.4	29500	RIDE		8.6	8.5	8.1	8.3	7.9	7.9		7.7	7.8	7.5				8.4	
CR 42(1.5C)					FC5																	
4112563	0.000	1.404	C	2010	0213	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.5	3.0*	
D.A.B. CONSTRUCTORS, INC				(2012)	SPRIDE			7.7	8.3	8.4	8.3	8.3	8.3	8.0	8.0	8.0	8.0	8.0	8.0	7.9	7.7	
4526941	0.000	1.540	C	2029	0226																	
36050000	1.904	3.744	C	1	1 55	CRACKING		8.5	8.5	8.5	7.0	6.5	4.5*	4.5*	4.5*	4.5*		10.0	10.0	10.0		
35 301			2	20.3	15600	RIDE		8.6	8.5	8.1	8.3	7.9	7.9	7.1	7.5	7.5		8.4	8.4	8.3		
SE 151 ST(2.9L)					FC125																	
4195571	1.904	6.866	C	2008	0012	CRACKING		10.0	10.0	9.5	8.5	8.5	8.5	7.0	6.5	6.5	6.5	6.5	6.5	5.9*	3.5*	
C. W. ROBERTS CONTRACTING, INC				(2010)	SPRIDE			7.8	8.2	8.0	7.9	7.6	7.4	7.1	7.2	7.1	6.9	7.5	7.3	7.1	6.8	
4453021	1.540	3.747	C	2024	0012																	
36050000	3.744	6.866	R	1	1 55	CRACKING		10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.0	7.0		10.0	10.0	10.0		
35 301			2	20.3	15600	RIDE		8.8	8.9	8.7	8.5	8.3	8.3	8.1	8.2	8.2		8.4	8.4	8.3		
SE 139 ST(4.2R)					FC5																	
4195571	1.904	6.866	C	2008	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.9	3.0*	
C. W. ROBERTS CONTRACTING, INC				(2010)	SPRIDE			7.9	8.3	8.4	8.5	8.4	8.4	8.5	8.5	8.5	8.5	8.5	8.4	8.5	8.3	
4542151	3.747	6.866	C	2029	0012																	
36050000	3.744	6.866	L	1	1 55	CRACKING		10.0	8.5	8.5	7.0	7.0	6.5	4.5*	4.5*	4.5*		10.0	10.0	10.0		
35 301			2	20.3	15600	RIDE		8.5	8.6	8.5	8.2	8.0	7.9	7.8	7.8	7.7		8.5	8.5	8.4		
SE 142 PL(3.9L)					FC125																	
4195571	1.904	6.866	C	2008	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	6.5	6.5	6.7	4.5*	
C. W. ROBERTS CONTRACTING, INC				(2010)	SPRIDE			8.1	8.4	8.4	8.5	8.5	8.4	8.5	8.5	8.5	8.5	8.4	8.4	8.4	8.1	
4542151	3.747	6.866	C	2029	0012																	
36050000	0.000	1.904	L	1	1 55	CRACKING		8.5	8.5	8.5	7.0	6.5	4.5*		3.5*	3.5*	3.5*			10.0		
35 301			2	16.4	29500	RIDE		8.6	8.5	8.1	8.3	7.9	7.9		7.7	7.8	7.5			8.3		
SE 177 PL(0.3L)					FC5																	
4112563	0.000	1.404	C	2010	0213	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	6.5	6.5	6.5	6.5	6.5	3.0*	
D.A.B. CONSTRUCTORS, INC				(2012)	SPRIDE			7.9	8.3	8.2	8.2	8.2	8.2	7.9	7.8	7.9	7.8	7.9	7.9	7.8	7.6	
4526941	0.000	1.540	C	2029	0226																	
36060000	0.000	0.619	R	1	1 35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.0	9.0	9.0		
45 41			2	25.1	21500	RIDE		8.4	8.2	7.7	8.0	7.5	7.6	7.4	7.1	7.5	7.4	7.4	7.2	7.3		
CR-484/PENN AVE(0.3R)					FC3																	
2386571	0.000	0.735	C	1998	0012	CRACKING		8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	3.0*	
D.A.B. CONSTRUCTORS, INC				(2000)	S RIDE			7.1	7.1	7.0	7.5	7.6	7.5	7.4	7.3	7.4	7.4	7.4	7.4	7.3	7.0	
4485261	0.100	1.410	R	2025	0012																	
36060000	0.619	1.532	R	1	1 35	CRACKING		7.5	7.5	7.5	7.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
45 41			2	8.5	22500	RIDE		8.1	8.0	7.8	8.1		7.7	7.5	7.6	7.8	7.8	7.7	7.8	7.8		
E MCKINNEY AVE(0.6R)					FC125																	
2387401	0.619	1.662	C	2003	0213	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.0	7.0	7.5	5.0*	
D.A.B. CONSTRUCTORS, INC				(2005)	SPRIDE			7.7	7.5	7.5	7.3	7.3	7.3	7.1	7.0	7.1	6.9	7.0	6.8	6.9	6.6	
4485261	0.100	1.410	R	2025	0012																	
36060000	1.532	4.939	C	1	1 55	CRACKING		7.5	7.5	7.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	7.0	6.5	10.0		
45 41			2	8.5	22500	RIDE		8.1	8.0	7.8	8.1	8.0	7.9	7.8	7.8	7.7	7.7	7.8	7.7	8.0		
SW 108 PL(1.6R)					FC125R																	
4195841	1.621	4.939	C	2011	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	7.0	7.0	7.0	7.0	4.3*	2.5*	
V. E. WHITEHURST & SONS, INC				(2012)	RIDE			7.8	7.6	7.5	7.3	7.3	7.3	7.2	7.1	7.1	7.1	7.1	6.9	6.9	6.6	
2386481	1.438	5.556	C	2030	0213																	
36060000	4.939	11.928	C	1	1 60	CRACKING		9.0	9.0	9.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0		
45 41			2	13.4	5700	RIDE		8.8	8.6	8.6	8.5	8.3	8.2	8.1	8.1	8.2	8.7	8.6	8.5	8.4		
SW 61 ST(5.8R)					FC95																	
4171791	4.939	11.928	C	2008	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	8.0	8.0	7.6	5.5*	
STEVEN COUNTS, INC.				(2009)	RIDE			8.5	8.4	8.4	8.3	8.2	8.3	8.2	8.1	8.1	8.1	8.2	8.0	8.0	7.7	
36060000	0.619	1.532	L	1	1 35	CRACKING		7.5	7.5	7.5	7.5		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
45 41			2	8.5	22500	RIDE		8.1	8.0	7.8	8.1		7.5	6.9	7.4	7.8	7.7	7.8	7.9	7.7		
MAGNOLIA AVE(0.6L)					FC125																	
2387401	0.619	1.662	C	2003	0213	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.5	8.5	7.0	7.0	7.0	7.0	7.4	4.5*	
D.A.B. CONSTRUCTORS, INC				(2005)	SPRIDE			7.7	7.7	7.7	7.3	7.3	7.4	7.1	7.3	7.3	7.2	7.1	7.1	7.3	7.0	
4485261	0.175	1.431	L	2025	0012																	
36060000	0.000	0.619	L	1	1 35	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0		
45 41			2	25.1	21500	RIDE		8.7	8.2	8.8	8.6	8.2	8.1	8.2	8.1	7.9	8.0	8.1	7.6	7.6		
RIVER DR(0.1L)					FC3																	
2386571	0.000	0.735	C	1998	0012	CRACKING		8.5	8.5	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	7.0	7.3	4.0*	
D.A.B. CONSTRUCTORS, INC				(2000)	S RIDE			7.7	8.1	8.2	7.8	7.8	7.8	7.7	7.7	7.7	7.7	7.7	7.7	7.6	7.3	
4485261	0.175	1.431	L	2025	0012																	

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

											DISTRICT = 5 COUNTY = MARION																				
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED			YEAR										FUTURE										
SR	US	G BMP	G EMP	LN	%T	AADT	RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012											
INTERSECT AT (MP SIDE)	W BMP	W EMP	RW	FY-P	WKMX-P	ASTYPE	=====																								
ITMSEG-P	(AGE ONE YEAR)							2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030 (PMRS)										
CONTRACTOR	W BMP	W EMP	RW	FY-F	WKMX-F																										
ITMSEG-F																															
36070000	0.000	6.672	R	1	1 65	CRACKING		6.5	4.5*	3.5*			10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.0											
500 27			2	19.9	10300	RIDE		8.5	8.3	8.1			8.3	8.2	8.2	8.0	8.2	8.3	8.2	8.1											
NW 160 AVE(1.7C)					FC5M																										
4373391	0.000	6.672	C	2019	0012	CRACKING		9.0	7.0	7.0	6.0*	6.0*	6.0*	4.5*		10.0	10.0	10.0	10.0	8.9	7.0										
V. E. WHITEHURST & SONS, I(2021)						RIDE		8.1	8.0	7.9	8.0	8.0	7.9	7.9		8.8	8.6	8.5	8.4	8.3	8.1										
36070000	6.672	14.305	R	1	1 65	CRACKING		6.5				10.0	10.0	10.0	10.0	10.0	8.5	7.0	6.5	6.5											
500 27			2	19.9	10300	RIDE		8.5				8.2	8.2	8.1	8.1	8.1	7.9	7.8	7.7	7.4											
CR 326(6.8C)					FC5M																										
4290531	6.683	14.305	C	2015	0012	CRACKING		6.5	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.3	5.5*										
ANDERSON COLUMBIA CO., INC(2016)						RIDE		7.2	7.1	6.8	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.5	8.4	8.4	8.2										
36070000	14.305	17.912	R	1	1 55	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.5											
500 27			2	25.2	20200	RIDE			8.6	8.7	8.5	8.1	8.1	8.0	8.1	7.9	8.0	8.0	7.9	7.8											
CR 225A(14.5C)					FC5M																										
4290831	14.305	17.912	C	2015	0012	CRACKING		7.5	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	5.5*										
ANDERSON COLUMBIA CO., INC(2017)						RIDE		7.8	7.7	7.6		8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.3	8.1										
36070000	17.912	20.700	R	1	1 45	CRACKING			10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.0	8.0	7.0	7.0	7.0											
500 27			2	17.1	21400	RIDE			8.7	8.7	8.5	8.3	8.2	8.1	8.1	8.4	8.1	8.1	8.0	7.8											
NW 35 AVE RD(18.2C)					FC125M																										
4290831	17.912	20.700	C	2015	0012	CRACKING		7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	6.5										
ANDERSON COLUMBIA CO., INC(2017)						RIDE		7.8	7.6	7.6		8.0	8.0	7.8	7.8	7.9	7.8	7.8	7.8	7.8	7.5										
36070000	17.912	20.700	L	1	1 45	CRACKING			10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	7.0											
500 27			2	17.1	21400	RIDE			8.4	8.5	8.3	7.9	8.0	7.8	7.9	8.3	7.7	7.9	7.8	7.8											
FROM NW 35 AVE RD(18.1L)					FC125M																										
4290831	17.912	20.700	C	2015	0012	CRACKING		7.0	7.0	7.0		10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.0	7.9	6.5										
ANDERSON COLUMBIA CO., INC(2017)						RIDE		7.6	7.5	7.5		8.0	7.9	7.6	7.8	7.9	7.8	7.8	7.8	7.8	7.5										
36070000	14.305	17.912	L	1	1 55	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5											
500 27			2	25.2	20200	RIDE			8.8	8.7	8.6	8.3	8.2	8.2	8.2	8.3	8.1	8.1	8.0	7.9											
CR 225A(14.5C)					FC5M																										
4290831	14.305	17.912	C	2015	0012	CRACKING		7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.3	6.0*									
ANDERSON COLUMBIA CO., INC(2017)						RIDE		7.8	7.3	7.5		8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.0										
36070000	6.672	14.305	L	1	1 65	CRACKING		6.5				10.0	10.0	10.0	10.0	9.0	9.0	8.5	7.5	7.5											
500 27			2	19.9	10300	RIDE		8.5				8.3	8.2	8.1	8.2	8.1	8.1	8.1	8.0	7.8											
NW 131 CT(6.7L)					FC5M																										
4290531	6.683	14.305	C	2015	0012	CRACKING		7.5	6.5	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.9	5.5*										
ANDERSON COLUMBIA CO., INC(2016)						RIDE		7.8	7.3	7.4	8.3	8.3	8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.2	8.0										
36070000	0.000	6.672	L	1	1 65	CRACKING		6.5	4.5*	3.5*			10.0	10.0	10.0	9.5	9.5	9.5	9.5	9.5											
500 27			2	19.9	10300	RIDE		8.5	8.3	8.1			8.3	8.2	8.2	8.2	8.2	8.1	8.1	8.0											
COUNTY ROAD 316(0.1L)					FC5M																										
4373391	0.000	6.672	C	2019	0012	CRACKING		8.0	7.0	6.5	6.0*	6.0*	6.0*	5.0*		10.0	10.0	10.0	10.0	9.0	7.5										
V. E. WHITEHURST & SONS, I(2021)						RIDE		8.0	7.8	7.5	7.9	7.9	7.7	7.8		8.9	8.7	8.6	8.4	8.4	8.2										
36080000	0.000	6.494	R	1	1 45	CRACKING		7.0	7.0	6.5	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	10.0											
40			2	6.5	22270	RIDE		7.6	7.3	7.2	6.9	6.2*	5.9*		7.7	7.7	7.8	7.8	7.7	7.7											
OCALA CITY LIMITS(0.0C)					FC125																										
4135701	0.000	6.499	C	2005	0012	CRACKING		10.0	10.0	10.0	8.5	8.5	8.5	8.0	8.0	7.0	7.0	7.0	7.0	6.9	4.5*										
STEVEN COUNTS, INC. (2007)					SPRIDE			7.7	7.7	7.7	7.4	7.4	7.4	7.4	7.4	7.4	7.3	7.4	7.3	7.3	7.0										
4509511	2.356	6.494	@ C	2026	0226																										
36080000	6.494	9.640	C	1	1 55	CRACKING		10.0	10.0	9.0	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	9.0	9.0											
40			2	11.3	18100	RIDE		8.5	8.6	8.5	8.3	7.6	7.6	7.3	7.2	6.8	6.2*	8.5	8.4	8.3											
SR 326(7.2L)					FC95																										
4171601	6.494	9.617	C	2007	0012	CRACKING		9.0	9.0	9.0	8.5	8.5	8.5	7.5	7.5	7.5	7.5	7.5	7.5	7.0	5.0*										
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE			8.2	8.2	8.2	7.9	7.9	7.8	7.7	7.7	7.7	7.7	7.8	7.7	7.7	7.4										
4106742	6.146	11.473	C	2030	0213																										
36080000	10.157	12.615	C	1	1 55	CRACKING		10.0	9.0	9.0	6.5		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0											
40			2	6.7	13600	RIDE		8.3	8.0	8.2	7.9		8.2	8.2	8.2	8.4	8.4	8.4	8.4	8.3											
COLBY WOODS CAMPGROUNDS(10.4L)					FC125																										
4116601	10.157	14.112	C	2003	0012	CRACKING		9.0	9.0	9.0	8.5	8.5	8.5	7.5	7.5	7.0	6.0*	6.0*	6.0*	5.7*	3.0*										
ANDERSON COLUMBIA CO., INC(2005)					SPRIDE			8.3	8.3	8.2	8.1	8.1	8.1	8.0	8.0	8.0	8.0	7.9	7.9	7.9	7.6										
4509481	10.148	20.643	C	2026	0012																										

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

ALL SYSTEM PAVEMENT CONDITION FORECAST

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)																						
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P																	
CONTRACTOR (AGE ONE YEAR)					ASTYPE																	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																2030 (PMRS)	
36080000	27.540	28.623	C	1	1 55	CRACKING		7.0	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
40			2	7.1	5400	RIDE		8.6	8.6	7.9	7.8		8.4	8.4	8.4	8.5	8.5	8.5	8.4	8.3		
JUNIPER SPRINGS(27.6L)					FC4																	
4116621	23.528	32.206	C	2003	0012	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	7.0	6.0*	6.0*	6.0*	4.8*	2.0*	
ANDERSON COLUMBIA CO., INC(2005)					SPRIDE			8.4	8.3	8.3	8.2	8.2	8.1	8.0	8.0	8.1	7.9	7.8	7.8	7.7	7.4	
4509482	20.643	32.206	C	2028	0226																	
36080000	28.623	29.627	C	1	1 55	CRACKING		7.0	7.0	7.0	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
40			3	7.1	5400	RIDE		8.5	7.9	7.6	6.4*		8.5	8.3	8.4	8.4	8.4	8.4	8.4	8.3		
					FC4																	
4116621	23.528	32.206	C	2003	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.0	6.0*	6.0*	6.0*	4.7*	2.0*	
ANDERSON COLUMBIA CO., INC(2005)					SPRIDE			8.1	8.2	8.0	7.9	8.1	8.0	7.7	7.9	7.9	7.8	7.8	7.7	7.7	7.4	
4509482	20.643	32.206	C	2028	0226																	
36080000	29.627	32.206	C	1	1 55	CRACKING		6.5	6.5	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
40			2	7.1	5400	RIDE		8.7	8.4	8.0	7.7		8.3	8.3	8.3	8.2	8.2	8.2	8.2	8.1		
SR 19(32.1C)					FC4																	
4116621	23.528	32.206	C	2003	0012	CRACKING		10.0	10.0	9.0	9.0	8.5	8.5	8.0	8.0	6.5	6.0*	6.0*	6.0*	5.3*	2.5*	
ANDERSON COLUMBIA CO., INC(2005)					SPRIDE			8.0	8.0	7.9	7.7	7.7	7.6	7.6	7.6	7.6	7.4	7.5	7.4	7.4	7.1	
4509482	20.643	32.206	C	2028	0226																	
36080000	0.000	6.494	L	1	1 45	CRACKING		6.5	6.5	4.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0		
40			2	6.5	22270	RIDE		7.8	7.8	7.5	7.2	6.7	6.6		7.8	8.1	8.1	8.0	7.9	7.9		
OCALA CITY LIMITS(0.0C)					FC125																	
4135701	0.000	6.499	C	2005	0012	CRACKING		8.5	8.5	8.5	8.5	8.5	8.5	8.0	8.0	7.0	7.0	7.0	7.0	6.8	4.5*	
STEVEN COUNTS, INC. (2007)					SPRIDE			7.9	7.9	7.9	7.7	7.6	7.5	7.3	7.5	7.6	7.5	7.4	7.5	7.4	7.1	
4509511	2.356	6.494	C	2026	0226																	
36090000	0.000	3.057	C	1	1 55	CRACKING		3.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0		
19			2	15.5	2000	RIDE		8.3	8.1		8.6	8.2	8.3	8.2	8.3	8.2	8.0	7.9	7.8	7.5		
SR 40(0.2C)					FC125																	
2387701	0.000	15.808	C	2001	0012	CRACKING		9.0	9.0	9.0	9.0	9.0	9.0	8.5	8.5	8.5	8.5	8.5	8.5	8.3	5.5*	
THE MIDDLESEX CORPORATION (2003)					SPRIDE			7.4	7.3	7.2	7.4	7.4	7.3	7.1	7.3	7.3	7.2	7.2	7.2	7.2	6.9	
36090000	3.868	15.780	C	1	1 55	CRACKING		3.5*	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0		
19			2	22.7	2200	RIDE		8.3	8.1		8.6	8.2	8.3	8.2	8.3	8.2	8.0	7.9	7.8	7.6		
THE YEARLING TR(6.1L)					FC125																	
2387701	0.000	15.808	C	2001	0012	CRACKING		9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	8.5	5.5*	
THE MIDDLESEX CORPORATION (2003)					SPRIDE			7.5	7.4	7.3	7.4	7.4	7.4	7.3	7.3	7.4	7.3	7.2	7.3	7.3	7.0	
36090000	15.780	17.448	C	1	1 55	CRACKING		8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	7.0	10.0	10.0	10.0	10.0		
19			2	12.9	4700	RIDE		8.0	8.1	7.6	7.7	7.3	7.1	6.9	6.9	7.1	8.4	8.3	8.3	8.2		
NE 133 PL(15.8L)					FC125M																	
4195831	15.780	17.448	C	2009	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.7	5.5*	
P & S PAVING, INC. (2009)					RIDE			8.2	8.2	8.1	7.6	7.6	7.6	7.4	7.5	7.5	7.4	7.4	7.4	7.4	7.1	
36090100	0.000	0.811	C	1	1 55	CRACKING																
19			2	15.5	2000	RIDE																
3331 FT S/BR 360067(0.0C)					FC125																	
(2011)								10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.3	5.0*	
								8.0	7.8	7.6	7.4	7.5	7.4	7.1	7.0	7.1	7.0	6.9	6.9	6.7	6.4*	
36100000	0.000	5.795	C	1	1 55	CRACKING		10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.5	7.0	6.5	6.5		
200			2	10.7	17500	RIDE		9.0	8.9	8.9	8.7	8.2	8.1	8.0	8.0	8.1	7.6	7.7	7.4	7.1		
SW 137 CT(0.2R)					FC125M																	
4286871	0.000	5.815	C	2013	0012	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	9.0	7.5	7.5	7.0	7.0	7.0	5.0*	
C. W. ROBERTS CONTRACTING, (2014)					RIDE				8.8	8.7	8.6	8.6	8.6	8.5	8.5	8.6	8.5	8.5	8.5	8.5	8.2	
36100000	5.795	11.983	R	1	1 50	CRACKING					10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	8.0		
200			3	12.6	37000	RIDE					8.7	8.3	8.4	8.2	8.2	8.3	8.2	8.1	7.6	7.9		
CR 484(6.0C)					FC5M																	
4368791	5.981	11.983	C	2019	0012	CRACKING		8.0	8.0	7.5	4.5*	4.5*	4.5*	4.5*		10.0	10.0	10.0	10.0	9.6	8.0	
ANDERSON COLUMBIA CO., INC(2021)					RIDE			7.8	7.5	7.4	7.8	7.7	7.6	7.6		8.7	8.6	8.7	8.6	8.6	8.4	
36100000	11.983	14.635	R	1	1 50	CRACKING		10.0	10.0	10.0	9.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0		
200			3	3.4	42733	RIDE		8.5	8.6	8.6	8.2		8.0	7.9	8.0	8.0	8.0	7.9	7.9	7.7		
SW 66 ST(12.2R)					FC5HP																	
4373441	11.983	14.750	C	2018	0012	CRACKING		8.0	8.0	6.5	4.5*	4.5*	4.5*	3.5*		10.0	10.0	10.0	10.0	10.0	8.5	
D.A.B. CONSTRUCTORS, INC (2021)					RIDE			7.7	7.3	7.1	7.6	7.5	7.3	7.3		8.3	8.2	8.2	8.1	8.1	7.9	

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT		RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
INTERSECT AT (MP SIDE)							=====														
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-X-P			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030
CONTRACTOR (AGE ONE YEAR)					ASTYPE																(PMRS)
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-X-F																
36100000	14.635	15.040	R	1	1 45	CRACKING	10.0	10.0	10.0	9.0			10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	
200			3	3.4	42733	RIDE	8.5	8.6	8.6	8.2			8.0	7.9	8.0	8.0	8.0	7.9	7.9	7.7	
SW 38 CT(14.7C)					FC5HP																
				(2022)		CRACKING	8.0	8.0	6.5	4.5*	4.5*	4.5*	3.5*				10.0	10.0	10.0	9.0	7.5
						RIDE	7.7	7.3	7.1	7.6	7.5	7.3	7.3				7.3	7.4	7.3	7.4	7.2
36100000	15.040	17.870	R	1	1 45	CRACKING	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	
200			3	12.7	34500	RIDE	7.7	7.6	7.6	7.5	7.0	6.9	6.3	7.1	7.6	7.6	7.5	7.5	7.4	7.3	
SW 36 AVE(15.1R)					FC125																
4135831	15.074	18.427	C	2005	0012	CRACKING	8.0	8.0	7.5	7.0	7.0	7.0	6.5	6.5	6.5	6.0*	6.0*	6.0*	4.6*	2.0*	
ANDERSON COLUMBIA CO., INC(2007)						RIDE	7.2	7.2	7.1	7.1	7.0	7.0	6.9	6.9	6.9	6.8	6.8	6.6	6.7	6.4	
36100000	17.870	18.405	R	1	1 45	CRACKING	6.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	9.5	9.5	9.0		
200			2	15.6	27000	RIDE	7.7	7.6	7.6	7.5	7.0	6.9	6.3	7.1	6.6	7.8	7.8	7.8	7.4		
SW 7 RD(18.0R)					FC125																
4135831	15.074	18.427	C	2005	0012	CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	5.4*	3.0*	
ANDERSON COLUMBIA CO., INC(2007)						RIDE	7.5	7.4	7.2	7.6	7.5	7.5	6.5	7.3	7.4	7.3	7.2	7.0	6.8	6.5	
36100000	17.870	18.405	L	1	1 45	CRACKING	7.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	10.0	10.0	10.0		
200			2	15.6	27000	RIDE	8.2	7.7	7.8	7.0	7.0	7.0	6.6	7.6	6.7	6.6	6.6	6.8	6.8	6.8	
SW 10 AVE(18.0L)					FC125																
4135831	15.074	18.427	C	2005	0012	CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.5	6.5	6.5	6.5	4.8*	2.5*	
ANDERSON COLUMBIA CO., INC(2007)						RIDE	6.8	6.7	6.6	6.8	7.4	7.0	6.8	7.1	6.7	6.6	6.9	6.5	6.3	6.0	
4392341	15.070	18.391	L	2024	0012																
36100000	15.060	17.870	L	1	1 45	CRACKING	7.0	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	10.0	10.0	9.0	9.0	8.5		
200			3	12.7	34500	RIDE	8.2	7.7	7.8	7.0	7.0	7.0	6.6	7.6	7.7	7.7	7.7	7.7	7.6	7.6	
SW 36 TER(15.1L)					FC125																
4135831	15.074	18.427	C	2005	0012	CRACKING	7.5	7.5	7.5	7.0	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	5.8*	3.5*	
ANDERSON COLUMBIA CO., INC(2007)						RIDE	7.5	7.5	7.4	7.2	7.1	7.2	6.9	6.9	6.9	6.9	7.0	6.9	6.8	6.5	
4392341	15.070	18.391	L	2024	0012																
36100000	14.635	15.060	L	1	1 45	CRACKING	10.0	10.0	10.0	9.0			10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	
200			3	3.4	42733	RIDE	8.7	8.6	8.6	8.3			8.2	7.8	7.9	7.8	7.8	7.8	7.7	7.6	
SW 38 CT(14.7C)					FC5HP																
				(2022)		CRACKING	8.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*				10.0	10.0	10.0	8.8	7.5
						RIDE	7.7	7.5	7.3	7.6	7.6	7.2	7.3				7.1	7.1	7.1	7.2	7.0
36100000	11.983	14.635	L	1	1 50	CRACKING	10.0	10.0	10.0	9.0			10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	
200			3	3.4	42733	RIDE	8.7	8.6	8.6	8.3			8.2	7.8	7.9	7.8	7.8	7.8	7.7	7.6	
SW 58 CT(12.2L)					FC5HP																
4373441	11.983	14.750	C	2018	0012	CRACKING	8.0	7.5	4.5*	4.5*	3.5*	3.5*	3.5*				10.0	10.0	10.0	9.0	7.5
D.A.B. CONSTRUCTORS, INC (2021)						RIDE	7.7	7.5	7.3	7.6	7.6	7.2	7.3				8.5	8.4	8.4	8.3	8.1
36100000	5.795	11.983	L	1	1 50	CRACKING				10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	8.5	
200			3	12.6	37000	RIDE				8.7	8.4	8.3	8.2	8.3	8.2	8.1	8.0	8.0	8.0	7.8	
CR 484(6.0C)					FC5M																
4368791	5.981	11.983	C	2019	0012	CRACKING	7.5	6.5	6.5	4.5*	3.5*	3.5*	3.5*				10.0	10.0	10.0	9.7	8.0
ANDERSON COLUMBIA CO., INC(2021)						RIDE	7.7	7.6	7.4	7.7	7.6	7.5	7.4				8.8	8.7	8.7	8.6	8.4
36110000	6.600	15.847	C	1	1 55	CRACKING	7.5	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*			10.0	10.0	10.0	
40			2	24.0	8600	RIDE	8.1	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5			8.1	8.1	8.0	
SR 45(6.6C)					FC95																
4171821	6.643	19.588	C	2007	0012	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	6.6	4.5*	
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE		8.0	7.8	7.9	7.8	7.7	7.7	7.5	7.5	7.6	7.5	7.5	7.4	7.4	7.1	
4526361	6.632	15.750	C	2027	0012																
36110000	15.847	19.589	R	1	1 55	CRACKING	7.5	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*			10.0	10.0	10.0	
40			2	7.3	17900	RIDE	8.1	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5			8.1	8.1	8.0	
SW 119 AVE(15.9R)					FC5M																
2387191	15.847	19.589	C	2014	0213	CRACKING	10.0	10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.8	6.5	
D.A.B. CONSTRUCTORS, INC (2017)					SPRIDE		8.0	7.8	7.9		8.3	8.3	8.3	8.3	8.3	8.3	8.2	8.2	8.2	8.2	8.0
36110000	19.589	22.747	R	1	1 55	CRACKING	7.5	7.5	7.5	6.5	6.5	4.5*	4.5*			10.0	10.0	10.0	10.0	10.0	
40			2	3.3	23500	RIDE	8.1	8.1	7.9	7.9	7.4	7.2	6.8			8.1	8.1	8.1	8.1	8.1	
SW 80 AVE(19.9R)					FC5																
2387621	19.588	22.805	C	2006	0213	CRACKING	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.0	6.5	6.5	6.5	5.0*	1.0*	
ANDERSON COLUMBIA CO., INC(2008)					SPRIDE		8.1	8.0	7.9	8.2	8.1	8.1	8.1	8.1	8.2	8.0	8.1	8.0	8.0	7.8	
4506651	19.572	22.776	C	2028	0226																

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR												FUTURE
SR US	G BMP	G EMP	LN	%T	AADT		RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
INTERSECT AT (MP SIDE)							=====														
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-X-P																
CONTRACTOR (AGE ONE YEAR)					ASTYPE			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-X-F																(PMRS)
36110000	22.747	23.800	R	1	1 50	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	
40			2	15.6	28500	RIDE		8.6	8.6	8.5	8.5	8.3	8.2	8.0	8.2	8.4	8.1	8.3	8.3	8.2	
SW 49 AVE(23.0R)					FC125M																
4306561	22.747	24.138	C	2016	0012	CRACKING		9.0	9.0	9.0	8.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0
MASCI GENERAL CONTRACTORS				(2017)		RIDE		8.1	8.2	7.9	7.9	8.7	8.7	8.6	8.6	8.5	8.5	8.5	8.4	8.4	8.1
36110000	23.800	26.311	R	1	1 45	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	
40			2	15.1	21500	RIDE			8.3	8.2	8.1	7.5	7.5	7.4	7.7	7.5	7.5	7.7	7.8	7.7	
HOLIDAY TRAVEL PARK(23.8R)					FC95																
2387571	23.719	26.705	C	1999	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.3	4.0*
ANDERSON COLUMBIA CO., INC				(2001)		SPRIDE		7.7	7.6	7.5	7.5	7.5	7.3	7.3	7.4	7.4	7.3	7.3	7.2	7.2	6.9
36110000	23.800	26.311	L	1	1 45	CRACKING			10.0	10.0	10.0	10.0	8.5	7.0	7.0	10.0	9.5	9.5	9.5	9.5	
40			2	15.1	21500	RIDE			8.2	8.1	7.8	7.3	7.3	7.1	7.1	7.3	7.5	7.5	7.5	7.3	
OAK TREE DR W(24.4L)					FC95																
4137191	23.808	26.705	C	2005	0216	CRACKING		9.5	9.5	9.0	9.0	9.0	9.0	9.0	9.0	8.5	8.5	8.5	8.5	7.7	5.5*
STEVEN COUNTS, INC.				(2008)		SPRIDE		7.0	7.4	7.4	7.2	7.1	7.2	7.1	7.1	7.1	6.9	6.9	6.9	6.9	6.6
36110000	22.747	23.800	L	1	1 50	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.0	7.0	7.0	7.0	
40			2	15.6	28500	RIDE		8.6	8.6	8.6	8.4	7.8	7.9	7.8	8.3	8.2	8.2	8.0	8.0	7.9	
NW 49 AVE(23.0L)					FC125M																
4306561	22.747	24.138	C	2016	0012	CRACKING		7.0	7.0	7.0	7.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.2	6.5
MASCI GENERAL CONTRACTORS				(2017)		RIDE		7.8	7.6	7.4	7.7	8.5	8.6	8.5	8.5	8.5	8.4	8.3	8.2	8.3	8.0
36110000	19.589	22.747	L	1	1 55	CRACKING		7.5	7.5	7.5	6.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0	
40			2	3.3	23500	RIDE		8.1	8.1	7.9	7.9	7.4	7.2	6.8		8.1	8.1	8.1	8.1	8.1	
NW 82 CT(19.7L)					FC5																
2387621	19.588	22.805	C	2006	0213	CRACKING		10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	6.5	2.5*
ANDERSON COLUMBIA CO., INC				(2008)		SPRIDE		8.1	8.1	8.0	8.1	8.2	8.1	8.1	8.1	8.2	8.1	8.1	8.0	8.0	7.8
4506651	19.572	22.776	C	2028	0226																
36110000	15.847	19.589	L	1	1 55	CRACKING		7.5	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*		10.0	10.0	10.0	
40			2	7.3	17900	RIDE		8.1	8.1	7.9	7.9	7.4	7.2	6.8	6.6	6.5		8.1	8.1	8.0	
CR 328(16.3L)					FC5M																
2387191	15.847	19.589	C	2014	0213	CRACKING		10.0	10.0	10.0		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	6.5
D.A.B. CONSTRUCTORS, INC				(2017)		SPRIDE		8.0	7.8	7.9		8.3	8.3	8.4	8.3	8.4	8.3	8.3	8.3	8.3	8.1
36110500	0.000	0.358	R	1	6 30	CRACKING										3.5*	10.0	10.0	10.0	10.0	
40			2	11.9	21400	RIDE										5.0*	5.7	5.4*	6.1		
SW BROADWAY(0.0R)					FC95																
(2009)						CRACKING		10.0	10.0	9.0	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.5	4.0*
						RIDE															
36110500	0.000	0.358	L	1	6 30	CRACKING										3.5*	10.0	10.0	10.0	10.0	
40			2	11.9	21400	RIDE										5.0*	7.7	7.7	7.6		
BROADWAY AVE W(0.0C)					FC95																
(2009)						CRACKING		10.0	9.0	9.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.5	7.5	6.5	4.0*
						RIDE															
36180000	12.560	14.003	R	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	
326			2	14.9	25500	RIDE		8.4	8.3	8.0	8.1	7.8	7.5	7.5	7.5	7.7	8.1	8.0	8.1	8.0	
NW 42ND AVE RD(13.2R)					FC125																
4170051	12.827	14.003	C	2007	0216	CRACKING		10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	7.0	7.0	7.0	7.0	4.5*
ANDERSON COLUMBIA CO., INC				(2009)		RIDE		7.9	8.0	7.9	7.5	7.4	7.5	7.3	7.5	7.5	7.3	7.3	7.3	7.4	7.1
36180000	12.560	14.003	L	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	
326			2	14.9	25500	RIDE		8.4	7.7	8.0	7.7	7.4	7.3	7.3	7.0	7.2	7.9	7.8	7.8	7.5	
NW 47 AVE(12.7L)					FC125																
(2014)						CRACKING		8.5	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	6.5	4.5*	
						RIDE		7.6	8.1	8.1	7.7	7.8	7.4	7.4	7.7	7.6	7.4	7.4	7.4	7.1	6.8
36180001	0.000	1.674	R	1	1 55	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.5	6.0*	10.0	10.0	
326			2	12.2	11500	RIDE		8.4	8.7	8.6	8.6	8.2	7.9	8.1	8.0	8.1	7.9	7.7	7.9	8.0	
36180 MEDIAN GORE(0.0C)					FC2																
4233481	0.000	1.674	C	2010	0226	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	8.3	4.5*
ANDERSON COLUMBIA CO., INC				(2011)		RIDE		8.0	8.1	8.0	8.4	8.4	8.4	8.4	8.5	8.5	8.4	8.5	8.5	8.5	8.3

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 5 COUNTY = MARION

RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	RATINGS	SURVEYED YEAR												FUTURE	
INTERSECT	AT	(MP)	(SIDE)									2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKM-F	ASTYPE																			
CONTRACTOR	(AGE)	ONE	YEAR																						
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKM-F																				(PMRS)
36180001	0.000	1.674	L	1	1	55	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	6.0*	6.0*	10.0	10.0		
326			2	12.2	1	11500	RIDE		8.4	8.4	8.5	8.4	7.9	7.8	7.7	7.6	7.4	7.1	6.8	7.8	7.9				
36180	MEDIAN	GORE(	0.0C)				FC2																		
4233481	0.000	1.674	C	2010	0226		CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.0	3.5*	
ANDERSON	COLUMBIA	CO.,	INC(2011)				RIDE		7.8	7.9	7.8	8.3	8.2	8.2	8.3	8.3	8.2	8.3	8.2	8.3	8.2	8.1	7.9		
36210000	0.000	13.905	R	4	7	70	CRACKING		10.0	9.0	9.0	7.5	7.5	6.5	6.5	4.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
93	I75	334.4	348.3	3	21.6	87000	RIDE		9.1	8.9	8.9	8.7	8.1	7.8	7.6	7.5	8.0	8.3	8.3	8.3	8.3	8.2			
4431701	0.000	13.993	R	2022	0012		CRACKING		10.0	10.0	10.0	9.0	7.5	7.5	6.5	6.5	4.5*	4.5*	3.5*	3.5*	10.0	9.0			
ANDERSON	COLUMBIA	CO.,	INC(2025)				SPRIDE		8.1	8.0	7.9	8.4	8.3	8.2	8.4	8.4	8.4	8.4	8.4	8.1	8.0	8.7	8.6		
36210000	13.905	18.482	R	4	1	70	CRACKING		10.0	9.0	9.0	9.0	9.0	7.0	7.0	7.0	7.0	7.0	6.0*	10.0	10.0	10.0	10.0		
93	I75	348.3	352.9	3	24.1	95500	RIDE		9.0	9.0	8.7	8.9	8.4	8.1	8.0	7.9	7.8	7.5	8.2	8.2	8.2	8.2			
4194371	13.991	18.436	C	2009	0012		CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	7.5	5.5*	4.5*	1.5*			
ANDERSON	COLUMBIA	CO.,	INC(2010)				SPRIDE		8.2	8.1	8.1	8.4	8.4	8.4	8.6	8.6	8.6	8.6	8.6	8.5	8.4	8.3	8.2		
4520741	13.991	22.000	C	2025	0548																				
36210000	18.482	38.282	R	4	1	70	CRACKING		10.0	10.0	7.5	4.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0		
93	I75	352.9	372.7	3	29.7	68000	RIDE		8.9	8.6	8.6	8.0	7.3	6.9	7.9	8.0	7.9	7.9	7.8	7.7	7.5				
ALACHUA	CO	LINE(38.3C)					FC5M																		
4306431	18.482	38.282	C	2015	0012		CRACKING		7.5	7.5	6.5	4.5*		10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.6	8.6	6.5		
ANDERSON	COLUMBIA	CO.,	INC(2018)				SPRIDE		7.5	7.3	6.8	7.6		8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.6	8.5	
36210000	18.482	38.282	L	4	1	70	CRACKING		10.0	9.0	7.5	6.5	4.5*	1.0*	10.0	10.0	10.0	10.0	9.0	8.0	7.5	7.5			
93	I75	352.9	372.7	3	29.7	68000	RIDE		8.9	8.8	8.6	8.2	7.5	7.1	8.0	7.9	7.9	7.9	7.6	7.8	7.6	7.4			
ALACHUA	CO	LINE(38.3C)					FC5M																		
4306431	18.482	38.282	C	2015	0012		CRACKING		6.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	9.0	9.0	9.0	8.4	6.5			
ANDERSON	COLUMBIA	CO.,	INC(2018)				SPRIDE		7.3	6.8	6.2*	7.3		8.6	8.7	8.6	8.6	8.6	8.6	8.6	8.6	8.5	8.4	8.4	
36210000	13.905	18.482	L	4	1	70	CRACKING		10.0	9.0	9.0	9.0	8.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0		
93	I75	348.3	352.9	3	24.1	95500	RIDE		9.0	8.6	8.9	8.7	8.2	7.9	7.8	7.6	7.6	7.6	7.6	8.2	8.3	8.2			
4194371	13.991	18.436	C	2009	0012		CRACKING		10.0	10.0	10.0	10.0	9.0	9.0	9.0	9.0	7.5	7.5	6.5	4.5*	4.5*	1.5*			
ANDERSON	COLUMBIA	CO.,	INC(2010)				SPRIDE		8.2	8.2	8.1	8.5	8.4	8.3	8.5	8.5	8.6	8.5	8.4	8.4	8.1	8.0			
4520741	13.991	22.000	C	2025	0548																				
36210000	0.000	13.905	L	4	7	70	CRACKING		10.0	9.0	9.0	9.0	7.5	6.5	4.5*	4.5*		10.0	10.0	10.0	10.0	10.0			
93	I75	334.4	348.3	3	21.6	87000	RIDE		9.0	8.9	8.8	8.5	8.0	7.8	7.6	7.5		8.3	8.3	8.3	8.3	8.3			
4431701	0.000	13.993	L	2022	0012		CRACKING		10.0	10.0	10.0	9.0	7.5	7.5	6.5	6.5	4.5*	4.5*	4.5*	4.5*	10.0	9.0			
ANDERSON	COLUMBIA	CO.,	INC(2025)				SPRIDE		8.1	8.1	7.9	8.3	8.2	8.2	8.4	8.4	8.4	8.4	8.1	7.9	8.6	8.5			
36220000	0.000	8.760	R	1	1	55	CRACKING		10.0	9.0	9.0	7.0	6.5	4.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0			
500	27		2	20.3	1	18200	RIDE		9.1	9.0	8.9	8.6	8.2	8.0	7.8	7.7	7.6	7.6	8.2	8.3	8.3	8.2			
SE 178 PL(	0.2C)						FC5																		
4155241	0.000	8.760	C	2007	0012		CRACKING		10.0	10.0	10.0	10.0	10.0	9.5	9.0	9.0	7.5	6.5	4.5*	4.5*	4.5*	0.5*			
ANDERSON	COLUMBIA	CO.,	INC(2009)				SPRIDE		7.7	8.2	8.2	8.3	8.3	8.3	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.3	8.1		
4506371	0.228	8.430	C	2026	0226																				
36220000	0.000	8.760	L	1	1	55	CRACKING		10.0	9.0	9.0	7.0	6.5	4.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0			
500	27		2	20.3	1	18200	RIDE		9.0	9.0	8.9	8.7	8.3	8.1	7.8	7.6	7.6	7.6	8.3	8.3	8.3	8.3			
SE 178 PL(	0.2C)						FC5																		
4155241	0.000	8.760	C	2007	0012		CRACKING		10.0	10.0	10.0	10.0	10.0	9.5	9.0	8.5	6.5	6.5	4.5*	4.5*	4.5*	0.5*			
ANDERSON	COLUMBIA	CO.,	INC(2009)				SPRIDE		7.9	8.3	8.2	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.4	8.3	8.2	8.0		
4506371	0.228	8.430	C	2026	0226																				
36518000	0.000	0.288	R	1	1	45	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	10.0	10.0			
326			2	14.9	1	11800	RIDE			8.0	8.0	7.4	7.4	7.6	6.8	6.2	6.5	6.5	6.4	7.3	7.1				
SR 200(	0.0C)						OGFC																		
4452171	0.024	8.428	C	2023	0012																				
36518000	0.288	8.460	C	1	8	55	CRACKING			0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	9.0			
326			2	14.9	1	12500	RIDE			6.8	6.2*	8.3	8.3	8.2	8.1	8.1	8.2	8.1	8.1	8.1	8.1	8.0			
NW 8	AVE(	0.5R)					FC125																		
4071411	0.288	8.427	C	2002	0012		CRACKING		8.5	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	6.0*	3.5*				
ANDERSON	COLUMBIA	CO.,	INC(2003)				SPRIDE		8.0	7.9	7.9	7.7	7.6	7.6	7.6	7.6	7.6	7.4	7.4	7.4	7.4				
4452171	0.024	8.428	C	2023	0012																				

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

-----								DISTRICT = 5 COUNTY = MARION												-----			
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR												FUTURE			
SR	US	G_BMP	G_EMP	LN	%T	AADT	RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012			
INTERSECT	AT	(MP SIDE)					=====																
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKMX-P																		
CONTRACTOR	(AGE	ONE YEAR)			ASTYPE			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030		
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKMX-F																(PMRS)		
36518000	0.000	0.288	L	1	1	45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	10.0	10.0			
326			2	14.9		11800	RIDE		7.8	8.1	7.7	6.6	6.8	6.5	7.4	6.5	7.2	6.8	6.9	7.0			
SR 200(0.0C)																							
													</										

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 "**" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 "@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).