

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = SUWANNEE																						
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR													FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT AT (MP SIDE)																						
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-X-P			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
CONTRACTOR (AGE ONE YEAR)					ASTYPE																(PMRS)	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-X-F																	
37010000	0.000	4.983	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	7.0	7.0	7.0		
10 90			2	5.6	3600	RIDE	8.9	8.8	8.8	8.6	7.9	8.1	8.0	7.9	8.0	7.8	7.9	7.8	7.6			
OLD LOCATION OF SR 10(0.1L)					FC125M																	
4342961	0.000	4.952	C	2019	0012	CRACKING	7.0	6.5	6.0*	6.0*	6.0*	4.0*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	7.5		
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE		7.6	7.6	7.4	7.5	7.4	7.5	7.4	7.3	8.7	8.4	8.3	8.1	8.0	7.6		
37010000	4.983	6.252	R	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5		
10 90			2	5.6	3600	RIDE	8.3	8.2	8.3	8.3	8.3	7.9	8.0	7.9	7.8	7.8	8.5	7.9	7.8	7.8		
					FC125M																	
					(2020)																	
2135604	4.963	6.272	C	2026	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	9.5		10.0	7.5	7.0	7.0	6.0*	4.0*	2.5*		
						RIDE	8.7	8.5	8.4	8.3	8.3	8.2		8.4	8.3	8.1	8.0	8.0	7.8	7.4		
37010000	6.252	12.270	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5		
10 90			2	5.6	8300	RIDE	8.8	8.7	8.8	8.8	8.1	8.0	8.0	7.8	7.9	7.8	8.0	7.8	7.7			
161 RD(6.4R)					FC125M																	
4342961	6.261	10.177	C	2019	0012	CRACKING	8.5	7.0	7.0	7.0	7.0	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	8.9	7.5		
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE		7.5	7.5	7.5	7.3	7.2	7.3	7.0	7.0	8.5	8.2	8.1	7.9	7.8	7.4		
37010000	12.270	13.320	C	1	1 35	CRACKING	5.5*	3.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5			
10 90			2	5.6	9400	RIDE	6.6	6.7		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4			
GREEN AVE(12.4R)					FC125M																	
					(2021)																	
						CRACKING	7.5	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.0	7.5		
						RIDE	7.3	7.4	7.3	7.3	7.3	7.3	7.2	7.2	7.7	7.3	7.1	7.1	6.9	6.5		
37010000	13.320	15.090	C	1	1 45	CRACKING	5.5*	4.5*		10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	8.5	7.5			
10 90			2	6.1	5600	RIDE	8.0	7.9		8.5	8.1	8.1	7.7	7.6	7.6	7.8	7.9	7.5	7.4			
CONNER ST(13.3C)					FC125M																	
					(2021)																	
						CRACKING	7.5	7.0	7.0	7.0	6.0*	4.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	9.5	8.0		
						RIDE	7.3	7.4	7.3	7.3	7.3	7.3	7.2	7.2	8.4	8.3	8.1	8.0	7.8	7.4		
37010000	15.090	26.152	C	1	1 60	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5		
10 90			2	6.1	9200	RIDE	8.7	8.7	8.7	8.7	8.4	8.3	8.2	8.1	8.0	7.9	8.0	7.8	7.7			
97TH LN(15.3L)					FC125M																	
4432831	15.035	26.152	C	2022	0012	CRACKING	8.5	7.0	7.0	6.0*	6.0*	4.5*	4.0*	4.0*	4.0*	4.0*	4.0*	10.0	10.0	9.0		
ANDERSON COLUMBIA CO., INC(2024)					SPRIDE		7.6	7.6	7.5	7.6	7.6	7.7	7.7	7.7	7.7	7.6	7.6	8.9	8.9	8.5		
37010000	4.983	6.252	L	1	1 45	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.0	7.0		
10 90			2	5.6	3600	RIDE	8.3	8.2	8.6	8.6	7.8	8.0	8.0	7.9	7.9	7.8	7.8	7.5	7.6			
169 RD(5.3L)					FC125M																	
					(2013)																	
2135604	4.963	6.272	C	2026	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	6.0*	6.0*	3.5*	
						RIDE	8.8	8.5	8.5	8.3	8.3	8.3	7.5	7.5	7.0	7.0	8.2	8.2	8.0	8.0	7.6	
37030000	0.000	0.449	C	1	1 35	CRACKING	6.5	4.5*	4.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0		
20 27			2	8.0	6600	RIDE	7.1	7.2	6.3	6.6	7.9	7.9	7.7	7.4	7.9	7.9	7.8	7.8	7.7			
SR 249(0.1L)					FC125																	
2127343	0.000	8.530	C	2003	0012	CRACKING	8.5	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.7*	0.5*		
ANDERSON COLUMBIA CO., INC(2004)					SPRIDE		7.7	7.6	7.6	7.4	7.4	7.4	7.3	7.1	7.3	7.2	7.1	7.0	6.9	6.5		
2127344	0.000	8.559	C	2025	0012																	
37030000	0.449	3.962	C	1	1 60	CRACKING	3.5*	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0		
20 27			2	8.0	4800	RIDE	8.4	8.1	7.8	7.6	8.5	8.5	8.5	8.5	8.5	8.6	8.5	8.4	8.4	8.3		
83 PL(0.7L)					FC125																	
2127343	0.000	8.530	C	2003	0012	CRACKING	8.5	8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	4.0*	4.0*	4.0*	3.5*	3.5*	0.0*		
ANDERSON COLUMBIA CO., INC(2004)					SPRIDE		8.0	8.0	8.0	7.9	8.0	7.9	7.9	7.9	7.9	7.8	7.8	7.8	7.7	7.3		
2127344	0.000	8.559	C	2025	0012																	
37030000	3.962	4.857	C	1	1 60	CRACKING	3.5*	3.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0		
20 27			2	7.3	6500	RIDE	8.4	8.1	7.8	7.6	8.5	8.5	8.5	8.5	8.5	8.5	8.4	8.4	8.3			
US-129/SR-49(4.2R)					FC125																	
2127343	0.000	8.530	C	2003	0012	CRACKING	8.5	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*	0.0*		
ANDERSON COLUMBIA CO., INC(2004)					SPRIDE		8.2	7.9	8.1	7.9	7.9	8.0	7.8	7.9	7.9	7.7	7.8	7.8	7.6	7.2		
2127344	0.000	8.559	C	2025	0012																	
37030000	4.857	8.623	C	1	1 60	CRACKING	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.0			
20 27			2	7.3	6500	RIDE	8.4	8.3	7.8	7.8	8.5	8.5	8.5	8.5	8.4	8.4	8.3	8.2	8.1			
274 PL(5.1R)					FC125																	
2127343	0.000	8.530	C	2003	0012	CRACKING	9.0	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.0*	4.0*	4.0*	4.0*	3.5*	0.0*		
ANDERSON COLUMBIA CO., INC(2004)					SPRIDE		8.1	7.9	8.0	7.9	7.9	7.9	7.9	7.9	7.9	7.8	7.8	7.7	7.6	7.2		
2127344	0.000	8.559	C	2025	0012																	

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = SUWANNEE

RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED	YEAR												FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS		2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	
INTERSECT AT (MP SIDE)							=====														
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-F	ASTYPE		2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030
CONTRACTOR (AGE ONE YEAR)																					(PMRS)
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-F																
37040000	0.000	0.438	C	1	1 30	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	10.0	10.0	10.0	
249 129			4	14.6	6400	RIDE		7.3	6.5	6.5	6.5	6.6	6.0	5.8	6.2	6.0	6.4	8.2	7.8	7.9	
US-27/US-129/SR-20(0.0R)					FC125M																
2108063	0.000	0.347	C	2008	0221	CRACKING		10.0	10.0	9.0	9.0	9.0	9.0	9.0	8.5	7.5	7.0	7.0	7.0	6.5	4.0*
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE			7.9	7.8	7.6	7.6	7.5	7.5	7.5	7.4	7.5	7.4	7.5	7.1	7.1	6.7
37040000	0.438	12.889	C	1	1 60	CRACKING		10.0	8.5	8.5	7.0	5.5*	5.5*	3.5*	3.5*	3.5*		10.0	10.0	10.0	
249 129			2	14.6	3356	RIDE		8.8	8.7	8.6	8.5	7.9	7.8	7.5	7.4	7.2		8.5	8.4	8.3	
HENRY AVE NW(0.4C)					FC125M																
2108063	0.438	12.889	C	2008	0221	CRACKING		10.0	9.0	8.5	8.5	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	7.0	4.5*
ANDERSON COLUMBIA CO., INC(2010)					SPRIDE			8.2	8.1	8.1	8.1	8.0	8.1	7.9	7.9	7.9	7.8	7.8	7.6	7.6	7.2
37040000	12.889	23.138	C	1	1 60	CRACKING		5.5*	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.5	9.5	9.5	7.5	
249 129			2	14.6	5200	RIDE		8.5	8.1	7.7	8.9	8.4	8.4	8.4	8.3	8.5	8.4	8.4	8.4	8.2	
OLD ALIGN RD(13.0L)					FC125M																
4454011	12.851	22.495	C	2023	0012	CRACKING		7.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	4.0*	4.0*	1.5*	1.5*	10.0	10.0	9.0
ANDERSON COLUMBIA CO., INC(2024)					SPRIDE			8.2	8.0	8.0	8.0	7.9	7.9	7.7	7.9	7.9	7.7	7.8	8.5	8.4	8.0
37040000	23.138	24.685	R	1	1 35	CRACKING			10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	7.5	7.5	7.5	7.5	
249 129			1	14.6	6900	RIDE			7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.1	7.0	6.7	6.8	6.2	
MANOR ST(23.3R)					FC125M																
4305571	23.141	24.178	R	2016	0012	CRACKING		6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.0	8.0	7.5	6.0*
ANDERSON COLUMBIA CO., INC(2018)					SPRIDE			6.1	6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6	7.4	7.2	7.2	6.9	6.5
37040000	24.685	25.200	R	1	1 35	CRACKING		10.0	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	
51 129			2	4.9	14300	RIDE		7.9	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	
HAINES ST(24.7C)					DGFC																
2107502	24.651	25.322	C	2008	0012	CRACKING		8.5	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.6	7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.5	6.9	6.5	6.1
2107503	24.685	27.201	C	2025	0012																
37040000	25.200	25.610	R	1	1 45	CRACKING		8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	8.5	8.5	8.5	8.5	
51 129			2	4.9	13900	RIDE		8.5	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	7.6	7.5	7.6	7.5	
HAMILTON ST(25.3R)					DGFC																
2107502	25.322	25.610	C	2008	0012	CRACKING		8.5	7.5	7.5	6.0*	6.0*	5.5*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*	0.0*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.5	7.2	7.1	6.4	6.4	6.5	7.7	7.4	7.6	7.5	7.5	7.6	7.3	6.9
2107503	24.685	27.201	C	2025	0012																
37040000	25.610	27.579	R	1	1 45	CRACKING		8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	
51 129			2	4.9	14000	RIDE		8.5	8.3	8.5	8.5	7.8	7.8	7.8	7.7	7.7	8.5	8.3	8.2	8.3	
GRAND ST(25.8R)					FC125M																
2107502	25.610	27.579	C	2008	0012	CRACKING		10.0	9.0	8.5	8.5	8.5	7.5	6.5	6.5	5.5*	5.5*	5.5*	5.5*	3.5*	0.5*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			8.2	8.3	8.1	8.1	8.1	8.1	8.0	8.1	8.0	7.8	7.9	7.8	7.8	7.4
2107503	24.685	27.201	C	2025	0012																
37040000	27.579	32.407	C	1	1 60	CRACKING		8.0	7.0	7.0	7.0	5.5*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	
51 129			2	4.9	6100	RIDE		8.3	8.2	8.3	8.2	7.8	7.7	7.5	8.3	8.4	8.4	8.5	8.4	8.4	
58TH ST(28.6R)					FC125																
						CRACKING		10.0	9.0	8.5	8.5	8.5	8.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	0.5*
						RIDE		8.3	8.3	8.3	8.1	8.1	8.1	8.0	8.1	8.0	7.9	8.0	7.9	8.0	7.6
2107814	27.925	32.407	C	(2007) 2026	0012																
37040000	25.610	27.579	L	1	1 45	CRACKING		10.0	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	9.0	
51 129			2	4.9	14000	RIDE		8.7	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.3	8.2	8.3	8.0	
72ND TRACE(26.4C)					FC125M																
2107502	25.610	27.579	C	2008	0012	CRACKING		8.5	8.5	8.5	8.5	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	0.0*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			8.1	8.0	8.1	7.9	8.0	7.9	7.8	7.9	7.8	7.6	7.8	7.7	7.7	7.3
2107503	24.685	27.201	C	2025	0012																
37040000	25.200	25.610	L	1	1 45	CRACKING		10.0	8.5	8.5	7.0	6.0*	3.0*	3.0*	3.0*	3.0*	8.5	8.5	7.5	7.5	
51 129			2	4.9	13900	RIDE		8.7	8.6	8.5	8.5	7.9	8.0	7.8	7.9	7.9	8.0	7.8	7.9	7.7	
HAMILTON ST(25.3L)					FC4																
2107502	25.322	25.610	C	2008	0012	CRACKING		7.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	5.5*	3.5*	3.5*	3.5*	3.0*	0.0*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.5	7.4	7.5	7.4	7.3	7.1	7.1	7.2	7.1	7.0	6.8	6.9	6.8	6.4
2107503	24.685	27.201	C	2025	0012																
37040000	24.685	25.200	L	1	1 35	CRACKING		10.0	10.0	10.0	10.0	8.5	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	
51 129			2	4.9	14300	RIDE		7.9	7.9	7.5	7.0	7.3	7.5	6.5	7.0	7.1	8.0	7.8	7.7	7.8	
HAINES ST(24.7C)					FC125M																
2107502	24.651	25.322	C	2008	0012	CRACKING		8.5	8.5	8.5	7.0	7.0	6.0*	0.0*	0.0*	0.0*	0.0*	6.0*	6.0*	5.5*	2.5*
ANDERSON COLUMBIA CO., INC(2009)					SPRIDE			7.6	7.5	7.2	6.8	6.7	6.8	7.3	6.9	6.7	7.0	6.8	7.2	6.7	6.3
2107503	24.685	27.201	C	2025	0012																

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = SUWANNEE																									
RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	RATINGS	SURVEYED YEAR												FUTURE	
INTERSECT AT (MP SIDE)	AT	(MP SIDE)	W_BMP	W_EMP	RW	FY-P	WKM-F	ASTYPE	WKM-F	SPRIDE	CRACKING	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2030 (PMRS)
37040000	249	129	23.138	24.685	L	1	1	35	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	9.5		7.5	7.5	7.5	
LAVONIA ST(23.2L)						1	14.6	6900	RIDE				7.4	7.7	7.6	7.3	7.3	7.0	7.0	7.5		6.7	6.8	6.2	
4305571			23.141	24.178	L	2016	0012	CRACKING				6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	8.0	8.5	8.5	7.0	5.5*
ANDERSON COLUMBIA CO., INC(2018)								SPRIDE				6.1	6.9	6.9	7.1	6.8	7.8	7.8	7.8	7.6		7.6	7.6	7.3	6.9
37050000	136		0.000	0.424	C	1	7	45	CRACKING			10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	7.0	10.0	10.0	10.0	
DGFC						2	7.2	2500	RIDE			7.5	8.2	8.4	8.2	7.4	7.6	7.2	7.2	7.4	7.0	8.3	8.2	8.2	
(2025)								CRACKING				10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.0	7.0	7.0	10.0	9.0
								RIDE				7.8	8.1	8.1	7.7	7.5	7.6	7.3	7.6	7.5	7.3	7.1	7.1	7.6	7.2
37050000	136		0.424	1.046	C	1	1	55	CRACKING			7.0	7.0	7.0	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0	
EXIT FARMERS MARKET(0.5R)						2	7.2	2500	RIDE			8.4	8.3	8.3	8.2	7.1	6.7	6.3*	8.0	8.5	8.3	8.2	8.3	8.2	
2107752			0.424	0.789	C	2006	0012	CRACKING				9.0	8.5	8.5	7.5	7.0	7.0	6.5	6.5	6.0*	6.0*	6.0*	5.5*	5.5*	2.5*
ANDERSON COLUMBIA CO., INC(2007)								SPRIDE				8.1	8.3	8.2	8.0	7.9	7.9	7.8	7.9	7.9	7.8	7.8	7.7	7.6	7.2
37060000	51		0.000	17.455	C	1	1	60	CRACKING			3.5*	0.0*	0.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	
COUNTY LINE INSPECTION S(1.3C)						2	8.4	5200	RIDE			8.5	8.3	8.3	8.8	8.5	8.4	8.4	8.4	8.4	8.3	8.3	8.2	8.0	
4322611			0.000	16.658	C	2016	0012	CRACKING				7.0	5.5*	5.5*	5.5*	10.0	10.0	10.0	10.0	10.0	8.5	7.5	7.5	7.0	5.0*
ANDERSON COLUMBIA CO., INC(2017)								SPRIDE				8.0	7.9	7.8	7.8	8.6	8.5	8.3	8.0	7.8	7.7	7.6	7.6	7.6	7.2
37060000	51		17.455	17.491	C	1	6	35	CRACKING			3.5*	0.0*	0.0*		10.0	10.0	10.0	10.0	10.0					
S WALKER AVE(17.5R)						1	8.4	9500	RIDE			8.5	8.3	8.3											
(2004)								CRACKING								8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	8.3	5.0*
								RIDE																	
37060000	51		17.491	17.994	C	1	7	35	CRACKING			10.0	9.0	9.0	6.5	6.5	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0	
BYNUM AVE SW(17.6R)						1	8.4	9500	RIDE			6.9	6.7	6.8	6.1	5.8	7.3	6.9	6.6	6.2	5.5	7.7	7.5	7.3	
(2025)								CRACKING				10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	7.0	6.0*			10.0	9.0
								RIDE				7.2	7.0	6.9	6.4	6.3	6.2	6.0	6.0	6.1	5.8			7.2	6.8
37070000	49	129	0.000	2.755	C	1	1	60	CRACKING			9.0	8.5	8.5	7.5	7.5	7.0	7.0	5.5*	5.5*	5.5*	10.0	10.0	8.5	
SANDY POINT RD(0.0L)						2	10.8	3800	RIDE			8.4	8.6	8.5	8.4	8.1	8.0	7.9	7.6	7.4	7.4	8.7	8.2	8.2	
2107762			0.000	2.648	C	2009	0012	CRACKING				8.5	8.5	8.5	8.5	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.0*
ANDERSON COLUMBIA CO., INC(2010)								RIDE				8.2	8.3	8.2	8.2	8.1	8.0	7.9	7.9	7.8	7.7	7.7	7.6	7.4	7.0
2107763			0.000	2.276	C	2029	0012																		
37080000	247		0.000	0.600	C	1	2	35	CRACKING			9.0	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.5*	5.5*	10.0	10.0	10.0	
SR 249(0.0C)						2	16.5	3633	RIDE			8.5	8.4	8.3	8.3	7.8	7.6	7.4	7.2	6.5	6.8	8.4	7.9	7.8	
2107192			0.000	0.600	C	2008	0221	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	7.0	7.0	7.5	5.0*
ANDERSON COLUMBIA CO., INC(2010)								RIDE				8.0	8.0	8.0	7.8	7.8	7.8	7.8	7.8	7.8	7.7	7.5	7.5	7.4	7.0
37080000	247		0.600	10.700	C	1	1	60	CRACKING			9.0	9.0	9.0	7.0	7.0	6.0*	5.5*	5.5*	5.0*		10.0	10.0	10.0	
SIDE ROAD(1.2C)						2	14.6	5200	RIDE			8.5	8.4	8.3	8.3	7.8	7.6	7.4	7.2	7.1		8.7	8.6	8.5	
2107192			0.690	10.700	C	2008	0221	CRACKING				10.0	10.0	10.0	9.0	9.0	8.5	8.5	8.5	7.0	7.0	7.0	7.0	6.7	4.0*
ANDERSON COLUMBIA CO., INC(2010)								RIDE				8.4	8.1	8.1	8.2	8.1	7.9	7.9	7.9	7.8	7.8	7.7	7.6	7.4	7.0
37120000	8	110	0.000	5.861	R	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	10.0	10.0	10.0	10.0	10.0	
			268.2	274.1	2	24.6	26000	RIDE				8.6	8.9	8.9	8.9	8.4	8.4	8.0	8.3	8.0	8.1	8.2	8.2	8.1	
4413371			0.000	5.861	C	2021	0012	CRACKING				10.0	10.0	10.0	9.0	9.0	9.0	7.5	6.5	6.5		10.0	10.0	9.7	8.5
ANDERSON COLUMBIA CO., INC(2023)								SPRIDE				8.1	8.1	8.0	8.3	8.3	8.5	8.4	8.4	8.4		8.8	8.8	8.7	8.6
37120000	8	110	5.861	15.099	R	4	1	70	CRACKING			10.0	10.0	10.0	10.0	10.0	9.0	8.0	7.5	7.5	7.5	6.5	6.0*		
			274.1	283.3	2	27.1	24000	RIDE				9.0	8.9	8.9	8.9	8.3	8.2	8.0	8.0	7.7	7.6	7.3	7.0		
2135603			5.861	15.099	C	2011	0012	CRACKING				10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	6.5	6.5	6.5	4.0*
PREFERRED MATERIALS, INC. (2013)								SPRIDE				8.7	8.7	8.6	8.9	8.9	9.1	9.0	9.0	9.1	9.1	8.9	8.8	8.7	8.6
2135604			5.861	15.132	C	2026	0012																		

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = SUWANNEE																						
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR														FUTURE
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
INTERSECT	AT (MP SIDE)																					
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKM-X-P																	
CONTRACTOR	(AGE ONE YEAR)				ASTYPE			2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKM-X-F																(PMRS)	
37120000	15.099	25.508	R	4	1 70	CRACKING	10.0	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
8 I10	283.3	293.8	2	27.1	32875	RIDE	9.1	9.0	8.6	8.3	7.7	6.8	6.4*	8.4	8.5	8.5	8.5	8.5	8.5	8.4		
					FC5M																	
2135202	15.144	25.523	C	2006	0012	CRACKING	10.0	9.0	9.0	9.0	7.5	7.5	4.5*	4.5*	4.5*	4.5*	3.5*	1.0*	1.0*	0.0*		
ANDERSON	COLUMBIA CO., INC	(2007)				RIDE	8.3	8.1	7.9	8.3	8.3	8.6	8.5	8.5	8.5	8.4	8.2	8.0	8.0	7.9		
37120000	15.099	25.508	L	4	8 70	CRACKING	10.0	10.0	9.0	6.5	6.5	3.5*	1.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
8 I10	283.3	293.8	2	27.1	32875	RIDE	9.0	8.9	8.7	8.3	7.4	7.0	6.7	8.5	8.5	8.5	8.5	8.5	8.4	8.3		
					FC5M																	
2135202	15.144	25.523	C	2006	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	4.5*	4.5*	4.5*	4.5*	4.5*	1.0*				
ANDERSON	COLUMBIA CO., INC	(2007)				RIDE	8.2	8.1	7.9	8.4	8.3	8.7	8.5	8.5	8.4	8.1	7.8	7.8				
37120000	5.861	15.099	L	4	1 70	CRACKING	10.0	10.0	10.0	10.0	9.0	9.0	8.0	7.5	7.5	6.5	6.0*	6.0*				
8 I10	274.1	283.3	2	27.1	24000	RIDE	8.9	8.8	8.8	8.8	8.2	8.1	7.9	7.7	7.4	7.4	7.1	6.6				
					FC5M																	
2135603	5.861	15.099	C	2011	0012	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	9.0	7.0	7.0	6.5	6.5	4.0*		
PREFERRED	MATERIALS, INC.	(2013)				SPRIDE	8.7	8.7	8.6	8.8	8.8	9.0	8.9	8.9	9.1	9.0	8.8	8.8	8.6	8.5		
2135604	5.861	15.132	C	2026	0012																	
37120000	0.000	5.861	L	4	1 70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	10.0	10.0	10.0	10.0	10.0			
8 I10	268.2	274.1	2	24.6	26000	RIDE	8.8	8.8	8.9	8.9	8.4	8.3	8.2	8.2	8.1	8.1	8.2	8.2	8.1			
					FC5M																	
4413371	0.000	5.861	C	2021	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	6.5	6.5	6.5		10.0	10.0	9.6	8.5		
ANDERSON	COLUMBIA CO., INC	(2023)				SPRIDE	8.1	8.0	7.8	8.3	8.2	8.5	8.4	8.4	8.4		8.9	8.8	8.8	8.7		
37130000	0.000	3.385	R	4	7 70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	10.0	10.0	10.0			
93 I75	438.3	441.7	3	29.4	43000	RIDE	8.9	8.5	8.9	8.9	8.3	8.3	8.1	7.9	7.7	7.5	8.7	8.7	8.7	8.6		
					FC5M																	
4455451	0.000	3.656	R	2022	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5	7.5	10.0	9.0		
ANDERSON	COLUMBIA CO., INC	(2025)				SPRIDE	8.6	8.5	8.3	8.7	8.6	9.0	8.8	8.9	8.9	8.8	8.6	8.6	8.9	8.8		
37130000	3.385	3.656	R	4	1 70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	10.0	10.0	10.0			
93 I75	441.7	442.0	3	29.4	43000	RIDE	8.7	8.5	8.8	8.7	8.1	8.1	7.9	7.9	7.7	7.6	8.7	8.7	8.6			
					FC5M																	
2135542	0.000	3.656	R	2009	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	7.5	7.5	6.0*	3.0*		
			(2010)			RIDE	8.6	8.5	8.3	8.7	8.6	9.0	8.8	8.9	8.9	8.8	8.6	8.6	8.1	8.0		
4455451	0.000	3.656	C	2022	0012																	
37130000	3.385	3.656	L	4	1 70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.0	10.0	10.0	10.0			
93 I75	441.7	442.0	3	29.4	43000	RIDE	8.7	8.8	8.8	8.8	7.8	7.2	8.0	8.1	7.7	7.5	8.6	8.6	8.5			
					FC5M																	
2135542	0.000	3.656	L	2009	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	6.5	4.5*	4.5*	1.5*		
PREFERRED	MATERIALS, INC.	(2010)				SPRIDE	8.5	8.4	8.2	8.5	8.5	8.7	8.6	8.6	8.6	8.3	8.2	8.1	7.4	7.3		
4455451	0.000	3.656	C	2022	0012																	
37130000	0.000	3.385	L	4	7 70	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	7.5	7.0	10.0	10.0	10.0			
93 I75	438.3	441.7	3	29.4	43000	RIDE	8.9	8.9	8.9	8.8	8.4	8.3	8.2	8.1	8.0	7.7	8.6	8.6	8.5			
					FC5M																	
4455451	0.000	3.656	L	2022	0012	CRACKING	10.0	10.0	10.0	9.0	9.0	9.0	7.5	7.5	7.5	7.5	6.5	4.5*	10.0	9.0		
ANDERSON	COLUMBIA CO., INC	(2025)				SPRIDE	8.5	8.4	8.2	8.5	8.5	8.7	8.6	8.6	8.6	8.3	8.2	8.1	8.7	8.6		

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).