

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = TAYLOR																					
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR													
SR US	G BMP	G EMP	LN	%T	AADT	RATINGS	=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	FUTURE
INTERSECT AT (MP SIDE)																					
ITMSEG-P	W BMP	W EMP	RW	FY-P	WKMX-P																
CONTRACTOR (AGE_ONE YEAR)					ASTYPE																
ITMSEG-F	W BMP	W EMP	RW	FY-F	WKMX-F																2030 (PMRS)
38010000	0.000	7.831	R	1	1 65	CRACKING		8.5	8.5	8.5	7.0	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	
55 19			2	12.4	5800	RIDE		8.9	8.9	8.4	8.9	8.4	8.4		8.6	8.3	8.5	8.4	8.3	8.2	
SR 51(0.2C)					FC5M																
4376181	0.000	7.831	C	2019	0012	CRACKING		10.0	10.0	9.0	9.0	7.5	7.5	4.5*		10.0	10.0	10.0	10.0	9.6	7.5
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE			8.1	8.1	7.9	8.1	7.9	8.0	8.0		8.9	8.9	8.9	8.7	8.7	8.5
38010000	7.831	24.844	R	1	1 65	CRACKING		7.5	6.5	4.5*	4.5*	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	
55 19			2	12.4	5800	RIDE		8.8	8.7	8.6	8.5	7.8	7.8	7.6		8.3	8.4	8.4	8.3	8.3	
JOSH MCCALL(8.8R)					FC5HP																
4410591	7.831	24.844	R	2021	0012	CRACKING		10.0	10.0	10.0	9.0	7.5	7.5	4.5*	4.5*	4.5*		10.0	10.0	9.7	8.0
ANDERSON COLUMBIA CO., INC(2023)					SPRIDE			8.2	8.1	7.9	8.1	8.1	8.3	8.2	8.1	8.0		8.9	8.9	8.8	8.6
38010000	24.844	27.458	R	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	
55 19			2	12.4	10300	RIDE		8.3	8.3	8.3	8.4	8.2	8.2	7.8	8.0	8.1	8.1	8.0	7.9	7.8	
CARLTON CEMETERY RD(24.9R)					FC125M																
4361651	24.832	27.395	C	2018	0012	CRACKING		7.0	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	9.0	7.5
CAPITAL ASPHALT INC				(2020)	SPRIDE			7.8	7.7	7.7	7.7	7.7	7.9	7.7	8.5	8.5	8.4	8.4	8.4	8.3	7.9
38010000	24.844	27.458	L	1	1 45	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	
55 19			2	12.4	10300	RIDE		8.5	8.3	8.5	8.4	8.1	8.0	7.8	7.9	8.1	8.2	8.0	8.0	7.9	
UNSIGNED(24.9L)					FC125M																
4361651	24.832	27.395	C	2018	0012	CRACKING		6.0*	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	8.7	7.0
CAPITAL ASPHALT INC				(2020)	SPRIDE			7.8	7.8	7.7	7.8	7.7	7.9	7.7	8.5	8.4	8.4	8.4	8.3	8.2	7.8
38010000	7.831	24.844	L	1	1 65	CRACKING		9.0	6.5	6.5	4.5*	3.5*	3.5*	1.0*		10.0	10.0	10.0	10.0	10.0	
55 19			2	12.4	5800	RIDE		9.0	8.7	8.9	8.8	8.3	8.2	8.0		8.3	8.4	8.4	8.4	8.3	
FISH CREEK RD(9.4L)					FC5HP																
4410591	7.831	24.844	L	2021	0012	CRACKING		10.0	10.0	9.0	9.0	8.0	8.0	7.5	6.5	4.5*	10.0	10.0	10.0	9.8	8.0
ANDERSON COLUMBIA CO., INC(2022)					SPRIDE			8.3	8.2	8.1	8.4	8.4	8.6	8.5	8.5	8.4	9.0	8.9	8.9	8.9	8.7
38010000	0.000	7.831	L	1	1 65	CRACKING		8.5	8.5	8.5	7.0	7.0	6.0*		10.0	10.0	10.0	10.0	10.0	10.0	
55 19			2	12.4	5800	RIDE		9.0	8.8	8.5	8.8	8.3	8.2		8.6	8.2	8.6	8.6	8.5	8.5	
SR 51(0.2C)					FC5M																
4376181	0.000	7.831	C	2019	0012	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	7.5		10.0	10.0	10.0	10.0	9.7	7.5
ANDERSON COLUMBIA CO., INC(2021)					SPRIDE			8.4	8.4	8.3	8.4	8.4	8.4	8.3		8.8	8.8	8.8	8.7	8.7	8.5
38020000	0.000	1.784	R	1	1 40	CRACKING		7.5	7.5	7.5	5.5*	5.5*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	
30 19			2	10.9	11000	RIDE		8.1	8.0	8.0	7.7	7.0	7.2	6.5	6.5	8.4	8.3	8.3	8.0	8.0	
US-221/SR-55/JEFFER(0.0R)					FC125M																
2108782	0.000	1.784	C	2007	0012	CRACKING		10.0	10.0	10.0	9.0	9.0	9.0	9.0	8.5	7.0	7.0	7.0	6.0*	4.9*	2.0*
ANDERSON COLUMBIA CO., INC(2008)					SPRIDE			7.9	7.9	7.9	7.9	7.8	7.9	7.8	7.7	7.6	7.6	7.6	7.6	7.5	7.1
2108784	0.000	1.784	C	2028	0012																
38020000	1.784	17.387	R	1	1 65	CRACKING		10.0	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	
20 19			2	10.9	6100	RIDE		8.9	8.9	8.8	8.8	8.4	8.3	8.1	8.1	7.9	7.7	7.5	8.5	8.5	
CR 356(2.0C)					FC5M																
2108783	1.784	17.387	R	2009	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.1	2.0*
ANDERSON COLUMBIA CO., INC(2011)					SPRIDE			8.5	8.5	8.5	8.7	8.7	8.8	8.7	8.7	8.7	8.7	8.7	8.6	8.6	8.4
38020000	1.784	17.387	L	1	1 65	CRACKING		10.0	10.0	10.0	9.0	9.0	6.5	6.5	3.5*	3.5*	3.5*	3.5*	10.0	10.0	
20 19			2	10.9	6100	RIDE		8.6	8.8	8.8	8.8	8.3	8.3	8.0	7.9	7.3	7.1	7.0	8.6	8.6	
CR 356(2.0C)					FC5M																
2108783	1.784	17.387	L	2009	0012	CRACKING		10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	7.5	7.5	7.5	7.5	7.0	2.0*
ANDERSON COLUMBIA CO., INC(2011)					SPRIDE			8.5	8.6	8.5	8.8	8.8	8.9	8.9	8.8	8.9	8.8	8.8	8.8	8.7	8.5
38020000	0.000	1.784	L	1	1 40	CRACKING		7.5	7.5	7.5	5.5*	5.0*	3.0*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	
30 19			2	10.9	11000	RIDE		8.0	8.3	8.0	7.7	7.0	6.6	6.4	6.1	8.2	8.1	8.1	8.1	7.8	
CR-361A PUCKETT RD(0.0L)					FC125M																
2108782	0.000	1.784	C	2007	0012	CRACKING		10.0	10.0	10.0	9.0	9.0	6.5	6.5	6.5	6.0*	6.0*	6.0*	5.5*	4.4*	1.5*
ANDERSON COLUMBIA CO., INC(2008)					SPRIDE			7.8	7.8	7.9	7.6	7.7	7.7	7.6	7.6	7.5	7.4	7.4	7.4	7.1	6.7
2108784	0.000	1.784	C	2028	0012																
38030000	0.000	0.686	C	1	1 30	CRACKING		10.0	10.0	10.0	10.0	8.5	8.5	8.5	8.5	8.5	7.5	7.0	7.0	7.0	
20 27			2	12.9	5900	RIDE		7.5	7.0	7.5	7.3	6.8	6.6	6.3	6.4	6.3	6.4	6.5	5.8	5.6	
US-19/27A/98/SR-30(0.0R)					FC125M																
4305491	0.020	0.683	C	2015	0012	CRACKING		7.0	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.0	5.0*
ROBERTS AND ROBERTS, INC. (2016)					SPRIDE			5.6	6.0	6.0	7.6	7.6	7.4	7.1	6.8	7.0	7.0	6.9	6.6	6.5	6.1

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = TAYLOR

RDWYID	SR	US	BMP	G_BMP	EMP	RW	SYS	TYP	SPD	AADT	DISTRESS	SURVEYED YEAR												FUTURE		
INTERSECT AT (MP SIDE)	AT	MP	W_BMP	W_EMP	RW	FY-P	WKMX-P	ASTYPE			=====	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012		
CONTRACTOR (AGE ONE YEAR)			W_BMP	W_EMP	RW	FY-F	WKMX-F					2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030	(PMRS)
ITMSEG-F			W_BMP	W_EMP	RW	FY-F	WKMX-F																			
38030000	20	27	0.686	3.979	C	1	50	CRACKING	6.5	6.5	7.0	7.0	6.0*	6.0*	5.5*	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
MAPLE AVE(			0.7C)			4	12.9	4400	8.1	8.0	7.6	7.2	6.8	6.7	6.5	8.5	8.5	8.5	8.6	8.6	8.5	8.4				
2108652			0.686	6.704	C	2006		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2007)			0012	10.0	8.5	8.5	7.5	7.5	7.5	7.0	7.0	6.5	6.0*	6.0*	4.0*	3.5*	0.5*				
2108656			0.686	3.979	C	2027		0012	8.4	8.1	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.7	7.9	7.7	7.7	7.7	7.7	7.7	7.3	
38030000	20	27	3.979	4.642	C	1	50	CRACKING	6.5	6.5	6.5	6.5	6.5	6.5	6.5	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0		
HENRY GIBSON RD(			4.0R)			4	12.9	3100	7.8	7.6	7.7	7.7	7.1	6.9	6.7	8.2	8.2	8.2	8.2	8.1	7.9	7.5				
2108652			0.686	6.704	C	2006		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2007)			0012	10.0	8.5	8.5	8.5	7.5	7.5	6.0*	6.0*	6.0*	6.0*	6.0*	6.0*	5.5*	3.5*	0.5*			
2108655			4.036	6.649	C	2024		0012	7.6	7.7	7.7	7.8	7.7	7.4	7.8	7.7	7.7	7.6	7.7	7.6	7.6	7.6	7.6	7.2		
38030000	20	27	4.642	6.704	C	1	60	CRACKING	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0	10.0	10.0	10.0	10.0	10.0	9.5			
CR 30(			4.7R)			2	12.9	3400	8.9	8.8	8.8	8.8	8.0	7.9	7.7	8.5	8.6	8.5	8.5	8.5	8.4	8.2				
2108652			0.686	6.704	C	2006		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2007)			0012	9.5	9.0	9.0	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*	6.0*	5.5*	3.5*	0.5*				
2108655			4.036	6.649	C	2024		0012	8.1	8.0	8.0	8.1	8.1	8.2	8.0	8.0	8.0	8.0	8.1	8.0	8.0	8.0	7.6			
38030000	20	27	6.704	14.697	C	1	60	CRACKING	9.0	9.0	9.0	7.0	6.5	6.5	6.5	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0			
SIDE ROAD(			7.1C)			2	12.9	3400	9.0	9.0	8.9	8.9	8.1	7.9	7.5	7.2	7.2	8.8	8.8	8.7	8.6					
2108653			6.704	14.697	C	2008		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2009)			0012	10.0	10.0	10.0	10.0	9.0	9.0	8.5	8.5	7.0	7.0	7.0	7.0	7.0	6.5	3.5*			
2108657			6.704	14.697	C	2029		0012	8.4	8.5	8.4	8.4	8.3	8.3	8.1	8.2	8.2	8.1	8.1	8.1	8.1	8.1	8.0	7.6		
38040000	55	221	0.000	0.358	C	1	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	5.5*	10.0				
CR 361A(			0.0C)			4	2.4	11000	8.2	8.4	8.1	7.6	7.1	7.7	7.4	7.3	7.1	7.0	7.1	7.0	6.9	8.1				
								FC3																		
									10.0	10.0	8.5	8.5	8.5	8.5	7.0	6.0*	6.0*	6.0*	5.5*	5.5*	4.9*	2.5*				
									7.3	7.6	7.0	7.0	6.5	6.9	6.6	6.8	7.2	6.5	6.5	6.1	6.5	6.1				
38040000	55	221	0.358	0.933	C	1	40	CRACKING	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	8.5	7.5	5.5*	7.0				
E JONES ST(			0.4R)			4	2.4	10200	7.9	8.4	8.1	8.1	7.3	7.7	7.4	7.3	7.1	7.0	7.1	7.0	6.9	6.2				
4323101			0.351	0.872	L	2018		FC125M																		
PREFERRED MATERIALS, INC.			(2019)					0012	5.5*	5.5*	5.0*	3.5*	3.0*	3.0*	10.0	10.0	10.0	10.0	10.0	10.0	9.0	8.0	6.5			
									6.2	5.7	6.5	6.6	6.4	6.6	8.5	8.0	8.3	8.1	7.8	7.8	7.6	7.2				
38040000	55	221	3.210	14.620	C	1	7	60	CRACKING	6.0*	6.0*	6.0*	5.5*	5.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0			
CR 359A(			3.4L)			2	8.8	3000	8.6	8.5	8.2	8.0	7.2			8.6	8.5	8.4	8.4	8.4	8.4	8.4	8.2			
4410581			3.447	13.387	C	2023		FC125H																		
ANDERSON			COLUMBIA	CO.,	INC(2025)			0012	10.0	8.5	8.5	7.5	7.0	7.0	6.0*	6.0*	5.5*	5.5*	5.5*		10.0	9.0				
									8.1	7.9	7.9	7.9	7.7	7.9	7.7	7.7	7.7	7.6	7.5		8.4	8.0				
38070000	51		0.346	2.127	C	1	30	CRACKING	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	9.0	9.0	9.0	9.0	9.0	9.0	9.0			
FIRST AVE S(			0.3L)			2	9.5	1100	7.6	7.2	7.2	7.0	6.4	8.1	7.9	7.8	7.7	7.8	7.6	7.4	7.3					
4088671			0.000	1.906	C	2004		FC95																		
ANDERSON			COLUMBIA	CO.,	INC(2005)			0012	8.5	7.0	7.0	7.0	7.0	7.0	5.5*	5.5*	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	0.0*			
4088672			0.346	1.933	C	2027		0012	7.2	7.0	6.9	6.9	6.8	6.8	6.6	6.5	6.4	6.4	6.2	6.2	6.3	5.9				
38070000	51		2.127	11.853	C	1	60	CRACKING	7.5	7.0	7.0	3.5*	3.5*	3.5*	3.5*	3.5*	3.5*	10.0	10.0	10.0	10.0	10.0	10.0			
FIRST AVE N(			2.2L)			2	9.5	1100	8.1	8.1	8.0	8.0	7.1	7.1	6.7	6.8	6.5	8.5	8.4	8.3	7.9					
2108502			2.127	11.853	C	2007		FC95																		
ANDERSON			COLUMBIA	CO.,	INC(2009)			0221	8.5	8.5	8.5	8.5	7.0	7.0	6.0*	6.0*	4.5*	4.5*	4.5*	4.5*	4.5*	4.5*	1.5*			
4470761			1.933	11.853	C	2023		0012	7.8	7.5	7.3	7.6	7.4	7.4	7.3	7.2	7.1	7.0	7.0	7.0	6.9	6.5				
38090000	30	98	0.259	11.687	C	1	60	CRACKING	10.0	10.0	8.5	8.5	7.0	7.0	7.0	6.0*	6.0*	6.0*	10.0	10.0	10.0	10.0	10.0			
AUCILLA LANDING RD(			0.3L)			2	31.7	2390	8.9	8.8	8.8	8.8	8.4	8.2	8.0	7.9	7.9	7.9	7.7	7.5	8.6	8.6				
2108832			0.000	11.861	C	2009		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2011)			0012	10.0	10.0	10.0	10.0	10.0	10.0	9.0	9.0	8.0	8.0	7.0	7.0	7.3	4.5*				
2108833			0.000	11.861	C	2029		0012	8.5	8.5	8.5	8.4	8.3	8.3	8.2	8.2	8.1	8.1	8.1	8.0	8.0	8.0	7.6			
38090000	30	98	11.687	24.698	C	1	60	CRACKING	3.5*		10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0	10.0			
CABBAGE GROVE(12.3L)						2	2.4	3000	7.8		8.8	8.8	8.5	8.4	8.3	8.2	8.0	8.2	8.4	8.3	8.1					
4433111			11.825	24.682	C	2022		FC125M																		
ANDERSON			COLUMBIA	CO.,	INC(2024)			0012	9.0	8.5	8.5	8.5	7.5	7.5	7.0	7.0	6.0*	6.0*		10.0	10.0	9.0				
									8.2	8.1	8.1	7.9	7.9	7.9	7.8	7.7	7.6	7.6		8.5	8.4	8.0				

*** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 *** INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 @ INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).

FLORIDA DEPARTMENT OF TRANSPORTATION**ALL SYSTEM PAVEMENT CONDITION FORECAST****PAVEMENT IMPROVEMENT PROJECTS IN FM WPA TENTATIVE PLAN – 2026 - 2031, EXTRACTED ON 08/28/2025**

SORT BY RDWYID MILEPOST R ASCENDING L DESCENDING

DISTRICT = 2 COUNTY = TAYLOR																														
RDWYID	BMP	EMP	RW	SYS	TYP	SPD	DISTRESS	SURVEYED YEAR													FUTURE									
SR US	G_BMP	G_EMP	LN	%T	AADT		RATINGS	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012										
INTERSECT AT	(MP SIDE)	SURFTYPE =====																												
ITMSEG-P	W_BMP	W_EMP	RW	FY-P	WKMX-P																									
CONTRACTOR	(AGE ONE YEAR)	ASTYPE															2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2030
ITMSEG-F	W_BMP	W_EMP	RW	FY-F	WKMX-F																	(PMRS)								
38501000	0.000	1.346	C	1	7	45	CRACKING																							
359A 221			2	2.4		1400	RIDE																							
						DGFC																								
4410581	0.000	1.346	C	2023	0012		CRACKING																							
ANDERSON	COLUMBIA	CO., INC(2025)					SPRIDE																							
															8.5	8.5	8.5	8.5	8.5	10.0	9.0									
															7.6	7.2	7.2	7.2	7.3	8.3	7.9									

"*" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2006, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 50 MPH.
 "**" INDICATES PAVEMENT DEFICIENT (ANY RATING <=6); START 2002, RIDE RATING OF 6 NOT CONSIDERED DEFICIENT WHEN SPEED LIMIT < 45 MPH.
 "@" INDICATES G1 PROJECT LENGTH SHORTER THAN ROADWAY SEGMENT 1 MILE OR MORE.
 2030 FORECASTED BY PAVEMARS (PMRS).