

6850000 TRAFFIC CONTROL SYSTEM AUXILIARIES
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

.....
Ananth Prasad
aprasad@ftba.com
(850) 942-1405

Comments: (7/27/22, Internal)

A couple of comments:

685-2.2.5 – Requires a 30A GFCI receptacle. These may exist but I’ve never seen GFCI circuits integrated into a 30A receptacle. This would probably require installing a 30A circuit breaker to feed the 30A receptacle. The language could be changed to “must include a 30A GFCI protected receptacle”. That would allow for installing a GFCI receptacle (if you can find one) or using a standard receptacle with and GFCI breaker.

996-7.2.5 – Should the GFCI receptacle in this spec match the one in 685-2.2.5? 30A versus 20A

Response:

Ananth Prasad
aprasad@ftba.com
(850) 942-1405

Comments: (7/29/22, Internal)

See the comment below ... we need to discuss this further.

685-5 Warranty (UPS)

No way the Mfgs are on board with the warranty provisions in todays market providing battery warranty for 3 years (if internal) and 5 years (if external). And more so, lead times for most Mfgs & models is well greater than the specified replacement within 10 days.

Response:
