

5270201 DETECTABLE WARNINGS
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Ananth Prasad
(850) 942-1404 ext 4
aprasad@ftba.com

Comments: (5-28-19, Internal)

See the comments below. Let's discuss and close the loop on this.

1. As discussed earlier, we have a problem with the immediately after completing the concrete cure period in accordance with 520-8. We need to be able to do these in bulk and not on a daily basis.
2. I am not sure what the point of this additional language is. It is creating a time deadline on something that does not matter. Seems like it is creating a potential argument that should not exist.

Response:

No Name

Comments: (5-30-19, Industry)

The description on this page is 5270201 Performance Turf. The link is for Detectable Warnings (2 pages)

Response:

Mary Anne Koos
(850) 414 -4321
Maryanne.Koos@dot.state.fl.us

Comments: (6-7-19, Industry)

Should the spec include concrete sidewalks and shared use paths, since both require detectable warnings. As written, it only applies to sidewalks. Then what about detectable warnings on asphalt paths? Maybe it should say is "For installations on newly placed concrete sidewalk or shared use path, use materials that may be installed during casting or applied to the concrete surface immediately after completing the concrete curing period specified. I'm wondering what benefit the new sentence adds?

Response:
