

SP0090201LS MEASUREMENT AND PAYMENT (LUMP SUM)
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

C Carlson
(813) 612-3200
Christine.Carlson@dot.state.fl.us

Comments: (6-7-19, Industry)

There are several references to section 9-2.3.2. There is not a section 9-2.3.2 for the Lump Sum SP0090201LS. It appears to be a typo and the section is actually 9-2.2.2?

Response:

Jimmy Fontaine
(407) 406-4694
jfontaine@mhcorbin.com

Comments: (6-19-19, Industry)

S102-0400 is our current QPL number. I'm trying to update this but the link is broken when I click on it. We want to make sure our system stays on the QPL with the proper updates.

Response:

Gerry Oliver
(704) 996-7248
gerry@patternpaving.com

Comments: (6-27-19, Industry)

For surface applied products that are resin adhered can we have a 48 hour window once the concrete has been placed?

Response:
