

6760201 TRAFFIC CABINETS
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Neil Monkman
(239) 462-7371
neil.monkman@wcgfl.com

Comments: (5-28-20, Industry)

Appears maybe a grammar error. ITS field cabinets must have dual thermostatically controlled fans ("with" or "and"???) one thermostat per fan, rated for continuous duty with a service life of at least three years

Response: Agree. We have added the word "with."

Tony Mendoza
(954) 448-0649
tmendoza@elandeng.com

Comments: (6-25-20, Industry)

676-3.3: Can the addition "Mounting straps must not obstruct pole handholes" be modified to include that conduits and LFMC also should not block handholes nor impede placement of the lowering device? This is something that has occurred on multiple occasions in recent projects where they run the just below the lowering device handhole and then the lowering tool is not able to be secured to the handhole for use.

Response: The standard plans should address where conduits enter the pole. We don't address conduit placement from the cabinet to the pole in the spec. No change at this time.
