## 0040309 SCOPE OF THE WORK COMMENTS FROM INDUSTRY REVIEW

Dongming White Work Phone: 850-597-2878

E-Mail: dongming.white@dot.state.fl.us

Comments: (7-24-23 Industry)

In 4-3.9.7, Florida Statues section 337.11(17) was referenced, though this could not be found in the online released version. In 4-3.9.7, for the case that the contractor's share to be at 45%, Just curious why the condition is "may be" instead of "shall be" in this case?

## **Response:**

Florida Statues section 337.11(17) is a new subsection of 337 and was passed and signed by the governor.

The condition is "may be" because the split is not always 45% depending on the negotiation/participation. The statute requires a split with the CEI and EOR; however, the language on the split depends on their participation and the percentage is a is a not to exceed percentage.