EXPECTED IMPLEMENTATION JULY 2024 (FY 2024-25)



SUBARTICLE 685-2.1 is deleted and the following substituted:

685-2 Materials.

685-2.1: General: Meet the following requirements:

ARTICLE 685-5 is deleted ad the following substituted:

685-5 Warranty.

Ensure the UPS includes a manufacturer's warranty covering defects for a minimum of 3 years (5 years for the batteries in accordance with 685-2.2) from the date of final acceptance in accordance with 5-11 and Section 608. The warranty must include provisions for providing a replacement UPS within 10 calendar days of notification for any UPS found to be defective during the warranty period at no cost to the FDOT or the maintaining agency.

Ensure the RPMU includes a manufacturer's warranty covering defects for a minimum of 3 years from the date of final acceptance in accordance with 5-11 and Section 608.