

9730000 COMMENT RECEIVED FROM INDUSTRY REVIEW

Section 973

Structural Plastics

Review Comments - June 2006

Ghulam Mujtaba

1. Page 1, 973-1, Paragraph 1
 1. “(NSCL)” The acronym NSCL does not match the description.
2. Page 1, 973-2, Paragraph 2
 1. The sentence is fragmented. Change the sentence to read: “In accordance with Section 6, provide manufacturer’s certification that the material meets the requirements of this section.”
3. Page 2. Table 1, No Headings
 1. Each column should have a heading describing the properties. For example, Column No. 1 would be “Properties”, Column No 2 “Specification”. It is not clear what “Skin” and “Core” mean.
4. Page 3, Table 2, No Headings
 1. See Comment No. 3.
 2. Also note that when the table breaks to another page as in Table 2, the Headings should carry over to define the columns.
5. Page 3, Table 4A, No Headings
 1. See Comment No. 3.
 2. See Comment No. 4-2
6. Page 4, Paragraph 1, Sentence 1
 1. Change “...14 foot span...” to “...14-foot span...”
7. Page 4, Table 5, No Headings
 1. See Comment No. 3
8. Page 4, Table 6A, No Headings
 1. See Comment No. 3
9. Page 4, Table 6B, No Headings
 1. See Comment No. 3
10. Page 5, Paragraph 1, Sentence 1
 1. Change “...”54 feet long...” to “...54-foot long...”

11. Page 5, Paragraph 2

1. The publisher of the book should be described.