

502 SHEAR CONNECTORS - DESCRIPTION.
(REV 10-16-08) (FA 12-10-08) (7-09)

ARTICLE 502-1 (Page 571) is deleted and the following substituted:

502-1 Description.

Furnish and install welded shear connectors on steel beams and girders at locations shown in the Contract Documents. Field weld shear connectors located on the top flange only after the deck forms are in place. However, if workers who walk on the top flange of erected girders have 100% fall protection in compliance with OSHA requirements, shear connectors located on the top flange of girders may be furnished and installed in the fabrication plant.