

4580000 BRIDGE DECK JOINTS
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

Barry Smith
414-4776

Comment: (4-16-11)

1. Suggest rewording as follows:

458-2.1 Poured Joint: *Furnish joint sealer or a Type A, B or C silicone sealant material* ~~Meeting~~ the requirements of Section 932 ~~for Joint Sealer or a Type A, B, or C Low Modulus Silicone Sealant material~~ that is *listed* on the Qualified Products List (QPL).

Response:

2. 458-2.3 Strip Seal Joint System, 2nd sentence:

Manufacturers seeking ~~approval of Strip Seal Joint Systems for inclusion on the QPL~~ *evaluation of their product for the QPL* shall submit an application in accordance with Section 6.

Response:

Thomas Bowles
941-757-0080

Comments: (5-18-11)

I do not know how the changes will affect the price point of these Sidewalk Joint Cover Plates. However, if it does not reduce the cost by a factor of ten, the public is getting a real screwing. There is no way one can contend that the benefit rises to the cost. These plates are ridiculously priced. It is shameful to waste public monies in this fashion. Further, I hesitate to point to the trip hazard a 1/4" thick plate represents for fear that the next proposed improvement will required the plate be recessed to achieve a flush condition.

Response:
