

# EXPECTED IMPLEMENTATION JANUARY 2012

## 102 MAINTENANCE OF TRAFFIC. (REV 8-3-11) (FA 8-9-11) (1-12)

SUBARTICLE 102-13.12.1 (Page 124) is deleted and the following substituted:

**102-13.12.1 Redirective:** Price and payment will be full compensation for furnishing, installing, maintaining and subsequently removing such crash cushions. Payment for restoring damaged crash cushions will be the manufacturer's/distributor's invoice price for the new materials/parts plus 20% markup. The 20% markup is compensation for all necessary work including; but not limited to, labor, equipment, supplies and profit, as authorized by the Engineer. Additional MOT required for the repair of the crash cushion will be paid for under the appropriate MOT pay item.

D

R

A

F

T