

502 SHEAR CONNECTORS.

(REV 2-22-10) (FA 4-15-10) (1-11)

ARTICLE 502-1 (Page 635) is deleted and the following substituted:

502-1 Description.

Furnish and install welded shear connectors on steel beams and girders at locations shown in the Contract Documents. Field weld shear connectors located on the top flange only after the deck forms are in place. Installation of shear connectors in the fabrication plant is not permitted.