

6320200 SIGNAL CABLE
COMMENTS FROM INTERNAL/INDUSTRY REVIEW

D4 Const.

Comment: (1-20-14)

While I agree that the specs shouldn't have the same language in several places, this change refers the user to Section 633, however 633 is revised to refer to 632???

Response: Agree. Additional requirements for support wire have been added to the language in Section 632 and the reference to Section 633 has been deleted.

Changes made.
