

PLAN VIEW



ELEVATION VIEW OF SADDLE PLATE

END VIEW



FIXED BEARING KEEPER BAR DETAIL

FIXED BEARING DETAILS



PLAN VIEW



ELEVATION VIEW OF SADDLE PLATE

END VIEW



EXPANSION BEARING KEEPER BAR DETAIL

EXPANSION BEARING DETAILS

LAST REVISION	REVISION	DESCRIPTION:
07/01/06		

FDOT DESIGN STANDARDS 2013

TEMPORARY DETOUR BRIDGE DETAILS - TIMBER PILE FOUNDATIONS

INDEX NO. 21610

SHEET NO. 1

6/28/2012 1:16:06 PM rd960rh C:\d\projects\standards\structures\2013book\21610-1of3.dgn



* Center ∠ 3 X 2 on ½" Top Cap PL.

PLAN VIEW



ELEVATION VIEW

END VIEW

BACKWALL BENT DETAILS

LAST REVISION	REVISION	DESCRIPTION:			INDEX NO.	SHEET NO.
07/01/06			FDOT DESIGN STANDARDS 2013	TEMPORARY DETOUR BRIDGE DETAILS - TIMBER PILE FOUNDATIONS	21610	2

C:\d\projects\standards\structures\2013book\21610-2of3.dgn
rd960rh
1:16:08 PM
6/28/2012



VIEW B-B
(SHOWING END OF CAP PLATES)



SECTION A-A



STRAP PLATE DETAIL



HOLD DOWN STRAP ASSEMBLY DETAIL



CAP BUTT SPLICE PLATE DETAIL

BACKWALL BENT DETAILS

LAST REVISION	REVISION	DESCRIPTION:				
07/01/06			FDOT DESIGN STANDARDS 2013	TEMPORARY DETOUR BRIDGE DETAILS - TIMBER PILE FOUNDATIONS	INDEX NO. 21610	SHEET NO. 3

C:\d\projects\standards\structures\2013book\21610-3of3.dgn
rd960rh
1:16:10 PM
6/28/2012