

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Letting: 01210318 Call Order: 003 Proposal: E1U34-R0 District:01
 Counties: DESOTO, GLADES, HARDEE, HENDRY, HIGHLANDS
 Road Name: Pipe Lining, Repair, Desilting and Video Inspection
 Limits: Midpoint
 Project(s): 43792917240(*) Federal Aid No: N/A
 Total Roadway Length: 0.000 Miles Contract Days: 365
 Total Bridge Length: 0.000 Miles Letting Date: 03/18/21
 Total Proposal Length: 0.000 Miles Contract Execution Days: 10
 Special Start Date: N/A
 Aquis/Flexible Start Time:

Proposal Budget Estimate: \$268,000.00

Please read the full advertisement

Description:

The work under this Contract consists of Pipe Lining, Repair, Desilting, and Video Inspection

Call Order: 003 Proposal: E1U34-R0

ALT	Item	Description	Unit	Quantity
Section 0001 PRESSURE GROUTING (CF)				
	0121- 70- 2	FLOWABLE FILL, MAINTENANCE CONTRACTS ONLY	CY	30.000
	0173- 71-	DRILLING HOLES FOR PRESSURE GROUTING	EA	20.000
	0173- 76-	GROUT PIPE INSTALLATION	LF	10.000
	0173- 77- 3	SUBSURFACE PRESSURE GROUTING, CEMENT SLURRY	CY	30.000
	0425- 74- 1	MANHOLES & INLETS CLEANING & SEALING, <10'	EA	10.000
	0425- 74- 2	MANHOLES & INLETS CLEANING & SEALING, >10'	EA	10.000
	0430-821- 25	CLEANING & SEALING EXISTING PIPE JOINT, 18" STORM SEWER	EA	10.000
	0430-821- 29	CLEANING & SEALING EXISTING PIPE JOINT, 24" STORM SEWER	EA	10.000
	0430-821- 33	CLEANING & SEALING EXISTING PIPE JOINT, 30" STORM SEWER	EA	10.000
	0430-821- 38	CLEANING & SEALING EXISTING PIPE JOINT, 36" STORM SEWER	EA	10.000
	0430-821- 40	CLEANING & SEALING EXISTING PIPE JOINT, 42", STORM SEWER	EA	5.000
	0430-821- 41	CLEANING & SEALING EXISTING PIPE JOINT, 48", STORM SEWER	EA	5.000
	0430-821- 42	CLEANING & SEALING EXISTING PIPE JOINT, 54", STORM SEWER	EA	5.000
	0430-821- 43	CLEANING & SEALING EXISTING PIPE JOINT, 60", STORM SEWER	EA	2.000
	0430-821- 61	CLEANING & SEALING EXISTING PIPE JOINT, >60", STORM SEWER	EA	1.000
	0430-950-	DESILTING CONCRETE BOX CULVERT	CY	30.000
	0432- 3- 2	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 18"	EA	1.000
	0432- 3- 4	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 24"	EA	1.000
	0432- 3- 5	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 30"	EA	1.000
	0432- 3- 6	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 36"	EA	1.000
	0432- 3- 7	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 42"	EA	1.000
	0432- 3- 8	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 48"	EA	1.000
	0432- 3- 9	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 54"	EA	1.000
	0432- 3- 10	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 66"	EA	1.000
	0432- 3- 11	CHEMICAL GROUT REPAIR, PIPE, NON-TEST, 60"	EA	1.000

Call Order: 003 Proposal: E1U34-R0

ALT	Item	Description	Unit	Quantity
	0906-173- 34	SINGLE COMPONENT POLYURETHANE INJECTION, PROJECT 437929 -1-72-24	GA	10.000
	0906-173- 35	TWO COMPONENT POLYURETHANE INJECTION, PROJECT 437929-1- 72-24	LB	1,000.000
	E425- 73- 1	CLEANING MANHOLES AND INLETS (MECHANICAL)	EA	50.000
	E425- 73- 2	REPAIR LEAKS IN MANHOLES AND INLETS	EA	50.000
	E425- 73- 3	FRAME AND GRATE (F&I)	EA	2.000
	E425- 73- 6	SECURE MANHOLE / INLET LIDS	EA	2.000
	E425- 73- 7	MANHOLE FRAME & COVER	EA	2.000
	E425- 73- 8	MANHOLE COVER	EA	2.000
	E430- 94- 1	DESILT PIPE, 0 to 24"	LF	5,000.000
	E430- 94- 2	DESILT PIPE, 25-36"	LF	5,000.000
	E430- 94- 3	DESILT PIPE, 37-48"	LF	1,000.000
	E430- 94- 4	DESILT PIPE, 49-60"	LF	150.000
	E430- 94- 5	DESILT PIPE, 61" OR GREATER	LF	150.000
	E430-949- 13	DESILTING PIPE (UNDERDRAIN) (4")	LF	100.000
	E430-949- 16	DESILTING PIPE (UNDERDRAIN) (6")	LF	100.000
	E431- 1- 21	PIPE LINER, CURED IN PLACE, 0-24"	LF	100.000
	E431- 1- 22	PIPE LINER, CURED IN PLACE, 25-36"	LF	50.000
	E431- 1- 23	PIPE LINER, CURED IN PLACE, 37-48"	LF	50.000
	E431- 1- 24	PIPE LINER, CURED IN PLACE, 49-60"	LF	50.000
	E431- 1- 25	PIPE LINER, CURED IN PLACE, 61" AND GREATER	LF	10.000
	E431- 1- 31	PIPE LINER, SLIP LINER, 0-24"	LF	100.000
	E431- 1- 32	PIPE LINER, SLIP LINER, 25-36"	LF	50.000
	E431- 1- 33	PIPE LINER, SLIP LINER, 37-48"	LF	50.000
	E431- 1- 34	PIPE LINER, SLIP LINER, 49-60"	LF	50.000
	E431- 1- 35	PIPE LINER, SLIP LINER, 61" AND GREATER	LF	10.000
	E432- 4-	STORM SEWER INSPECTION (VIDEO CAMERA)	LF	1,000.000