

**Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities**

Letting:	01210520	Call Order: 003	Proposal: E1U53-R0	District:01
Counties:	GLADES, HENDRY			
Road Name:	Guardrail Repair			
Limits:	Midpoint			
Project(s):	43274417257(*)	Federal Aid No: N/A		
Total Roadway Length:	0.000 Miles	Contract Days:	365	
Total Bridge Length:	0.000 Miles	Letting Date:	05/20/21	
Total Proposal Length:	0.000 Miles	Contract Execution Days:	10	
		Special Start Date:	N/A	
		Aquis/Flexible Start Time:		

Proposal Budget Estimate: \$120,000.00

Please read the full advertisement

Description:

The work under this Contract consists of GUARDRAIL REPAIR.

Call Order: 003 Proposal: E1U53-R0

ALT	Item	Description	Unit	Quantity
Section 0001 ASPHALT REPAIR (MANUAL) (TN)				
	0339- 1-	MISCELLANEOUS ASPHALT PAVEMENT	TN	10.000
	0515- 2-311	PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,42" TYPE 1	LF	1.000
	0515- 2-321	PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,54" TYPE 1	LF	1.000
	0536- 7- 1	SPECIAL GUARDRAIL POST- DEEP POST FOR SLOPE BREAK CONDITION- TIMBER OR STEEL	EA	1.000
	0536- 73-	GUARDRAIL REMOVAL	LF	50.000
	0536- 85- 26	GUARDRAIL END TREATMENT- TYPE CRT	EA	2.000
	0538- 1-	GUARDRAIL RESET	LF	100.000
	0544- 2- 1	CRASH CUSHION, TL-2, NARROW	EA	1.000
	0544- 3- 1	CRASH CUSHION, TL-3, NARROW	EA	1.000
	E536- 3-141	GUARDRAIL STANDARD PANEL (REPLACE) (SHOP BENT)	LF	1.000
	E536- 3-142	GUARDRAIL STANDARD PANEL (REPLACE) (0' - 50')	LF	2,000.000
	E536- 3-143	GUARDRAIL STANDARD PANEL (REPLACE) (51' - 200')	LF	2,000.000
	E536- 3-144	GUARDRAIL STANDARD PANEL (REPLACE) (> 200')	LF	500.000
	E536- 3-242	GUARDRAIL THRIE BEAM (REPLACE) (0' - 50')	LF	10.000
	E536- 3-540	GUARDRAIL (PIPE RAIL) (REPLACE)	LF	5.000
	E536- 5- 1	THRIE BEAM (TERMINAL CONNECTOR)	EA	2.000
	E536- 5- 2	THRIE BEAM (RAIL SPLICE)	EA	2.000
	E536- 5- 3	THRIE BEAM (TRANSITION SECTION)	EA	2.000
	E536- 5- 4	THRIE BEAM (MODIFIED OFFSET BLOCK)	EA	2.000
	E536- 6- 47	END ANCHORAGE ASSEM (REPLACE) (BARRIER WALL)	EA	2.000
	E536- 6- 48	END ANCHORAGE ASSEM (REPLACE) (TYPE SRT-350)	EA	2.000
	E536- 6-412	END ANCHORAGE ASSEM (REPLACE) (TYPE MELT)	EA	2.000
	E536- 6-424	END ANCHORAGE ASSEM (REPLACE) (PARALLEL)	EA	2.000
	E536- 6-425	GUARDRAIL END TREATMENT-FLARED APPROACH TERMINAL, REPLACE, MASH	EA	2.000
	E536- 12-604	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN CONC.)	EA	2.000

Call Order: 003 Proposal: E1U53-R0

ALT	Item	Description	Unit	Quantity
	E536- 12-605	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN ASPH.)	EA	50.000
	E536- 12-606	GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN SOIL)	EA	20.000
	E536- 12-608	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN ASPH.)	EA	20.000
	E536- 12-609	GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN SOIL)	EA	20.000
	E536- 12-615	GUARDRAIL REPAIRS (REPLACE) (FILLER BLOCKS)	EA	10.000
	E536- 15-	MISCELLANEOUS GUARDRAIL MAINTENANCE	LF	20.000
	E536- 65-	END ANCHORAGE ASSEM (REMOVE)	EA	1.000
	E536-301-502	END ANCHOR ASSEM TYPE II (REPL ROUND END SECT)	EA	4.000
	E536-302-503	END ANCHOR ASSEM TYPE IV (REPL BUFFER END SECT)	EA	2.000
	E536-302-504	END ANCHOR ASSEM TYPE IV (REPL ANCHOR PANEL SECT)	EA	2.000
	E536-302-505	END ANCHOR ASSEM TYPE IV (REPL CABLE ASSEMBLY)	EA	2.000
	E536-302-506	END ANCHOR ASSEM TYPE IV (REPL STEEL TUBE & POST)	EA	2.000
	E536-302-507	END ANCHOR ASSEM TYPE IV (REPL ANCHOR PLATE)	EA	2.000
	E536-302-508	END ANCHOR ASSEM TYPE IV (REPL TIMBER BREAK POST)	EA	10.000
	E536-306-501	END ANCHOR ASSEM BRIDGE (REPL SPECIAL END SHOE)	EA	2.000
	E536-306-503	END ANCHOR ASSEM BRIDGE (REPL TIMBER FILL BLOCK)	EA	2.000
	E536-314-501	END ANCHOR ASSEM SRT-350/8 (REPL CABLE ASSEMBLY)	EA	2.000
	E536-314-503	END ANCHOR ASSEM SRT-350/8 (REPL AMBER REFL SHT)	EA	2.000
	E536-314-504	END ANCHOR ASSEM SRT-350/8 (REPL BEARING PLATE)	EA	2.000
	E536-314-505	END ANCHOR ASSEM SRT-350/8 (REPL TIMBER BRK POST)	EA	10.000
	E536-314-509	END ANCHOR ASSEM SRT-350/8 (REPL STRUT/YOKE ASSM)	EA	2.000
	E536-314-510	END ANCHOR ASSEM SRT-350/8 (REPL TMBR LINE POST)	EA	2.000
	E536-314-511	END ANCHOR ASSEM SRT-350/8 (REPL GUARDRAIL BEAM)	EA	2.000
	E536-322-501	END ANCHOR ASSEM FLARED (REPL FLARED END SECT)	EA	2.000
	E536-322-502	END ANCHOR ASSEM FLARED (REPL ROUND END SECT)	EA	2.000
	E536-322-503	END ANCHOR ASSEM FLARED (REPL BUFFER END SECT)	EA	2.000
	E544- 76- 1	CRASH CUSHION (RESET)	EA	1.000
	E544-031-001	ATTENUATOR (QUADGUARD) F&I (FENDER PANEL)	EA	1.000
	E544-031-020	ATTENUATOR (QUADGUARD) F&I (DIAPHRAM)	EA	1.000
	E544-031-027	ATTENUATOR (QUADGRARD) F&I (HAZARD RFLT-9 BUTTON)	EA	1.000
	E544-031-039	ATTENUATOR (QUADGUARD) F&I (CARTRIDGE ASSEMBLY)	EA	2.000
	E544-031-040	ATTENUATOR (QUADGUARD) F&I (NOSE ASSEMBLY)	EA	2.000
	E544-031-041	ATTENUATOR (QUADGUARD) F&I (END SHOE, VERTICAL)	EA	1.000
	E544-031-046	ATTENUATOR (QUADGUARD) F&I (MONORAIL, 3 BAY)	EA	1.000
	E544-031-047	ATTENUATOR (QUADGUARD) F&I (MUSHROOM BOLT ASSM)	EA	1.000