

Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities

Letting: 01220818 Call Order: 005 Proposal: E1V66-R0 District:01
Counties: GLADES, HENDRY
Road Name: Guardrail Repair
Limits: Midpoint
Project(s): 43274417261(*) Federal Aid No: N/A
Total Roadway Length: 0.000 Miles Contract Days: 365
Total Bridge Length: 0.000 Miles Letting Date: 08/18/22
Total Proposal Length: 0.000 Miles Contract Execution Days: 10
Special Start Date: N/A
Aquis/Flexible Start Time:

Proposal Budget Estimate: \$180,000.00

Please read the full advertisement

Description:

The work under this Contract consists of Guardrail Repair.

Florida Department of Transportation
Bid Solicitation Notice and Approximate Quantities

Call Order: 005 Proposal: E1V66-R0

| ALT | Item | Description | Unit | Quantity |
|--|--------------|---|------|----------|
| Section 0001 ASPHALT REPAIR (MANUAL) (TN) | | | | |
| | 0339- 1- | MISCELLANEOUS ASPHALT PAVEMENT | TN | 20.000 |
| | 0515- 2-311 | PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,42" TYPE 1 | LF | 200.000 |
| | 0515- 2-321 | PEDESTRIAN/ BICYCLE RAILING, ALUMINUM ONLY,54" TYPE 1 | LF | 50.000 |
| | 0536- 7- 1 | SPECIAL GUARDRAIL POST- DEEP POST FOR SLOPE BREAK CONDITION- TIMBER OR STEEL | EA | 4.000 |
| | 0536- 73- | GUARDRAIL REMOVAL | LF | 50.000 |
| | 0538- 1- | GUARDRAIL RESET | LF | 100.000 |
| | 0544- 3- 1 | CRASH CUSHION, TL-3, NARROW | EA | 2.000 |
| | E536- 3-141 | GUARDRAIL STANDARD PANEL (REPLACE) (SHOP BENT) | LF | 100.000 |
| | E536- 3-142 | GUARDRAIL STANDARD PANEL (REPLACE) (0' - 50') | LF | 700.000 |
| | E536- 3-143 | GUARDRAIL STANDARD PANEL (REPLACE) (51' - 200') | LF | 150.000 |
| | E536- 3-144 | GUARDRAIL STANDARD PANEL (REPLACE) (> 200') | LF | 250.000 |
| | E536- 3-242 | GUARDRAIL THRIE BEAM (REPLACE) (0' - 50') | LF | 100.000 |
| | E536- 6-424 | END ANCHORAGE ASSEM (REPLACE) (PARALLEL) | EA | 21.000 |
| | E536- 6-425 | GUARDRAIL END TREATMENT-FLARED APPROACH TERMINAL, REPLACE, MASH | EA | 21.000 |
| | E536- 12-604 | GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN CONC.) | EA | 5.000 |
| | E536- 12-605 | GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN ASPH.) | EA | 50.000 |
| | E536- 12-606 | GUARDRAIL REPAIRS (REPLACE) (STEEL POST IN SOIL) | EA | 10.000 |
| | E536- 12-608 | GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN ASPH.) | EA | 50.000 |
| | E536- 12-609 | GUARDRAIL REPAIRS (REPLACE) (WOOD POST IN SOIL) | EA | 10.000 |
| | E536- 12-615 | GUARDRAIL REPAIRS (REPLACE) (FILLER BLOCKS) | EA | 100.000 |
| | E536- 15- | MISCELLANEOUS GUARDRAIL MAINTENANCE | LF | 100.000 |
| | E536-322-502 | END ANCHOR ASSEM FLARED (REPL ROUND END SECT) | EA | 3.000 |
| | E536-322-506 | END ANCHOR ASSEM FLARED (REPL GUARDRAIL BEAM) | EA | 1.000 |
| | E536-322-508 | END ANCHOR ASSEM FLARED (REPL TIMBER BREAK POST) | EA | 1.000 |
| | E536-322-515 | END ANCHOR ASSEM FLARED (REPL AMBER REFLECT SHEET) | EA | 10.000 |
| | E536-322-517 | END ANCHOR ASSEM FLARED (REPL SHORT TIMBR BREAK POST) | EA | 1.000 |
| | E536-324-515 | END ANCHOR ASSEM PARALLEL (REPL AMBER REFLECT SHEET) | EA | 10.000 |